

US EPA ARCHIVE DOCUMENT

DRAFT

**Coal Combustion Residue Impoundment
Round 9 - Dam Assessment Report**

*Glen Lyn Power Plant
Ash Pond Management Units
Appalachian Power
d/b/a American Electric Power
Glen Lyn, VA*

Prepared for:

United States Environmental Protection Agency
Office of Resource Conservation and Recovery

Prepared by:

Dewberry & Davis, LLC
Fairfax, Virginia



Under Contract Number: EP-09W001727
April 2011

DRAFT

INTRODUCTION, SUMMARY CONCLUSIONS AND RECOMMENDATIONS

The release of over five million cubic yards of coal combustion waste from the Tennessee Valley Authority's Kingston, Tennessee facility in December 2008 flooded more than 300 acres of land, damaging homes and property. In response the U.S. EPA is assessing the stability and functionality of coal combustion ash impoundments and other management units across the country and, as necessary, identifying any needed corrective measures.

This assessment of the stability and functionality of the Glen Lyn Power Station Ash Pond Management Units (Bottom Ash Pond and Fly Ash Pond) is based on a review of available documents and site assessment conducted by Dewberry personnel on February 16, 2011. In general, we found the supporting technical documentation provided to be adequate for preparation of this report (Section 1.1.3). In summary, the Bottom Ash Pond and Fly Ash Pond are **FAIR** for continued safe and reliable operation

PURPOSE AND SCOPE

The U.S. Environmental Protection Agency (EPA) is embarking on an initiative to investigate the potential for catastrophic failure of Coal Combustion Surface Impoundments (i.e., management units) from occurring at electric utilities in an effort to protect lives and property from the consequences of a dam failure or the improper release of impounded slurry. The EPA initiative is intended to identify conditions that may adversely affect the structural stability and functionality of a management unit and its appurtenant structures (if present); to note the extent of deterioration (if present), status of maintenance and/or a need for immediate repair; to evaluate conformity with current design and construction practices; and to determine the hazard potential classification for units not currently classified by the management unit owner or by a state or federal agency. The initiative will address management units that are classified as having a Less-than-Low, Low, Significant or High Hazard Potential ranking. (For Classification, see pp. 3-8 of the 2004 Federal Guidelines for Dam Safety)

In early 2009 the EPA sent its first wave of letters to coal-fired electric utilities seeking information on the safety of surface impoundments and similar facilities that receive liquid-borne material that store or dispose of coal combustion residue. This letter was issued under the authority of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 104(e), to assist the Agency in assessing the structural stability and functionality of such management units, including which facilities should be visited to perform a safety assessment of the berms, dikes, and dams used in the construction of these impoundments.

EPA requested that utility companies identify all management units including surface impoundments or similar diked or bermed management units or management units designated as

DRAFT

landfills that receive liquid-borne material used for the storage or disposal of residuals or by-products from the combustion of coal, including, but not limited to, fly ash, bottom ash, boiler slag, or flue gas emission control residuals. Utility companies provided information on the size, design, age and the amount of material placed in the units. The EPA used the information received from the utilities to determine preliminarily which management units had or potentially could have High Hazard Potential ranking.

The purpose of this report is **to evaluate the condition and potential of residue release from management units for hazard potential classification**. This evaluation included a site visit. Prior to conducting the site visit, a two-person team reviewed the information submitted to EPA, reviewed any relevant publicly available information from state or federal agencies regarding the unit hazard potential classification (if any) and accepted information provided via telephone communication with the management unit Owner (Appalachian Power d/b/a American Electric Power). Also, after the field visit, additional information was received by Dewberry & Davis LLC from the Owner about the Glen Lyn Ash Pond Management Units. The additional information was reviewed and also used in preparation of this report.

Factors considered in determining the hazard potential classification of the management units(s) included the age and size of the impoundment, the quantity of coal combustion residuals or by-products that were stored or disposed of in these impoundments, its past operating history, and its geographic location relative to down gradient population centers and/or sensitive environmental systems.

This report presents the opinion of the assessment team as to the potential of catastrophic failure and reports on the condition of the management unit(s).

LIMITATIONS

The assessment of dam safety reported herein is based on field observations and review of readily available information provided by the owner/operator of the subject coal combustion residue management unit(s). Qualified Dewberry engineering personnel performed the field observations and review and made the assessment in conformance with the required scope of work and in accordance with reasonable and acceptable engineering practices. No other warranty, either written or implied, is made with regard to our assessment of dam safety.

DRAFT

Table of Contents

	<u>Page</u>
INTRODUCTION, SUMMARY CONCLUSIONS AND RECOMMENDATIONS	II
PURPOSE AND SCOPE.....	II
1.0 CONCLUSIONS AND RECOMMENDATIONS.....	1-1
1.1 CONCLUSIONS.....	1-1
1.1.1 Conclusions Regarding the Structural Soundness of the Management Unit(s)	1-1
1.1.2 Conclusions Regarding the Hydrologic/Hydraulic Safety of the Management Unit(s)	1-1
1.1.3 Conclusions Regarding the Adequacy of Supporting Technical Documentation	1-2
1.1.4 Conclusions Regarding the Description of the Management Unit(s)	1-2
1.1.5 Conclusions Regarding the Field Observations	1-2
1.1.6 Conclusions Regarding the Adequacy of Maintenance and Methods of Operation	1-2
1.1.7 Conclusions Regarding the Adequacy of the Surveillance and Monitoring Program	1-2
1.1.8 Classification Regarding Suitability for Continued Safe and Reliable Operation.....	1-2
1.2 RECOMMENDATIONS.....	1-3
1.2.1 Recommendations Regarding the Structural Stability	1-3
1.2.2 Recommendations Regarding the Hydrologic/Hydraulic Safety	1-3
1.2.3 Recommendations Regarding the Supporting Technical Documentation.....	1-3
1.2.4 Recommendations Regarding the Maintenance and Methods of Operation.....	1-3
1.3 PARTICIPANTS AND ACKNOWLEDGEMENT	1-4
1.3.1 List of Participants:	1-4
1.3.2 Acknowledgement and Signature.....	1-5
2.0 DESCRIPTION OF THE COAL COMBUSTION RESIDUE MANAGEMENT UNIT(S).....	2-1
2.1 LOCATION AND GENERAL DESCRIPTION	2-1
2.2 COAL COMBUSTION RESIDUE HANDLING	2-2
2.2.1 Fly Ash.....	2-2
2.2.2 Bottom Ash.....	2-3
2.3 SIZE AND HAZARD CLASSIFICATION	2-3
2.4 AMOUNT AND TYPE OF RESIDUALS CURRENTLY CONTAINED IN THE UNIT(S) AND MAXIMUM CAPACITY.....	2-4
2.5 PRINCIPAL PROJECT STRUCTURES	2-5
2.5.1 Earth Embankment	2-5
2.5.2 Outlet Structures.....	2-5
2.6 CRITICAL INFRASTRUCTURE WITHIN FIVE MILES DOWN GRADIENT	2-6
3.0 SUMMARY OF RELEVANT REPORTS, PERMITS, AND INCIDENTS.....	3-1
3.1 SUMMARY OF LOCAL, STATE, AND FEDERAL ENVIRONMENTAL PERMITS	3-1
3.2 SUMMARY OF SPILL/RELEASE INCIDENTS.....	3-1
4.0 SUMMARY OF HISTORY OF CONSTRUCTION AND OPERATION	4-1
4.1 SUMMARY OF CONSTRUCTION HISTORY	4-1
4.1.1 Original Construction.....	4-1
4.1.2 Significant Changes/Modifications in Design since Original Construction	4-1
4.1.3 Significant Repairs/Rehabilitation since Original Construction	4-2

DRAFT

4.2	SUMMARY OF OPERATIONAL PROCEDURES	4-2
4.2.1	<i>Original Operational Procedures</i>	4-2
4.2.2	<i>Significant Changes in Operational Procedures and Original Startup</i>	4-2
4.2.3	<i>Current Operational Procedures</i>	4-2
4.2.4	<i>Other Notable Events since Original Startup</i>	4-3
5.0	FIELD OBSERVATIONS	5-1
5.1	PROJECT OVERVIEW AND SIGNIFICANT FINDINGS	5-1
5.2	FLY ASH POND	5-1
5.2.1	<i>Crest</i>	5-1
5.2.2	<i>Upstream/Inside Slope</i>	5-3
5.2.3	<i>Downstream/Outside Slope and Toe</i>	5-4
5.2.4	<i>Abutments and Groin Areas</i>	5-6
5.3	BOTTOM ASH POND	5-7
5.3.1	<i>Crest</i>	5-7
5.3.2	<i>Upstream/Inside Slope</i>	5-8
5.3.3	<i>Downstream/Outside Slope and Toe</i>	5-10
5.3.4	<i>Abutments and Groin Areas</i>	5-11
5.4	OUTLET STRUCTURES	5-12
5.4.1	<i>Overflow Structure</i>	5-12
5.4.2	<i>Outlet Conduit</i>	5-14
6.0	HYDROLOGIC/HYDRAULIC SAFETY.....	6-1
6.1	SUPPORTING TECHNICAL DOCUMENTATION	6-1
6.1.1	<i>Flood of Record</i>	6-1
6.1.2	<i>Inflow Design Flood</i>	6-1
6.1.3	<i>Spillway Rating</i>	6-1
6.1.4	<i>Downstream Flood Analysis</i>	6-1
6.2	ADEQUACY OF SUPPORTING TECHNICAL DOCUMENTATION	6-1
6.3	ASSESSMENT OF HYDROLOGIC/HYDRAULIC SAFETY	6-1
7.0	STRUCTURAL STABILITY	7-1
7.1	SUPPORTING TECHNICAL DOCUMENTATION	7-1
7.1.1	<i>Stability Analyses and Load Cases Analyzed</i>	7-1
7.1.2	<i>Design Parameters and Dam Materials</i>	7-1
7.1.3	<i>Uplift and/or Phreatic Surface Assumptions</i>	7-2
7.1.4	<i>Factors of Safety and Base Stresses</i>	7-2
7.1.5	<i>Liquefaction Potential</i>	7-2
7.1.6	<i>Critical Geological Conditions</i>	7-2
7.2	ADEQUACY OF SUPPORTING TECHNICAL DOCUMENTATION	7-3
7.3	ASSESSMENT OF STRUCTURAL STABILITY	7-3
8.0	ADEQUACY OF MAINTENANCE AND METHODS OF OPERATION.....	8-1
8.1	OPERATING PROCEDURES	8-1
8.2	MAINTENANCE OF THE DAM AND PROJECT FACILITIES	8-1
8.3	ASSESSMENT OF MAINTENANCE AND METHODS OF OPERATIONS	8-1
8.3.1	<i>Adequacy of Operating Procedures</i>	8-1
8.3.2	<i>Adequacy of Maintenance</i>	8-1

DRAFT

9.0	ADEQUACY OF SURVEILLANCE AND MONITORING PROGRAM.....	9-1
9.1	SURVEILLANCE PROCEDURES	9-1
9.2	INSTRUMENTATION MONITORING	9-1
9.3	ASSESSMENT OF SURVEILLANCE AND MONITORING PROGRAM	9-1
9.3.1	<i>Adequacy of Inspection Program.....</i>	<i>9-1</i>
9.3.2	<i>Adequacy of Instrumentation Monitoring Program.....</i>	<i>9-1</i>

DRAFT

EXHIBITS

- Exhibit 1: USGS Peak Streamflow, USGS 03176500 New River at Glen Lyn, VA
- Exhibit 2: FEMA Giles County FIS Study, Table 1-Summary of Discharges.
- Exhibit 3: FEMA Giles County FIRM, Map Number 51071C0176C
- Exhibit 4: FEMA Giles County FIRM, Map Number 51071C0038C
- Exhibit 5: USGS Seismic-Hazard Map for Central/Eastern US, 2%/50Years, 2008

APPENDIX A

- Document 1: Virginia DCR Inventory Number 07101 Certificate, Inventory Report and Operation & Maintenance Program
- Document 2: Virginia DCR Inventory Number 07102 Certificate, Inventory Report and Operation & Maintenance Program
- Document 3: Dam Safety Inspection Report, by Woodward-Clyde Consultants
- Document 4: AEP Engineering Drawings
- Document 5: AEP Dam & Dike Inspection and Maintenance Program Summary
- Document 6: Glen Lyn Plant, Annual Dam & Dike Inspection Report 2009, by AEP
- Document 7: Glen Lyn Plant, Dike Inspection Checklist 2009
- Document 8: Final Design Report, by GAI Consultants
- Document 9: EPA Impoundment Inventory in Response to February 2009 Letter
- Document 10: DCR Inspection Email to AEP 2008
- Document 11: AEP Annual Inspection Form & Report to VA DCR
- Document 12: Glen Lyn Plant, Annual Dam & Dike Inspection Report 2010, by AEP
- Document 13: Glen Lyn Plant Aerial Survey, Auxiliary Fly Ash Pond
- Document 14: Glen Lyn Plant Aerial Survey, Bottom Ash Pond
- Document 15: Stability Assessment Report, Bottom Ash Pond, March 16, 2011, by AEP

APPENDIX B

- Document 16: Fly Ash Pond, Dam Inspection Checklist
- Document 17: Bottom Ash Pond, Dam Inspection Checklist

DRAFT

1.0 CONCLUSIONS AND RECOMMENDATIONS

1.1 CONCLUSIONS

Conclusions are based on visual observations from a one-day site visit, February 16, 2011, and review of technical documentation provided by the Owner, which is provided in Appendix A.

1.1.1 Conclusions Regarding the Structural Soundness of the Management Unit(s)

The Fly Ash Pond and Bottom Ash Pond did not show any areas of significant structural concern during the one-day site visit.

Fly Ash Pond

The stability analysis report for the Fly Ash Pond was prepared by GAI engineers but did not draw specific conclusions regarding the structural soundness of the perimeter dike though factors of safety were provided for static and seismic loading conditions assuming the facility serves as a landfill in the future. Under these conditions, the minimum factors of safety calculated for static and seismic loading are 1.29 and 1.01, respectively. The GAI report submitted was unsigned and unsealed.

An analysis should also be performed that assumes the facility acts as an impoundment with a permanent pool at the crest of the existing spillway.

Bottom Ash Pond

The stability analysis report for the Bottom Ash Pond was prepared, signed and sealed by the Owner's engineers and indicates that the main perimeter dike for the Bottom Ash Pond is performing as intended. The minimum factors of safety calculated for static and seismic loading conditions are 1.60 and 1.08, respectively.

1.1.2 Conclusions Regarding the Hydrologic/Hydraulic Safety of the Management Unit(s)

Hydrologic/Hydraulic calculations were not provided for either pond; therefore, conclusions regarding the Hydrologic/Hydraulic Safety of the ponds cannot be made at this time.

DRAFT

1.1.3 Conclusions Regarding the Adequacy of Supporting Technical Documentation

The supporting technical documentation provided is adequate for preparation of this report. Documentation reviewed did not contain hydrologic/hydraulic calculations. A discussion on liquefaction at either pond was not provided. Technical documentation reviewed in preparation of this report is provided in Appendix A.

1.1.4 Conclusions Regarding the Description of the Management Unit(s)

The description of the Fly Ash Pond and Bottom Ash Pond provided by the Owner was an accurate representation of what Dewberry observed in the field.

1.1.5 Conclusions Regarding the Field Observations

Dewberry staff was provided adequate access to the Fly Ash Pond and Bottom Ash Pond to complete the field assessment. The visual assessment of the perimeter dikes for both ponds showed no significant signs of erosion, settlement or instability. Embankments appeared to be structurally sound. No indications of unsafe conditions or conditions needing immediate remedial action were noted during the one-day site visit.

1.1.6 Conclusions Regarding the Adequacy of Maintenance and Methods of Operation

Current operation and maintenance procedures appear adequate for the Fly Ash Pond and Bottom Ash Pond.

1.1.7 Conclusions Regarding the Adequacy of the Surveillance and Monitoring Program

Current surveillance and monitoring program procedures appear adequate for the Fly Ash Pond and Bottom Ash Pond. Both facilities are regulated and periodically inspected by Virginia Department of Conservation of Recreation (VA DCR), Division of Dam Safety.

1.1.8 Classification Regarding Suitability for Continued Safe and Reliable Operation

The Fly Ash Pond and Bottom Ash Pond are rated FAIR with acceptable performance expected under static and seismic loading

DRAFT

conditions in accordance with applicable safety regulatory criteria. A hydrologic and hydraulic analysis is required for both facilities to demonstrate adequate hydrologic loading conditions. The Fair classification is based on the one-day visual assessment performed by Dewberry and supporting technical documentation provided in Appendix A of this report.

1.2 RECOMMENDATIONS

1.2.1 Recommendations Regarding the Structural Stability

Perform a stability analysis of the Fly Ash Pond that assumes a proposed breaching of the perimeter dike of the Fly Ash Pond in accordance with appropriate regulations and requirements so that it does not impound water. Address the potential for liquefaction at the Fly Ash Pond and Bottom Ash Pond as it appears that this was not addressed in either stability analysis report.

1.2.2 Recommendations Regarding the Hydrologic/Hydraulic Safety

It is recommended that the Owner confirm with VA DCR, Division of Dam Safety whether or not a hydrologic and hydraulic analysis should be performed to evaluate the hydrologic/hydraulic safety of the Fly Ash Pond and Bottom Ash Pond. If so, perform the analysis in accordance with VA DCR requirements, and, if not, document the reasons why the analysis is not required by VA DCR.

1.2.3 Recommendations Regarding the Supporting Technical Documentation

It is recommended that technical documentation be prepared and submitted that addresses the potential for liquefaction at the Fly Ash Pond and Bottom Ash Pond.

1.2.4 Recommendations Regarding the Maintenance and Methods of Operation

It is recommended that all underbrush and trees be removed from the Fly Ash Pond and Bottom Ash Pond in accordance with VA DCR Dam Safety requirements. This includes all woody vegetation at and beyond the toe of the Fly Ash Pond perimeter dike as well as the embankment and toe of the Bottom Ash Pond adjacent to East River.

DRAFT

It is recommended that any animal burrows located along the perimeter dike of the Fly Ash Pond and Bottom Ash Pond be backfilled in accordance with standard geotechnical engineering practices for dams, and monitored for future reoccurrence.

It is recommended that the Owner perform an interior inspection of the outlet pipe for the Bottom Ash Pond. Interior inspection should focus on the structural integrity of the pipe, seepage, and debris accumulation. The inspection report should summarize all findings and remedial action required, if any. An interior inspection of the outlet pipe for the Fly Ash Pond doesn't appear warranted at this time as the facility is currently inactive; however, if it becomes active then an interior pipe inspection should be performed as well.

1.3 PARTICIPANTS AND ACKNOWLEDGEMENT

1.3.1 List of Participants:

Gary Zych, American Electric Power
Senior Engineer, Civil Engineering

Behrad Zand, American Electric Power
Engineer II, Geotechnical Engineering

Frank Tanner, American Electric Power
Glen Lynn Plant Director

Greg Lee, American Electric Power

Thomas I. Roberts, PE, CFM, VA Dept. of Conservation & Recreation
Dam Safety Regional Engineer

Jim Kohler, United States Environmental Protections Agency
LCDR, Public Health Services

Patrick Kelly, United States Environmental Protections Agency
Public Health Services

Scott Clarke, P.E., Dewberry
Associate, Water Resources

Lorainne Ramos Nieves, P.E., CFM, Dewberry
Engineer III, Water Resources

DRAFT

1.3.2 Acknowledgement and Signature

We acknowledge that the management units referenced herein was assessed on February 16, 2011.

Scott Clarke, P.E.

Lorraine Ramos Nieves, P.E.,CFM

DRAFT

2.0 DESCRIPTION OF THE COAL COMBUSTION RESIDUE MANAGEMENT UNIT(S)

2.1 LOCATION AND GENERAL DESCRIPTION

The Glen Lyn Power Plant, owned and operated by Appalachian Power d/b/a American Electric Power, is located just inside Giles County corporate limits in Glen Lyn, VA. The Plant is located along three watercourses; the New River to the north, Adair Run just east of the Fly Ash Pond and East River just west of the Bottom Ash Pond. The Plant functions as a coal fired electric power station, operating since 1919, and consists of two generator units with a total generation capacity of 335 MW. See Figure 2.1-1 Location Map and Figure 2.1-2 Aerial Photograph.

The Plant contains two management units for storing CCR, a Bottom Ash Pond and an auxiliary Fly Ash Pond. The Bottom Ash Pond is a multi-cell facility consisting of north, south and clearwater cells. The Fly Ash Pond is a single-cell facility that is currently inactive and does not receive CCR. Table 2.1 provides some general dimensions of both Ash Ponds.




Figure 2.1-1: Location Map

DRAFT



Figure 2.1-2: Aerial Photograph

Table 2.1: Summary of Approximate Dimensions and Size of Ash Ponds		
	Fly Ash Pond	Bottom Ash Pond
Dam Height (ft)	43	27
Crest Width (ft)	30	25-40
Length (ft)	2230	2500
Side Slopes (upstream) H:V	2.5:1	2:1
Side Slopes (downstream) H:V	2:1	1.5:1

2.2 COAL COMBUSTION RESIDUE HANDLING

2.2.1 Fly Ash

Fly ash generated inside boilers at this facility is collected by electrostatic precipitators (ESPs) and moved by forced draft air fans through ducts and into hoppers. Vacuum lines then carry dry ash collected within hoppers to a concrete fly ash silo. The concrete silos at the plant are about 35 ft tall and 30 ft in diameter; each rests on a concrete pad. No secondary containment exists for either the hopper or concrete silos. Once in silos, fly ash is conditioned with water to prevent dust emissions as well as to facilitate in its transportation. Wet fly ash residuals are either sold for

DRAFT

beneficial use or hauled in trucks for disposal at an offsite landfill located in West Virginia.

2.2.2 Bottom Ash

Bottom ash and clinkers from boiler tubes are collected inside hoppers below the boilers. The CCR are ground and sluiced through a concrete lined open channel, which leads to a tank where the slurry is then pumped into basalt-lined iron pipes measuring up to 1000 ft and leading into the bottom ash pond. The slurry pipes are primarily located above ground and have no secondary containment.

2.3 SIZE AND HAZARD CLASSIFICATION

According to VA DCR, Division of Dam Safety inventory reports, the Fly Ash Pond has a maximum capacity of 185 acre-feet with a maximum design height for storage of 43 feet (Appendix A, Document 1). The Bottom Ash Pond has a maximum capacity of approximately 90 acre-feet with a maximum design height for storage of 27 feet (Appendix A, Document 2). Based on Table 2.2a, the Fly Ash Pond is classified as an **Intermediate** size impoundment and the Bottom Ash Pond is classified as a **Small** size impoundment since dam height controls for both Ash Ponds.

**Table 2.2a: USACE ER 1110-2-106
Size Classification**

Category	Impoundment	
	Storage (Ac-ft)	Height (ft)
Small	50 and < 1,000	25 and < 40
Intermediate	1,000 and < 50,000	40 and < 100
Large	> 50,000	> 100

Both the Fly Ash Pond and Bottom Ash Pond have a **Low Hazard Classification** based on Table 2.2b.

The Fly Ash Pond is located along left bank of the New River and portion of the left bank of Adair Run near its confluence with the New River. A failure of this facility would be limited to the New River and/or Adair Run with no probable loss of human life and relatively low economic and/or environmental losses. VA DCR, Division of Dam Safety currently regulates this facility as a Low Hazard impoundment.

DRAFT

The Bottom Ash Pond is located along the left bank of the New River and portion of the East River near its confluence with the New River. A failure of this facility would be limited to the New River and/or East River with no probable loss of human life and relatively low economic and/or environmental losses. VA DCR, Division of Dam Safety currently regulates this facility as a Low Hazard impoundment.

Table 2.2b: FEMA Federal Guidelines for Dam Safety Hazard Classification		
	Loss of Human Life	Economic, Environmental, Lifeline Losses
Low	None Expected	Low and generally limited to owner
Significant	None Expected	Yes
High	Probable. One or more expected	Yes (but not necessary for classification)

2.4 AMOUNT AND TYPE OF RESIDUALS CURRENTLY CONTAINED IN THE UNIT(S) AND MAXIMUM CAPACITY

The Fly Ash Pond is currently inactive and did not appear to have any CCR stored in its impoundment area. The volume of CCR stored in the Bottom Ash Pond at the time of the one-day field assessment was not available by the Owner. Table 2.3 summarizes the storage capacity for the Ash Ponds.

Table 2.3: Approximate Maximum Capacity of Ash Ponds		
	Fly Ash Pond¹	Bottom Ash Pond (North & South Cells/ Clearwater Pond)
Maximum Pool Surface Area (acre)	10	5.8
Maximum Capacity (cubic yards)	303,845	145,200
Maximum Capacity (acre-feet)	185	90
Top of Dam (feet)	1540	1523
Normal Pool (feet)	1510	1505.5/1501.3

¹When pond was active.

2.5 PRINCIPAL PROJECT STRUCTURES

2.5.1 Earth Embankment

Fly Ash Pond

According to a Dam Safety Inspection report dated July 18, 1978 (Appendix A, Document 3); the original layout of the Fly Ash Pond consisted of three separate fly ash pond cells: Upper, Middle and Lower. The Middle pond cell is currently a permitted landfill and the Lower pond cell serves as a storm-water management (SWM) basin for the landfill. The Upper pond cell, which is known today as the auxiliary Fly Ash Pond, is the facility that was assessed for this report. The Fly Ash Pond earthen embankment was originally constructed of clayey shale to a top elevation of approximately 1536 ft. Based on the documentation provided, it is not clear what transitions took place to raise the embankment to its current elevation, 1540 ft. The auxiliary Fly Ash Pond is understood to have an earthen embankment consisting of a compacted fly ash core and a 3 ft thick clay blanket along the inside slope of the embankment. The upstream and downstream slopes of the embankment are approximately 2.5H: 1V and 2H: 1V, respectively.

Bottom Ash Pond

According to a Stability Assessment Report dated March 16, 2011 (Appendix A, Document 15), the original crest of the perimeter dike was at elevation 1525 ft and later lowered to elevation 1515 ft, its current elevation today. The upstream and downstream slopes of the perimeter embankment are approximately 3.0H: 1V and 2H: 1V, respectively. The overburden foundation material consists of clay shale, sand and gravel and sandy clay layers. The aforementioned 1979 inspection report states that the perimeter embankment was constructed of a lean clay and shale mixture. The Stability Assessment Report assumes the embankment was constructed of lean clay and bottom ash. The original design drawings of the Bottom Ash Pond perimeter embankment are not available.

2.5.2 Outlet Structures

Fly Ash Pond

The only outlet structure is located at the east end of the pond (Appendix A, Document 4). The outlet structure consists of a skimmer barrier

DRAFT

connected to an overflow drainage shaft and 24 inch diameter corrugated metal pipe to Adair Run.

Bottom Ash Pond

The only outlet structure is located at the west end of the clearwater pond cell (Appendix A, Document 4). The outlet structure consists of a skimmer barrier connected to an overflow drainage shaft and a 30 inch diameter reinforced concrete pipe to East River.

2.6 CRITICAL INFRASTRUCTURE WITHIN FIVE MILES DOWN GRADIENT

To the best of Dewberry's knowledge, there is no critical infrastructure within five miles downstream of both Management Units. The nearest downstream town is Hinton, West Virginia approximately 20.5 miles downstream of the Ash Ponds.

DRAFT

3.0 SUMMARY OF RELEVANT REPORTS, PERMITS, AND INCIDENTS

3.1 SUMMARY OF LOCAL, STATE, AND FEDERAL ENVIRONMENTAL PERMITS

VA DCR has a Dam Safety Program, under which both the Fly Ash Pond (Inventory Number 070101) and Bottom Ash Pond (Inventory Number 070102) are State Regulated. Each pond was issued a six-year Regular Class III Operation and Maintenance Certificate on March 20, 2008 (Appendix A, Document 1 and Document 2). Under the dam safety program, the Owner is required to submit annual inspection reports to DCR as well as an engineer's inventory report and a renewal certification application at the conclusion of each six-year term. Permitting is administered by VA DCR dependent on information provided by the Owner regarding basic inventory of each pond, an emergency action plan and an operation and maintenance review.

Additionally, the ponds are permitted through Virginia Department of Environmental Quality (VA DEQ). The Fly Ash Pond and the Bottom Ash Pond are currently listed as Outfall 006 and Outfall 004 respectively, under NPDES Permit No. VA0000370, issued July 15, 2009.

3.2 SUMMARY OF SPILL/RELEASE INCIDENTS

Fly Ash Pond

Documents supplied by the Owner indicated that a slope failure of the northern dike occurred upon first filling of the pond as well as a 10 ft deep sink hole along the south-west corner of the dike. The slope failure and sinkhole incidents appear to have occurred at separate times prior to 1978; however, no documentation could be found that confirmed a spill and/or release of CCRs due to these incidents. In response to the incidents it was recommended that the suitability of compacted fly ash as an embankment material be evaluated (Appendix A, Document 3).

Bottom Ash Pond

No documented spill/release incidents have occurred in association with the Bottom Ash Pond to the best of Dewberry's knowledge.

DRAFT

4.0 SUMMARY OF HISTORY OF CONSTRUCTION AND OPERATION

4.1 SUMMARY OF CONSTRUCTION HISTORY

4.1.1 Original Construction

Fly Ash Pond

The Fly Ash Pond was constructed in 1965. The original layout consisted of three separate fly ash pond cells: Upper, Middle and Lower.

Bottom Ash Pond

The Bottom Ash Pond was constructed in 1963. The original layout consisted of an earthen embankment running along both the East River and New River.

4.1.2 Significant Changes/Modifications in Design since Original Construction

Fly Ash Pond

Since original construction, the Middle pond cell has become a permitted landfill and the Lower pond cell has become a storm-water management (SWM) basin that serves the landfill. The Upper pond cell, which is known today as the auxiliary Fly Ash Pond, is the facility that was assessed for preparation of this report.

Engineering drawings provided by the Owner indicate some modifications to the Fly Ash Pond (Appendix A, Document 4). The outlet structure was modified to improve the drainage shaft masonry and reinforcement in 1965, and, in 1973, a pipe trestle was added to the slurry pipes that discharge into the pond. Drawings also indicate an increase in the capacity of upstream storage area in 1976; however, it is unclear whether this increase was for the Fly Ash Pond or Landfill storage areas. No record was found that documents the date and details of the installation of piezometers and observation wells along the embankment of the facility. This is also true for the toe drain system and riprap armor on the downstream embankment running along the New River.

Bottom Ash Pond

The Bottom Ash Pond layout was modified in 1976 to its current multi-cell layout. Engineering drawings note the modification of the bottom ash

DRAFT

storage area and construction of the intermediate outfalls from the north pond cell and south pond cell to the clearwater pond cell (Appendix A, Document 4). No records were found that document the date and details of the installation of piezometers and observations wells along the embankment. This is also true for the riprap armor added to the downstream embankment running along the New River.

4.1.3 Significant Repairs/Rehabilitation since Original Construction

Fly Ash Pond

The slope and sinkhole failures that occurred as discussed under Section 3.2 were repaired, but based on documentation provided no information was found regarding the design and construction of the repairs. It appears no other significant repairs/rehabilitation have occurred since original construction based on the documentation provided by the Owner.

Bottom Ash Pond

It appears no significant repairs/rehabilitation have occurred since original construction based on the documentation provided by the Owner.

4.2 SUMMARY OF OPERATIONAL PROCEDURES

4.2.1 Original Operational Procedures

Data reviewed by Dewberry did not contain the original operational procedures for the Fly Ash Pond or Bottom Ash Pond.

4.2.2 Significant Changes in Operational Procedures and Original Startup

Significant changes in operation procedures and original startup cannot be confirmed based on the documentation reviewed by Dewberry.

4.2.3 Current Operational Procedures

Fly Ash Pond

The Fly Ash Pond is currently not in operation and appears to be empty of CCRs. On the day of the assessment, the bottom of the facility was mostly dry with the exception of a small isolated low spot near the outfall of the pond where rainwater had collected. Until early 2009, the pond was used as an emergency backup pond for storing wet fly ash. From the 1970's to

DRAFT

2009 the pond intermittently received wet fly ash (on average four times a year) until 2009 when the slurry pipes to the pond were turned off. Today the Plant hauls 100% of all generated fly ash to permitted offsite landfills.

Bottom Ash Pond

The Bottom Ash Pond consists of two splitter dikes that create three cells: north, south and clearwater cells. Bottom ash from the Plant is sluiced to either the north or south cell while the other cell remains inactive. The inactive cell is periodically dredged of bottom ash after dewatering, and the material is loaded onto trucks where it is hauled offsite for permitted disposal. Overflow from the active cell is discharged to the clearwater cell through an outlet structure. Water from the clearwater cell flows into a skimmer structure and into a decant tower where it is conveyed to East River through a 30 inch diameter concrete pipe.

4.2.4 Other Notable Events since Original Startup

Based on the documentation provided, no other notable events have occurred with regards to operations since original startup of the Fly Ash Pond and Bottom Ash Pond.

DRAFT

5.0 FIELD OBSERVATIONS

5.1 PROJECT OVERVIEW AND SIGNIFICANT FINDINGS

Dewberry personnel Scott Clarke, P.E. and Lorainne Ramos Nieves, P.E., CFM performed a site visit on February 16, 2011 in company with the participants listed under Section 1.3.1.

The site visit began at 8:30 AM. The weather was clear and sunny. Photographs were taken of conditions observed and selected photographs are included in this report for visual reference. All pictures were taken by Dewberry personnel during the site visit. Appendix B includes two Coal Combustion Dam Inspection Checklist Forms; one for the Fly Ash Pond and one for the Bottom Ash Pond. These checklists provide a good summary and inventory of the items assessed during the site visit.

5.2 FLY ASH POND

5.2.1 Crest

The crest of the perimeter dike had no significant signs of depressions, tension cracks or other indications of settlement or shear failure. Figure 5.2.1-1 and Figure 5.2.1-2 shows the typical crest conditions along the perimeter dike.

DRAFT



Figure 5.2.1-1: Crest, Northwest. New River to the right not seen in this figure.



Figure 5.2.1-2: Crest, Southeast. Route 649 to the right.

DRAFT

5.2.2 Upstream/Inside Slope

The upstream slope of the perimeter dike, including all groins, had adequate and well maintained cover of grasses/weeds. There were no obvious signs of scarps, bulging cracks, depressions or other indications of slope instability. Some woody vegetation was noted growing on the northwest upstream slope of the pond. Figures 5.2.2-1 and 5.2.2-2 show representative upstream slope sections of the perimeter dike.



Figure 5.2.2-1: Upstream slope, Southeast. Note woody vegetation to right in foreground.



Figure 5.2.2-2: Upstream slope, North.

5.2.3 Downstream/Outside Slope and Toe

The downstream slope of the perimeter dike is vegetated with various species of maintained grasses and weeds. Significant woody vegetation and underbrush was noted growing at and beyond the toe of the north dike towards the New River. Based on what could be visually assessed, there were no scarps, sloughs, bulging, cracks, depressions or other indications of slope instability. Figures 5.2.3-1 thru 5.2.3-3 show representative downstream slope sections of the perimeter dike.

DRAFT



Figure 5.2.3-1: Downstream slope, Southeast. Note woody vegetation and trees growing at toe of the embankment.



Figure 5.2.3-2: Downstream slope, Southwest.

DRAFT



Figure 5.2.3-3: Downstream slope, Northwest.

5.2.4 Abutments and Groin Areas

All groins appear stable with a well maintained cover of grass. There were no observed scarps, sloughs, bulging, cracks, depressions or other indications of slope instability.



Figure 5.2.4: Groin, Northwest.

DRAFT

5.3 BOTTOM ASH POND

5.3.1 Crest

The crest of the perimeter dike had no significant signs of depressions, tension cracks or other indications of settlement or shear failure. Figure 5.3.1-1 and Figure 5.3.1-2 shows the typical crest conditions along the perimeter dike.



Figure 5.3.1-1: Crest, Northwest.

DRAFT

Figure 5.3.1-2: Crest, Northwest. New River to the right.

5.3.2 Upstream/Inside Slope

The upstream slope of the perimeter dike, including all groins, had adequate and well maintained cover of grasses/weeds. Some minor erosion repair work done along the upstream slope adjacent to outlet structure but overall no obvious signs of scarps, bulging cracks, depressions or other indications of slope instability. Figures 5.3.2-1 and 5.3.2-2 show representative upstream slope sections of the perimeter dike.

DRAFT



Figure 5.3.2-1: Upstream slope, Southwest.



Figure 5.3.2-2: Upstream slope, Southwest. Outlet structure in the background with erosion repairs to the right.

DRAFT

5.3.3 Downstream/Outside Slope and Toe

The downstream slope of the perimeter dike is vegetated with various species of maintained grasses and weeds. Significant woody vegetation and underbrush was noted growing on the slope of the dike adjacent to East River. Lower section of the dike adjacent to New River is protected with rip-rap armoring. Based on what could be visually assessed, there were no scarps, sloughs, bulging, cracks, depressions or other indications of slope instability. Figures 5.3.3-1 thru 5.3.3-2 show representative downstream slope sections of the perimeter dike.



Figure 5.3.3-1: Downstream slope, Northwest. New River to the right.



Figure 5.3.3-2: Downstream slope, East. East River to the right. Note woody vegetation and trees growing on dike.

5.3.4 Abutments and Groin Areas

All groins appear stable. All are covered with grass that is maintained except the north groin adjacent to the outlet structure where erosion has been repaired with rip-rap armor. There were no observed scarps, sloughs, bulging, cracks, depressions or other indications of slope instability. Figure 5.3.4 shows the groin with the repair.



Figure 5.3.4: North groin, Note rip-rap placed in groin area.

5.4 OUTLET STRUCTURES

5.4.1 Overflow Structure

Fly Ash Pond

When the Fly Ash Pond was active, flow would exit the outlet structure over a skimmer and weir and into a discharge pipe that would convey the outflow to Adair Run. The invert of the weir is well above the invert of the pond implying there used to be a permanent pool when the facility was active. There is no low level drain for the facility. The outlet structure appears to be in satisfactory condition despite its discontinued use (Figure 5.4.1-1). Because there is no low level drain, runoff puddles at the bottom of the inactive facility until it evaporates and/or infiltrates into the ground.



Figure 5.4.1-1: Outlet structure, Northeast.

Bottom Ash Pond

The overflow spillway structure is located at the northwest perimeter dike (Figure 5.4.1). The structure appears to be in satisfactory condition. The water exiting the outlet structure into the East River appeared to be flowing clear and there were no signs of clogging.

DRAFT

Figure 5.4.1: Outlet Structure, Southwest.

5.4.2 Outlet Conduit

Fly Ash Pond

Outlet conduit (Figure 5.4.2-1) consists of a 24-inch corrugated metal pipe with a weir at its outlet. It's suspected the weir was used for monitoring purposes when the facility was active. The conduit appeared to be in satisfactory shape based on what could be observed in the field. No signs of clogging were observed.



Figure 5.4.2-1: Fly Ash Pond outlet conduit to East River.

Bottom Ash Pond

Outlet conduit (Figure 5.4.2-2) consists of a 30-inch reinforced concrete pipe. The conduit appeared to be in satisfactory shape based on what was observed in the field; however, it was noted that there was some soil and rock debris inside the conduit lessening its capacity. Water exiting the outlet appeared to be flowing clear.

DRAFT



Figure 5.4.2-2: Bottom Ash Pond outlet conduit to East River.

6.0 HYDROLOGIC/HYDRAULIC SAFETY

6.1 SUPPORTING TECHNICAL DOCUMENTATION

6.1.1 Flood of Record

No documentation was provided to Dewberry regarding local flood records. USGS river gage (USGS 03176500) located along the New River at Glen Lyn shows the largest peak flows occurred during 1916 and 1940 (Exhibit 1). These peak flows are comparable to the New River 1% annual chance (100-year) discharges found in the Giles County FIS Study (Exhibit 2). Therefore, it appears that the flood of record is comparable to the base flood elevation of 1525 to 1526 feet specified in the Giles County FIRM dated December 25, 2009, Map Number 51071C0176C and the FIRM dated September 25, 2009, Map Number 51071C038C (Exhibits 3 and 4).

6.1.2 Inflow Design Flood

Data reviewed by Dewberry did not contain Inflow Design Flood information.

6.1.3 Spillway Rating

Data reviewed by Dewberry did not contain Spillway Rating information.

6.1.4 Downstream Flood Analysis

Data reviewed by Dewberry did not contain a downstream flood analysis

6.2 ADEQUACY OF SUPPORTING TECHNICAL DOCUMENTATION

Data reviewed by Dewberry did not contain the necessary documentation to make a proper determination on adequacy of hydrologic and hydraulic safety factors that were or were not considered in the design of the Fly Ash Pond and Bottom Ash Pond.

6.3 ASSESSMENT OF HYDROLOGIC/HYDRAULIC SAFETY

No technical documentation was submitted regarding Hydrologic and Hydraulic Safety; therefore, an assessment cannot be made at this time.

DRAFT

7.0 STRUCTURAL STABILITY

7.1 SUPPORTING TECHNICAL DOCUMENTATION

7.1.1 Stability Analyses and Load Cases Analyzed

Fly Ash Pond

A stability analysis report was provided for the Fly Ash Pond (Appendix A, Document 8). The report was prepared by GAI in 2007 and revised in 2009. The report was prepared as part of a proposed expansion of the existing onsite landfill into the inactive Fly Ash Pond. The slope stability analysis of the Fly Ash Pond perimeter dike considered static and seismic loading assuming the facility acted as a landfill with soil saturated to existing groundwater levels (phreatic surface).

Bottom Ash Pond

A stability analysis report was provided for the Bottom Ash Pond (Appendix A, Document 16). The report was prepared by the Owner in 2011. The report was prepared as supporting documentation for use in preparation of this report. The slope stability analysis of the Bottom Ash Pond perimeter dike considered varying conditions of static and seismic loading.

7.1.2 Design Parameters and Dam Materials

Fly Ash Pond

Ten boring logs were completed in 2006 by GAI (Appendix A, Document 8). Borings indicate that soils consist primarily of fly ash and alluvium with lesser amounts of residuum. The thickness of the fly ash ranges from 28 ft to 50 ft. Alluvial and residual soils, consisting of sands with varying amounts of silt, clay and gravel, were encountered at all borings. Bedrock consisted primarily of shale. The steepest slope used in the analysis was 2.2H: 1V.

Bottom Ash Pond

Nine boring logs were completed in 1995 by the Owner (Appendix A, Document 8). Overburden foundation material consists of layers of clay shale, sand and gravel, and sandy clay. Boring log shows bottom ash material throughout the embankment whereas the 1978 inspection report

DRAFT

(Appendix A, Document 3) states that the dikes were constructed of a lean clay and shale mixture. For the purposed of the slope stability analysis the embankment was assumed to be constructed of lean clay and bottom ash.

7.1.3 Uplift and/or Phreatic Surface Assumptions

Fly Ash Pond

Piezometer water-level readings vary from approximately elevation 1501 ft to 1487 ft and are significantly impacted by the New River according to the report by GAI (Appendix A, Document 3). Phreatic surfaces were incorporated into the stability analyses with the surface elevation between elevation 1488 ft and 1500 ft for Section A-A and at elevation 1500 ft for Section B-B.

Bottom Ash Pond

Uplift and/or Phreatic Surface Assumptions are not discussed in the stability analysis report.

7.1.4 Factors of Safety and Base Stresses

Fly Ash Pond

Factors of Safety range from 1.01 to 2.73 for static and seismic loading cases for landfill scenario (Appendix A, Document 3, Page 6 of 6).

Bottom Ash Pond

Factors of Safety range from 1.08 to 1.73 for static and seismic loading cases (Appendix A, Document 3, Page 6 of 8).

7.1.5 Liquefaction Potential

Liquefaction potential was not discussed in any of the documents submitted by the Owner for either pond.

7.1.6 Critical Geological Conditions

Documents submitted did not appear to indicate any critical geological conditions in the vicinity of the two ponds. It was noted by the Owner during the one-day site visit that the Plant is located near a fault that runs just south and approximately parallel to the ponds.

DRAFT

7.2 ADEQUACY OF SUPPORTING TECHNICAL DOCUMENTATION

The supporting technical documentation submitted to support the structural stability of the Bottom Ash Pond appears to be adequate. As well, the supporting technical documentation submitted to support the structural stability of the Fly Ash Pond appears to be adequate though static and seismic loading cases should be evaluated assuming the facility acts as an impoundment (instead of a landfill) with its pool full to the crest of its existing spillway.

7.3 ASSESSMENT OF STRUCTURAL STABILITY

Fly Ash Pond

Based on a visual site assessment and review of documentation provided, the overall structural stability of the perimeter dikes for the Fly Ash Pond appears to be fair. This rating considers the fact that there were no obvious signs of structural instability during the one-day site visit; that the facility is currently well maintained and inspected regularly; that the drainage area to the facility is contained to the perimeter dikes; but, that the facility has an undocumented history of the slope and sinkhole failures that occurred prior to 1978; liquefaction potential was not evaluated; and, the slope stability analysis did not evaluate the static and seismic loading cases where the facility acts as an impoundment (instead of a landfill).

Bottom Ash Pond

Based on a visual site assessment and review of documentation provided, the overall structural stability of the perimeter dikes for the Bottom Ash Pond appears to be fair. This rating considers the fact that there were no obvious signs of structural instability during the one-day site visit; that the facility is currently well maintained and inspected regularly; that the drainage area to the facility is contained to the perimeter dikes; but, that liquefaction potential was not evaluated; and the dike along the East River is heavily covered with woody vegetation making inspection of the dike in that area difficult.

DRAFT

8.0 ADEQUACY OF MAINTENANCE AND METHODS OF OPERATION

8.1 OPERATING PROCEDURES

Operating procedures reviewed appear adequate for the Fly Ash Pond and Bottom Ash Pond. Today only the Bottom Ash Pond is in operation whereas the Fly Ash Pond is currently inactive and being considered for transition into an extension of the adjacent onsite ash landfill.

8.2 MAINTENANCE OF THE DAM AND PROJECT FACILITIES

In 1983, the Owner adopted a Dam and Dike Inspection and Maintenance Program (DIMP), where all earthen dams and dikes used for ash storage or disposal, waste water ponds, and large cooling water storage facilities under the Owner's management are routinely inspected, documented, and monitored. Under this program, there are four separate levels of inspection. First is to routinely make inspections by plant personnel to monitor visible changes; second is to make formal 'checklist type' inspections completed by plant personnel on a quarterly basis; third is to routinely schedule engineering inspections supervised by a professional engineer according to the risk classification of the dam; and, fourth are non routine inspections completed after heavy rains, seismic activity or other major events. The inspection and maintenance program continues today for the Fly Ash Pond and Bottom Ash Pond.

8.3 ASSESSMENT OF MAINTENANCE AND METHODS OF OPERATIONS

8.3.1 Adequacy of Operating Procedures

Operating procedures appear adequate.

8.3.2 Adequacy of Maintenance

Maintenance procedures appear adequate.

DRAFT

9.0 ADEQUACY OF SURVEILLANCE AND MONITORING PROGRAM

9.1 SURVEILLANCE PROCEDURES

Surveillance procedures are in conformance with the Owner's adopted DIMP as discussed under Section 8.2.

9.2 INSTRUMENTATION MONITORING

Instrumentation including piezometers and observation wells were installed at the Fly Ash Pond and Bottom Ash Pond as temporary measures to collect data for use in the slope stability analyses for each pond. A continuous record of observations from these instruments is not tracked

9.3 ASSESSMENT OF SURVEILLANCE AND MONITORING PROGRAM

9.3.1 Adequacy of Inspection Program


Inspection program appears adequate.

9.3.2 Adequacy of Instrumentation Monitoring Program

No permanent instrumentation monitoring program.

DRAFT

Exhibit 1: USGS Peak Streamflow, USGS 03176500 New River at Glen Lyn, VA



DRAFT

1930	Oct. 03, 1929	16.75 ³	99,000	1978	Nov. 07, 1977	18.12	110,000 ⁶
1931	Aug. 23, 1931	7.66 ³	19,600	1979	Feb. 26, 1979	13.62	63,600 ⁶
1932	May 02, 1932	7.94 ³	21,200	1980	Apr. 15, 1980	12.08	49,700 ⁶
1933	Oct. 18, 1932	9.84 ³	32,500	1981	May 29, 1981	9.59	31,600 ⁶
1934	Mar. 28, 1934		35,000 ²	1982	Feb. 04, 1982	12.14	50,400 ⁶
1935	Jan. 23, 1935	13.40 ³	63,600	1983	Apr. 10, 1983	12.96	57,100 ⁶
1936	Feb. 15, 1936	12.00 ³	51,600	1984	Feb. 15, 1984	11.96	48,700 ⁶
1937	Jan. 20, 1937	10.95 ³	43,500	1985	Aug. 19, 1985	8.95	24,700 ⁶
1938	Oct. 20, 1937	12.65 ³	56,600	1986	Nov. 05, 1985	12.55	53,600 ⁶
1939	Jan. 31, 1939	7.60 ³	20,100 ⁶	1987	Apr. 25, 1987	15.97	85,200 ⁶
1940	Aug. 14, 1940	27.50	226,000 ⁶	1988	Jan. 20, 1988	6.47	12,900 ⁶
1941	Jul. 06, 1941	8.30	24,300 ⁶	1989	Sep. 23, 1989	17.71	103,000 ⁶
1942	May 22, 1942	10.91	43,100 ⁶	1990	Nov. 17, 1989	11.38	44,300 ⁶
1943	Dec. 31, 1942	9.55	33,200 ⁶	1991	Mar. 31, 1991	9.61	31,600 ⁶
1944	Feb. 18, 1944	11.01	43,900 ⁶	1992	Jun. 05, 1992	17.47	100,000 ⁶
1945	Sep. 18, 1945	14.50	76,000 ⁶	1993	Mar. 24, 1993	17.47	100,000 ⁶
1946	Jan. 08, 1946	13.50	66,000 ⁶	1994	Aug. 18, 1994	13.58	62,400 ⁶
1947	Jan. 21, 1947	11.10	44,700 ⁶	1995	Jan. 16, 1995	19.83	125,000 ⁶
1948	Feb. 15, 1948	11.32	46,300 ⁶	1996	Jan. 19, 1996	18.01	105,000 ⁶
1949	Dec. 04, 1948	11.66	49,700 ⁶	1997	Dec. 02, 1996	11.28	43,500 ⁶
1950	Feb. 02, 1950	9.09	29,600 ⁶	1998	Apr. 20, 1998	12.93	56,700 ⁶
1951	Dec. 08, 1950	14.85	79,000 ⁶	1999	May 15, 1999	6.88	16,300 ⁶
1952	Mar. 12, 1952	9.90	35,400 ⁶	2000	Apr. 19, 2000	7.49	18,100 ⁶
1953	Feb. 22, 1953	11.42	47,100 ⁶	2001	May 23, 2001	9.82	33,200 ⁶
1954	Mar. 01, 1954	11.93	51,500 ⁶	2002	Mar. 19, 2002	11.28	43,500 ⁶
1955	Apr. 15, 1955	10.13	36,900 ⁶	2003	Feb. 23, 2003	15.71	82,700 ⁶
1956	Apr. 17, 1956	11.13	44,700 ⁶	2004	Nov. 20, 2003	17.40	99,600 ⁶
1957	Apr. 06, 1957	13.57	66,700 ⁶	2005	Mar. 29, 2005	10.64	38,900 ⁶
1958	Mar. 31, 1958	10.41	35,300 ⁶	2006	Jun. 28, 2006	11.01	41,500 ⁶
1959	Dec. 29, 1958	12.15	52,000 ⁶	2007	Mar. 17, 2007	8.54	24,300 ⁶
1960	Mar. 31, 1960	13.60	66,000 ⁶	2008	Oct. 27, 2007	8.45	23,700 ⁶
1961	May 13, 1961	12.14	51,000 ⁶	2009	May 08, 2009	8.76	25,300 ⁶

■ Peak Gage-Height Qualification Codes.

- 3 -- Gage height at different site and(or) datum


DRAFT

Exhibit 2: FEMA Giles County FIS Study, Table 1-Summary of Discharges.

TABLE 2. SUMMARY OF DISCHARGES					
FLOODING SOURCE AND LOCATION	DRAINAGE AREA (sq. miles)	PEAK DISCHARGES (cubic feet per second)			
		10-Percent- Annual- Chance	2-Percent- Annual- Chance	1-Percent- Annual- Chance	0.2-Percent- Annual- Chance
DOE CREEK					
At mouth, Pembroke	8.6	1,040	1,690	2,200	3,850
Above Mays Hollow, Pembroke	7.7	950	1,550	2,000	3,550
At U.S. Highway 460	6.9	830	1,350	1,700	3,150
Above U.S. Route 460, Pembroke	6.9	890	1,450	1,850	3,350
At State Route 678	5.3	720	1,180	1,500	2,815
At State Route 615	4	610	1,010	1,290	2,460
EAST RIVER					
U.S. Highway 460, Glen Lyn	76	5,200	8,150	9,750	14,000
GREENBRIER BRANCH					
At Mouth	2.8	300	480	600	900
At U.S. Highway 460	1.6	150	245	315	485
At State Route 608	1.1	140	230	290	450
LAUREL BRANCH					
At Mouth	4.3	535	890	1,125	1,740
At Private Route (State Route 628 Extended)	3.3	420	690	880	1,365
LITTLE STONY CREEK					
At Mouth, Pembroke	24.2	2,200	4,000	5,180	7,900
Johnson Avenue, Pembroke	22.8	2,100	3,850	4,900	7,450
At State Route 688	21.7	2,100	3,600	4,500	6,900
At Jefferson National Forest Boundary	19.3	1,935	3,200	4,000	6,100
MAYS HOLLOW					
At Mouth, Pembroke	0.4	165	290	365	590
MILL CREEK					
At Mouth, Narrows	6.8	603	1,140	1,423	2,230
College Street, Narrows	6.5	578	1,095	1,378	2,090
PINEY CREEK					
At Mouth	3.04	400	650	825	1,275
6,900 Feet above Mouth	1.85	275	450	575	900
NEW RIVER					
At U.S. Highway 460, Glen Lyn	3,768	98,500	174,000	230,000	450,000
Cross Section F at Rich Creek	3,760	98,500	174,000	230,000	450,000
Downstream of Narrows	3,725	97,400	172,400	227,750	446,300


DRAFT

Exhibit 3: FEMA Giles County FIRM, Map Number 51071C0176C




DRAFT

Exhibit 4: FEMA Giles County FIRM, Map Number 51071C0038C



DRAFT

Exhibit 5: USGS Seismic-Hazard Map for Central/Eastern US, 2%/50Years, 2008



APPENDIX A

L. Preston Bryant, Jr.
Secretary of Natural Resources



Joseph H. Maroon
Director

COMMONWEALTH of VIRGINIA
DEPARTMENT OF CONSERVATION AND RECREATION

203 Governor Street, Suite 206
Richmond, Virginia 23219-2010
(804) 371-6095 Fax (804) 371-2630

April 4, 2008

Appalachian Power Company
Attn: William Smith
Post Office Box 2021
Roanoke, VA 24022-2122

RE: Glen Lyn Fly Ash Dam, Inventory Number 07101

Dear Mr. Smith:

The Operation and Maintenance Certificate Application for Glen Lyn Fly Ash Dam, Inventory Number 07101, and the required supporting documents have been reviewed for compliance with the provisions of the Code of Virginia, Dam Safety Act, (Section 10.1-604 et. seq.) and the regulations promulgated by the Virginia Soil and Water Conservation Board (Board). Based on this information, on March 20, 2008, the Board issued a six-year (03/20/2008 - 3/31/2014) Regular Class III Operation and Maintenance Certificate (Certificate). The Certificate and other pertinent data are enclosed.

The Dam Safety Act requires dam owners to maintain their dam in a condition to prevent unreasonable threats to life and property of others. The classification of your dam and the Certificate issued were based on the current known downstream hazard potential from upstream characteristics, a re-inspection report, operation and maintenance application, and an emergency action plan. The actions contained in the documents accompanying your Certificate Application must be adhered to for the duration of the terms contained in the Certificate. To assist you in adhering to the terms of the Certificate, the following table provides a schedule of dates to submit required documents.

William Smith
April 4, 2008
Page 2

Annual Owner's Inspection Report	Owner's Engineer Inventory Report	Renewal Certification Six Year Application by Owner and Owner's Engineer
03/31/2009		
03/31/2010		
03/31/2011		
03/31/2012		
03/31/2013	12/31/2013	12/31/2013

Should you have questions, please direct them to Thomas I. Roberts, P.E., Dam Safety Regional Engineer, Department of Conservation and Recreation, Dam Safety and Floodplain Management Division, 8 Radford Street, Suite 203, Christiansburg, VA 24073, telephone 540-394-2550 or via e-mail at Thomas.Roberts@dcr.virginia.gov.

Sincerely,



William G. Browning
Director, Dam Safety & Floodplain Management Division

Enclosures as stated:

c: James M. Robinson, P.E., Dam Safety Program Manager
Thomas I. Roberts, P.E. Dam Safety Regional Engineer

DATA SHEET - OPERATION AND MAINTENANCE CERTIFICATE

Department of Conservation & Recreation
Division of Dam Safety & Floodplain Management
203 Governor Street, Suite 206
Richmond, VA 23219-2094

Name of Dam Glen Lyn Fly Ash Dam	Inventory Number 07101
Location Offstream Dam Near New River	City/County Giles
Owner Appalachian Power Company Attn: William Smith	Designed by Casa Grande Consultants
Address 40 Franklin Road, P.O. Box 2021	Constructed by George Lynch
City/Town/Zip Roanoke, VA 24022-2121	Year Constructed 1965
Type of Dam Earthfill	Purpose Sediment-Fly Ash
Drainage Area (Sq. Mi.) 0.02	Type of Watershed N/A
Total Height (Ft.) 43	Elevation 1540
Normal Pool Height (Ft.): 13	Elevation 1510
Maximum Capacity (Acre Ft.) 300	Maximum Area (Acres) 10
Normal Capacity (Acre Ft.) 80	Normal Area (Acres) 5
Size Classification Medium	Hazard Classification III
Required Spillway Design Flood 14% PMF	Available Spillway Design Flood Impounds PMF
Type of Spillway N/A	<i>(Note if Section 130)</i>

Operation and Maintenance Plans & Schedule by

AEP/Pedro Jose Amaya-Trujillo, VA PE #036174

() Reinspection or (X) Inventory Report by

AEP/Pedro Jose Amaya-Trujillo, VA PE #036174

Emergency Action Plan filed with:

(X) Virginia Dept. of Emergency Management

(X) Local Coordinator of Emergency Services

City/County: **Giles County**Application Reviewed and Recommended for: **Six-Year Regular O & M Certificate (3/20/2008-3/31/2014)**By **Thomas I Roberts, PE # 19966**Date **March 17, 2008**

Concurrence with the Recommendation

By **William G. Browning, Director**Date **March 19, 2008**

US EPA ARCHIVE DOCUMENT



COMMONWEALTH of VIRGINIA

DEPARTMENT OF CONSERVATION AND RECREATION
DIVISION OF DAM SAFETY
VIRGINIA SOIL AND WATER CONSERVATION BOARD

**DAM SAFETY CERTIFICATE
REGULAR
CLASS III OPERATION & MAINTENANCE CERTIFICATE NUMBER 07101**

Appalachian Power Company, owner of Glen Lyn Fly Ash Dam in Giles County, is entitled to operate and maintain this dam pursuant to the provisions of the Dam Safety Act (Section 10.1-604 et seq., Code of Virginia) and Regulations promulgated thereunder.

This certificate is for a term of six years. It becomes effective March 20, 2008 and expires March 31, 2014. In accordance with §4VAC50-20-100F of the Regulations, the owner shall apply for a new certificate 90 days prior to its expiration.

Joseph H. Maun



INVENTORY REPORT FOR CLASS III AND CLASS IV IMPOUNDING STRUCTURES

Reference: Impounding Structure Regulations, 4VAC50-20-00 et seq., Virginia Soil and Water Conservation Board

1 Project Information:

- a. Name of Impounding Structure Glen Lyn Fly Ash Dam
- b. Inventory Number 071.01 Other Name (if any) Fly Ash Pond
- c. Name of Reservoir Glen Lyn Plant Fly Ash Pond
- d. Purpose of Reservoir Standby use for impoundment of coal combustion fly ash. Sediment and stormwater runoff pond for ash landfill

2 Location of Impounding Structure:

- a. City/County Giles County Magisterial District _____
- b. Located 1 feet/miles upstream/downstream of Highway No 460
- c. Name of River or Stream Upground Reservoir adjacent to New River
- d. Latitude N37 22' 30" Longitude W80 52'

3. Ownership:

- a. Owner's Name Appalachian Power Company
- b. Mailing Address 40 Franklin Road; P.O. Box 2011
Roanoke, VA 24022-2121
- c. Telephone (800) 956-4237

4 Owner's Engineer:

- a. Engineering Firm/Engineer American Electric Power Service Corporation
- b. Professional Engineer Virginia Number Pedro Jose Amaya-Trujillo VA#036174
- c. Mailing Address 1 Riverside Plaza
Columbus, Ohio 43215
- d. Telephone (614) 716-1000 or (614) 716-2926

5. Impounding Structure Data (All elevations NGVD unless noted):

a. Type of Material earth X concrete _____ masonry _____

Other: _____

Design Configurationb. Top of Dam 1540 Feet (if known)c. Downstream Toe (Lowest) appr. 1497 Elev (if known)d. Height of Dam 43 Feete. Crest Length (Exclusive of Spillway) 2230 Feetf. Crest Width 30 Feetg. Upstream Slope 2.5 H: 1 Vh. Downstream Slope 2 H: 1 V

6. Reservoir Data

Design Configurationa. Maximum Capacity 185 Acre-feetb. Maximum Pool 1538 Elev (if known)c. Maximum Pool Surface Area 10 Acresd. Normal Capacity 155 Acre-feete. Normal Pool appr. 1510 Elev (if known)

f. Normal Pool Surface Area _____ Acres

g. Freeboard (Normal Pool to Top) 30 Feeth. Freeboard (Normal Pool to Emergency) N/A Feet

7. Spillway Data

TypeConstruction MaterialMaximum Capacitya. Low Level Drain N/A _____b. Principal Spillway Weir & Pipe Concrete & Steel 300 cfsc. Emergency Spillway N/A _____Design Configurationd. Low Level Drain N/A Feet (if known)e. Principal Spillway 1538.0 Elev (if known)f. Emergency Spillway N/A Elev (if known)

g. Briefly describe the low level drain and principal spillway to include dimensions, materials of construction, trash guards, location in reservoir and through dam, and orientation of intake and discharge to dam if looking downstream: N/A

h. Describe the emergency spillway to include dimensions, whether the spillway is an earth channel or other construction, spillway surface protection, and orientation to dam if looking downstream: N/A

8. Watershed Data (Class III only):

a. Drainage Area 10.5 Acres
.016 Sq. Miles

b. Type and Extent of Watershed Development Roadway around the crest of dike.

c. Time of Concentration -- Method --

d. Spillway Design Flood used (mark appropriate box)

☐ PMF, source _____
☐ 1/2 PMF, source _____
☐ 100 Year, source _____
☐ 50 Year, source _____
☐ Other, source Not Applicable

e. Design inflow hydrograph: Volume -- acre-feet;

Peak inflow -- CFS;

Rainfall duration of design inflow hydrograph -- hours

f. Freeboard during passage of spillway design flood -- feet

9. Impounding Structure History

a. Date construction completed 1965

b. Design by Casagrande Consultant Date: 1964

c. Built by unknown Date: 1965

- d. Inspection dates 1978, 1980, 1982, and annually from 1984-2007
- e. Inspections by Woodward-Clyde Consultants, AEPSC, & Geosyntec Consultants
- f. Description of repairs Brush and tree cutting, filling erosion, gullies, filling animal holes, repairs to several seepage collection pipes.
- g. Has the impounding structure ever been overtopped? Yes ☒ No

10 Impounding Structure Assessment:

a. Provide brief descriptions for each item:

- i. Condition of the impounding structure Good
- ii. Condition of the reservoir Good
- iii. Condition of the upstream area N/A
- iv. Condition of the downstream area Good

b. Provide a narrative describing any recent changes in the impounding structure, reservoir, upstream area, and downstream area: No recent changes

This upground reservoir remains out of service for and is utilized very infrequently for wet ash disposal.

c. Recommendations for remedial measures: Routine maintenance such as trees and brush cutting, filling of erosion gullies or animal burrows if they occur

11 Provide a sketch of the impounding structure

See Attached Sketch


CERTIFICATION BY OWNER'S ENGINEER (Class III only)

I hereby certify that the information provided in this Inventory Report has been examined by me and found to be true and correct in my professional judgment

Signed Pedro J. Amaya
(Professional Engineer)

Virginia Number 036174

This 21 day of January, 20 08



CERTIFICATION BY OWNER (Class IV only)

I hereby certify that the information provided in this Inventory Report is true and correct

Signed Bradford
(Owner)

This 28 day of January, 20 08

Please fill out and mail to:
Department of Conservation and Recreation
Division of Dam Safety
203 Governor Street
Richmond, Virginia 232192094

PAGE 9 OF 10
REVISION 1
2/10/94

10. AUXILIARY FLY ASH POND - NOTES
AND COMMENTS INCLUDING REMEDIAL
WORK SINCE LAST INSPECTION:

LATERAL DRAIN
PIPES SPACED
100' APART

FLOW

NEW RIVER

TOP OF RIPRAP
ELEV. 1508

TOE OF DIKE
ELEV. 1490

0 50 100 200 300
SCALE 1" = 200' FT

SLOPE LINE
V's POINT DOWN SLOPE

POWER POLE

MONITORING WELL
MW-11

GLEN LYN PLANT: AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN

AEPGL000080



Department of Conservation & Recreation
CONSERVING VIRGINIA'S NATURAL & RECREATIONAL RESOURCES

OPERATION AND MAINTENANCE APPLICATION CLASS I, II AND III IMPOUNDING STRUCTURES

Reference: Impounding Structures Regulations, 4VAC 50-20-00 et seq., Virginia Soil and Water Conservation Board

1 Name of Impounding Structure: Glen Lyn Fly Ash Dam
Inventory Number: 07101 Other Name (if any): Fly Ash Pond

2. Hazard Potential Classification from Table I, Impounding Structure Regulations:

(Circle One) Class I Class II Class III

3 Name of Owner: Appalachian Power Company

Address: 40 Franklin Road, P.O. Box 2021, Roanoke, VA 24022-2121

Telephone: (Business) (800) 956-4237 (Residential) ()

4 Operating Plan and Schedule

Provide a narrative for each item:

a Operation of control gates and spillways Fixed weir elevation - See Attachment I

b Operation of Reservoir Drain (not to exceed 1/2 foot drawdown per day on embankment dams).

See Attachment I

5 Maintenance Plan and Schedule

Provide a narrative for each item:

a Embankment Dams:

(1) embankment: See Attachment I

(2) principal spillway: See Attachment I

(3) emergency spillway: See Attachment I

(4) low level outlet: See Attachment I

(5) reservoir area: See Attachment I

(6) downstream channel: See Attachment I

(7) other: See Attachment I

b Concrete dams (including masonry and others):

(1) upstream face: N/A

- (2) downstream face: N/A
- (3) crest: N/A
- (4) galleries: N/A
- (5) tunnels, etc.: N/A
- (6) abutments: N/A
- (7) spillways: N/A
- (8) gates and outlets: N/A
- (9) other: N/A

6 Inspection schedule (attach schedule and checklist):

- (1) operator inspection (daily, weekly, etc) Inspected Weekly - No Checklist
- (2) maintenance inspection (monthly, quarterly, semi-annual, annual) Quarterly by plant personnel, plus annual by AEP Civil Engineering Division - checklist attached
- (3) technical safety reinspection by a professional engineer (required for certification update: Class I dams every two years, Class II dams every three years. All dams inspected after overtopping)
Inspection annually by a Professional Engineer and reports are submitted to the

7 Emergency Action Plan Schedule Virginia Dept. of Conservation and Recreation - Dam Safety
 Provide the information that initiates the Emergency Action Plan:

- a rainfall amounts and/or: N/A
- b spillway flows: N/A
- c frequency of observation: N/A

8 For a newly constructed impounding structure, provide certification from a Professional Engineer who has inspected the impounding structure during construction that, to the best of the engineer's judgment, knowledge and belief, the impounding structure and all appurtenances have been constructed in conformance with the plans, specifications and drawings submitted to the Department of Conservation and Recreation

N/A

OPERATION AND MAINTENANCE PERMIT APPLICATION

OPERATION AND MAINTENANCE SCHEDULES
CERTIFICATION BY OWNER

I hereby certify that the operation and maintenance plans and schedules provided herewith will be adhered to during the life of the project except in cases of unanticipated emergency requiring departure therefrom in order to mitigate hazards to life and property, at which time my engineer and the Department of Conservation and Recreation will be notified

Signed: _____

Bradford
(Owner)

This ..

28

day of

January

, 20

08

CERTIFICATE BY OWNER'S ENGINEER

I hereby certify that the information provided in this form has been examined by me and found in my professional judgment to be appropriate to operation and maintenance considerations for this dam

Signed: _____

Pedro J. Amaya
Professional Engineer

Virginia Number: _____

036174

This ..

21

day of


January

, 20

08

Remarks: _____

Please fill out and mail this form to:
Department of Conservation and Recreation
Division of Dam Safety
203 Governor Street
Richmond, Virginia 23219-2094



**GLEN LYN FLY ASH DAM
INVENTORY NUMBER: 07101**

**OPERATION AND MAINTENANCE APPLICATION
Attachment 1**

Item No. 5a.

- (1) **Embankment:** The upstream and downstream slopes are visually inspected by plant personnel several times each week. Items observed include signs of instability, seepage, erosion and vegetative cover. Tree and brush cutting is done as needed, usually in the Fall. Rodent burrows are filled in when they are found.
- (2) **Principal Spillway:** The principal spillway for the area referenced as the Auxiliary Fly Ash Pond has not operated in many years because this upground reservoir receives fly ash slurry very infrequently and at very short durations. It is checked periodically. The structure would need to be thoroughly inspected and repaired if plant operations were to necessitate resumption of wet disposal. The principal spillway for the area referenced as the West Pond consists of a sloping shaft and metal conduit. The structure has a fixed weir crest (constant stop log elevation) and a skimmer structure. This is routinely inspected via the weekly visits by plant personnel and the quarterly inspections.
- (3) **Emergency Spillway:** There is no emergency spillway along any section of the diking.
- (4) **Low Level Outlet:** Not applicable due to the nature of the sedimentation function of the ponds.
- (5) **Reservoir Area:** The pool area in the Auxiliary Fly Ash Pond varies depending on the use of the wet disposal system. It is generally less than 1 acre in surface area and an average of 2-3 feet deep. The reservoir area for the West Pond is approximately 2 acres at normal pool. The shoreline along both of these areas are inspected quarterly and observed during visits by plant personnel.
- (6) **Downstream Channel:** Plant personnel observe the receiving channel several times each week. Observations are recorded quarterly and repairs will be performed as necessary. To date, there has not been the need for any repairs since the last certification.
- (7) **Other:** No additional items associated with this facility.

GLEN LYN PLANT
DIKE INSPECTION CHECKLIST

1. GENERAL INFORMATION

Date of Inspection _____

Inspected by _____

Weather _____

Temperature _____

Rainfall (inches) since _____
 _____ (date) _____

Pond levels: _____

North Bottom Ash Pond (1505.5*) _____

South Bottom Ash Pond (1506.3*) _____

Clearwater Pond (1501.3*) _____

Auxiliary Fly Ash Pond _____

West Pond _____

2. EMBANKMENT CONDITION AT BOTTOM ASH AND CLEARWATER PONDS

- A. Please refer to the Bottom Ash Pond Inspection Location Plan which is found on Page 8. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion _____

Ruts in Crest Road _____

Animal Burrows _____

- * Approximate normal pool levels when in service.

DESCRIPTIONLOCATION CODE

Leaking Ash Pipe

Seepage/Watness

Trees on Slope

Vegetation condition

Cracks/Bulges/Slides

Other (Please specify)

- B. Has there been any significant deterioration, erosion or displacement of the riprap at the river shoreline since the last inspection? If so, please describe condition and the river flow event which caused it.

- C. Has there been erosion of the shoreline inside the bottom ash ponds because of the ash inflow pipes?

3. OUTLET WORKS AT BOTTOM ASH AND CLEARWATER PONDS

- A. Please inspect the following drainage structures and check the appropriate space below:

	GOOD CONDITION	PROBLEM
North B. A. Pond Skimmer		
North B. A. Pond Overflow Lip & Pipe		
South B. A. Pond Skimmer		
South B. A. Pond Overflow Lip & Pipe		
Perforated Water Distribution Pipe		
Clearwater Pond Skimmer		

PAGE 3 OF 10
 REVISION 1
 2/10/94

	GOOD CONDITION	PROBLEM
Clearwater Pond Overflow Lip & Chute		
Clearwater Pond Spillway Tower		
Access Steps to Spillway Tower		
Outfall Pipe to East River		
Access Path to Outfall Pipe		

B. Please describe problems below:

4. EMBANKMENT CONDITION AT AUXILIARY FLY ASH POND

- A. Please refer to the Auxiliary Fly Ash Pond Inspection Location Plan which is found on Page 9. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

<u>DESCRIPTION</u>	<u>LOCATION CODE</u>
Erosion	
Ruts in Crest Road	
Animal Burrows	
Leaking Ash Pipe	
Leaking Embankment Drain Pipe	
Seepage/Wetness	
Trees on Slope	

Exposed Ash on Slope _____
Cracks/Bulges/Slides _____
Sinkhole _____
Other (Please specify) _____

- B. Has this pond been used since the previous inspection? If so, when and for approximately what duration?

- C. Has the water level in the pond been high enough to cause the embankment drains to become active?

5. OUTLET WORKS AT AUXILIARY FLY ASH POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel Trough	_____	_____
Wooden Skimmer	_____	_____
Trough or Skimmer supports	_____	_____
Concrete structure	_____	_____
Other (Please specify)	_____	_____

- B. Please describe problems below: _____

PAGE 5 OF 10
 REVISION 1
 2/10/94

- C. Please observe the outlet end of the 24" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate:

- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:

6. EMBANKMENT CONDITION AT WEST POND

- A. Please refer to the West Pond Inspection Location Plan which is found on Page 10. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion

Ruts in Crest Road

Animal Burrows

Seepage/Wetness

Woody Vegetation on Dikes

Cracks/Bulges/Slides

Sediment Buildup in Inlet
 Ditches

- B. Has there been significant runoff from the landfill since the last inspection? _____

PAGE 6 OF 10
 REVISION 1
 2/10/94

- C. Has the water level reached the steel overflow trough since the last inspection? _____. Please record the current water level relative to the overflow trough _____

- D. Other problems (please describe): _____

7. OUTLET WORKS AT WEST POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel Trough		
Wooden Skimmer		
Inlet Structure		
Pipe Problems		
Other (please specify)		

- B. Please describe observed problems below: _____

- C. Please observe the outlet end of the 36" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate, in gallons per minute: _____


- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:

8. GENERAL EMBANKMENT CONDITIONS - ALL PONDS

- A. Has any mowing, brush and tree cutting or spraying been done since the previous inspection? If so, please state below what was done, when and by whom, and show the area on the location plan.

- B. Has the river level come up significantly since the last inspection, and if so, approximately what elevation was it and when?

- C. Was there any apparent damage to the dikes when the river level receded? If so, please indicate below what the damage was (erosion, slides, etc.) and show its location on the location plan.



AEI PGL000092

10. AUXILIARY FLY ASH POND - NOTES
AND COMMENTS INCLUDING REMEDIAL
WORK SINCE LAST INSPECTION:

LATERAL DRAIN
PIPES SPACED
100' APART

FLOW

NEW RIVER

TOP OF RIPRAP
ELEV. 1508

TOE OF DIKE
ELEV. 1490

0 50 100 200 300
SCALE 1" = 200 FT

SLOPE LINE
V's POINT DOWN SLOPE

POWER POLE

MONITORING WELL
MW-11

GLEN LYN PLANT: AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN

L. Preston Bryant, Jr.
Secretary of Natural Resources



Joseph H. Maroon
Director

COMMONWEALTH of VIRGINIA
DEPARTMENT OF CONSERVATION AND RECREATION

203 Governor Street, Suite 206
Richmond, Virginia 23219-2010
(804) 371-6695 Fax (804) 371-2630

April 4, 2008

Appalachian Power Company
Attn: William Smith
Post Office Box 2021
Roanoke, VA 24022-2121

RE: Glen Lyn Bottom Ash Dam, Inventory Number 07102

Dear Mr. Smith:

The Operation and Maintenance Certificate Application for Glen Lyn Bottom Ash Dam, Inventory Number 07102, and the required supporting documents have been reviewed for compliance with the provisions of the Code of Virginia, Dam Safety Act, (Section 10.1-604 et. seq.) and the regulations promulgated by the Virginia Soil and Water Conservation Board (Board). Based on this information, on March 20, 2008, the Board issued a six-year (03/20/2008 - 3/31/2014) Regular Class III Operation and Maintenance Certificate (Certificate). The Certificate and other pertinent data are enclosed.

The Dam Safety Act requires dam owners to maintain their dam in a condition to prevent unreasonable threats to life and property of others. The classification of your dam and the Certificate issued were based on the current known downstream hazard potential from upstream characteristics, a re-inspection report, operation and maintenance application, and an emergency action plan. The actions contained in the documents accompanying your Certificate Application must be adhered to for the duration of the terms contained in the Certificate. To assist you in adhering to the terms of the Certificate, the following table provides a schedule of dates to submit required documents.

Annual Owner's Inspection Report	Owner's Engineer Inventory Report	Renewal Certification Six Year Application by Owner and Owner's Engineer
03/31/2009		
03/31/2010		
03/31/2011		
03/31/2012		
03/31/2013	12/31/2013	12/31/2013

Should you have questions, please direct them to Thomas I. Roberts, P.E., Dam Safety Regional Engineer, Department of Conservation and Recreation, Dam Safety and Floodplain Management Division, 8 Radford Street, Suite 203, Christiansburg, VA 24073, telephone 540-394-2550 or via e-mail at Thomas.Roberts@dcr.virginia.gov.

Sincerely,



William G. Browning
Director, Dam Safety & Floodplain Management Division

Enclosures as stated:

c: James M. Robinson, P.E., Dam Safety Program Manager
Thomas I. Roberts, P.E. Dam Safety Regional Engineer

DATA SHEET - OPERATION AND MAINTENANCE CERTIFICATE

Department of Conservation & Recreation
Division of Dam Safety & Floodplain Management
203 Governor Street, Suite 206
Richmond, VA 23219-2094

Name of Dam Glen Lyn Bottom Ash Dam	Inventory Number 07102
Location Offstream Dam Near New River	City/County Giles
Owner Appalachian Power Company Attn: William Smith Address: 40 Franklin Road, P.O. Box 2021 City/Town/Zip Roanoke, VA 24022-2121	Designed by Casa Grande Consultants Constructed by: Unknown Year Constructed 1950
Type of Dam Earthfill	Purpose Sediment-Fly Ash
Drainage Area (Sq. Mi.) 0.01	Type of Watershed N/A
Total Height (ft.) 28	Elevation 1523
Normal Pool Height (ft.) 14	Elevation 1509
Maximum Capacity (Acre Ft.) 90	Maximum Area (Acres) 5.8
Normal Capacity (Acre Ft.) 31	Normal Area (Acres) 3.7
Size Classification Small	Hazard Classification III
Required Spillway Design Flood: 60 Yr	Available Spillway Design Flood Impounds PMF
Type of Spillway: N/A	<i>(Note of Section 130)</i>

Operation and Maintenance Plans & Schedule by:

AEP/Pedro Jose Amaya-Trujillo, VA PE #036174


() Reinspection or (X) Inventory Report by

AEP/Pedro Jose Amaya-Trujillo, VA PE #036174

Emergency Action Plan filed with

(X) Virginia Dept. of Emergency Management

(X) Local Coordinator of Emergency Services

City/County **Giles County**Application Reviewed and Recommended for: **Six-Year Regular O & M Certificate (3/20/2008-3/31/2014)**By **Thomas I Roberts, PE # 19966**Date **March 17, 2008**

Concurrence with the Recommendation:

By  **William G. Browning, Director**Date **March 19, 2008**



COMMONWEALTH of VIRGINIA

DEPARTMENT OF CONSERVATION AND RECREATION
DIVISION OF DAM SAFETY
VIRGINIA SOIL AND WATER CONSERVATION BOARD

**DAM SAFETY CERTIFICATE
REGULAR
CLASS III OPERATION & MAINTENANCE CERTIFICATE NUMBER 07102**

Appalachian Power Company, owner of Glen Lyn Bottom Ash Dam in Giles County, is entitled to operate and maintain this dam pursuant to the provisions of the Dam Safety Act (Section 10.1-604 et seq., Code of Virginia) and Regulations promulgated thereunder.

This certificate is for a term of six years. It becomes effective March 20, 2008 and expires March 31, 2014. In accordance with §4VAC50-20-100F of the Regulations, the owner shall apply for a new certificate 90 days prior to its expiration.

Joseph H. Mason



Department of Conservation & Recreation
CONSERVING VIRGINIA'S NATURAL & RECREATIONAL RESOURCES

INVENTORY REPORT FOR CLASS III AND CLASS IV IMPOUNDING STRUCTURES

Reference: Impounding Structure Regulations, 4VAC50-20-00 et seq., Virginia Soil and Water Conservation Board

1. Project Information:

- a. Name of Impounding Structure Glen Lyn Bottom Ash Dikes
- b. Inventory Number 07102 Other Name (if any) _____
- c. Name of Reservoir Glen Lyn Plant Bottom Ash Ponds
- d. Purpose of Reservoir Sedimentation of bottom ash and decanting of clear ash transport water

2. Location of Impounding Structure:

- a. City/County Giles County Magisterial District _____
- b. Located at feet/miles upstream/downstream of Highway No US 460
- c. Name of River or Stream upground Reservoir adjacent to New River & East River
- d. Latitude N37 22' 30" Longitude W80 52'

3. Ownership:

- a. Owner's Name Appalachian Power Company
- b. Mailing Address 40 Franklin Road; P.O. Box 2011
Roanoke, VA 24022-2121
- c. Telephone (800) 956-4237

4. Owner's Engineer:

- a. Engineering Firm/Engineer American Electric Power Service Corporation
- b. Professional Engineer Virginia Number Pedro Jose Amaya-Trujillo VA#036174
- c. Mailing Address 1 Riverside Plaza
Columbus, Ohio 43215
- d. Telephone (614) 716-1000 or (614) 716-2926

5. Impounding Structure Data (All elevations NGVD unless noted):

a Type of Material earth x concrete _____ masonry _____

Other _____

Design Configurationb Top of Dam 1523 Elev (if known)c Downstream Toe (Lowest) 1515 Elev (if known)d Height of Dam 20 27 Feete Crest Length (Exclusive of Spillway) 2500 Feetf Crest Width varies 35-40 Feetg Upstream Slope 2 H: 1 Vh Downstream Slope 1.5 H: 1 V

6 Reservoir Data

Design Configurationa Maximum Capacity 90 Acre-feetb Maximum Pool 1515 Elev (if known)c Maximum Pool Surface Area 5.9 Acresd Normal Capacity 31.4 Acre-feete Normal Pool * Elev (if known)f Normal Pool Surface Area 3.72 Acresg Freeboard (Normal Pool to Top) 17.5 & 21.7 Feeth Freeboard (Normal Pool to Emergency) N/A Feet

* Bottom Ash Ponds = 1505.5 Clearwater Pond = 1501.3

7 Spillway Data

a Low Level Drain None --- ---b Principal Spillway Drop tower w/concrete pipe 20 cfsc Emergency Spillway None --- ---Design Configurationd Low Level Drain --- Elev (if known)e Principal Spillway 1501.3 Elev (if known)f Emergency Spillway --- Elev (if known)

g. Briefly describe the low level drain and principal spillway to include dimensions, materials of construction, trash guards, location in reservoir and through dam, and orientation of intake and discharge to dam if looking downstream: No low level drains due to the sedimentation of ash. Drop tower has stoplog which are 2 feet long and empties into a 30" concrete discharge pipe. A timber skimmer barrier protects tower from floating debris.

h. Describe the emergency spillway to include dimensions, whether the spillway is an earth channel or other construction, spillway surface protection, and orientation to dam if looking downstream: There is no emergency spillway for this dam.

Note - This is an upground reservoir which receives water by pumping. Drainage area is the reservoir perimeter.

8. Watershed Data (Class III only):

- a. Drainage Area 5.8 Acres .009 Sq. Miles
- b. Type and Extent of Watershed Development None - Grass covered dike crest and u/s slope
- c. Time of Concentration -- Method --
- d. Spillway Design Flood used (mark appropriate box)
- PMF, source
- 1/2 PMF, source
- 100 Year, source
- 50 Year, source
- Other, source Not Applicable
- e. Design inflow hydrograph: Volume -- acre-feet;
- Peak inflow -- CFS;
- Rainfall duration of design inflow hydrograph -- hours
- f. Freeboard during passage of spillway design flood -- feet

9. Impounding Structure History

- a. Date construction completed 1950's; modified 1977
- b. Design by American Electric Power Date: 1950's; modified 1976
- c. Built by unknown Date: 1950's; modified 1977

- d. Inspection dates 1978, 1980, 1982, and annually from 1984-2007
- e. Inspections by Woodward-Clyde Consultants, ASF, & Geosyntec Consultants
- f. Description of repairs Brush and tree cutting, filling erosion, gullies, filling animal holes, repairs to leaking pip and repair at shoreline erosion in ponds.
- g. Has the impounding structure ever been overtopped? Yes ☒ No

10 Impounding Structure Assessment:

a. Provide brief descriptions for each item:

- i. Condition of the impounding structure Good
- ii. Condition of the reservoir Good
- iii. Condition of the upstream area N/A
- iv. Condition of the downstream area N/A

b. Provide a narrative describing any recent changes in the impounding structure, reservoir, upstream area, and downstream area: There have been no changes since last Certification in 2002.

c. Recommendations for remedial measures: Continue routine monitoring, brush and tree cutting, repair of erosion features, filling of animal burrows as req

11 Provide a sketch of the impounding structure

See Attached Sketch

CERTIFICATION BY OWNER'S ENGINEER (Class III only)

I hereby certify that the information provided in this Inventory Report has been examined by me and found to be true and correct in my professional judgment.

Signed

Pedro J. Amaya
(Professional Engineer)

Virginia Number

036174


This

21

day of

January

20 08



CERTIFICATION BY OWNER (Class IV only)

I hereby certify that the information provided in this Inventory Report is true and correct

Signed

Bradford
(Owner)

This

28

day of


January

20 08

Please fill out and mail to:

Department of Conservation and Recreation
Division of Dam Safety
203 Governor Street
Richmond, Virginia 232192094

9. BOTTOM ASH AND CLEARWATER PONDS - NOTES AND COMMENTS INCLUDING REMEDIAL MEASURES SINCE LAST INSPECTION:



SLOPE LINE

V's POINT
DOWN SLOPE

0 50 100 200 300
APPROXIMATE SCALE 1"=167 FT.

GLEN LYN PLANT; BOTTOM ASH POND
INSPECTION LOCATION PLAN



Department of Conservation & Recreation

CONSERVING VIRGINIA'S NATURAL & RECREATIONAL RESOURCES

OPERATION AND MAINTENANCE APPLICATION CLASS I, II AND III IMPOUNDING STRUCTURES

Reference: Impounding Structures Regulations, 4VAC 50-20-00 et seq., Virginia Soil and Water Conservation Board

1. Name of Impounding Structure: Glen Lyn Bottom Ash Dikes

Inventory Number: 07102 Other Name (if any) _____

2. Hazard Potential Classification from Table 1, Impounding Structure Regulations:

(Circle One)

Class I

Class II

Class III

3. Name of Owner: Appalachian Power Company

Address: 40 Franklin Road, P.O. Box 2027, Roanoke, VA 24022-2121

Telephone: (Business) (800) 956-4237 (Residential) () _____

4. Operating Plan and Schedule

Provide a narrative for each item:

a. Operation of control gates and spillways: Attachment I

b. Operation of Reservoir Drain (not to exceed 1/4 foot drawdown per day on embankment dams)

See Attachment I

5. Maintenance Plan and Schedule

Provide a narrative for each item:

a. Embankment Dams:

(1) embankment: See Attachment I

(2) principal spillway: See Attachment I

(3) emergency spillway: See Attachment I

(4) low level outlet: See Attachment I

(5) reservoir area: See Attachment I

(6) downstream channel: See Attachment I

(7) other: See Attachment I

b. Concrete dams (including masonry and others):

(1) upstream face: N/A

- (2) downstream face: N/A
- (3) crest: N/A
- (4) galleries: N/A
- (5) tunnels, etc.: N/A
- (6) abutments: N/A
- (7) spillways: N/A
- (8) gates and outlets: N/A
- (9) other: N/A

6. Inspection schedule (attach schedule and checklist):

- (1) operator inspection (daily, weekly, etc.) Weekly - No Checklist
- (2) maintenance inspection (monthly, quarterly, semi-annual, annual) Quarterly by plant personnel, plus annual by AEP Civil Engineering Division - checklist attached
- (3) technical safety reinspection by a professional engineer. (required for certification update: Class I dams every two years, Class II dams every three years. All dams inspected after overtopping)
Inspection annually by a Professional Engineer

7. Emergency Action Plan Schedule

Provide the information that initiates the Emergency Action Plan:

- a. rainfall amounts and/or: This is an underground reservoir with no drainage area beyond its own perimeter. Water inflow is controlled by pumping of ash/
- b. spillway flows: water slurry. EAP would be triggered by embankment instability
- c. frequency of observation: or failure due to piping or erosion.

8. For a newly constructed impounding structure, provide certification from a Professional Engineer who has inspected the impounding structure during construction that, to the best of the engineer's judgment, knowledge and belief, the impounding structure and all appurtenances have been constructed in conformance with the plans, specifications and drawings submitted to the Department of Conservation and Recreation

N/A

OPERATION AND MAINTENANCE PERMIT APPLICATION

OPERATION AND MAINTENANCE SCHEDULES
CERTIFICATION BY OWNER

I hereby certify that the operation and maintenance plans and schedules provided herewith will be adhered to during the life of the project except in cases of unanticipated emergency requiring departure therefrom in order to mitigate hazards to life and property, at which time my engineer and the Department of Conservation and Recreation will be notified

Signed: Bradford

(Owner)

This 28 day of January, 2008

CERTIFICATE BY OWNER'S ENGINEER


I hereby certify that the information provided in this form has been examined by me and found in my professional judgment to be appropriate to operation and maintenance considerations for this dam

Signed: Pedro J. Amaya Virginia Number: 036174
Professional Engineer

This 21 day of January, 2008

Remarks: _____

Please fill out and mail this form to:
Department of Conservation and Recreation
Division of Dam Safety
203 Governor Street
Richmond, Virginia 23219-2094



GLEN LYN BOTTOM ASH DIKES
INVENTORY NUMBER: 07102

OPERATION AND MAINTENANCE APPLICATION
Attachment 1

Item No. 4

a: Operation for Control Gates and Spillway: The discharge structure for this pond consists of a concrete tower with a fixed weir elevation (stop-logs) connected to a 30-diameter concrete pipe. There are no variable gates to be controlled. Freeboard at this point is sufficient to store the Probable Maximum Flood.

b: Operation of Reservoir Drain: There is no reservoir drain for this facility because such a drain would either become clogged with or would discharge bottom ash from the pond. The pond can be drained by pumping if desired.

Item No. 5a.

- (1) Embankment: The upstream and downstream slopes are visually inspected by plant personnel several times each week. Items observed include signs of instability, seepage, erosion and vegetative cover. Tree and brush cutting is done as needed, usually in the Fall. Rodent burrows are filled in when they are found.
- (2) Principal Spillway: The principal spillway for this upground reservoir consists of a concrete tower with a fixed weir elevation (stop-logs) connected to a 30-diameter concrete pipe. It is inspected visually several times per week by plant personnel, and would be repaired promptly by plant personnel or contracted forces if necessary.
- (3) Emergency Spillway: There is no emergency spillway – see 4a above.
- (4) Low Level Outlet: Not applicable – see 4b above.
- (5) Reservoir Area: Since this is an upground reservoir, the reservoir area is checked when the upstream slopes are observed.
- (6) Downstream Channel: The outlet from the 30-inch diameter pipe discharges directly into the East River, which is a tributary to the New River. The size and flow capacity of the East River far exceeds the discharge from the pond. There have been no problems experienced with blockage or restrictions
- (7) Other: No additional items associated with this facility.

GLEN LYN PLANT
DIKE INSPECTION CHECKLIST

1. GENERAL INFORMATION

Date of Inspection _____

Inspected by _____

Weather _____

Temperature _____

Rainfall (inches) since _____
 _____ (date) _____

Pond levels: _____

North Bottom Ash Pond (1505.5*) _____

South Bottom Ash Pond (1506.3*) _____

Clearwater Pond (1501.3*) _____

Auxiliary Fly Ash Pond _____

West Pond _____

2. EMBANKMENT CONDITION AT BOTTOM ASH AND CLEARWATER PONDS

- A. Please refer to the Bottom Ash Pond Inspection Location Plan which is found on Page 8. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion _____

Ruts in Crest Road _____

Animal Burrows _____

* Approximate normal pool levels when in service.

DESCRIPTION

LOCATION CODE

Leaking Ash Pipe

Seepage/Wetness

Trees on Slope

Vegetation condition

Cracks/Bulges/Slides

Other (Please specify)

- B. Has there been any significant deterioration, erosion or displacement of the riprap at the river shoreline since the last inspection? If so, please describe condition and the river flow event which caused it.

- C. Has there been erosion of the shoreline inside the bottom ash ponds because of the ash inflow pipes?

3. OUTLET WORKS AT BOTTOM ASH AND CLEARWATER PONDS:

- A. Please inspect the following drainage structures and check the appropriate space below:

	GOOD CONDITION	PROBLEM
North B. A. Pond Skimmer		
North B. A. Pond Overflow Lip & Pipe		
South B. A. Pond Skimmer		
South B. A. Pond Overflow Lip & Pipe		
Perforated Water Distribution Pipe		
Clearwater Pond Skimmer		

PAGE 3 OF 10
 REVISION 1
 2/10/94

	GOOD CONDITION	PROBLEM
Clearwater Pond Overflow Lip & Chute		
Clearwater Pond Spillway Tower		
Access Steps to Spillway Tower		
Outfall Pipe to East River		
Access Path to Outfall Pipe		

B. Please describe problems below:

4. EMBANKMENT CONDITION AT AUXILIARY FLY ASH POND
- A. Please refer to the Auxiliary Fly Ash Pond Inspection Location Plan which is found on Page 9. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

<u>DESCRIPTION</u>	<u>LOCATION CODE</u>
Erosion	
Ruts in Crest Road	
Animal Burrows	
Leaking Ash Pipe	
Leaking Embankment Drain Pipe	
Seepage/Wetness	
Trees on Slope	

Exposed Ash on Slope _____

Cracks/Bulges/Slides _____

Sinkhole _____

Other (Please specify) _____

- B. Has this pond been used since the previous inspection? If so, when and for approximately what duration?
- _____
- _____

- C. Has the water level in the pond been high enough to cause the embankment drains to become active?
- _____
- _____

5. OUTLET WORKS AT AUXILIARY FLY ASH POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel Trough	_____	_____
Wooden Skimmer	_____	_____
Trough or Skimmer supports	_____	_____
Concrete structure	_____	_____
Other (Please specify)	_____	_____

- B. Please describe problems below: _____
- _____
- _____

PAGE 5 OF 10
REVISION 1
2/10/94

- C. Please observe the outlet end of the 24" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate:

- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:

6. EMBANKMENT CONDITION AT WEST POND

- A. Please refer to the West Pond Inspection Location Plan which is found on Page 10. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion

Ruts in Crest Road

Animal Burrows

Seepage/Wetness

Woody Vegetation on Dikes

Cracks/Bulges/Slides

Sediment Buildup in Inlet
Ditches

- B. Has there been significant runoff from the landfill since the last inspection?

PAGE 6 OF 10
 REVISION 1
 2/10/94

- C. Has the water level reached the steel overflow trough since the last inspection? _____ Please record the current water level relative to the overflow trough _____

- D. Other problems (please describe): _____

7. OUTLET WORKS AT WEST POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel Trough		
Wooden Skimmer		
Inlet Structure		
Pipe Problems		
Other (please specify)		

- B. Please describe observed problems below: _____

- C. Please observe the outlet end of the 36" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate, in gallons per minute: _____

PAGE 7 OF 10
REVISION 1
2/10/94

- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:


8. GENERAL EMBANKMENT CONDITIONS - ALL PONDS

- A. Has any mowing, brush and tree cutting or spraying been done since the previous inspection? If so, please state below what was done, when and by whom, and show the area on the location plan.

- B. Has the river level come up significantly since the last inspection, and if so, approximately what elevation was it and when?

- C. Was there any apparent damage to the dikes when the river level receded? If so, please indicate below what the damage was (erosion, slides, etc.) and show its location on the location plan.

9. BOTTOM ASH AND CLEARWATER
PONDS - NOTES AND COMMENTS
INCLUDING REMEDIAL MEASURES
SINCE LAST INSPECTION:



SLOPE LINE

V's POINT
DOWN SLOPE

0 50 100 200 300
APPROXIMATE SCALE 1"=167 FT.

GLEN LYN PLANT: BOTTOM ASH POND
INSPECTION LOCATION PLAN

AEI PGL000059

LATERAL DRAIN
PIPES SPACED
100' APART -

FLOW

NEW RIVER

TOP OF RIPRAP
ELEV. 1508

TOE OF DIKE
ELEV 1490

SLOPE LINE
V' s POINT DOWN SLOPE

4 POWER POLE

• MONITORING WELL
MW-11

AEPLGL000060

Report On
Dam Safety Inspection
GLEN LYN FLY ASH &
BOTTOM ASH POND
GLEN LYN POWER PLANT
Glen Lyn, Virginia

Report On
Dam Safety Inspection
GLEN LYN FLY ASH &
BOTTOM ASH POND
GLEN LYN POWER PLANT
Glen Lyn, Virginia

Prepared by
Woodward-Clyde Consultants
Clifton, New Jersey

For
AMERICAN ELECTRIC POWER SERVICE CORPORATION
Two Broadway
New York, New York

18 July 1978

77C110

TABLE OF CONTENTS

	<u>Page</u>
1.0 INTRODUCTION	1
2.0 PROJECT DESCRIPTION	1
3.0 SITE GEOLOGY	6
4.0 SUMMARY OF ENGINEERING DATA AVAILABLE	6
5.0 RESULTS OF VISUAL INSPECTION	7
6.0 OPERATIONAL PROCEDURES	9
7.0 HYDROLOGIC AND HYDRAULIC EVALUATION	10
8.0 OVERALL EVALUATION	10

TABLES

FIGURES

APPENDIX A - PHOTOGRAPHS

APPENDIX B - VISUAL INSPECTION CHECKLIST

GLEN LYN POWER PLANT

1.0 INTRODUCTION

The results of a dam safety inspection of the fly ash and bottom ash dikes at the Glen Lyn Power Plant are presented in this report. The purposes of the investigation were to gather and evaluate available data on the design and construction of the dams at the power plant and to complete a visual inspection of the integrity of the dikes so that an evaluation could be made of the need for additional investigation and/or remedial action.

The investigation was performed in accordance with our proposal dated 11 October 1977. It consisted of review of data concerning the Glen Lyn Dikes available in AEP's files, field inspection of the dikes, engineering evaluation and the preparation of this report. The field inspection was performed on 11 May 1978 by Messrs. John H. Frederick, Jr. and Noel Ravneberg.

2.0 PROJECT DESCRIPTION

The location of the Glen Lyn Power Plant is shown in Fig. 1. Two diked areas for storage of fly ash and bottom ash are currently in service at the Glen Lyn Plant.

2.1 Fly Ash Dikes

The fly ash storage area consists of a series of dikes enclosing three separate fly ash retention ponds. The layout and cross section of the three ponds, referred to herein as the upper, middle and lower ponds, is shown in Fig. 2.

The fly ash storage area, constructed in 1965 (according to the information contained in the Directory of Dams & Dikes, prepared by AEPSC), consisted originally of one large area with dikes on the river side abutting the hill on the west. The original dike was constructed of locally available clayey shale fill to approximately el 1536 ft.* Sometime between 1965 and 1973 the storage area was partitioned to form its present configuration of three separate ponds.

2.1.1 Upper Pond

Within the last several years, the capacity of the upper pond appears to have been increased. This increase is indicated on AEPSC Drawing No. 16-3540-2 by a note dated 12/6/76. We are uncertain as to the modifications made to increase the storage capacity of the upper pond. The drawing indicates the crest of the dike at el 1540 ft. It is not clear whether the original dike in this area was at el 1536 ft and the dikes were raised to 1540 ft or whether new dikes were built to form the upper pond, i.e., the original dikes did not encompass what is now the upper pond. We understand that the dikes forming the upper pond consist of a compacted fly ash core and a clay blanket.

*All elevations are USGS mean sea level datum.

The interior face of the present dikes, against which the water impinges to form the upper pond, is shown on AEPSC Dwg. 16-3544 inclined at 2.5H:1V. Based on the ground surface contours shown on the drawing, the downstream face appears inclined at approximately 2H:1V. The bottom of the pond varies from el 1490 ft to el 1500 ft.

The clay blanket is shown on AEPSC Dwg. 16-3544 to have typically an 8 ft horizontal dimension. For an inclination of the face of the dike of about 2.5H:1V, a thickness perpendicular to the slope of approximately 3 ft. is required. On the north dike however, we understand that only a 1 ft thick clay blanket was placed.

A 12 inch diam corrugated metal pipe for transportation of fly ash slurry to the pond was constructed on timber bents founded in the northern dike. We have been told that, on first filling, a slope failure occurred in the northern dike, washing out the timber bents and the header pipe. The slope has not yet been repaired and the pond is still out of service.

A skimmer barrier and outlet pipe is located at the southern end of the pond.

2.1.2 Middle Pond

The Middle Pond has been filled with fly ash sediment to the top of the perimeter dikes. At the present time, dry fly ash is being placed in the Middle Pond above the level of the top of the dikes. AEPSC drawing 16-3640-2 dated 10/2/73 indicates that compacted fly ash is to be placed to el 1585 ft over the entire Middle Pond. The sides of this fly ash embankment are to be inclined at 3H:1V. At the time of our inspection it appeared that approximately two thirds of the pond area has now been filled. As currently operated, the Middle Pond no longer functions as a water impounding area.

2.1.3 Lower Pond

This is the only pond in the fly ash storage area currently in service. The dikes surrounding this pond are constructed of local borrow material and crest at el 1536 ft, approximately 17 ft above the toe of the dike. The dikes are shown on AEPSC drawing 16-3540-2 inclined towards the reservoir at 3H:1V.

The dike spillway consists of a 2.5 ft diameter drainage pipe which channels the overflow towards the New River. A skimmer barrier, similar to that constructed at the upper pond, is provided.

2.2 Bottom Ash Dikes

The bottom ash storage area is shown in Fig. 3.

The perimeter dikes and the divider dike separating the two sections of the pond are constructed of compacted clayey shale. The crest of the perimeter dike is at el 1520 while that of the divider dike is at el 1511.

As currently operated, only half of the storage area is used at any one time. While one pond is in operation, a front end loader removes bottom ash from the other pond for sale to a cinder block manufacturer.

Water from the storage pond in use, overflows through an 18 in dia. corrugated metal pipe to a clear water pond. Water from the clear water pond flows under a skimmer barrier and through a 30 in dia. concrete pipe to the East River. The bottom of bottom ash pond is shown on AEPSC Drawing No. 16-11249-35-64-1 at el 1500 ft while that of the clear water pond is shown at el 1499 ft. The depth of water in the bottom ash pond is approximately 7 to 8 ft while that in the clear water pond is approximately 5 to 6 ft.

Although portions of the bottom ash perimeter dike and intake structure were raised to provide increased storage capacity, this work was never completed.

3.0 SITE GEOLOGY

The Glen Lyn Power Plant is located within the Valley and Ridge physiographic province. Bedrock consists of the Bluefield and Hinton formations of Mississippian age.

The Bluefield formation, which underlies the bottom-ash pond, is a shale with some thin interbedded layers of sandstone, siltstone and limestone. Although there are no outcrops of the Bluefield at the bottom-ash pond, exposures along a nearby roadcut show a competent, though steeply dipping, bedrock.

Outcrops of the Hinton Formation, interbedded shale and sandstones, are exposed in road cuts adjacent to the fly ash ponds. Also adjacent to the ponds is a deeply weathered portion of the formation which is presently being used as a borrow area for dike construction material.

4.0 SUMMARY OF ENGINEERING DATA AVAILABLE

The drawings made available to us by AEP, for use in this investigation are listed in Table 1. The drawings listed in Table 1 contain references to other drawings on which additional details on the dikes and the outlet structures are to be found. These additional drawings, however, were not available to us.

No design data or calculations were found in AEP's Glen Lyn file.

5.0 RESULTS OF VISUAL INSPECTION

The inspection consisted of a visual survey of the dikes and outlet structures. The results of the visual inspection of both the fly ash and bottom ash dikes are described in the Visual Inspection Check Lists contained in Appendix 3 (a separate checklist was completed for the fly ash and bottom ash dikes) and are summarized below. Photos of the dikes are presented in Appendix A.

5.1 Fly Ash Storage Areas

Upper Pond

1. There was no visual evidence of surface cracks or of unusual movement at or beyond the toe. The vertical and horizontal alignment of the crest appeared normal to the eye.
2. A sinkhole was noted in the crest of the dike at the location shown in Fig. 2. Ponded surface water apparently seeped into the fly ash i.e., found an opening in the clay blanket, and washed out material at the downstream face. This localized piping failure appears to have resulted in subsequent collapse and enlargement of the sinkhole. The sinkhole is approximately 10 ft. deep.
3. There was no evidence of displacement or erosion of the downstream dike slopes. These slopes are protected by riprap.

4. The slopes of the dikes forming the upper pond were completely exposed at the time of the inspection. The failure of a portion of the dike on the northern portion of the pond was described earlier. Some erosion was noted on the slope of the southern dikes at a point where it appeared that the inflow pipe had once been located.

Lower Pond

1. In general, the condition of the dike appeared good, with no evidence of cracks, misalignment, or seepage, that might suggest movement or deterioration of the dikes.

2. Runoff from the hills located immediately southwest of the pond is presently channeled into a drainage ditch adjacent to Route 649, running approximately parallel to the west dike of the pond. Some blockage of the ditch was noted. The blockage has caused a portion of the flow in the ditch to be diverted toward the toe of the dike. This flow has resulted in minor erosion.

5.2 Bottom Ash Storage Area

At the time of the inspection, both halves of the pond were out of service and operators were converting from operation of the south half to operation of the north half. Water was standing in the clear water pond. Some water was ponded on the surface of the sediment in the recently-filled south half.

1. There was no visual evidence of surface cracks or of unusual movement at or beyond the toe. The vertical and horizontal alignment of the crest appeared to the eye to be normal.
2. Considerable sloughing of the dike separating the two portions of the pond was noted.
3. There was no evidence of seepage through the dikes.
4. The outflow from the clear water pond appeared clear and less turbid than the river water.

6.0 OPERATIONAL PROCEDURES

6.1 Maintenance and Operation

We understand that there are no documented operation or maintenance procedures established for either the fly ash or bottom ash ponds.

6.2 Monitoring and Warning System

There is no instrumentation installed to monitor the performance of the dikes or to provide advance warning of impending problems. We understand that plant personnel inspect the dikes daily to ascertain the condition of the dikes. However, there is no documented procedure for response to damage or to deterioration of the dikes.

7.0 HYDROLOGIC AND HYDRAULIC EVALUATION

7.1 Hydrology

The fly ash and bottom ash storage areas are enclosed impoundments. As such, there is no natural drainage into the reservoir. Flow is piped in under controlled conditions. The only source of inflow other than the piped-in slurry is rainfall precipitation. The maximum 1-hr precipitation for the 100 year storm in this portion of Virginia is 3.5 inches.* The maximum rainfall results in a flow increment of approximately 35 cfs in the flyash lower pond (which has the largest surface area).

7.2 Hydraulic Considerations

At the time of our inspection, only the lower fly ash pond was in service. The 30 inch outflow pipe had only a few inches of flow under the normal operating conditions. Thus, it appears that there is ample reserve capacity available to handle temporary increases due to rainfall inflow. However, no computations have been done to substantiate this conclusion.

8.0 OVERALL EVALUATION

8.1 Fly Ash Ponds

The only pond currently in service is the lower pond. The dikes of this pond are constructed of the locally available clayey shale material. There appeared to be no evidence of cracks, misalignment, or seepage which

*U.S. Dept of Commerce, "Rainfall Frequency Atlas of the United States",
Technical Paper No. 40, May, 1961

might indicate malfunction or deterioration of the dikes. The ditch for diverting side hill runoff bordering the easternmost dike shows some signs of erosion and blockage. This ditch should be cleaned and repaired.

As a result of the slope failure that occurred during initial filling, the upper pond has not yet been put into service. In our opinion, the suitability of compacted fly ash as an embankment material needs to be evaluated in light of the slope failure and the evidence of erosion of the dike material at locations where the clay blanket has been breached. The existing sinkhole in the Upper Pond dike should be repaired before the pond is returned to service.

8.2 Bottom Ash Pond

There was no visual evidence of cracking, misalignment or seepage which might indicate malfunction or deterioration of the perimeter dikes. Sloughing of the partition dike between the two halves of the pond was noted. However, this does not, in our opinion, adversely affect the retention capability of the pond as a whole.

8.3 Hazard Rating

In general, we see little cause for concern about the integrity of the dikes. However, if one of the dikes were to fail, the result would be a release of either flyash or bottom ash slurry into the adjacent river. Since the volume of material contained in any of the dike areas is relatively small, it is unlikely that release of this material into the river would cause significant flooding or damage downstream.

Fly Ash Ponds

Based on the above observations, it is not clear that the classification of "high" hazard potential classification assigned to this dam in the U.S. Army Corps of Engineers' National Inventory of Dams is appropriate. This classification suggests that if the dikes were to fail, "more than a few" lives would be lost and "excessive" property damage would occur. In our opinion, a "significant" rating may be more appropriate for these dikes.

Bottom Ash Pond


The field inspection disclosed significant differences between inventoried and actual dimensions of this facility. Although construction was started several years ago to raise the level of the dikes and overflow structure to the inventoried heights, this work was never completed. As currently operated, the hydraulic head in the pond is never more than seven feet. Furthermore, the pond is partitioned so that only half of the area is filled at any given time.

Consistent with these observations, it is recommended that the inventories (both Corps. of Engineers and AEPSC) be corrected to reflect true conditions. As corrected, we believe these data will indicate a "Low" hazard potential classification, rather than the "High" classification assigned by the Corps.

TABLE 1

LIST OF DRAWINGS AVAILABLE FROM AEP
GLEN LYN POWER PLANT
FLY ASH AND BOTTOM ASH STORAGE PONDS

<u>Drawing No.</u>	<u>Date</u>	<u>Date of Last Revision</u>	<u>Title</u>
16-11249-3564-1	7/15/76	8/16/76	Bottom Ash Storage Area Modification
16-3540-2	10/2/73	12/6/76	Fly Ash Storage Area-General Plan
16-3542-1	10/2/73	12/6/76	Fly Ash Storage Area-Dikes sheet 2 of 3
16-3543-1	10/2/73	12/6/76	Fly Ash Storage Area-Dikes sheet 3 of 3
16-3548A-1	9/14/76	1/17/77	Fly Ash Storage Area-Modification of Overflow Structure
16-3544	10/2/73	none	Fly Ash Storage Area-Dike Sections



REFERENCE DRAWINGS



1. MAP SOURCE FOR KEY MAP IS COMMONWEALTH OF VIRGINIA HIGHWAY MAP, DATED 1975
2. MAP SOURCES FOR SITE MAP ARE USGS 7.5 MINUTE SERIES (TOPOGRAPHIC) NARROWS QUADRANGLE, NARROWS, VA. - W. VA., 1976 EDITION AND PETERSTOWN QUADRANGLE, PETERSTOWN, W. VA. - VA., 1965 EDITION

**SITE LOCATION PLAN
GLEN LYN POWER PLANT
FLY ASH AND BOTTOM ASH PONDS**



WOODWARD-CLYDE CONSULTANTS

CONSULTING ENGINEERS, GEOLOGISTS AND ENVIRONMENTAL SCIENTISTS
CLIFTON, NEW JERSEY


DR. BY:	DRS	SCALE:	1" = 2000'	PROJ. NO.:	77C110
CK'D. BY:	SAL	DATE:	5 JULY 1978	FIG. NO.:	1



MIDDLE POND
SECTION A-A




UPPER POND
SECTION B-B



NOTE:
LAYOUT OF DIKES AND DIKE CROSS SECTIONS BASED ON
AEP DRAWING NO. 16-3540-2, DATED 10-2-73 AND DWG NO.
16-3544 DATED 10-2-73 AND ON OBSERVATIONS MADE
DURING THE SITE INSPECTION

1531.50
1527.00
3.50
10/19/93
12/22/93



FLYASH PONDS
GLEN LYN POWER PLANT

WOODWARD-CLYDE CONSULTANTS
CONSULTING ENGINEERS, GEOLOGISTS AND ENVIRONMENTAL SCIENTISTS
CLIFTON, NEW JERSEY

DR. BY: DRS	SCALE: AS SHOWN	PROJ. NO: 77C110
CK'D BY: SAL	DATE: 18 JULY 1978	FIG. NO: 2

APPENDIX A
PHOTOGRAPHS



Photo 1. Middle Fly Ash Pond, Looking North




Photo 2. Lower Fly Ash Pond, Looking East




Photo 3. Upper Fly Ash Pond, Sinkhole on NE Crest of Dike




Photo 4. Upper Fly Ash Pond, Looking West




Photo 5. Bottom Ash Pond, Showing Skimmer
Barrier of Clear Water Pond




Photo 6. West Half of Bottom Ash Pond

APPENDIX B
VISUAL INSPECTION CHECKLIST

GLEN LYN
FLY ASH POND

A.E.P. DAM SAFETY INSPECTION
VISUAL INSPECTION CHECK LIST

Name Dam Upper and Lower Flyash Pond County Giles State VA.

Type of Dam Homogeneous Clay Hazard Category ⁺ High

Date(s) Inspection 5/11/78 Weather Clear Temperature + 75

+ From U.S. Army Corps of Engineers' National Inventory of Dams

Pool Elevation at Time of Inspection 1527 M.S.L. Tailwater at Time of Inspection 1494 M.S.L.

Inspection Personnel:

Noel Baumborg
Jack Frederick

Jack Frederick Recorder

Remarks:

Glen Lyn Flyash dam actually three separate systems of dikes enclosing upper, middle and lower ponds.

At time of inspection middle pond full and out of service. Upper pond dry and lower pond in full service.

Unless otherwise noted, remarks pertain to both upper and lower pond dikes.

CONCRETE/MASONRY DAMS

Not Applicable

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE (faces, abutments, toe, etc...)	N/A	
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS		
DRAINS, CHARACTERISTICS OF DISCHARGE		
WATER PASSAGES (Erosion, cavitation, obstructions, cracks, etc...)		
FOUNDATION (possible damage or undermining of downstream toe)		

CONCRETE/MASONRY DAMS

Not Applicable

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES		
STRUCTURAL CRACKING		
VERTICAL AND HORIZONTAL ALIGNMENT (abnormal settle- ments, heaving, deflections etc....)		
MONOLITH AND CONSTRUCTION JOINTS (filler material movement, leak- age, etc....)		
ABUTMENTS (instability, excessive weathering, etc....)		

EMBANKMENT

<u>VISUAL EXAMINATIONS OF</u>	<u>OBSERVATIONS</u>	<u>REMARKS OR RECOMMENDATIONS</u>
-------------------------------	---------------------	-----------------------------------

SURFACE CRACKS None noted

UNUSUAL MOVEMENT OR
CRACKING AT OR BEYOND
THE TOE None noted

SLOUGHING SLIDING OR EROSION OF
EMBANKMENT AND ABUTMENT
SLOPES

Large (30-40 yd³) sinkhole in crest of upper flyash pond dike formed by erosion (piping) of flyash embankment material. Surface water collecting on crest of dam apparently seeped into flyash and washed out material at face of downstream slope, with subsequent collapse and enlargement of sinkhole.

None noted in the lower pond dikes

VERTICAL AND HORIZONTAL
ALIGNMENT OF THE CREST

Appears normal

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

RIPRAP FAILURES	Downstream toe of dikes adjacent to river are covered with 1-2 yd ³ rocks and rip-rap to protect against erosion. No evidence of displacement or erosion at toe of slope.	
-----------------	--	--

JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM (erosion, leakage etc...)	None noted	
--	------------	--

ANY NOTICEABLE SEEPAGE (embankment and abutment downstream slopes, toe, etc...)	No seepage noted	
--	------------------	--

DRAINS, CHARACTERISTICS OF DISCHARGE	Not applicable	
---	----------------	--

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Not applicable	
INTAKE STRUCTURE	Upper pond: not in service Lower pond: appeared normal	
OUTLET STRUCTURE	Upper Pond: not in service Lower pond: no evidence of seepage around outside of pipe	
EMERGENCY GATE	Not applicable	
STILLING BASIN	Not applicable	

Not Applicable

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE WEIR

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

STILLING BASIN

Not applicable

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

CONCRETE SILL		
---------------	--	--

APPROACH CHANNEL		
------------------	--	--

DISCHARGE CHANNEL		
-------------------	--	--

BRIDGE AND PIERS		
------------------	--	--

GATES AND OPERATION EQUIPMENT		
----------------------------------	--	--

STILLING BASIN		
----------------	--	--

RESERVOIR

Sheet 9 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SLOPES	Upper pond slopes were completely exposed (pond empty). Northwest slope had failed on first filling with resulting collapse of discharge header pipe pile foundations. Because of this, pond was emptied and placed out of service. Some erosion of southwest slope was also noted at point where it appeared that inflow pipe was once located. Otherwise all slopes appeared to be stable and free of displacements.	
--------	--	--

SEDIMENTATION

Purpose of reservoirs is to collect flyash sediments. At time of inspection middle pond was full of sediment with no free water on surface, upper pond was completely empty and dry, and lower pond was in active service. Soundings were being made by others to determine depth of sediment in lower pond. Estimated life of lower pond at present rate of filling reported to be an additional 12 to 18 months.

POTENTIAL UPSTREAM
HAZARD AREAS

No natural drainage into reservoir. All flow is piped in under controlled conditions. Limited watershed (less than 1.0 MI²) from natural side hill, west of the lower pond, is diverted through side channel ditch boarding easternmost dike of lower pond. Natural springs and erosion in this area have caused some blockage along diversion ditch. This ditch should be cleared and regraded to prevent run off from entering flyash pond. Runoff from the hill located west of the upper pond is picked up by storm sewer facilities adjacent to Route 649. There is virtually no watershed between Route 649 and the Upper Pond.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (Obstruction, debris, etc...)	No obstructions or debris, free flow directly into New River.	
SLOPES	Downstream channel is essentially river bed of New River	
POTENTIAL DOWNSTREAM HAZARD AREAS (No. of homes, population, etc...)	None. Ponds exist immediately adjacent to New River with no inhabitants or developed property between ponds or river. Any spill would go directly into river with slight rise in water level, probably confined to existing flood plain.	

INSTRUMENTATION

Sheet 11 of 11

VISUAL EXAMINATION	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURVEY MONUMENT	No formal instrumentation installed. However, daily inspection is made by plant personnel to ascertain condition of piping system and ponds. At time of visit, others were making a field survey to determine the extent of siltation in lower pond. This included determination of depth of water at fixed grid locations over entire area of pond.	
SETTLEMENT PLATES, INCLINOMETERS		
OBSERVATIONS WELLS, PIEZOMETERS		
WEIRS/FLOW MEASURING DEVICES		
HEADWATER, TAIL WATER GAGES		
OTHER		

GLEN LYN
BOTTOM ASH POND

A.E.P. DAM SAFETY INSPECTION
VISUAL INSPECTION CHECK LIST

Name Dam Glen Lyn Bottom Ash Dam County Giles State Virginia
Type of Dam Earth Embankment Hazard Category ⁺ High
Date(s) Inspection 11 May 1978 Weather Clear Temperature + 75° F
+ From U.S. Army Corps of Engineers' National Inventory of Dams
Pool Elevation at Time of Inspection N/A M.S.L. Tailwater at Time of Inspection M.S.L.

Inspection Personnel:

Noel RavnebergJack FrederickJack Frederick Recorder

Remarks:

At time of inspection operators were converting from operation of the south
half to operation of the north half of pond.

CONCRETE/MASONRY DAMS N/A

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
ANY NOTICEABLE SEEPAGE (faces, abutments, toe , etc...)		
STRUCTURE TO ABUTMENT/EMBANKMENT JUNCTIONS		
DRAINS, CHARACTERISTICS OF DISCHARGE		
WATER PASSAGES (Erosion, cavitation, obstructions, cracks, etc...)		
FOUNDATION (possible damage or undermining of downstream toe)		

CONCRETE/MASONRY DAMS N/A

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
SURFACE CRACKS CONCRETE SURFACES		
STRUCTURAL CRACKING		
VERTICAL AND HORIZONTAL ALIGNMENT (abnormal settle- ments, heaving, deflections etc...)		
MONOLITH AND CONSTRUCTION JOINTS (filler material movement, leak- age, etc...)		
ABUTMENTS (instability, excessive weathering, etc...)		

EMBANKMENT

VISUAL EXAMINATIONS OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
------------------------	--------------	----------------------------

SURFACE CRACKS	None Noted	
----------------	------------	--

UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None noted	
---	------------	--

SLOUGHING SLIDING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	Considerable sloughing of partition dike which separates the pond in half. No displacement of perimeter dike which contains the impoundment.	
--	--	--

VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Normal	
---	--------	--

EMBANKMENT

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
RIPRAP FAILURES	Large (1-2 yard ³) stone and riprap on lower half of downstream slope to protect embankment from high river flow. No displacement failures noted.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM (erosion, leakage etc...)	Closed perimeter dike with no natural abutments.	
ANY NOTICEABLE SEEPAGE (embankment and abutment downstream slopes, toe, etc...)	None noted.	
DRAINS, CHARACTERISTICS OF DISCHARGE	No natural flow into impoundment. All inflow controlled by pumping from plant. Overflow discharges into fixed elevation skimmer trough and through outlet conduit to East River. Outflow from pond appears clear and less turbid than flow in river.	

OUTLET WORKS

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CRACKING AND SPALLING OF CONCRETE SURFACES IN OUTLET CONDUIT	Concrete surfaces appear fresh with no significant cracking or spalling.	
INTAKE STRUCTURE	Rectangular concrete intake tower extends about 15 feet above pond level of stilling basin. Provision to place stop logs in open slot of one wall to raise pond level has never been used. Overflow remains fixed at present level by virtue of tressle supported metal skimming trough collection system, connected to intake.	
OUTLET STRUCTURE	Concrete box culvert connects to 30" RCP outlet conduit through embankment to East River at D.S. toe of slope.	
EMERGENCY GATE	None	
STILLING BASIN	A separate stilling basin exists upstream from the intake structure and downstream from the bottom ash ponds. It is connected by overflow pipes which collect essentially clear water from the surface of the ponds. This water undergoes a second settling process before passing over the lip of the skimmer troughs connected to the intake/outlet structure.	

UNGATED SPILLWAY NONE

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONCRETE WEIR		
APPROACH CHANNEL		
DISCHARGE CHANNEL		
BRIDGE AND PIERS		
STILLING BASIN		

GATED SPILLWAY

NONE

Sheet 8 of 11

REMARKS OR RECOMMENDATIONS

OBSERVATIONS

VISUAL EXAMINATION OF

CONCRETE SILL

APPROACH CHANNEL

DISCHARGE CHANNEL

BRIDGE AND PIERS

GATES AND OPERATION
EQUIPMENT

STILLING BASIN

RESERVOIR

Sheet 9 of 11

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
-----------------------	--------------	----------------------------

SLOPES

Severe sloughing of partitional dike between separate halves of bottom ash pond. No significant sloughing of upstream slopes of main dikes.

SEDIMENTATION

Used for purposes of sedimentation. Left half full of sediment. Right half recently excavated to remove all sediment and begin new cycle.

POTENTIAL UPSTREAM
HAZARD AREAS

None. Operates as self-contained unit with no natural watershed or natural upstream slopes.

The only constant reservoir is the stilling basin which is estimated to contain less than 10 acre-ft. of water.

VISUAL EXAMINATION OF	OBSERVATIONS	REMARKS OR RECOMMENDATIONS
CONDITION (Obstruction, debris, etc...)	The outlet works connect directly to East River which is a natural water course.	
SLOPES	Natural river channel	
POTENTIAL DOWNSTREAM HAZARD AREAS (No. of homes, population, etc...)	None beyond those posed by normal flooding of East and New Rivers.	

INSTRUMENTATION NONE

REMARKS OR RECOMMENDATIONS

VISUAL EXAMINATION

OBSERVATIONS

SURVEY MONUMENT

SETTLEMENT PLATES, INCLINOMETERS


OBSERVATIONS WELLS, PIEZOMETERS

WEIRS/FLOW MEASURING DEVICES

HEADWATER, TAIL WATER GAGES

OTHER





REVISIONS	
DATE	DESCRIPTION
10/1/75	1. ADDED FIVE TREESTLACK
10/1/75	2. ADDED FIVE TREESTLACK
10/1/75	3. ADDED DISPOSAL AREA FOR SILT


THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED TO YOU ON THE CONDITION THAT IT IS NOT TO BE REPRODUCED, COPIED, IN WHOLE OR IN PART, OR USED FOR ANY PURPOSE, WITHOUT THE WRITTEN CONSENT OF THE AEP SERVICE CORP. INTEREST AND IS TO BE RETURNED UPON REQUEST.

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN VIRGINIA
FLYASH STORAGE AREA
GENERAL PLAN

DR. NO. 16-3540-3

ARCH.	ELEC.	MECH.	STR.
SCALE 1" = 100'	ENGINEERING DIV.	DESIGN DIV.	
BY J.M.	CH. D.P.C.	SO. LOR. M.E.	
DATE 10/1/75			

AMERICAN ELECTRIC POWER SERVICE CORP.
2 BROADWAY
NEW YORK



SHEET 2 OF 3

SCALE: 1" = 50'

CONTOUR INTERVAL: 2'

AERIAL SURVEYS, INC.
CLEVELAND, OHIO
431 611

PREPARED BY PHOTOGRAMMETRIC METHODS FROM AERIAL PHOTOGRAPH TAKEN 12-22-71 @ 1:4,000

VERTICAL AND HORIZONTAL CONTROL FURNISHED BY APALACHIAN POWER CO.

DATE	NO.	DESCRIPTION	APPROVED
12/22/71	1	INCREASED CAPACITY OF UPSTREAM STORAGE AREA	W.L.

THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED UPON CONDITION THAT IT IS NOT TO BE REPRODUCED OR COPIED IN WHOLE OR IN PART OR USED FOR FURNISHING INFORMATION TO ANY PERSON WITHOUT THE WRITTEN CONSENT OF THE AEP SERVICE CORP. OR FOR ANY PURPOSE DETRIMENTAL TO THEIR INTEREST, AND IS TO BE RETURNED UPON REQUEST.

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN - VIRGINIA
FLYASH STORAGE AREA
DIKES

SHEET 2 OF 3

DR. NO. 16-3542-1

ARCH.	ELEC.	MECH.	STR.
-------	-------	-------	------

SCALE: 1" = 50'


DESIGNED BY: J.M.

CH. D.B.C.


APPROVED BY: [Signature]

DATE: 12/22/71


AMERICAN ELECTRIC POWER SERVICE CORP.
2 BROADWAY
NEW YORK




A B C D E F G H J K L M N O




SECTION 2-C
1"=100' (16-3542)



DETAIL 2-H
1"=40' (16-3542)



SECTION 4-C
1"=20' (16-3543)



SECTION 5-C
1"=20' (16-3541)

REVISIONS

"THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED UPON CONDITION THAT IT IS NOT TO BE REPRODUCED OR COPIED, IN WHOLE OR IN PART, OR USED FOR FURNISHING INFORMATION TO ANY PERSON WITHOUT THE WRITTEN CONSENT OF THE AEP SERVICE CORP., OR FOR ANY PURPOSE DETRIMENTAL TO THEIR INTEREST, AND IS TO BE RETURNED UPON REQUEST."

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN VIRGINIA


FLYASH STORAGE AREA
DIKE SECTIONS
SH. 1 OF 2

DR. NO. 16-3544

ARCH.	ELC.	MCH.	STR.
SCALE: 1/2"=1'-0"	ENGINEERING DIV.	DESIGNED BY	CHK'D BY
DR. J. M.	DR. J. M.	DESIGN BY	CHK'D BY
CH. D.R.C.	APPROVED BY	DATE	

AMERICAN ELECTRIC POWER SERVICE CORP.
2 BROADWAY NEW YORK

A B C D E F G H J K L M N O



GENERAL NOTES

DATE	NO.	DESCRIPTION	APP'D.
REVISIONS			
"THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED TO YOU FOR CONSTRUCTION. IT IS NOT TO BE REPRODUCED OR COPIED IN WHOLE OR IN PART, OR FOR ANY PURPOSE, WITHOUT THE WRITTEN CONSENT OF THE AEP SERVICE CORP. OR FOR ANY PURPOSE, OBTAINABLE TO THESE INTERESTS, AND IS TO BE RETURNED UPON REQUEST."			
APPALACHIAN POWER CO. GLEN LYN POWER PLANT GLEN LYN VIRGINIA			
FLYASH STORAGE AREA DIKE SECTIONS SH. 2 OF 2			
DR. NO. 16-3545			
ARCH.	ELEC.	MERCH.	SYL.
SCALE: AS NOTED	ENGINEERING DIV.		
DR. J.M.	CH. D.R.C.		
SG. LDR. T.A.E.	DATE: 10/2/53		
AMERICAN ELECTRIC POWER SERVICE CORP. 2 BROADWAY NEW YORK			

GENERAL NOTES

DO NOT SCALE THIS DRAWING.
ALL TIMBER TO BE STRUCTURAL
DOUGLAS FIR
POLES ARE TO BE STRUCTURAL
SOUTHERN PINE

ALLOWABLE STRESSES

BENDING 2100 PSI
HORIZONTAL SHEAR 145 PSI
COMPRESSION (TYPICAL) 4100 PSI
COMPRESSION (STAGGERED) 4100 PSI
SOIL PRESSURE 2000 PSI

MATERIAL

ALL MATERIAL TIME-SET
TO BE FURNISHED BY FIELD

REFERENCE DWGS

16-3540-EXTENSION OF FLY ASH
PILING
6-5278-A-FLY ASH STORAGE
AREA-GENERAL PLAN

TIMBER SCHEDULE

QUANTITIES	SIZE	LENGTH	TOTAL LENGTH	REMARKS
10	2"x4"	3'-8"	38'-0"	RAIL POST
4	2"x4"	50'-0"	200'-0"	RAILING
12	2"x4"	3'-4"	40'-0"	FACE BRACE
2	3"x10"	20'-0"	40'-0"	BRACE
2	3"x10"	17'-3"	34'-6"	"
2	3"x10"	17'-0"	34'-0"	"
1	3"x10"	11'-6"	11'-6"	"
1	3"x10"	11'-0"	11'-0"	"
1	3"x10"	10'-0"	10'-0"	"
1	3"x10"	3'-6"	3'-6"	"
1	3"x10"	8'-0"	8'-0"	"
1	3"x10"	7'-6"	7'-6"	"
1	3"x10"	6'-0"	6'-0"	"
2	2"x4"	3'-8"	7'-6"	RAIL POST
6	6"x6"	10'-0"	60'-0"	PIPE SUPPORT
4	6"x12"	20'-0"	80'-0"	STRINGERS
4	12"x12"	7'-0"	28'-0"	CAP BEAM
5	6"x6"	20'-0"	100'-0"	DECK PLANKS
				TOTAL BOARD FT. 2275

TRESTLE-B

QUANTITIES	SIZE	LENGTH	TOTAL LENGTH	REMARKS
10	2"x4"	3'-8"	38'-0"	RAIL POST
10	2"x4"	3'-4"	34'-0"	RAIL BRACE
4	2"x4"	37'-0"	148'-0"	RAILING
2	3"x10"	11'-0"	22'-0"	BRACE
1	3"x10"	7'-3"	7'-3"	"
1	3"x10"	5'-6"	5'-6"	"
5	6"x6"	10'-0"	50'-0"	PIPE SUPPORT
6	6"x12"	14'-0"	84'-0"	STRINGERS
4	12"x12"	7'-0"	28'-0"	CAP BEAM
5	6"x6"	35'-5"	177'-5"	DECK PLANKS
				TOTAL BOARD FT. 1750

CREOSOTED DISTRIBUTION POLES

QTY	TYPE	SIZE	LENGTH	QTY	TYPE	SIZE	LENGTH
2	BATTER	12"	9'-0"	2	BATTER	12"	6'-1"
2	BATTER	12"	15'-4"	2	BATTER	12"	8'-6"
2	BATTER	12"	22'-0"	2	BATTER	12"	10'-0"

BOLT SCHEDULE

TRESTLE-A					TRESTLE-B				
MARK	QTY	SIZE	LENGTH	REMARKS	MARK	QTY	SIZE	LENGTH	REMARKS
B1	9	7/8"	1'-6"	3/4" HD. 2" BUSHINGS	B1	6	7/8"	1'-6"	3/4" HD. 2" BUSHINGS
B2	5	7/8"	1'-0"	3/4" HD. 2" BUSHINGS	B2	NIL	-	-	-
DB1	22	7/8"	1'-0"	DRIFT BOLT	DB1	16	7/8"	1'-0"	DRIFT BOLT
DB2	8	7/8"	1'-10"	DRIFT BOLT	DB2	8	7/8"	1'-10"	DRIFT BOLT

MATERIAL	RELEASE DATE
STRUCT. STEEL	-
REIN. STEEL	-
DECKING	-
GRATING	-
STAIR TREADS	-
HANDRAILING	-
PIPE	-

NOTE:
CHECKER IS RESPONSIBLE
TO SEE THAT THE ABOVE
APPLICABLE MATERIALS
TO BE ORDERED ARE
BRUGHT TO HIS/HER
LEADER'S ATTENTION.

"THIS DRAWING IS THE PROPERTY OF THE
AMERICAN ELECTRIC POWER SERVICE
CORP. AND IS LOANED UPON CONDITION
THAT IT IS NOT TO BE REPRODUCED OR
COPIED, IN WHOLE OR IN PART, OR USED
FOR FURNISHING INFORMATION TO ANY
PERSON WITHOUT THE WRITTEN CONSENT
OF THE A.E.P. SERVICE CORP. OR FOR
ANY PURPOSE DETRIMENTAL TO THEIR
INTEREST, AND IS TO BE RETURNED UPON
REQUEST."

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN, VIRGINIA
FLY ASH STORAGE AREA
TRESTLES

DR. No. 16-3546
ARCH. [] ELEC. [] MECH. [] STR. []
SCALE: 1/4"=1'-0"
ENGIN. DIV.
DR. V.R.G.
CH. S.S.
SQ. L.M.E.
DATE: 11/2/73
AMERICAN ELECTRIC POWER SERVICE CORP.
2 BROADWAY NEW YORK

REVISIONS

DATE	NO.	DESCRIPTION	APPRO.
------	-----	-------------	--------

16-3540-16-3546

PLAN

TOP OF PIPES SUPPORTS EL 1540-72
TRESTLE A (FOR LOCATION SEE DWG 16-3540)

PLAN

TOP OF PIPES SUPPORT EL 1535-6
TRESTLE B (FOR LOCATION SEE DWG 16-3540)

SECTION 4-J

SECTION 5-C

SECTION 6-H

SECTION 6-K

SECTION 7-B

SECTION 9-B

SECTION 9-D

SECTION 9-F

SECTION 9-H

A B C D E F G H J K L M N O

DR. NO. 16-3547

GENERAL NOTES

DO NOT SCALE THIS DRAWING
ALL DIMENSIONS TO BE FIELD
ALL DIMENSIONS TO BE DOUBLED UP UNLESS OTHERWISE NOTED
ALLOWABLE SOIL BEARING PRESSURE 1000 P.S.F.

TIMBER SCHEDULE

QUANTITIES	SIZE	LENGTH	REMARKS
16	6" x 6"	5'-8"	70'-8"
2	8" x 8"	7'-8"	15'-4"
32	8" x 8"	11'-9"	376'-0"
2	8" x 8"	12'-1"	24'-2"
2	8" x 8"	7'-10"	15'-8"
16	3" x 5"	6'-5"	132'-0"
1	3" x 6"	10'-0"	17'-0"
1	3" x 8"	6'-3"	8'-3"
12	4" x 2"	15'-0"	180'-0"
2	4" x 3"	18'-0"	36'-0"

MATERIAL

ALL MATERIAL TIMBER DIMENSIONS TO BE
FURNISHED IN FIELD

BOLT SCHED

MARK	QTY	SIZE	LENGTH	TYPE	REMARKS
B1	36	7/8"	1'-0"	30 HEAD WASHERS 30 NUT & SHIMLARS	
B2	48	7/8"	1'-6"	DRIFT BOLT	WEDGE FT BUTTER NUT
B3	4	7/8"	1'-5"	DRIFT BOLT	DO
B4	24	7/8"	1'-1"	SHIMLARS	2 WASHERS 10 NUT & SHIMLARS
B5	4	7/8"	1'-3"	DO	DO

REFERENCE DWGS

16-3541 FLY ASH STORAGE AREA PILES

PLAN

FOR LOCATION SEE DWG 16-3541

TYPICAL PIPE SECTION

SECTION 6-H (AS SHOWN)
SECTION 6-H (OPPOSITE HAND)
1"=1'-0"

SECTION 6-B
1"=1'-0"

SECTION 5-E (AS SHOWN)
SECTION 6-E (AS NOTED)
1"=1'-0"

SECTION 9-K
1"=1'-0"

SECTION 8-E (AS SHOWN)
SECTION 8-E (OPPOSITE HAND)
1"=1'-0"

REVISIONS

THIS DRAWING IS THE PROPERTY OF THE AMERICAN
ELECTRIC POWER SERVICE CORP. AND IS LOANED
UPON CONDITION THAT IT IS NOT TO BE REPRODUCED
OR COPIED, IN WHOLE OR IN PART, OR USED FOR FURNISHING
INFORMATION TO ANY PERSON WITHOUT THE
WRITTEN CONSENT OF THE A.E.P. SERVICE CORP. OR
FOR ANY PURPOSE DETRIMENTAL TO THEIR INTEREST,
AND IS TO BE RETURNED UPON REQUEST.

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN VIRGINIA
FLYASH STORAGE AREA
SUPPORTS FOR FLY ASH
DISCHARGE PIPE LINES

DR. NO. 16-3547


MATERIAL	RELEASE DATE
STRUCT. STEEL	FIELD
REINFT. STEEL	-
DECKING	-
STEEL WIRE GALVANE	FIELD
STAIR TREADS	-
HANDRAILING	-
DOCS	FIELD
PIPE	FIELD

ARCH.	ELEC.	MECH.	STR.
SCALE: 1/4"=1'-0"	SCALE: 1/4"=1'-0"	ENGINEERING DIV.	
DR. V. AIRI			
CH. [Signature]			
DESIGN DIV.			
DO. LOR M.E.			
DATE: 10/2/72			


AMERICAN ELECTRIC POWER SERVICE CORP.

A B C D E F G H J K L M N O


DR. NO. 16-3548A




PLAN




SECTION 5-C
10'-0" x 1'-0"




SECTION 5-E
3'-0" x 1'-0"




SECTION 5-H
3'-0" x 1'-0"




DET. 7-C
3'-0" x 1'-0"




DET. 7-E
3'-0" x 1'-0"




SECTION 7-H
12'-0" x 1'-0"



DET. 9-C
12'-0" x 1'-0"



SECTION 9-E
12'-0" x 1'-0"



SECTION 9-H
12'-0" x 1'-0"

BOLT SCHEDULE						
WK.	QTY	SIZE	LENGTH	TYPE	REMARKS	
B1	T2	5/8"	0'-10"	HEX. HEAD E	1-5/8" x 105 E	WASHERS/NEEDLES
B2	80	5/8"	1'-0"	DD	DD	DD

GENERAL NOTES

DO NOT SCALE THIS DRAWING

ALL MATERIAL SHALL BE THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED TO THE USER UNDER THE CONDITION THAT IT IS NOT TO BE REPRODUCED OR COPIED, IN WHOLE OR IN PART, OR USED FOR ANY PURPOSE DETRIMENTAL TO THE INTERESTS OF THE AMERICAN ELECTRIC POWER SERVICE CORP. WITHOUT THE WRITTEN CONSENT OF THE A.E.P. SERVICE CORP.

ALL STEEL TO BE A-24 UN

MATERIAL

STEEL & RUBBER GASKETS
BY: DAVE STEEL CORP.
ORDER NO.: 05662-021-6
BOLTS: BY FIELD
CLOSURE R: BY FIELD (DET. 7-H)

REFERENCE DWGS

16-3541 FLY ASH STORAGE AREA DIKES
16-3548 SUPPORTS FOR OVERFLOW STRUCTURE

DATE	NO.	DESCRIPTION	APPRO.
1/17/77	1	DELETED LAG SCREWS BASED ON 16-3548	W.S.

THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED TO THE USER UNDER THE CONDITION THAT IT IS NOT TO BE REPRODUCED OR COPIED, IN WHOLE OR IN PART, OR USED FOR ANY PURPOSE DETRIMENTAL TO THE INTERESTS OF THE AMERICAN ELECTRIC POWER SERVICE CORP. WITHOUT THE WRITTEN CONSENT OF THE A.E.P. SERVICE CORP.

APPALACHIAN POWER CO.
GLEN LYN POWER PLANT
GLEN LYN VIRGINIA
FLY ASH STORAGE AREA
MODIFICATION OF
OVERFLOW STRUCTURE


DR. NO. 16-3548 A-1

MATERIAL	RELEASE DATE
STRUCT. STEEL	8/2/76
REINFT. STEEL	---
DOCKING	---
GRATING	---
STAIR TREADS	---
HANDRAILING	---

NOTE: CHECKER IS RESPONSIBLE TO SEE THAT THE ABOVE APPLICABLE MATERIALS TO BE ORDERED AND BROUGHT TO HIS/HERS LEADER'S ATTENTION.

AMERICAN ELECTRIC POWER SERVICE CORP.

WORK THIS DWG. WITH DWG. 16-3548



SECTION 9-M
1" = 20'

DR. NO. 16-11249-3564-1				
ARCH.	☒ ELEC	☐ MECH.	☒ STR.	☐
SCALE AS NOTED		ENGINEERING DIV		
DR. J.M.		GR 20-1-25		
CH.		DESIGN DIV		
SO. LON M.C.		GP Field		
DATE: 7/15/50		APPROVED BY		

AMERICAN ELECTRIC POWER SERVICE CORP.

SUMMARY OF AEP'S DAM AND DIKE INSPECTION AND MAINTENANCE PROGRAM (DIMP)

Subject: Dam and Dike Inspection and Maintenance Program

Category: CIVIL (Maintenance)

CL # CLM CL 0100

Revision:

Revised to reflect the addition of the dam and dike inspection and maintenance program to the AEP System.

Purpose:

To describe the inspection, documentation and routine maintenance duties and responsibilities of Plant, Region Engineering, Environmental Services and Engineering Services under the AEP Dam Inspection and Maintenance Program. The program applies to all existing dams and dikes used for ash or FGD sludge storage and disposal, waste water ponds and large cooling water storage facilities on the AEP System. Section IV of this letter briefly discusses Emergency Action Plans (EAPs) but does not address actions to be taken under emergency conditions. For response to emergency conditions refer to the facility's Emergency Action Plan if applicable, or contact AEP SO Geotechnical Engineering Section.

Background:

From the 1940's through the 1970's, as the AEP System was expanded, AEP contracted extensively on its dams and dikes with one of the pioneers of geotechnical engineering, Professor Arthur Casagrande of Harvard University. If a dam or dike exhibited problems, AEP would monitor and report under his guidance. In the 1960's and 1970's, large consulting companies engineered major dam construction projects with Casagrande Consultants acting as the owner's reviewer.

In the 1970's, AEP began to perform dam inspections with internal staff. In addition, the U.S. Army Corps of Engineers inspected several AEP dams in the late 1970's as part of a national program in response to the Buffalo Creek disaster in West Virginia. In 1979, AEP contracted with Woodward Clyde Consultants to begin inspecting existing ash disposal dams and dikes on the AEP System every two years. In 1983, AEP Civil Engineering initiated the Dam Inspection and Maintenance Program. Its purpose was to provide for systematic inspection, follow-up on significant inspection findings and to establish a contact point for plant concerns. Inspection checklists were created, and the plants were asked to perform periodic inspections.

Through the 1990's to the present, the program has been uniform and consistent. The purpose of this revision is to further strengthen the program throughout the entire AEP System and to reinforce the need to perform and document routine and formal inspections, collect instrumentation data where applicable and implement maintenance and remedial activities to assure the facilities are operated and maintained in a condition consistent with their design basis.

The Geotechnical Engineering Section (GES) of AEP SO Engineering Services coordinates the overall program, which is largely based on state regulations, Federal Emergency Management Agency guidelines, and sound engineering practice.

The inspection component of the program consists of four levels of inspection: (1) routine surveillance inspections by Plant personnel looking for changes in conditions (slips along dam face, erosion, gullies, excessive settlement, malfunctioning drains, new seepage areas, etc.); (2) formal checklist type inspections by Plant or Region Engineering staff performed on a scheduled basis; (3) engineering inspections performed under the direction of a P.E. at a frequency determined by the dam's risk classification (1, 2, or 3 year intervals); and (4) non-routine plant inspections after unusual events such as heavy rains, seismic events, or other events that could cause a change in the condition of the facility.

Inspection Schedule for Plant Formal (checklist) Inspections	
VA	
Clough River FAD 1A/1B	Inspect Quarterly
Clough River FAD 2	Inspect Quarterly
Older Lynn FAP	Inspect Quarterly
Older Lynn SAP	Inspect Quarterly
Older Lynn West FAP	Inspect Quarterly

**DAM & DIKE INSPECTION REPORT
BOTTOM ASH POND COMPLEX
AUXILIARY FLY ASH POND
WEST POND**

**GLEN LYN PLANT
GLEN LYN, VIRGINIA**

INSPECTION DATE January 13, 2009

PREPARED BY Mary F. Zych
Gary F. Zych, P.E.

DATE 2/16/09


REVIEWED BY B. Zand
Behrad Zand

DATE 2-16-2009

APPROVED BY Pedro J. Amaya
Pedro J. Amaya, P.E.
Manager - Geotechnical Engineering

DATE 2-16-2009

QA/QC DOCUMENT NO.
GERS - 09 - 003



**PROFESSIONAL ENGINEER
SEAL & SIGNATURE**

**2009 INSPECTION REPORT
BOTTOM ASH POND COMPLEX
AUXILIARY FLY ASH POND
WEST POND**

**GLEN LYN PLANT
GLEN LYN, VIRGINIA**

**PREPARED BY
GEOTECHNICAL ENGINEERING
AEP SERVICE CORPORATION
1 RIVERSIDE PLAZA
COLUMBUS, OHIO**

2009 INSPECTION REPORT
 BOTTOM ASH POND COMPLEX
 AUXILIARY FLY ASH POND
 WEST POND

GLEN LYN PLANT
 GLEN LYN, WEST VIRGINIA

INTRODUCTION	2
SUMMARY OF VISUAL OBSERVATIONS	2
General	2
Bottom Ash Pond Complex	3
Auxiliary Fly Ash Pond	4
West Pond	5
ASSESSMENT OF RECENT INSTRUMENTATION DATA	6
CONCLUSIONS	6
Bottom Ash Pond Complex	6
Auxiliary Pond	6
West Pond	6
RECOMMENDATIONS	7
Bottom Ash Pond Complex	7
Auxiliary Pond	7
West Pond	7
FIGURE 1: Bottom Ash Pond Inspection Location Plan	
FIGURE 2: Auxiliary Fly Ash Pond Inspection Location Plan	
FIGURE 3: West Pond Inspection Location Plan	
APPENDIX A: Bottom Ash Pond Photographs	
APPENDIX B: Auxiliary Fly Ash Pond Photographs	
APPENDIX C: West Pond Photographs	

INTRODUCTION

AEPSC Civil Engineering administers the company's Dam Inspection and Maintenance Program (DIMP). As part of DIMP, staff from the Geotechnical Engineering Section periodically conduct the dike and dam inspections. Mr. Gary F. Zych, P.E. conducted the 2009 inspection. This report has been prepared under the direction of Mr. Pedro J. Amaya, P.E. and presents a summary of the inspection and assessment of the condition of the facilities.

Mr. Joe Ryder, Jr., Plant Civil Engineer at the Glen Lyn Plant, was the project facility contact. The inspection was performed on January 13, 2009. Weather conditions were sunny and cool. The temperature was 37° F. There was approximately 1.5 inches of rainfall and 2 inches of snow during the seven days prior to the inspection. All of the snow was completely melted by the day of the inspection.

At the Glen Lyn Plant there are three ponds that are part of the annual dike and dam inspection. These ponds are the Bottom Ash Pond Complex, the Auxiliary Fly Ash Pond and the West Pond, and are depicted in plan in Figures 1, 2 and 3, respectively. The Bottom Ash Pond Complex consists of the North and South Bottom Ash Ponds and a Clear Water Pond. The New River and the East River border it. The Auxiliary Fly Ash Pond is a wet fly ash pond adjacent to the New River and is used only as an emergency backup pond. The West Pond is a stormwater runoff pond for the dry ash landfill, which is located west of the Auxiliary Fly Ash Pond and of the landfill. In general, all ponds have earth embankments less than or equal to 50-ft in height and slopes of 2 to 3 Horizontal to 1 Vertical.

SUMMARY OF VISUAL OBSERVATIONS

General

The summary of the visual observations uses terms to describe the general appearance or condition of an observed item, activity or structure. Their meaning of these terms is as follows:

Good:	A condition or activity that is generally better or slightly better than what is minimally expected or anticipated from a design or maintenance point of view.
Fair or Satisfactory:	A condition or activity that generally meets what is minimally expected or anticipated from a design or maintenance point of view.
Poor:	A condition or activity that is generally below what is minimally expected or anticipated from a design or maintenance point of view.
Minor:	A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is below what is normal

or desired, but which is not currently causing concern from a structure safety or stability point of view.

Excessive: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is above or worse than what is normal or desired, and which may have affected the ability of the observer to properly evaluate the structure or particular area being observed or which may be a concern from a structure safety or stability point of view.

Appendices A, B and C contain selected photographs taken during the inspection of the Bottom Ash Pond, Auxiliary Fly Ash Pond and West Pond, respectively.

Bottom Ash Pond Complex (refer to Figure 1)

1. The South Bottom Ash Pond was the active pond for receiving ash sluice water. The North Bottom Ash Pond was inactive and completely drained to accommodate dredging of the bottom ash. (Photo 1)
2. The interior slopes of both the North and South Bottom Ash Ponds appeared stable and in good condition. The crest and slopes of the Splitter dike between the two ponds also appeared stable and in good condition.
3. Flow over the South Bottom Ash Pond discharge structures was smooth with no obstructions. The structures appeared in good condition. In particular, the North BA Pond discharge structure was fully visible and no issues were noted about its condition. Modifications/repairs to the outfall structures were completed in Summer 2008. (Photo 2)
4. The South Bottom Ash Pond exterior slope, opposite to the discharge channel, was well vegetated and contained no visible animal burrows or areas of slope instability.
5. The North Bottom Ash Pond exterior slope along the New River appeared stable and well protected with vegetation and riprap. There were no signs of movement or displacement of the riprap. (Photo 3)
6. The interior slopes of the Clearwater Pond were also well vegetated and in good condition. The riprap in the northeast corner of the pond was stable.
7. Visible portions of the Clearwater Pond concrete discharge structure, wood steps, wood railing, platform, and intake structure were in satisfactory condition. The vegetation growing along the intake structure and within the stoplog channel of the discharge structure as noted in the past Inspection Reports have been removed. (Photo 4)
8. The Clearwater Pond outfall pipe (RCP 30-inch diameter), walkway and railing were in satisfactory condition. Discharge from the outfall pipe was unobstructed and there was

no erosion or scour at the outlet. There was no visual evidence of significant settlement or depressions above the pipe alignment. There was no seepage from around the outside of the pipe.

9. The inlet structure and distribution pipe at the Clearwater Pond was in good condition. This structure was also repaired during 2008. The structure is performing as intended.
10. The dike roads are in good condition as shown in several of the photographs referenced.

Auxiliary Fly Ash Pond (refer to Figure 2)

1. There was more water than normal in the Auxiliary Pond. The approximate water line is shown on Figure 2. Discussions with Mr. Joe Ryder indicated that the plant had recently used the wet ash handling system and sluiced into the pond for 48 hours.
2. The lower section of the north dike (exterior slope along the New River) is part of the natural river bank and has vegetation and tree cover. There was no indication from the top of the bench that any instability exists.
3. The upper section of the exterior slope along the New River is well vegetated. The dike appeared to be mowed late in 2008 because the height of the vegetation was very low. This slope appeared stable and there were no new signs of surficial sloughing and there were no signs of any movement or displacement. (Photo 1)
4. The old erosion slide at the northeast corner of the exterior slope at the tree line did not appear to worsen. There were no signs of more exposed soil at the scarp interface.
5. The exterior slope of the east dike appeared satisfactory with no signs of apparent instability. This section of dike had been mowed recently. There were no signs of rodent holes or erosion gullies. As noted in other reports, the exterior slopes are steeper than the north dike. (Photo 2)
6. The outlet of the pond's discharge pipe, wood steps and railing were inspected and found in good condition. There was less than 1 gpm of flow through the open valve from the outfall. This flow is presumed to be from leakage into the discharge tower.
7. The exterior slope of the south side dike along Route 649 was also well vegetated. There were no signs of slope instability or any recent erosion gullies. Also as noted in other reports, the exterior slopes are steep along the eastern length of the dike. (Photo 3)
8. The interior slopes of all three dikes appeared stable and well vegetated. The slopes were recently mowed. (Photo 4)
9. The pond was inactive at the time of inspection. The current discharge into the pond is located in the central portion of the pond. Ash transfer pipes run down the slope and

discharge to the bottom of the pond. The approximate limits of exposed ash and water line are shown on the Inspection Plan.

West Pond (refer to Figure 3)

1. The northwest interior slope of the pond and visible portions of the wood baffle structure and the discharge structure including platform and wood railings were in fair condition. The discharge from the pond was directed through the center weir box via the inverted pipe skimmer in the box. The water level in the pond was approximately 2-3 inches above the weir crest. (Photo 1)
2. The NPDES Outfall No. 007 discharge pipe located at the west end of the pond was unobstructed and in satisfactory condition. Flow was through the pipe and slightly over the concrete plug/weir. The slopes and dike surface above the pipe did not exhibit any evidence of settlement or instability and the flow was clear. The wood steps and railing were in good condition.
3. The western section of dike was well maintained and mowed in Fall 2008. This section of dike appears to be stable and there are no signs of sloughing. There were several isolated woody stems on the slope that were not cut by the mowing operation. (Photos 2 & 3)
4. The toe area from about the west abutment to just east of the access stairs was dry as compared to past several inspections. There were no wet or moist areas observed.
5. There was a moist area from the toe to approximately one-third up the slope along the eastern end of the dike. This area has not been reported as moist in past inspections. The moist zone was limited in depth 2-3 inches and presumed to be due to the snow melt and earlier precipitation. There were no signs of sloughing or other movement.
6. The interior slope of the western road dike is in satisfactory condition. Slopes are protected with riprap. There were several 2-4 inch diameter trees growing on the slope, and vegetation is growing through the riprap at the shoreline.
7. The drainage ditch along the exterior slope of the western road dike was unobstructed and protected from erosion with riprap.
8. The top of dike road was in good condition with no evidence of significant dike settlement or misalignment.
9. The southeast end of the pond borders the landfill Leachate collection pond and dike. The dike and toe area appeared in good condition. The siphon from the Leachate pond into the West pond was not operating.

ASSESSMENT OF RECENT INSTRUMENTATION DATA

Pond water levels were obtained from Plant personnel for the date of the inspection. These levels are summarized below along with water levels measured during previous annual inspections. The Plant performs quarterly inspections and records pond levels and facility conditions.

Pond	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.
Name	13Jan2009	30Oct 2007	1Nov 2005	14 Dec 2004	9 Sep 2003
Clearwater	1501	1501.3	1501.3	1501.3	1501.3
NBAP	dewatered	dewatered	dewatered	dewatered	1505.5
SBAP	1506.3 (full)	1506.3 (full)	1506.3 (full)	1506.3 (full)	1506.3
West	1531.5	1531.5	1531.5	1531.5	1531.5
Aux FAP	~ 1515	~1511	~1510	~ 1513	

The water level in the New River was elevation 1494.5 feet based on the USGS gage data. The water levels in the ponds are consistent with previous levels, except for the Aux FAP. No other instrumentation data is available for the dikes at the Plant.

CONCLUSIONS

Bottom Ash Pond Complex

The Bottom Ash Pond Complex earthen embankments and structures are in good condition. The slopes of the embankments are protected from erosion with vegetation or riprap and the facility is well maintained. The stone slope protection along the river was in satisfactory condition. The discharge structures were also in satisfactory condition.

Auxiliary Pond

Overall, the earthen embankments forming the Auxiliary Fly Ash Pond are in good condition. The vegetation covering the slopes is established and well maintained.

West Pond

Overall, the earthen embankments forming the West Pond are in good condition. The vegetation covering the slopes is established and well maintained. The inlet and outlet of the discharge structure are in satisfactory condition.

RECOMMENDATIONS

Bottom Ash Pond Complex

- I. Continue routine maintenance items as necessary.


Auxiliary Pond

- I. Continue routine maintenance items as necessary.

West Pond

- I. Continue routine maintenance items as necessary.

In general, routine inspections, monitoring and maintenance by plant personnel should continue. If you have any questions with regard to this report, please do not hesitate to contact Gary Zych at 614-716-2917 (audinet 200-2917).




GLEN LYN PLANT: BOTTOM ASH POND
INSPECTION LOCATION PLAN

FIGURE 2

Date: JAN 13, 2009

Weather: SUNNY, COOL



① EXTERIOR SLOPES NEATLY
MOWED - NO CONDITIONS
NOTED

② WATER LEVEL HIGHER
THAN NORMAL DUE TO
RECENT OPERATIONS

③ OUTLET IS NORMAL WITH
MINOR FLOW -

Legend

- A Animal Hole
- G Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Tv/Bt Trees & Brush


0 50 100 200 300
SCALE 1" = 200 FT

SLOPE LINE
V's POINT DOWN SLOPE

▲ POWER POLE

● MONITORING WELL
MW-11

GLEN LYN PLANT: AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN



Legend

- A Animal Hole
- G Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Ti/Br Trees & Brush

- ① MOIST AREA ALONG LOWER 1/3 SLOPE
- ② EXTERIOR SLOPE NEATLY MOWED
- ③ FLOW ≈ 2-3 INCH OVER WEIR CREST

APPENDIX A: BOTTOM ASH BOTTOM PHOTOGRAPHS



Photo #1 – Active south pond; excavated north pond




Photo #3 – Exterior slope of north dike




Photo #2 – Improvement to discharge structure



Photo #4 – Discharge tower with vegetation removed

APPENDIX B: AUXILIARY FLY ASH POND PHOTOGRAPHS



Photo #1 – Exterior slope of north dike, looking west




Photo #3 – Exterior slope of south dike, looking west



Photo #2 – View of east dike, looking south



Photo #4 – View of interior slopes and water level

APPENDIX C: WEST POND PHOTOGRAPHS




Photo #1 – View of outlet structure and skimmer




Photo #2 – Exterior slope of western portion



Photo #3 – Exterior slope of eastern portion

1) MFZ 3/18/09
 2) WR SMITH 3-19-09
 3) FILE

PAGE 1 OF 10
 REVISION 2
 1/16/98

GLEN LYN PLANT
DIKE INSPECTION CHECKLIST

1. GENERAL INFORMATION

Date of Inspection

3/11/09

Inspected by

Joe Ryder, Jr., P.E.

Weather

CLDY Light intermittent rain

Temperature

60°

Rainfall, (inches) since
 6" (date)

about + 1" above normal

Pond levels:

North Bottom Ash Pond (1505.5*)

DENATERED - Clean out in progress

South Bottom Ash Pond (1506.3*)

Full

Clearwater Pond (1501.3*)

Full

Auxiliary Fly Ash Pond

~1513

West Pond

Full Pond - outfall + 0.05'

2. EMBANKMENT CONDITION AT BOTTOM ASH AND CLEARWATER PONDS

- A. Please refer to the Bottom Ash Pond Inspection Location Plan which is found on Page 8. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion

Ruts in Crest Road

Animal Burrows

* Approximate normal pool levels when in service.

DESCRIPTION

LOCATION CODE

Leaking Ash Pipe

Seepage/Wetness

Trees on Slope

Vegetation condition

Cracks/Bulges/Slides

Other (Please specify)

all good

B. Has there been any significant deterioration, erosion or displacement of the riprap at the river shoreline since the last inspection? If so, please describe condition and the river flow event which caused it.

Good Shape

C. Has there been erosion of the shoreline inside the bottom ash ponds because of the ash inflow pipes?

Good Shape

3. OUTLET WORKS AT BOTTOM ASH AND CLEARWATER PONDS

A. Please inspect the following drainage structures and check the appropriate space below:

North B. A. Pond Skimmer

North B. A. Pond Overflow Lip & Pipe

South B. A. Pond Skimmer

South B. A. Pond Overflow Lip & Pipe

Perforated Water Distribution Pipe

Clearwater Pond Skimmer

GOOD CONDITION	PROBLEM
☒	
☒	
☒	
☒	
☒	
☒	

	GOOD CONDITION	PROBLEM
Clearwater Pond Overflow Lip & Chute	☒	
Clearwater Pond Spillway Tower	☒	
Access Steps to Spillway Tower	☒	
Outfall Pipe to East River	☒	
Access Path to Outfall Pipe	☒	

B. Please describe problems below:

Good shape all

4. EMBANKMENT CONDITION AT AUXILIARY FLY ASH POND

- A. Please refer to the Auxiliary Fly Ash Pond Inspection Location Plan which is found on Page 9. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion

Ruts in Crest Road

Animal Burrows

Leaking Ash Pipe

Leaking Embankment Drain Pipe

Seepage/Wetness

Trees on Slope

(A)

Exposed Ash on Slope _____

Cracks/Bulges/Slides _____

Sinkhole _____

Other (Please specify) _____

- B. Has this pond been used since the previous inspection? If so, when and for approximately what duration?

NO

- C. Has the water level in the pond been high enough to cause the embankment drains to become active?

NO

5. OUTLET WORKS AT AUXILIARY FLY ASH POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel Trough	<u>NA</u>	
Wooden Skimmer	<u>NA</u>	<u>to be removed</u>
Trough or Skimmer supports	<u>NA</u>	
Concrete structure		
Other (Please specify)		

- B. Please describe problems below:

Area dormant

- C. Please observe the outlet end of the 24" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate:

only trickle

- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:

—

6. EMBANKMENT CONDITION AT WEST POND

- A. Please refer to the West Pond Inspection Location Plan which is found on Page 10. Place a number or letter and, if appropriate, a descriptive sketch on the location plan at each problem area. Then place the same number(s) or letter(s) next to the appropriate descriptions below.

DESCRIPTION

LOCATION CODE

Erosion

Ruts in Crest Road

Animal Burrows

Seepage/Wetness

(A)

Woody Vegetation on Dikes

Cracks/Bulges/Slides

Sediment Buildup in Inlet
Ditches

- B. Has there been significant runoff from the landfill since the last inspection?

NO

- C. Has the water level reached the steel overflow ~~trough~~ since the last inspection? yes. Please record the current water level relative to the overflow trough _____

Full pond + 0.05'

- D. Other problems (please describe): NONE

W.H. Need some painting
H.s. Summer on Discharge Box

7. OUTLET WORKS AT WEST POND

- A. Please observe the features listed below and check the appropriate space:

	GOOD CONDITION	PROBLEM
Steel ^{Box} trough		<u>Need some paint</u>
Wooden Skimmer	☒	
Inlet Structure		<u>SAME</u>
Pipe Problems	☒	
Other (please specify)		

- B. Please describe observed problems below: _____

Overall Good Shape

- C. Please observe the outlet end of the 36" discharge pipe. If water is issuing from the pipe, please determine and record the flow rate, in gallons per minute: _____

~ 4 gpm

- D. Are there any other noteworthy conditions, such as water seeping around the outside of the pipe? If so, please describe:

No

8. GENERAL EMBANKMENT CONDITIONS - ALL PONDS

- A. Has any mowing, brush and tree cutting or spraying been done since the previous inspection? If so, please state below what was done, when and by whom, and show the area on the location plan.

Dormant

Some Yucca Plants to spray Aux Pond
Dike


- B. Has the river level come up significantly since the last inspection, and if so, approximately what elevation was it and when?

No

- C. Was there any apparent damage to the dikes when the river level receded? If so, please indicate below what the damage was (erosion, slides, etc.) and show its location on the location plan.


N/A

9. BOTTOM ASH AND CLEARWATER POND
PONDS - NOTES AND COMMENTS
INCLUDING REMEDIAL MEASURES
SINCE LAST INSPECTION:



SCOPE LINE

V's POINT
DOWN SLOPE



APPROXIMATE SCALE 1"=167 FT.



GLEN LYE PLANT: BOTTOM ASH POND
INSPECTION LOCATION PLAN

10. AUXILIARY FLY ASH POND - NOTES
AND COMMENTS INCLUDING REMEDIAL
WORK SINCE LAST INSPECTION:

LATERAL DRAIN
PIPES SPACED
100' APART

① Ground Hog Den
Put out Bait

Only Water



SLOPE LINE
V's POINT DOWN SLOPE

→ POWER POLE

• MONITORING WELL
MW-11

GLEN LYN PLANT; AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN

PAGE 10 OF 10
REVISION 2
6/30/97

N 390500

NORTH

DISCHARGE
STRUCTURE

SKIMMER

CREST

NEW RIVER
FLOW

GLEN LYN PLANT WEST POND
INSPECTION LOCATION PLAN

SCALE, FT.

11. WEST POND NOTES AND COMMENTS INCLUDING JOB ORDERS WRITTEN AND REMEDIAL WORK DONE SINCE LAST INSPECTION

① Wet area as usual, spongy



gai consultants

Final Design Report

Glen Lyn Landfill
Permit No. 222 Amendment
Appalachian Power Company
Glen Lyn Plant, Glen Lyn, Virginia
Volume 1 of 2

GAI Project Number: C050540.20

TR B

JULY 2009

~~August 2007~~

(TR 2 ~~MARCH 2007~~)

Prepared for American Electric Power Service Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Prepared by: GAI Consultants, Inc.
Pittsburgh Office
385 East Waterfront Drive
Homestead, Pennsylvania 15120-5005



... transforming ideas into reality

PART 7
SLOPE STABILITY ANALYSIS

SUBJECT: AEP GLEN LYN PLANT -LANDFILL AMENDMENTDEEP-SEATED STABILITY ANALYSESBY SDA DATE 03/23/2007 PROJ NO C05054G.20CHKD BY BLR DATE 4/2/07 SHEET NO. 1 OF 6**OBJECTIVE:**

Evaluate deep-seated rotational failure surfaces under static and seismic conditions for the proposed lateral expansion of the CCB landfill facility for AEP's Glen Lyn Power Plant

METHODOLOGY:

Stability will be evaluated for both static and seismic conditions using two-dimensional limit equilibrium methodology and the computer program STEDWin 2.79

REFERENCES:

1. Virginia Legislative Code, Chapter 80, Solid Waste Management Regulations, V A R December 19, 2005.
2. Hynes-Griffin, Mary, E., Arley, Franklin, G., Rationalizing the Seismic Coefficient Method, [Vicksburg, Mississippi], Department of the Army [Waterway Experiment Station, Corps of Engineers], July, 1984
3. Part B Application for Glen Lyn Industrial Waste Landfill, Final Report, November, 2006 GAI Consultants, Inc
4. Peak Acceleration (%g) with 2% Probability of Exceedance in 50 Years, USGS Map, October, 2002.

BACKGROUND:

American Electric Power is proposing the construction of a lateral expansion of the CCB landfill located at the Glen Lyn Plant, in Giles County, Virginia. The proposed expansion will occur over the Auxiliary Fly Ash Pond (AUX FAP) located to the east of the operational landfill. The proposed CCB landfill is shown in plan on Part 1. Located on the west bank of the New River, the existing landfill and the proposed lateral expansion are approximately 55 acres and 17 acres in size, respectively. Existing conditions and test boring locations are shown on the attached plan view.

Overburden soils consist predominately of fly ash and alluvium with lesser amounts of residuum. Composed of silt, the fly ash thickness ranged from 28 feet (06-GLLE-10) to 50 feet (06-GLLE-01). Alluvial and residual soils, consisting of sands with varying amounts of silt, clay and gravel, were encountered at each boring location and ranged from 5.2 to 16.4 feet thick in Borings 06-GLLE-03 and 06-GLLE-07, respectively.

Bedrock was sampled at boring locations (06-GLLE-01, -03, -04, -06, -07, and -08) and consisted primarily of shale. In each boring, soil sampling was terminated once an SPT value of 50 blows per 6 inches, or less, was recorded. Samples recovered from the borings at terminal depths were described as decomposed shale or shale fragments indicating the likely

SUBJECT: AEP GLEN LYN PLANT -LANDFILL AMENDMENT

DEEP-SEATED STABILITY ANALYSES

BY SDA DATE 03/23/2007 PROJ NO C050540.20

CHKD BY BLR DATE 4/2/07 SHEET NO 2 OF 6

gai consultants

bedrock surface. This surface elevation varied from elevation 1481.4 to 1494.1 feet above mean sea level

ANALYSIS:


In order to determine the factor of safety against sliding failure, overall thickness of each soil layer across the site, and engineering properties of each soil layer were determined. To conservatively estimate minimum factor of safety, the steepest slope was used for the dike analysis. Based on inspection of the proposed grading plan, the steepest slope (2.2H:1V) occurs in the southeast corner, on the AUX FAP embankment. This slope represents approximately 30 percent of the slopes considered in design. The remaining 70 percent of the slopes are either between 2.5H: 1.0V and 3.0H: 1.0V.

Upon consolidating all the needed information, the estimated factor of safety was determined for the most critical sections. Output files from the STEDWin program are provided as Part 7, Stability Analysis Results.

Subgrade elevations for the proposed landfill expansion are shown on Drawing No. E-M003 (Base Grade Plan) and will be attained primarily by placing and compacting structural fill, drainage material, or protective cover in the location of the proposed Reduced AUX FAP location. The basic geometry for landfill development will be:

- Subgrade sideslopes: 2.2H:1V (steepest); 3H:1V (typical);
- Landfill sideslopes: 4H:1V between benches; and
- Benches: 15 feet wide; spaced every 25 vertical feet

For these analyses, potential failure surfaces within the landfilled CCBs and through the landfill foundation will be evaluated. Generic cross-sections depicting these analysis limits are shown below:



Section AA

SUBJECT: AEF GLEN LYN PLANT - LANDFILL AMENDMENT


DEEP-SEATED STABILITY ANALYSES

BY SDA DATE 03/23/2007 PROJ NO C050540.20

CHKD BY BLR DATE 4/2/07 SHEET NO 3 OF 6



gai consultants



Section BB

Two cross-sections, one through the reduced capacity lagoon starting at boring 06-GLLF-10 and another through the containment dike adjacent to the river, were selected for this analysis. The cross-section locations are shown in plan on Figure E-B001. The cross-section locations were chosen based on following considerations:

- The proposed expansion is essentially a rectangle which will tend to align the most critical deep-seated analysis sections with the long and short axes;
- The critical insitu layers identified at the site include the dewatered fly ash within the AUX FAP and the embankment materials used to construction the containment dikes. These soils were designated as critical layers because they contain zones of moderate to low shear strength materials; and
- The critical engineered layers identified at the site include the structural fill layers placed within the proposed landfill expansion. These fill layers provide positive drainage from the upstream end of the AUX FAP to the proposed reduced AUX FAP at the toe of the CCB embankment. They were designated as critical layers because they will be the soil foundation layers evaluated in the deep-seated analysis sections.

The geometry and stratigraphy of the two sections were entered into the computer program STEDWin which was used to evaluate potential failure surfaces along the cross-sections. The analysis section data was compiled as follows:

Top of Rock – Data from the geologic characterization of the proposed landfill site were used to construct the approximate top of rock elevation. Data from the boring logs indicate that the top of rock varies along the analysis sections from elevation ~ 1493 feet to ~ 1481 feet. Based on this information, top of rock profiles were incorporated into the stability analyses. Since the bedrock under the proposed landfill is competent material, the deep-seated failure surfaces evaluated herein were constrained to the soil layers overlying the top of rock surface.

Temporal High Phreatic and Piezometric Surfaces – Data from the hydrogeologic characterization of the proposed landfill site were used to construct a potentiometric surface map. Based on data from the hydrogeologic investigation, the only phreatic or piezometric surface likely to affect the

SUBJECT: AEF GLEN LYN PLANT - LANDFILL - AMENDMENT

DEEP-SEATED STABILITY ANALYSES

BY SDA DATE 03/23/2007 PROJ NO C050546.20

CHKD BY BIA DATE 4/2/07 SHEET NO 4 OF 6

 **gai consultants**

stability of the facility during its development is the phreatic surface present in the AUX FAP Piezometer water level readings varied from ~ 1501 feet to ~ 1487 feet, and are significantly impacted by the New River. Based on this information, phreatic surfaces were incorporated into the stability analyses with the surface elevation between 1488 and 1500 for Section AA and at elevation 1500 for Section BB.

Subgrade – Elevations were obtained from Drawing No. E-M003 (Base Grading Plan) and incorporated into the stability analyses.

Ultimate Development Grades – Elevations were obtained from Drawing No. E-M006 (Final Topography Plan).

Soil and CCB Properties – The soils and CCBs that comprise the proposed landfill and landfill foundation consist of a variety of materials. All of these materials have varying index and shear strength properties that affect the evaluation of landfill stability. The engineering properties assigned to the proposed landfill soils and CCBs are summarized and discussed below:

SECTION AA

Soil Type	STEDWin Soil No.	γ_T (pcf)	γ_{Sat} (pcf)	$\phi=\phi'$ (Degrees)	$c=c'$ (psf)
New Ash	1	80	85	32	0
Ash No. 1	2	65	70	35	0
Clayface	3	120	125	0	1000
Ash No. 2	4	65	70	32	0
Ash No. 3	5	65	70	30	0
Ash No. 4	6	65	70	28	0
Ash No. 5	7	65	70	24	0
Snd&cl	8	110	115	28	0
Rock	9	150	155	30	1500

SECTION BB

Soil Type	STEDWin Soil No.	γ_T (pcf)	γ_{Sat} (pcf)	$\phi=\phi'$ (Degrees)	$c=c'$ (psf)
New Ash	1	80	85	32	0
Berm-New Ash	2	80	85	32	0
Ash No. 1	3	65	70	32	0
Ash No. 2	4	65	70	28	0
Snd&cl	5	110	115	28	0
Rock	6	150	155	30	1500

SUBJECT: AEP GLEN LYN PLANT - LANDFILL AMENDMENT

DEEP-SEATED STABILITY ANALYSES

BY SDA DATE 03/23/2007 PROJ NO C050540.20

CHKD BY BLR DATE 4/2/07 SHEET NO 5 OF 6



Insitu soils that comprise the proposed landfill expansion foundation (Soil Nos. 4 and 3 for Sections AA and BB, respectively) are fly ash sluiced then dewatered in-place. The insitu soils that comprise the protective dike (Soil Nos. 2, 4, and 8 from Cross-Section AA) consist of sand and clay for the portions constructed as part of the initial development and fly ash for the portions of the AUX FAP constructed during subsequent development.

Insitu sand and clay consists of low- to medium plasticity clays and silty clays with varying amounts of sand. Site-specific shear strengths were developed for these materials from bore hole dilatometer, CPT, and SPT testing.

Bedrock beneath the proposed landfill (Soil No. 9) is sedimentary in origin and consists of sandstone, shale, and siltstone. As previously noted, the properties of the bedrock underlying the site will not affect these analyses as deep-seated failure surfaces will be constrained to the overlying landfill layers which will be much weaker than bedrock. Therefore, for these analyses, no conditions significant to rock fracture mechanics are included in these analyses.

Seismic Conditions – The proposed expansion is located in north-central Giles County, as shown on Drawing No. 1 (Title Sheet and Location Map). This area is defined as a Seismic Impact Zone by VDEQ. Based on using a 2 percent probability of exceedance in 50 years of a maximum horizontal acceleration in lithified earth material, as a percentage of Earth's gravitational pull (g), equal to or greater than 0.10g, an $a_{max}=0.18(g)$ was used. This acceleration was estimated using Reference 4, which is included in Attachment 4. Site-specific load/response data is not available for the proposed facility to determine if, and to what extent, horizontal ground accelerations may be amplified or dampened. In lieu of this, the value obtained from the USGS figure was used for the stability analyses. Based on the Poisson Model, a 2% probability of exceedance in 50 years is approximately equal to a 10% probability of exceedance in 250 years, which is stated in 9VAC20-80-10. With guidance from Reference No. 2, 50% of a_{max} was used for the pseudostatic analysis ($a_{max}=0.09$).

SUMMARY:

Stability analyses prepared for the proposed facility are summarized in the following table. Static conditions were evaluated using Bishop's method, which is widely considered the most conservative of the typically used limit equilibrium analysis methods. A "search" routine in STEDWin was used to evaluate a large number of deep-seated failure surfaces and isolate the ten most critical surfaces for each analysis section.

Seismic analyses, using guidance from Reference 2, were run on each static stability failure surfaces. Graphical output files for the most critical failure surfaces are included as Part 10. The results of the deep-seated stability analyses are summarized on the next page:

SUBJECT: AEP GLEN LYN PLANT - LANDFILL AMENDMENT

DEEP-SEATED STABILITY ANALYSES

BY SDA DATE 03/23/2007 PROJ NO C050540.20

CHKD BY B.R. DATE 4/2/07 SHEET NO 6 OF 6




gai consultants

DEEP-SEATED FAILURE ANALYSIS				
Cross-Section	File Name	Analysis Condition	Analysis Zone	FSmin
3B	GLYNB8 PL2-Toe Failure Analysis	STATIC	BERM	1.90
	GLYNB7 PL2-Slope Length Analysis	SEISMIC	BERM	1.92
	GLYNB6 PL2- Slope Length Analysis	STATIC	BERM	2.73
	GLYNB5 PL2-Toe Failure Analysis	SEISMIC	BERM	1.45
AA	GLYNA3 PL2-Slope Length Analysis	STATIC	PROTECTIVE DIKE	2.12
	GLYNA4 PL2-Slope Length Analysis	SEISMIC	PROTECTIVE DIKE	1.23
	GLYNA2 PL2-Toe Failure Analysis	STATIC	PROTECTIVE DIKE	1.29
	GLYNA5 PL2-Toe Failure Analysis	SEISMIC	PROTECTIVE DIKE	1.01

US EPA ARCHIVE DOCUMENT

PART 8
STABILITY CROSS-SECTION LOCATIONS



STABILITY CROSS SECTION LOCATIONS

OWN: JCN	CHRD: SDA	APPO: DMC 04/2/07
SCALE: 1"=100'	TASK NO. 00	
PROJECT NO./TASK NO. 2005-540-10	DRAWING NO. E-B002	REV

PROPOSED SUBSURFACE INVESTIGATION PLAN GLEN LYN LANDFILL MODIFICATION GLEN LYN, VA	AMERICAN ELECTRIC POWER COLUMBUS, OHIO
--	---



ON G40 FILE: P:\2005-540-10\540-10-01-0001.dwg 1/1/04

PART 9

ANGLE OF FRICTION OF FLY ASH AND SOIL USING

LABORATORY AND IN-SITU TESTING METHODS

112

Angle of Friction of Fly Ash and Soil Using Laboratory and In-Situ Testing Methods Glen Lyn Landfill Permit Amendment

Depth (m)	Depth (ft)	Boring 06-GLLE-01			Boring 06-GLLE-03			Boring 06-GLLE-04			Boring 06-GLLE-07			Boring 06-GLLE-09		
		Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST
1.2	3.9		41			39			41			42			38	
1.4	4.6		40			40			40			42			36	
1.6	5.2		40			40			39			41			34	
1.8	5.9					39			38			41			31	
2	6.5		42			41			42			39			30	
2.2	7.2		40			41			42			39			30	
2.4	7.9		37						42			37			28	
2.6	8.5		33			47			43			36			28	
2.8	9.2		38						40			34			28	
3	9.8								39			34			27	
3.2	10.5		39	37		38			38			33			29	
3.4	11.2					40			38			34			34	
3.6	11.8		36			40			39			34			32	
3.8	12.5		35			38			39			32			33	
4	13.1		36			38			38			32			37	
4.2	13.8		36			37			37			34			35	
4.4	14.4		34			38			35			35			37	
4.6	15.1		33			39			33			34			34	
4.8	15.7		35			37			33			34			33	
5	16.4		35			36			33	28		33			31	
5.2	17.1		35			35			33		31	33	31		31	
5.4	17.7		37			34			34			32			31	
5.6	18.4		37			33			37			33			32	
5.8	19.0		36			33			28			33			30	
6	19.7		33			33			39			34			30	
6.2	20.3		33			33			34			36			29	
6.4	21.0		33			32			34			38			29	
6.6	21.6	36	34	35		35						38			28	
6.8	22.3		34			33						38			26	
7	22.9		33			32			34			38			23	
7.2	23.6		33			34			33			38			23	
7.4	24.3		35			30			33			36			27	
7.6	24.9		34			33			34			36			30	
7.8	25.6		33			32			32			36			32	
8	26.2		30			32			31			35			31	
8.2	26.9		31			33			32			33			31	
8.4	27.6		31			31			31			34			23	
8.6	28.2		31			33			31			35			23	
8.8	28.9		31			30			31			33			27	
9	29.5		21			30			31			31			28	
9.2	30.2		31			29			31			29			28	
9.4	30.8		31			30			31			27			28	
9.6	31.5	30	30	27		33			31	29		27			29	
9.8	32.1		30			31			29			26			29	
10	32.8		30			33			29			26			25	
10.2	33.5		31			23			29			26			26	
10.4	34.1		29			27			29			26			25	
10.6	34.8		29			25			30			26			25	
10.8	35.4		28			25			28			25			25	
11	36.1		29			30			29			24			25	
11.2	36.7		29			29			30			24			24	
11.4	37.4		29						31			25			23	
11.6	38.0		28			35						26				
11.8	38.7		25			36						24			23	
12	39.4		26			35						26			22	
12.2	40.0		24			36						26				
12.4	40.7	32		38								28			22	
12.6	41.3		24			32						30			23	
12.8	42.0		25									25				

**Angle of Friction of Fly Ash and Soil Using Laboratory and In-Situ Testing Methods
Glen Lyn Landfill Permit Amendment
(Continued)**

Depth (m)	Depth (ft)	Boring 06-GLLE-01			Boring 06-GLLE-03			Boring 06-GLLE-04			Boring 06-GLLE-07			Boring 06-GLLE-09		
		Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST	Lab	DMT	BST
13	42.6		25			36						27				
13.2	43.3		29									26			34	
13.4	44.0		30									26				
13.6	44.6		30									27				
13.8	45.3		25									25				
14	45.9		24									25				
14.2	46.6		24									25				
14.4	47.2		23									26				
14.6	47.9											26				
14.8	48.5		37									26				
15	49.2															
15.2	49.9															
15.4	50.5															
15.6	51.2															
15.8	51.8															
16	52.5															
16.2	53.1															
16.4	53.8															
16.6	54.4															
16.8	55.1															

Notes:

Lab = Laboratory Test Result (ASTM D3080-04)

DMT = Dilatometer Test Result

BST = Borehole Shear Test


 indicates soil. All other are fly ash materials

PART 10
STABILITY ANALYSIS RESULTS

Glen Lyn Landfill Modification Section AA

p 1200S2005-54 (1) d20 engineering stability analysis.p12 Run By: Simon D. Armstrong, GAI Consultants 4/2/2007 10:26AM C.K.: B.L.R 4/5/07

#	FS	Soil Desc.	Soil Type No.	Total Unit Wt (pcf)	Saturated Unit Wt (pcf)	Intercept (psi)	Friction Angle (deg)	Piez Surface No.
a	1.29	new ash	1	80.0	85.0	0.0	32.0	W1
b	1.36	ash1	2	65.0	70.0	0.0	35.0	W1
c	1.37	clayface	3	120.0	125.0	1000.0	0.0	W1
d	1.38	ash2	4	65.0	70.0	0.0	32.0	W1
e	1.40	ash3	5	65.0	70.0	0.0	30.0	W1
f	1.42	ash4	6	65.0	70.0	0.0	28.0	W1
g	1.42	ash5	7	65.0	70.0	0.0	24.0	W1
h	1.42	std&cl	8	110.0	115.0	0.0	28.0	W1
i	1.42	rock	9	150.0	155.0	1500.0	30.0	W1



PCSTABL5M/si FSmin=1.29
Safety Factors Are Calculated By The Modified Bishop Method



Glen Lyn Landfill Modification Section AA

p:\2005\2005-540\20Engineering\stabilityruns\glyn5.pl2 Run By: Simon D. Armstrong, GAI Consultants 4/2/2007 10:28AM CK: B.L.R. 4/5/07

210

#	FS	Soil Desc	Soil Type No	Total Unit Wt (pcf)	Saturated Unit Wt (pcf)	Intercept (psf)	Friction Angle (deg)	Piez Surface	Load Horiz Eqp	Value
a	1.01							NO		
b	1.07	new ash	1	80.0	85.0	0.0	32.3	W1		
c	1.07							W1		
d	1.08	ash1	2	65.0	70.0	0.0	35.3	W1		
e	1.08	clayface	3	120.0	125.0	1000.0	0.0	W1		
f	1.08	ash2	4	65.0	70.0	0.0	32.0	W1		
g	1.09	ash3	5	65.0	70.0	0.0	30.0	W1		
h	1.11	ash4	6	65.0	70.0	0.0	28.0	W1		
i	1.12	ash5	7	65.0	70.0	0.0	24.0	W1		
j	1.12	snd&cl	8	110.0	115.0	0.0	28.0	W1		
k	1.12	rock	9	150.0	155.0	1500.0	30.0	W1		

150

120

90

60

30

0

330

300

270

240

210

180

150

120

90

60

30

0

STED




PCSTABL5M/s/ FSmin=1.01

Safety Factors Are Calculated By The Modified Bishop Method

Glen Lyn Pond El 152/ D-D

p:\2005\2005-540\engineering\stabilityruns\glynd1.pl2 Run By: Username 1/31/2008 01:44PM



...stabilityruns\glynd1.dgn 2/1/2008 10:30:20 AM

Appendix X

Boring Logs, Construction Diagrams and Certification

PROJECT A.E.P. GLEN LYN LANDFILL MODIFICATIONS, GLEN LYN, VA

ELEVATION 1542.97 GWL 0 HRS 12.8

24 HRS 42.4

BORING NO 06-GLE-01

PROJECT NO C350540.20

DATE 12-17 JUL 2006

CLASSIFIED BY DAN SANGER

PAGE 1 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE RECOVERY/TYPE & SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	ROD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY, CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	14	10 S-1			M-DENSE	PAID	SILT AND SHALE FRAGMENTS, SOME CLAY	ml	DRY
3.0	12	10 REC 1.5		2.0	A-DENSE	DRY GRAY	FLYASH	ml	DRY
4.5	5	4 S-3		5.0	LOOSE				
6.0	6	2 REC 1.5		7.0	M-DENSE	BROWN GRAY	SANDY SILT, ROCK FRAGMENTS, FLYASH	ml	DRY
7.5	17	5 S-5			LOOSE		SHALE FRAG 6.0-6.2		
9.0	2	2 REC 1.5				DRY GRAY	FLYASH		
10.5	1	2 S-7			V-LOOSE				
12.0	3	2 REC 1.5		12.0					
13.5	1	2 S-9		13.5		BROWN	SANDY SILT, SOME CLAY	ml	DRY
15.0	2	1 REC 1.5				DRY GRAY AND CLAY	FLYASH	ml	DRY
16.5	1	1 S-11							
18.0	4	4 REC 1.5			LOOSE				
19.5	4	4 S-13							
21.0	3	3 REC 1.5							
22.5	4	4 S-15							
24.0	5	5 REC 1.5							
25.5	3	3 S-17							
27.0	2	2 REC 1.5							
28.5	2	2 S-19							
30.0	1	1 REC 1.5			V-LOOSE				

REMARKS ** DRILLED BY TERNA TESTING INC. OF WASHINGTON, PA USING A C.M.G. 45C RUBBER TRACK MOUNTED DRILL
BORING ADVANCED USING 3/4" 50. HOLLOW STEM AUGERS, CONTINUOUS SPT w/AUTOMATIC HAMMER NR-2 COATING TOOL

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-01

(B-1)

PROJECT A.E.P. GLEN LYN LANDFILL MODIFICATIONS GLEN LYN VABORING NO 06-GLE-01ELEVATION 1542.97 OWL 0 HRS 12.8PROJECT NO C050540102.5 HRS 47.4'DATE 12-17 JULY 2006CLASSIFIED BY DAN SANGERPAGE 2 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
30.5	2	S-21			LOOSE	DARK GRAY	FLY ASH (CONT)	ml	dry
	3	REC 1.5				RED GRAY			
33.0	3	REC 1.5							
34.5	1	S-23			V. LOOSE				
	2	REC 1.5							
36.0	2	REC 1.5							
37.5	1	S-25							slightly moist
	2	REC 1.5							
39.0	2	REC 1.5							
40.5	W.D.H. W.D.H.	S-27					- NO RECOVERY -		
	1	REC 1.5							
42.0	1	REC 0.7							wet
43.5	1	S-29							moist
	2	REC 1.5							
45.0	2	REC 1.5							moist
46.5	W.D.H. W.D.H.	S-31							wet
	W.D.H. W.D.H.	REC 1.5							
48.0	W.D.H. W.D.H.	REC 1.5							
49.5	W.D.H. W.D.H.	S-33							
	W.D.H. W.D.H.	REC 1.5							
51.0	5	REC 1.5			LOOSE	Brown	SILTY SAND	sm	moist
52.5	3	S-35							
54.0	5	REC 1.5							
	2	REC 1.5							
55.5	3	S-37							
	4	REC 1.5							
57.0	4	REC 1.5							
	3	S-39							
58.5	10	REC 3-40							
59.9	41/2	REC			V. loose	RED GRAY	SHALE FRAGMENTS	70	

REMARKS: "DANGER" Bob Lawrence, Gordon, Larry, Thorne.

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-01

(B-1)

PAGE 3 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION			USCS OR ROCK BROWNNESS	REMARKS*	
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR			
1	2	3	4	5	6	7	8	9	10
62.0-62.5	2	5-91 GOLF		61.7	HARD	LIGHT GRAY	SANDSTONE - THINLY BEDDED	BK	120' FMC GAS, 62.5' GL.
					M. SOFT	DARK GRAY	SHALE, FEW SILTY SHALE ZONES, U. THINLY BEDDED	YEL	~80' FMC GL.
	4.3	50	86%	0					
65.5				65.5					
							BOTTOM of Boring: 65.5'		

REMARKS "

* POCKET PENETROMETER READINGS

* METHOD OF ADVANCING AND CLEANING BORING

BOHRING 06-GLE-01
(B-1)

PROJECT AEP: GLEN LYN LANDFILL MODIFICATIONS GLEN LYN, VABORING NO. 06-GLE-03ELEVATION 1546.87 GWL 0 HRS 53.8PROJECT NO. C050540.20DATE 17-18 JULY 2006 24 HRS 50.1CLASSIFIED BY DAN SANDERPAGE 1 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE NO., TYPE & RECOVERY OR % ROCK RECOVERY	ROD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY, CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	4	S-1 REC 1.1		15	LOOSE	RED-BROWN	CLAYEY SILT, MICROSCOPIC, SAND	ML	DRY
3.0	4	REC 1.2			↓	↓	SAND	↓	↓
4.5	2	S-3 REC 1.1			LOOSE	GRAY	FLYASH	ML	DRY
6.0	2	S-4 REC 1.1			V-LOOSE	GRAY			
7.5	3	S-5 REC 1.3			↓	↓			
9.0	12	REC 1.5		80	↓	↓			
10.5	9	S-7 REC 1.5			M. DENSE	RED-BROWN	SPARSELY BEDDED CLAYEY TO SANDY SILT	ML	
12.0	8	S-8 REC 1.5		90	↓	GRAY	SAND, FLYASH		
13.5	3	S-9 REC 1.5			M. DENSE	GRAY	FLYASH	ML	DRY
15.0	4	S-10 REC 1.2			LOOSE				
16.5	3	S-11 REC 1.1							
18.0	2	S-12 REC 1.4			↓	↓			
19.5	1	S-13 REC 1.3			V-LOOSE				
21.0	2	S-14 REC 1.3							
22.5	2	S-15 REC 1.5							
24.0	5	S-16 REC 1.3			LOOSE				
25.5	2	S-17 REC 1.0			V-LOOSE				
27.0	2	S-18 REC 1.5			↓	↓			
28.5	3	S-19 REC 1.5			LOOSE				
30.0	2	S-20 REC 1.5			V-LOOSE				

REMARKS **DRILLED BY TERRA TESTING IN WASHINGTON, VA USING A CME-VISC RUBBER TRENCH MOUNTED DRILL.

BORING ADVANCED USING 4 1/4" I.D. MOUNTAIN STEEL RODS, CONTINUOUS SPT W/ AUTOMATIC HAMMER, 4" SPT ALL HAMMER, 1' ROCK

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-03
(B-3)

PROJECT A.E.P. GLEN LYN LANDFILL MODIFICATION GLEN LYN, VA BORING NO 06-GLE-03
ELEVATION 1540.02 GWL 0 HRS 53.8 PROJECT NO CA50548.20
DATE 17-18 JULY 2006 CLASSIFIED BY DAN SANGER PAGE 2 of 3

DEPTH (FT.)	BLOWS PER X INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RGD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
31.5	1	S-31			V. LOOSE	DARK GRAY	FLYASH (CONT)	ML	
33.0	2	REC 1.5				GRAY			
34.5	W.O.H. W.O.H.	S-33							WET
36.0	W.O.H. W.O.H.	REC 1.5							
37.5	W.O.H. W.O.H.	S-35							
39.0	3	REC 1.2			LOOSE	BROWN	SILTY SAND, MEDIUM GRAINED	SM	MOIST
40.5	2	S-37			M. DENSE				
42.0	5	REC 1.5							
43.5	3	S-39				BROWN	CLAYEY SAND	SC	M-DIT
45.0	7	REC 1.5					SILTY SAND	SM	MOIST TO WET
46.5	2	S-41							
48.0	7	REC 1.5							
49.5	1	S-43			LOOSE	BROWN	COARSE SAND, FINE GRAVEL	SP	WET
51.0	2	REC 1.5			V. LOOSE				
52.5	W.O.H. W.O.H.	S-45							
54.0	1	S-46							
55.5	1	REC 0.7							
							AIR HAMMER w/o SAMPLING		PG-AIR HAMMER
									UNDER LEVEL: 49.

REMARKS: DRILLER: BOB LAWRENCE, HELPER: DOUG MONROE

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-03
(9-3)

AE PGL000111

PROJECT A.E.P. GLEN LYN LANDFILL MODIFICATIONS GLEN LYN, VA

 ELEVATION 1539.73 GW: 0 HRS 54.4

 BORING NO 06-GLE-04

 PROJECT NO C050540.20

 DATE 31 JUL 09 2:06 PM

 CLASSIFIED BY DAN SANGER

 PAGE 1 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY RUN SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
			PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	8	9	10
1.5	24	S-1 REC 1.3	1.0	LOOSE	GRAY + BROWN	FLYASH AND SANDY SILT	ML	DRY
3.0	3	REC 1.2			BROWN	SANDY SILT	ML	DRY
4.5	1	S-3 REC 1.5		V. LOOSE				
6.0	2	REC 1.2						
7.5	1	S-5 REC 1.5		V. LOOSE	BROWN	SANDY SILT	ML	DRY
9.0	5	S REC 1.5	9.0	LOOSE				
10.5	3	S-7 REC 1.5		LOOSE	GRAY	FLYASH	ML/SM	DRY
12.0	3	REC 1.3						
13.5	2	S-9 REC 1.5						
15.0	2	REC 1.4		V. LOOSE				
16.5	1	S-11 REC 1.5						
18.0	2	REC 1.5		LOOSE				
19.5	4	S-13 REC 1.5						
21.0	8	S-14 REC 1.5		M. DENSE				
22.5	3	S-15 REC 1.5		LOOSE				
24.0	3	REC 1.5						
25.5	1	S-17 REC 1.3		V. LOOSE				
27.0	2	S-18 REC 1.5		LOOSE				
28.5	1	S-19 REC 1.5		V. LOOSE				
30.0	2	REC 1.0						

REMARKS * DRILLED BY TERRA TESTING INC. IN WASHINGTON, PA USING A CASE-HS RUBBER TROCK MOUNTED DRILL
 BORING ADVANCED USING 4 1/4" I.D. HOLLOW STEM AUGERS, CONTINUOUS SPT "H" AUTO HAMMER, 4" AIR HAMMER

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

 BORING 06-GLE-04
 (B-4)

PROJECT: A.E.P. : GLEF LHM LANDFILL MODIFICATIONS GLEF LHM VA BORING NO: 06-GLE-04
ELEVATION: 1539.73 GWL D HRS: 54.4 PROJECT NO: C050540.20
24 HRS: 54.4
DATE: 3 JUL - 09 AUG 2006 CLASSIFIED BY: DAD SAIGER PAGE: 2 of 3

DEPTH (FT.)	FLAWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	DESCRIPTION MATERIAL CLASSIFICATION	USCS OR ROCK BROKENNESS	REMARKS
30.5	2	S-21 REC 1.1 S-22			V. LOOSE	GRAY	FLYASH (CONT)	mtm	Dry
33.0	2	REC 1.5							
34.5	2	S-23 REC 1.2 S-24							
36.0	2	REC 1.2							
37.5	1	S-25 REC 1.2 S-26	37.0						MOIST TO WET
39.0	2	REC 1.4			V. LOOSE	Red	SILTY SAND AND SMALL ROCK FRAGMENTS AND GRAVEL, SOME CLAY	sm	MOIST
40.5	3	S-27 REC 1.5 S-28							
42.0	2	REC 1.2							
43.5	8	S-29 REC 1.5 S-30			M. DENSE				
45.0	2	REC 1.2			LOOSE				WET
46.5	5	S-31 REC 1.5 S-32			M. DENSE				MOIST
48.0	14	REC 1.3	47.0		DENSE				MOIST
49.5	15	S-33 REC 1.1 S-34					SANDY SILT AND ROCK FRAGMENTS	mtm	WET
51.0	12	REC 1.5			M. DENSE				
52.5	6	S-35 REC 1.5 S-36	52.9		V. DENSE				TOP OF ROCK 52.9
53.9	20/24								
							BORING DRILLED UP TO SAMPLING TO A DEPTH OF 121.0 FT		

REMARKS: DRILLER: ED WITKOWSKI, GEOPHYSICIAN: LARRY THORPE

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-04

PAGE 3 of 3

REMARKS: "

AE PGL000114

PROJECT A.E.P. : GLEN LYN LANDFILL MODIFICATION GLEN LYN, VA

BORING NO DB-GLE-06

ELEVATION 1540.62 G.M. 0 HRS 56.05

PROJECT NO 0050540.20

DATE 02-07 AUG 2004 24 HRS 56.1

CLASSIFIED BY DAJ SANGER

PAGE 1 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RCC (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BRAGNESS	REMARKS*
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	5	S-1 RCL 1.1		2.0	LOOSE	Brown	SANDY SILT, PLACED CLAY	ml	DRY
3.0	2	REC 1.1			LOOSE	GRAY	FLYASH	ml-ca	DRY
4.5	2	S-3 REC 1.5							
6.0	1	S-4 REC 1.5							
7.5	2	S-5 REC 1.5		8.0					
9.0	4	REC 1.5			LOOSE	RED BROWN	SILTY FINE SAND	sm	DRY
10.5	4	S-7 REC 1.5		10.11					
12.0	2	S-8 REC 1.5			LOOSE	GRAY	FLYASH	ml-sh	DRY
13.5	2	S-9 REC 1.5							
15.0	2	S-10 REC 1.5			V. LOOSE				
16.5	1	S-11 REC 1.5							
18.0	1	S-12 REC 1.5							
19.5	1	S-13 REC 1.5							
21.0	1	S-14 REC 1.2							
22.5	1	S-15 REC 1.2							
24.0	2	S-16 RCL 1.3							
25.5	2	S-17 REC 1.5							
27.0	3	S-18 REC 1.2			LOOSE				
28.5	5	S-19 REC 1.5							
30.0	2	S-20 REC 1.5			V. LOOSE				

REMARKS **DRILLED BY TULLA TESTING ENG. CO. WASHINGTON, PA USING A ONE-45C RUBBER TRACK MOUNTED DRILL

BORING EQUIPMENT USED - 1/2" DIA. HOLLOW STEEL AUGER, CONSTANT SPT 4/5000 HAMMER, 1" DIA AIR HAMMER

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING DB-GLE-06
(A-6)

PROJECT AEP: GLEN LYN LANDFILL MODIFICATION GLEN LYN VABORING NO 06-GLE-06ELEVATION 1542.62 GWL 0 HRS 56.55PROJECT NO C050540.2024 HRS 56.1DATE 02-07 AUG 2006CLASSIFIED BY DAN SANGERPAGE 2 of 3

DEPTH (FT)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE RECOVERY/RUN SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY, CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
30.1	2	3							
31.5	1	S-21			4 LOOSE	GRAY	FLYASH	MSM	
33.0	2	S-22			LOOSE				
34.5	1	S-23			VL LOOSE				SLIGHTLY MOIST
36.0	1	S-24							
37.5	1	S-25							WET
39.0	1	S-26			LOOSE				
40.5	1	S-27			M DENSE				
42.0	1	S-28			LOOSE				
43.5	1	S-29			VL LOOSE				
45.0	1	S-30							
46.5	1	S-31							
48.0	1	S-32							
49.5	1	S-33							
51.0	1	S-34							
52.5	1	S-35							
54.0	1	S-36							
55.5	1	S-37							
57.0	1	S-38							
58.5	1	S-39							
60.0	1	S-40							
61.5	1	S-41							
63.0	1	S-42							
64.5	1	S-43							
66.0	1	S-44							
67.5	1	S-45							
69.0	1	S-46							
70.5	1	S-47							
72.0	1	S-48							
73.5	1	S-49							
75.0	1	S-50							
76.5	1	S-51							
78.0	1	S-52							
79.5	1	S-53							
81.0	1	S-54							
82.5	1	S-55							
84.0	1	S-56							
85.5	1	S-57							
87.0	1	S-58							
88.5	1	S-59							
90.0	1	S-60							
91.5	1	S-61							
93.0	1	S-62							
94.5	1	S-63							
96.0	1	S-64							
97.5	1	S-65							
99.0	1	S-66							
100.5	1	S-67							
102.0	1	S-68							
103.5	1	S-69							
105.0	1	S-70							
106.5	1	S-71							
108.0	1	S-72							
109.5	1	S-73							
111.0	1	S-74							
112.5	1	S-75							
114.0	1	S-76							
115.5	1	S-77							
117.0	1	S-78							
118.5	1	S-79							
120.0	1	S-80							
121.5	1	S-81							
123.0	1	S-82							
124.5	1	S-83							
126.0	1	S-84							
127.5	1	S-85							
129.0	1	S-86							
130.5	1	S-87							
132.0	1	S-88							
133.5	1	S-89							
135.0	1	S-90							
136.5	1	S-91							
138.0	1	S-92							
139.5	1	S-93							
141.0	1	S-94							
142.5	1	S-95							
144.0	1	S-96							
145.5	1	S-97							
147.0	1	S-98							
148.5	1	S-99							
150.0	1	S-100							
151.5	1	S-101							
153.0	1	S-102							
154.5	1	S-103							
156.0	1	S-104							
157.5	1	S-105							
159.0	1	S-106							
160.5	1	S-107							
162.0	1	S-108							
163.5	1	S-109							
165.0	1	S-110							
166.5	1	S-111							
168.0	1	S-112							
169.5	1	S-113							
171.0	1	S-114							
172.5	1	S-115							
174.0	1	S-116							
175.5	1	S-117							
177.0	1	S-118							
178.5	1	S-119							
180.0	1	S-120							
181.5	1	S-121							
183.0	1	S-122							
184.5	1	S-123							
186.0	1	S-124							
187.5	1	S-125							
189.0	1	S-126							
190.5	1	S-127							
192.0	1	S-128							
193.5	1	S-129							
195.0	1	S-130							
196.5	1	S-131							
198.0	1	S-132							
199.5	1	S-133							
201.0	1	S-134							
202.5	1	S-135							
204.0	1	S-136							
205.5	1	S-137							
207.0	1	S-138							
208.5	1	S-139							
210.0	1	S-140							
211.5	1	S-141							
213.0	1	S-142							
214.5	1	S-143							
216.0	1	S-144							
217.5	1	S-145							
219.0	1	S-146							
220.5	1	S-147							
222.0	1	S-148							
223.5	1	S-149							
225.0	1	S-150							
226.5	1	S-151							
228.0	1	S-152							
229.5	1	S-153							
231.0	1	S-154							
232.5	1	S-155							
234.0	1	S-156							
235.5	1	S-157							
237.0	1	S-158							
238.5	1	S-159							
240.0	1	S-160							
241.5	1	S-161							
243.0	1	S-162							
244.5	1	S-163							
246.0	1	S-164							
247.5	1	S-165							
249.0	1	S-166							
250.5	1	S-167							
252.0	1	S-168							
253.5	1	S-169							
255.0	1	S-170							
256.5	1	S-171							
258.0	1	S-172							
259.5	1	S-173							
261.0	1	S-174							
262.5	1	S-175							
264.0	1	S-176							
265.5	1	S-177							
267.0	1	S-178							
268.5	1	S-179							
270.0	1	S-180							
271.5	1	S-181							
273.0	1	S-182							
274.5	1	S-183							
276.0	1	S-184							
277.5	1	S-185							
279.0	1	S-186							
280.5	1	S-187							
282.0	1	S-188							
283.5	1	S-189							
285.0	1	S-190							
286.5	1	S-191							
288.0	1	S-192							
289.5	1	S-193							
291.0	1	S-194							
292.5	1	S-195							
294.0	1	S-196							
295.5	1	S-197							
297.0	1	S-198							
298.5	1	S-199							
300.0	1	S-200							

REMARKS: *DRILLED WITH WIT-KOWSKI, NEWELL - LARRY THORPE

*POCKET PENETROMETER READINGS

**METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-06
(B.C.)

BORING NO 06-GLE-06

PROJECT NO C-50540.20

24MRS 56.10

CLASSIFIED BY DAN. SAN GEL

PAGE 3 of 3

[illegible]

REMARKS **

30RING 06-044E-01

(B-4)

PROJECT A.E.P.: GLEN LYN LANDFILL MODIFICATIONS GLEN LYN, VA BORING NO 06-GLE-07
ELEVATION 1540.98 GWL 0 HRS 26.1 PROJECT NO COSUS40.20
DATE 27-31 JUL 2006 24 HRS 33.8 CLASSIFIED BY DAN SANGER PAGE 1 of 2

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE RECOVERY/TYPE & SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	ROD (%) OR TORVANE	DESCRIPTION				USOR OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY, CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	2	S-1 REC 1.4 S-2		2.0	LOOSE - M-DENSE	RED- BROWN ↓ DARK GRAY TO BLACK	SILTY SAND, FEW ROCK FRAGMENTS	3m	DAY
3.0	4	REC 1.5 S-3			LOOSE		FLY ASH	4-5m	DAY
4.5	3	REC 1.5 S-4							
6.0	4	REC 1.5 S-5							
7.5	2	REC 1.5 S-6							
9.0	2	REC 1.5 S-7							
10.5	2	REC 1.5 S-8							
12.0	2	REC 1.4 S-9							
13.5	1	REC 1.4 S-10							
15.0	2	REC 1.5 S-11							
16.5	1	REC 1.5 S-12							
18.0	2	REC 1.5 S-13							
19.5	1	REC 1.5 S-14							
21.0	2	REC 1.4 S-15			LOOSE				
22.5	2	REC 1.3 S-16							
24.0	4	REC 1.5 S-17			M-DENSE				
25.5	3	REC 1.5 S-18			LOOSE				
27.0	5	REC 1.5 S-19							
28.5	2	REC 1.5 S-20							
30.0	4	REC 1.4							

REMARKS: DRILLED BY TERRA TESTING INC. OF WASHINGTON PA USING A CME-USE. KUBOTA TRACK MOUNTED DRILL
BORING ADVANCED USING 3/4" ID. HOLLOW STEM AUGER. CONTINUOUS SPT W/ AUTOMATIC HAMMER. NX COR. ALL MO.

* POCKET PENETROMETER READINGS
** METHOD OF ADVANCING AND CLEANING BORING

PROJECT A.E.P. : GLEN LYN LANDFILL MODIFICATIONS GLEN LYN, VA BORING NO 06-GLE-07
ELEVATION 1540.98 GWL 0 HRS 26.6 PROJECT NO CAS0543.20
DATE 27.31 JUL 2006 24 HRS 33.8 CLASSIFIED BY DAN SANGER PAGE 2 of 2

DEPTH (FT.)	BLOWS PER SIX INCHES OR	CORE RECOVERY/RUN SAMPLE NO., TYPE & RECOVERY OR	% ROCK RECOVERY	ROD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BOUNENESS	REMARKS
					PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
30.0	1	3	4	5	6	7	8	9	10	
31.5	1	S-21 W.O.B. REC 0.5			VL. LOOSE	GRAY	FLYASH			
33.0	1	REC 1.5							WATER @ 32'	
34.5	1	S-23 REC 1.5							WGT	
36.0	1	W.O.B. REC 1.5								
37.5	1	W.O.B. REC 1.5								
39.0	1	W.O.B. REC 1.5								
40.5	1	S-27 REC 1.5								
42.0	1	W.O.B. REC 1.5								
43.5	1	S-29 REC 1.5								
45.0	1	S-30 REC 1.5								
46.5	1	S-31 REC 1.1								
48.0	1	S-33 REC 1.5								
49.5	1	S-34 REC 1.5								
51.0	1	S-35 REC 1.5								
52.5	1	S-36 REC 1.5								
54.0	1	S-37 REC 1.5								
55.5	1	S-38 REC 1.5								
57.0	1	S-39 REC 1.5								
58.5	1	S-40 REC 1.5								
60.0	1	S-41 REC 1.5								
61.5	1	S-42 REC 1.5								
63.0	1	S-43 REC 1.5								
64.5	1	S-44 REC 1.5								
66.0	1	S-45 REC 1.5								
67.5	1	S-46 REC 1.5								
69.0	1	S-47 REC 1.5								
70.5	1	S-48 REC 1.5								
72.0	1	S-49 REC 1.5								
73.5	1	S-50 REC 1.5								
75.0	1	S-51 REC 1.5								
76.5	1	S-52 REC 1.5								
78.0	1	S-53 REC 1.5								
79.5	1	S-54 REC 1.5								
81.0	1	S-55 REC 1.5								
82.5	1	S-56 REC 1.5								
84.0	1	S-57 REC 1.5								
85.5	1	S-58 REC 1.5								
87.0	1	S-59 REC 1.5								
88.5	1	S-60 REC 1.5								
90.0	1	S-61 REC 1.5								
91.5	1	S-62 REC 1.5								
93.0	1	S-63 REC 1.5								
94.5	1	S-64 REC 1.5								
96.0	1	S-65 REC 1.5								
97.5	1	S-66 REC 1.5								
99.0	1	S-67 REC 1.5								
100.5	1	S-68 REC 1.5								
102.0	1	S-69 REC 1.5								
103.5	1	S-70 REC 1.5								
105.0	1	S-71 REC 1.5								
106.5	1	S-72 REC 1.5								
108.0	1	S-73 REC 1.5								
109.5	1	S-74 REC 1.5								
111.0	1	S-75 REC 1.5								
112.5	1	S-76 REC 1.5								
114.0	1	S-77 REC 1.5								
115.5	1	S-78 REC 1.5								
117.0	1	S-79 REC 1.5								
118.5	1	S-80 REC 1.5								
120.0	1	S-81 REC 1.5								
121.5	1	S-82 REC 1.5								
123.0	1	S-83 REC 1.5								
124.5	1	S-84 REC 1.5								
126.0	1	S-85 REC 1.5								
127.5	1	S-86 REC 1.5								
129.0	1	S-87 REC 1.5								
130.5	1	S-88 REC 1.5								
132.0	1	S-89 REC 1.5								
133.5	1	S-90 REC 1.5								
135.0	1	S-91 REC 1.5								
136.5	1	S-92 REC 1.5								
138.0	1	S-93 REC 1.5								
139.5	1	S-94 REC 1.5								
141.0	1	S-95 REC 1.5								
142.5	1	S-96 REC 1.5								
144.0	1	S-97 REC 1.5								
145.5	1	S-98 REC 1.5								
147.0	1	S-99 REC 1.5								
148.5	1	S-100 REC 1.5								
150.0	1	S-101 REC 1.5								
151.5	1	S-102 REC 1.5								
153.0	1	S-103 REC 1.5								
154.5	1	S-104 REC 1.5								
156.0	1	S-105 REC 1.5								
157.5	1	S-106 REC 1.5								
159.0	1	S-107 REC 1.5								
160.5	1	S-108 REC 1.5								
162.0	1	S-109 REC 1.5								
163.5	1	S-110 REC 1.5								
165.0	1	S-111 REC 1.5								
166.5	1	S-112 REC 1.5								
168.0	1	S-113 REC 1.5								
169.5	1	S-114 REC 1.5								
171.0	1	S-115 REC 1.5								
172.5	1	S-116 REC 1.5								
174.0	1	S-117 REC 1.5								
175.5	1	S-118 REC 1.5								
177.0	1	S-119 REC 1.5								
178.5	1	S-120 REC 1.5								
180.0	1	S-121 REC 1.5								
181.5	1	S-122 REC 1.5								
183.0	1	S-123 REC 1.5								
184.5	1	S-124 REC 1.5								
186.0	1	S-125 REC 1.5								
187.5	1	S-126 REC 1.5								
189.0	1	S-127 REC 1.5								
190.5	1	S-128 REC 1.5								
192.0	1	S-129 REC 1.5								
193.5	1	S-130 REC 1.5								
195.0	1	S-131 REC 1.5								
196.5	1	S-132 REC 1.5								
198.0	1	S-133 REC 1.5								
199.5	1	S-134 REC 1.5								
201.0	1	S-135 REC 1.5								
202.5	1	S-136 REC 1.5								
204.0	1	S-137 REC 1.5								
205.5	1	S-138 REC 1.5								
207.0	1	S-139 REC 1.5								
208.5	1	S-140 REC 1.5								
210.0	1	S-141 REC 1.5								
211.5	1	S-142 REC 1.5								
213.0	1	S-143 REC 1.5								
214.5	1	S-144 REC 1.5								
216.0	1	S-145 REC 1.5								
217.5	1	S-146 REC 1.5								
219.0	1	S-147 REC 1.5								
220.5	1	S-148 REC 1.5								
222.0	1	S-149 REC 1.5								
223.5	1	S-150 REC 1.5								
225.0	1	S-151 REC 1.5								
226.5	1	S-152 REC 1.5								
228.0	1	S-153 REC 1.5								
229.5	1	S-154 REC 1.5								
231.0	1	S-155 REC 1.5								
232.5	1	S-156 REC 1.5								
234.0	1	S-157 REC 1.5								
235.5	1	S-158 REC 1.5								
237.0	1	S-159 REC 1.5								
238.5	1	S-160 REC 1.5								
240.0	1	S-161 REC 1.5								
241.5	1	S-162 REC 1.5								
243.0	1	S-163 REC 1.5								
244.5	1	S-164 REC 1.5								
246.0	1	S-165 REC 1.5								
247.5	1	S-166 REC 1.5								
249.0	1	S-167 REC 1.5								
250.5	1	S-168 REC 1.5								
252.0	1	S-169 REC 1.5								
253.5	1	S-170 REC 1.5								
255.0	1	S-171 REC 1.5								
256.5	1	S-172 REC 1.5								
258.0	1	S-173 REC 1.5								
259.5	1	S-174 REC 1.5								
261.0	1	S-175 REC 1.5								
262.5	1	S-176 REC 1.5								
264.0	1	S-177 REC 1.5								
265.5	1	S-178 REC 1.5								
267.0	1	S-179 REC 1.5								
268.5	1	S-180 REC 1.5								
270.0	1	S-181 REC 1.5								
271.5	1	S-182 REC 1.5								
273.0	1	S-183 REC 1.5								
274.5	1	S-184 REC 1.5								
276.0	1	S								

PROJECT A.E.P.: GLEN LYN LANDFILL MODIFICATION GLEN LYN, VAELEVATION 1543.46 G.W. 0 HRS 54.2BORING NO. 06-GLE-08PROJECT NO. CD50540.2024 HRS 55.5DATE 19-20 JULY 2006CLASSIFIED BY DAN SANGERPAGE 1 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE RECOVERY/TYPE & SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROWNNESS	REMARKS*
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	3	S-1 REC. 15			LOOSE	RED-BROWN	CLAYEY SILT/SILTY CLAY, TRACE TO SOME FINE SAND	ML CL	DRY
2.0	4	S-2 REC. 15			↓				
4.5	8	S-3 REC. 0.2			M. DENSE				
6.0	10	S-4 REC. 0.0			↓				
7.5	2	S-5 REC. 1.1			V. LOOSE	DRY GRAY	FLY ASH	ML CL	DRY
9.0	3	S-6 REC. 1.5			M. DENSE	RED-BROWN	CLAYEY SILT/SILTY CLAY, TRACE FINE SAND	ML CL	
10.5	2	S-7 REC. 1.3			↓				
12.0	2	S-8 REC. 1.1			LOOSE	DRY GRAY	FLY ASH	ML CL	DRY
13.5	1	S-9 REC. 1.5			V. LOOSE				
15.0	2	S-10 REC. 0.9							
16.5	1	S-11 REC. 1.2							
18.0	2	S-12 REC. 1.5							
19.5	1	S-13 REC. 1.1							DRY TO SLIGHTLY MOIST
21.0	2	S-14 REC. 1.1							
22.5	3	S-15 REC. 1.5							
24.0	4	S-16 REC. 1.5			LOOSE				
25.5	3	S-17 REC. 1.1			↓				
27.0	4	S-18 REC. 1.3			LOOSE				
28.5	3	S-19 REC. 1.5							
30.0	4	S-20 REC. 1.1							

REMARKS** DRILLED BY TERRA TESTING, INC. OF WASHINGTON, PA USING A ONE-45C RABBIT BACK MONITOR DRILL

BORING ADVANCED USING 4 1/4" S.D. HOLLOW STEM AUGERS, CONTINUOUS SPT WITH AUTOMATIC WEAVER, 4 1/2" AIR HAMMER

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-08

(8.8)

PROJECT AEP: GLEN LYN LANDFILL MODIFICATION GLEN LYN, VA BORING NO 06-GLE-08
ELEVATION 1543.46 GWL 0 HRS 54.2 PROJECT NO C050540.00
24 HRS 57.5
DATE 19-20 JULY 2006 CLASSIFIED BY DAN SANGER PAGE 2 of 3

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/RUN	CORE RECOVERY/TYPE & SAMPLE NO. TYPE & RECOVERY OR % ROCK RECOVERY	ROD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
30.2	1	S-21			V. LOOSE	DRY CLAY TO SANDY	FLYASH (CONT)	ML/SM	WET
31.5	3	REC 14			LOOSE				MOIST
33.0	4	REC 15			V. LOOSE				
34.8	1	S-23							
36.0	2	REC 15							MOIST TO WET
37.5	1	S-25							
39.0	1	REC 15							WET
40.5	2	REC 15							
42.0	2	REC 15							
43.5	2	S-29							
45.0	2	REC 15							
46.5	1	S-31							
48.0	3	REC 15			STIFF	BROWN	SILTY CLAY, TRACE SAND	CL	± 6.0 TIF, MOIST
49.5	2	S-33							± 1.25 TIF, MOIST
51.0	4	REC 15			M. STIFF	RED-BROWN	SANDY CLAY	CL	± 1.25 TIF, MOIST
52.5	4	REC 15			STIFF				± 1.0 TIF, MOIST
54.0	8	REC 12					SOME ROCK FRAGMENTS		± 1.15 TIF, MOIST
55.5	5	REC 12							± 1.25 TIF, MOIST
57.0	50	REC 13			STIFF	RED	DISCONTINUOUS SHALE	SM	± 1.25 TIF, MOIST
							DRILLING DRAINED W/ SAMPLING TO A DEPTH OF 60.0 FT		TOP OF ROCK: 57.0'

REMARKS ** DRILLER: BOB LAWRENCE, HELPER: DOUG HAVOTH

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-08
(B.B.)

[illegible]

AE PGL000122

PROJECT AEP: GLEN LYN LANDFILL MODIFICATION GLEN LYN, VABORING NO 06-GLE-09ELEVATION 1529.84 GWL 0 HRS 37.4PROJECT NO C250540.2024 HRS 31.4DATE 12 JUL 2006CLASSIFIED BY DAN SARGERPAGE 1 of 2

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/IN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.5	3	S-1		PS	LOOSE		CLAYEY SILT AND SILTY CLAY	ML	JAY
3.0	3	REC. 1.5							
4.5	1	S-3			LOOSE				
6.0	1	REC. 1.5							
7.5	W.O.H.	S-5							
9.0	W.O.H.	REC. 1.1							
10.5	W.O.H.	S-7							
12.0	1	REC. 1.4							
13.5	1	S-9							
15.0	1	REC. 1.5							
16.5	1	S-11							
18.0	1	REC. 1.5							
19.5	1	S-13							
21.0	1	REC. 1.5							
22.5	W.O.H.	S-15							
24.0	1	REC. 1.5							
25.5	2	S-17							
27.0	1	REC. 1.5							
28.5	1	S-19							
30.0	W.O.H.	REC. 1.5							

REMARKS** DILLED BY TETRA TESTING, INC. DE WINTERGROW, PA USING A CASE-HSC RUBBER TRACK DRILL.Boring Advanced using 3/4" ID. Hollow Stem Augers, Continuous SPT w/ Automatic Hammer

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

BORING 06-GLE-09
(64)

PAGE 2 of 2

REMARKS: "DALLIN, BOB LAWRENCE"

AE PGL000124

PROJECT A.E.P. GLEN LYN LANDFILL MODIFICATION

 BORING NO. 06-GLE-10

 ELEVATION 1521.23 GWL @ HRS 23.0

 PROJECT NO. C050546.20

 DATE 10-11 JUL 2006 15 HRS 21.9

 CLASSIFIED BY DAN SANGER

 PAGE 1 of 2

DEPTH (FT.)	BLOWS PER SIX INCHES OR CORE RECOVERY/IN	SAMPLE NO., TYPE & RECOVERY OR % ROCK RECOVERY	RQD (%) OR TORVANE	DESCRIPTION				USCS OR ROCK BROKENNESS	REMARKS*
				PROFILE	SOIL DENSITY - CONSISTENCY OR ROCK HARDNESS	COLOR	MATERIAL CLASSIFICATION		
1	2	3	4	5	6	7	8	9	10
1.0	W.O.H.	S-1			VERY LOOSE	GRAY	FLYASH	20-30%	
3.0	W.O.H.	REC. 1.2							
4.0	W.O.H.	S-3							
6.0	W.O.H.	REC. 1.3							
7.0	W.O.H.	S-5							
9.0	W.O.H.	REC. 1.5							
10.0	W.O.H.	S-7							
12.0	W.O.H.	REC. 1.0							
13.0	W.O.H.	S-9							
15.0	W.O.H.	REC. 1.3							
16.0	W.O.H.	S-11							
18.0	W.O.H.	REC. 1.5							
20.0	W.O.H.	S-13							
22.0	W.O.H.	REC. 1.5							
24.0	W.O.H.	S-15							
26.0	W.O.H.	REC. 1.5							
28.0	W.O.H.	S-17							
30.0	W.O.H.	REC. 1.5							

REMARKS: * DRIILLED BY TERRA TESTING, INC. AT WASHINGTON, PA USING A CMG-415C RUBBER TRACK MOUNTED DRILL

BOREHOLE ADVANCED USING 3/4" I.D. YELLOW STEEL AUGERS AND CONTINUOUS SPT WITH AUTOMATIC HAMMER

* POCKET PENETROMETER READINGS

** METHOD OF ADVANCING AND CLEANING BORING

 BORING 06-GLE-10
 (B-1)

BOBING NO. 06-GLLE-10

PROJECT NO. CD5540.10

PAGE 2 of 2

CLASSIFIED BY DAN SANGER


REMARKS: DISCUSSION: DISCUSS THE DISCUSSION

BORING 02-GL66-10

(370)

MONITORING WELL CONSTRUCTION DIAGRAM
 (Not to Scale)

Project AE P: GLEN LYN. Project No. C050540.20
 Date 18 JUL 2006 Engineer/Geologist DBS Well No. 06-GLE-03
 Drilling Company TERA TESTING INC. Driller: Bob Lawrence




STANDPIPE PIEZOMETER INSTALLATION SKETCH

DIMENSIONS (Feet)					
A	B	C	D	E	F
2.88	2.55	3.0	3.0	1/4	3.0
G	H	I	J	K	
10.0	0.5	1/4	0.33	80.0	

Remarks $K = 1.985 \times 10^{-5}$ cm/sec

MONITORING WELL CONSTRUCTION DIAGRAM
(Not to Scale)

Project A.E.P. : GLEN LYN Project No C050540.20
Date 09 AUG 2006 Engineer/Geologist DBS Well No 06-GLE-04
Drilling Company TELLA TESTING Driller: BOB LAWRENCE




STANDPIPE PIEZOMETER INSTALLATION SKETCH

DIMENSIONS (Feet)					
A	B	C	D	E	F
2.30	2.02	3.0	3.0	N/A	3.0
G	H	I	J	K	
10.0	~10	N/A	0.33	121.0	

Remarks $K > 1.228 \times 10^{-4}$ cm/sec
NOTE: BAILED 3.37 GALLONS WITH
NO DROP IN INITIAL WATER LEVEL

MONITORING WELL CONSTRUCTION DIAGRAM
 (Not to Scale)

Project A.E.P. GUEN LYN Project No C05D540.20
 Date 07 Aug 2006 Engineer/Geologist DBS Well No 06-GLE-06
 Drilling Company TEKLA TESTING Driller BOB LAWRENCE




STANDPIPE PIEZOMETER INSTALLATION SKETCH

DIMENSIONS (Feet)					
A	B	C	D	E	F
2.73	2.31	3.0	3.0	N/A	3.0
G	H	I	J	K	
10.0	1.0	N/A	0.33	121	

Remarks $K = 1.228 \times 10^{-4}$ cm/sec.

MONITORING WELL CONSTRUCTION DIAGRAM
 (Not to Scale)

Project A.E.P. GLEN LYN Project No C050840.20
 Date 20 JUL 2006 Engineer/Geologist DBS Well No 06-GLE-08
 Drilling Company TERRA TEST, INC. Driller DOB LAWRENCE



STANDPIPE PIEZOMETER INSTALLATION SKETCH


DIMENSIONS (Feet)					
A	B	C	D	E	F
2.93	2.73	3.0	3.0	N/A	2.5
G	H	I	J	K	
10.0	N/A	N/A	0.33	80.0	

Remarks $K = 1.344 \times 10^{-6}$ cm/sec

CONSTRUCTION CERTIFICATION
GROUND WATER MONITORING WELLS
AEP GLEN LYN PLANT
GLEN LYN, VIRGINIA

I certify as a qualified ground water scientist that monitoring wells 06-GLLE-03, 06-GLLE-04, 06-GLLE-06 and 06-GLLE-08 were installed in accordance with the boring logs and monitoring well construction details provided for those wells to comply with 9VAC20-80-300, A, 3d. This certification has been prepared to comply with the requirements of 9VAC20-80-300, A, 3f (3).


Signature


Date

Robert J. Turka, PG, CPG
Senior Staff Hydrogeologist
GAI Consultants, Inc.
Pittsburgh Office
385 East Waterfront Drive
Homestead, Pennsylvania 15120-5005

* FOR INFORMATIONAL PURPOSES ONLY*

	COMPANY: Appalachian Power Company	Appalachian Power Company
	PLANT: Glen Lyn	Glen Lyn
	ASH MANAGEMENT UNIT: Bottom Ash Pond	Fly Ash Pond
QUESTION 1	Dam Hazard Rating: Low	Low
	Who Established Rating: VA DCR	VA DCR
	Basis for Rating: Health Hazard	Health Hazard
	No Rating Assigned: N/A	N/A
QUESTION 2	Year Commissioned: 1963	1965
	Year(s) Expanded: N/A	N/A
QUESTION 3 - Mark all that apply.	Fly Ash: ☐	☐
	Bottom Ash: ☒	☒
	Boiler Slag: ☐	☐
	Flue Gas Emission Control Residuals: ☐	☐
	Other (Specify): ☐	☐
QUESTION 4	Designed by P.E.: Not Available	Not Available
	Constructed under P.E. Supervision: Not Available	Not Available
	Inspection/Monitoring under P.E. Supervision: Yes	Yes
QUESTION 5	Date of Last Company Safety Assessment: 1/13/2009	1/13/2009
	Describe Evaluator's Credentials: VA P.E.	VA P.E.
	Describe Past Followup Corrective Actions: Routine maintenance	Routine maintenance
	Describe Credentials of Corrective Action Implementers: Under plant supervision	Under plant supervision
	Describe Planned Followup Actions: Routine maintenance	Routine maintenance
	Date of Next Safety Assessment: 2010	2010
QUESTION 6	Date of Last Regulatory Safety Inspection: 3/18/2008	3/18/2008
	Agency Name: Va DCR	Va DCR
	Date of Planned Regulatory Safety Inspection: N/A	N/A
	Agency Name: N/A	N/A
	Copy of Most Recent Regulatory Inspection Included: Yes	Yes
QUESTION 7	Safety Issues from Regulatory Inspections w/in Past Year: None	None
	Corrective Actions: N/A	N/A
	Documentation Included: N/A	N/A
QUESTION 8	Surface Area (acres): 5.1 acres - The bottom ash pond complex is a multi-pond system where other wastewaters are separately treated in contiguous cells. Those pond complexes typically also include secondary (and in some cases tertiary) settling ponds for final "polishing" of effluent quality. The information provided is based on the entire impoundment as regulated under dam safety rules.	7.6 acres
	Total Storage Capacity: 90 acre-ft	185 acre-ft
	Volume Currently Stored: Variable - ash is routinely removed for beneficial use	Unable to be determined in the time allotted to complete this survey
	Date of Volume Measurement: N/A	N/A
	Maximum Height (feet): 35	43
QUESTION 9	Spills or Unpermitted Release History (10 Years): No	No
QUESTION 10	All legal owner(s) and operator(s): Appalachian Power Company	Appalachian Power Company

GLEN LYN

AEPGL000061



"Thomas Roberts"
<Thomas.Roberts@dcv.virginia.gov>

To: <wrsmith@aep.com>

cc

03/18/2008 05:38 PM

bcc

Subject: 01701 & 01702 Glen Lyn Bottom & Fly Ash Dams visits

History:

This message has been forwarded:

William Smith:

Visited the Glen Lyn Bottom & Fly Ash Dams today with Joe Ryder. Both looked fine. Understand from Joe Ryder that future modifications are planned for the Fly Ash Dam that will greatly reduce its size. I told Joe Ryder that modifications of this type require an Alteration Permit. Based on the description by Joe Ryder, it sounds like when done the dam will be too small to be regulated. The Alteration Permit application is very simple and currently no application fee. I recommend applying as soon as possible to make it before the regulations change.

Will e-mail you after visiting Carbo.

Thank you for setting up these visits.

Tom Roberts

New Address and Contact Information:

Thomas I. Roberts P.E. - Regional Engineer - Dam Safety
Virginia Department of Conservation and Recreation
Dam Safety and Floodplain Management
8 Radford Street, Suite 201
Christiansburg, Virginia 24073 - 3341
Phone - 540 394 2550
Fax - 540 394 2551
cell - 888-408-5564
thomas.roberts@dcv.virginia.gov
Web Site <http://www.dcr.virginia.gov>

* FOR INFORMATIONAL PURPOSES ONLY*



**AMERICAN
ELECTRIC
POWER**

American Electric Power
1 Riverside Plaza
Columbus, OH 43215-2273
www.aep.com

Thomas J. Roberts P.E. - Region 4 Dam Safety Engineer
Virginia Department of Conservation and Recreation
Dam Safety Program
8 Radford St.
Christiansburg, Virginia 24073

April 17, 2009

Re: Clinch River Fly Ash Dike No. 1 (16701)
Clinch River Fly Ash Dike No. 2 (16702)
Glen Lyn Fly Ash Dam (07101)
Glen Lyn Bottom Ash Dam (07102)

Dear Mr. Roberts:

Enclosed please find the completed Annual Inspection Report for the Clinch River facility, Ash Ponds 1A and 1B (Fly Ash Dike No. 1), and the Glen Lyn facility, Fly Ash Dam and Bottom Ash Dam for 2009.

If you have any questions, or if I can be of further assistance, please do not hesitate to contact me at (614) 716-2906.

Sincerely,

William R. Smith
AEP Service Corp., Civil Engineering
wsmith@aep.com

Attachments: 1 2009 Annual Dam Inspection Report Clinch River Plant
2 2009 Annual Dam Inspection Report Glen Lyn Plant

cc: J. Saunders - Clinch River (w/ Clinch River attachments)
J. Ryder - Glen Lyn (w/ Glen Lyn attachments)
P. J. Amaya - AEP Service Corp., Geotechnical Engineering (w/o attachments)
File

US EPA ARCHIVE DOCUMENT

AEPGL000001

ANNUAL INSPECTION REPORT FOR VIRGINIA REGULATED IMPOUNDING STRUCTURES

Reference: Impounding Structures Regulations, 4VAC 50-20-10 et seq., including 4VAC 50-20-105, Virginia Soil and Water Conservation Board

Owner's Information

Name of Dam: Fly ash pond Inventory Number: 07101
Owner's Name: Glen Lyn Plant, Appalachian Power company Location-Country/City: Giles county
Contact Person (if different from above): _____
Owner's Address: 40 Franklin Road Hazard Classification: Class III
Name of reservoir: _____
Purpose of reservoir: Settling pond
Telephone No.: (Residential) (Business) 800-956-4237
Other means of communication: _____

Owner's Engineer

Name of Engineering Firm and Engineer: American Electric Power Service Corporation
Professional Engineer Virginia License Number: _____
Mailing Address: Civil Engineering,
1 Riverside Plaza
Columbus, OH 43215
Telephone No.: (Business) 614-716-2926

Directions: Make note of all pertinent conditions and changes since the last inspection, or, if this is the first inspection, since the filing of a design report

Date of This Inspection 1/13/09
Date of Last Inspection 10/25/2007

1 EMBANKMENT

- a. Any alteration made to the embankment? None
- b. Erosion on embankment? None - vegetative cover is full
- c. Settlement, misalignment or cracks in embankment? None observed during this inspection
- d. Seepage? If so, seepage flow rate and location (describe any turbidity and observed color within the flow): None observed

2 UPSTREAM SLOPE

- a. Woody vegetation discovered? None - recently mowed
- b. Rodent burrows discovered? None
- c. Remedial work performed? No remedial was previously recommended or required

3 INTAKE STRUCTURE

- a. Deterioration of concrete? Structure does not normally impound any more than 3 feet of water which is 15
- b. Exposure of rebar reinforcement? Feet or so below spillway crest.
- c. Is there a need to repair or replace the trash rack? _____
- d. Any problems with debris? _____
- e. Was the drawdown valve operated? No applicable since it is a settling pond

4. ABUTMENT CONTACTS

- a. Any seepage? If so, estimate the flow rate and describe the location of the seep or damp areas (describe any turbidity and observed color within the flow):

No seepage observed

5. EARTHEN EMERGENCY SPILLWAY

- a. Obstructions to flow? If so, describe plans to correct: Not applicable

b. Rodent burrows discovered?

c. Any deterioration in the approach or discharge channel?

6. CONCRETE EMERGENCY SPILLWAY

- a. Deterioration of concrete? Not applicable

b. Exposed steel reinforcement?

c. Any leakage below concrete spillway?

d. Obstructions to flow? If so, lists plans to correct:

7. DOWNSTREAM SLOPE

- a. Woody vegetation discovered? None - recently mowed

b. Rodent burrows discovered? none

c. Are seepage drains flowing? No seepage drains were observed

d. Any seepage or wet areas? No seepage areas were observed

8. OUTLET PIPE

- a. Any water flowing outside of discharge pipe through the impounding structure? none

b. Describe any deflection or damage to the pipe: None observed

9. STILLING BASIN

- a. Deterioration of concrete structures? Not applicable

b. Exposure of rebar reinforcement?

c. Deterioration of the basin slopes?

d. Repairs made?

e. Any obstruction to flow?

10. GATES

- a. Gate malfunctions or repairs? Not applicable

b. Corrosion or damage?

c. Were any gates operated? If so, how often and to what extreme?

11. RESERVOIR/WATERSHED

- a. New developments upstream of dam? Not applicable - this is an upground reservoir

b. Slides or erosion of lake banks around the rim?

c. General comments to include silt, algae or other influence factors:

12. INSTRUMENTS

- a List all instruments none
- b Any readings of instruments? _____
- c Any installation of new instruments? _____

13. DOWNSTREAM/HAZARD ISSUES

- a New development in downstream inundation zone? No new development
- b Note the maximum storm water discharge or peak elevation during the previous year Not applicable - no discharge
- c Was general maintenance performed on dam? If so, when? Yes, mowing was performed
- d List actions that need to be accomplished before the next inspection: Continue mowing

14. OVERALL EVALUATION OF IMPOUNDING STRUCTURE AND APPURTENANCES

(Check one) ☐ EXCELLENT ☒ GOOD ☐ POOR

General Comments: _____

Recommendations: _____


CERTIFICATION BY OWNER'S ENGINEER (required only when an inspection by an engineer is required)

I hereby certify that the information provided in this report has been examined by me and found to be true and correct in my professional judgment

Signed: _____ Virginia Number: _____
Professional Engineer's Signature Print Name

This _____ day of _____, 20 _____

Engineer's Virginia Seal:

**CERTIFICATION BY OWNER**

I hereby certify that the information provided in this report has been examined by me

Signed: Brad Jones _____ BRAD JONES _____
Owner's Signature Print Name

This 23 day of Feb, 20 09

Mail the executed form to the appropriate
Department of Conservation and Recreation
Division of Dam Safety and Floodplain Management
Regional Engineer

ANNUAL INSPECTION REPORT FOR VIRGINIA REGULATED IMPOUNDING STRUCTURES

Reference: Impounding Structures Regulations, 4VAC 50-20-10 et seq., including 4VAC 50-20-105, Virginia Soil and Water Conservation Board

Owner's Information

Name of Dam: Bottom ash pond Inventory Number: 07102
Owner's Name: Glen Lyn Plant, Appalachian Power company Location-County/City: Giles county
Contact Person (if different from above): _____
Owner's Address: 40 Franklin Road Hazard Classification: Class III
Name of reservoir: _____
Purpose of reservoir: Settling pond
Telephone No.: (Residential) _____ (Business) 800-956-4237
Other means of communication: _____

Owner's Engineer

Name of Engineering Firm and Engineer: American Electric Power Service Corporation
Professional Engineer Virginia License Number: _____
Mailing Address: Civil Engineering,
1 Riverside Plaza
Columbus, OH 43215
Telephone No.: (Business) 614-716-2926

Directions: Make note of all pertinent conditions and changes since the last inspection, or, if this is the first inspection, since the filing of a design report.

Date of This Inspection 1/13/09
Date of Last Inspection 10/25/2007

1. EMBANKMENT

- a Any alteration made to the embankment? None
- b Erosion on embankment? None - vegetative cover is full
- c Settlement, misalignment or cracks in embankment? None observed during this inspection
- d Seepage? If so, seepage flow rate and location (describe any turbidity and observed color within the flow): None observed

2. UPSTREAM SLOPE

- a Woody vegetation discovered? None - recently mowed
- b Rodent burrows discovered? None
- c Remedial work performed? No remedial was previously recommended or required

3. INTAKE STRUCTURE

- a Deterioration of concrete? Concrete of discharge tower was OK and no deterioration observed.
- b Exposure of rebar reinforcement? No exposure of rebar observed
- c Is there a need to repair or replace the trash rack? No - facility has a skimmer structure that is in good condition
- d Any problems with debris? None - this is an upground reservoir
- e Was the drawdown valve operated? No applicable since it is a settling pond

4. ABUTMENT CONTACTS

- a. Any seepage? If so, estimate the flow rate and describe the location of the seep or damp areas (describe any turbidity and observed color within the flow):

No seepage observed

5. EARTHEN EMERGENCY SPILLWAY

- a. Obstructions to flow? If so, describe plans to correct: Not applicable

b. Rodent burrows discovered?

c. Any deterioration in the approach or discharge channel?

6. CONCRETE EMERGENCY SPILLWAY

- a. Deterioration of concrete? Not applicable

b. Exposed steel reinforcement?

c. Any leakage below concrete spillway?

d. Obstructions to flow? If so, list plans to correct:

7. DOWNSTREAM SLOPE

- a. Woody vegetation discovered? None - recently mowed

b. Rodent burrows discovered? none

c. Are seepage drains flowing? No seepage drains were observed

d. Any seepage or wet areas? No seepage areas were observed

8. OUTLET PIPE

- a. Any water flowing outside of discharge pipe through the
Impounding Structure? none

b. Describe any deflection or damage to the pipe: None observed

9. STILLING BASIN

- a. Deterioration of concrete structures? Not applicable

b. Exposure of rebar reinforcement?

c. Deterioration of the basin slopes?

d. Repairs made?

e. Any obstruction to flow?

10. GATES

- a. Gate malfunctions or repairs? Not applicable

b. Corrosion or damage?

c. Were any gates operated? If so, how often and to what extent?

11. RESERVOIR/WATERSHED

- a. New developments upstream of dam? Not applicable - this is an upground reservoir

b. Slides or erosion of lake banks around the rim?

c. General comments to include silt, algae or other influence factors:

12. INSTRUMENTS

- a List all instruments none
- b Any readings of instruments? _____
- c Any installation of new instruments? _____

13. DOWNSTREAM/HAZARD ISSUES

- a New development in downstream inundation zone? No new development
- b Note the maximum storm water discharge or peak elevation during the previous year Not applicable - no discharge
- c Was general maintenance performed on dam? If so, when? Yes, mowing was performed
- d List actions that need to be accomplished before the next inspection: Continue mowing

14. OVERALL EVALUATION OF IMPOUNDING STRUCTURE AND APPURTENANCES

(Check one) ☐ EXCELLENT ☒ GOOD ☐ POOR

General Comments:

Recommendations:


CERTIFICATION BY OWNER'S ENGINEER (required only when an inspection by an engineer is required)

I hereby certify that the information provided in this report has been examined by me and found to be true and correct in my professional judgment

Signed: _____ Virginia Number: _____
Professional Engineer's Signature Print Name

This _____ day of _____, 20 _____

Engineer's Virginia Seal:

**CERTIFICATION BY OWNER**

I hereby certify that the information provided in this report has been examined by me

Signed: Brad Jones Brad Jones
Owner's Signature Print Name

This 23 day of Feb, 20 09

Mail the executed form to the appropriate
Department of Conservation and Recreation
Division of Dam Safety and Floodplain Management
Regional Engineer

**INSPECTION REPORT
2009 Calendar Year
BOTTOM ASH POND COMPLEX
AUXILIARY FLY ASH POND
WEST POND**

GRS - 09-015

**GLEN LYN PLANT
GLEN LYN, VIRGINIA**

**PREPARED BY
GEOTECHNICAL ENGINEERING
AEP SERVICE CORPORATION
1 RIVERSIDE PLAZA
COLUMBUS, OHIO**

**DAM & DIKE INSPECTION REPORT
BOTTOM ASH POND COMPLEX
AUXILIARY FLY ASH POND
WEST POND**

**GLEN LYN PLANT
GLEN LYN, VIRGINIA**


INSPECTION DATE October 28, 2009

PREPARED BY *Gary F. Zych* **DATE** 12-8-2009
Gary F. Zych, P.E.

REVIEWED BY *Behrad Zand* **DATE** 12-10-2009
Behrad Zand

APPROVED BY *Pedro J. Amaya* **DATE** 12-15-2009
Pedro J. Amaya, P.E. No. 036174
Manager - Geotechnical Engineering

QA/QC DOCUMENT NO.
GERS - 09 - 045



**PROFESSIONAL ENGINEER
SEAL & SIGNATURE**

2009 ANNUAL INSPECTION REPORT
 BOTTOM ASH POND COMPLEX
 AUXILIARY FLY ASH POND
 WEST POND

GLEN LYN PLANT
 GLEN LYN, WEST VIRGINIA

INTRODUCTION.....	2
SUMMARY OF VISUAL OBSERVATIONS.....	2
General.....	2
Bottom Ash Pond Complex.....	3
Auxiliary Fly Ash Pond.....	4
West Pond.....	4
ASSESSMENT OF RECENT INSTRUMENTATION DATA.....	5
CONCLUSIONS.....	6
Bottom Ash Pond Complex.....	6
Auxiliary Pond.....	6
West Pond.....	6
RECOMMENDATIONS.....	6
Bottom Ash Pond Complex.....	6
Auxiliary Pond.....	6
West Pond.....	6
FIGURE 1: Bottom Ash Pond Inspection Location Plan	
FIGURE 2: Auxiliary Fly Ash Pond Inspection Location Plan	
FIGURE 3: West Pond Inspection Location Plan	
APPENDIX A: Bottom Ash Pond Photographs	
APPENDIX B: Auxiliary Fly Ash Pond Photographs	
APPENDIX C: West Pond Photographs	

Excessive: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is above or worse than what is normal or desired, and which may have affected the ability of the observer to properly evaluate the structure or particular area being observed or which may be a concern from a structure safety or stability point of view.

Appendices A, B and C contain selected photographs taken during the inspection of the Bottom Ash Pond, Auxiliary Fly Ash Pond and West Pond, respectively.

Bottom Ash Pond Complex (refer to Figure 1)

1. The South Bottom Ash Pond was the active pond for receiving ash sluice water (Photo 1).
2. The North Bottom Ash Pond was inactive. It was completely drained and all bottom ash was excavated. Cohesive fill was recently placed on a portion of the bottom and interior slopes. (Photo 2)
3. The interior slopes of both the North and South Bottom Ash Ponds appeared stable and in good condition. The crest and slopes of the Splitter dike between the two ponds also appeared stable and in good condition.
4. Flow over the South Bottom Ash Pond discharge structure was smooth with no obstructions. The structures appeared in good condition. In particular, the North BA Pond discharge structure was fully visible and no issues were noted about its condition. (Photo 3)
5. The South Bottom Ash Pond exterior slope, adjacent to the discharge channel, was well vegetated and contained no visible animal burrows or areas of slope instability. (Photo 4)
6. The interior slopes of the Clearwater Pond were also well vegetated and in good condition. The riprap in the northeast corner of the pond was stable (Photos 5-6).
7. Visible portions of the Clearwater Pond concrete discharge structure, wood steps, wood railing, platform, and intake structure were in satisfactory condition.
8. The Clearwater Pond outfall pipe (RCP 30-inch diameter), walkway and railing were in satisfactory condition. Discharge from the outfall pipe was unobstructed and there was no erosion or scour at the outlet. There was no visual evidence of significant settlement or depressions above the pipe alignment. There was no seepage from around the outside of the pipe. (Photo 7)
9. The inlet structure and distribution pipe at the Clearwater Pond was in good condition. (Photo 8)
10. The dike roads are in good condition. There is no rutting along the surface.

2. The NPDES Outfall No. 007 discharge pipe located at the west end of the pond was unobstructed and in satisfactory condition. Due to the pumping operations, the flow was higher than normal. The slopes and dike surface above the pipe did not exhibit any evidence of settlement or instability and the flow was clear. The wood steps and railing leading to the outfall were in good condition.
3. The main dike was well maintained. This section of dike appears to be stable and there are no signs of sloughing. (Photo 2-3)
4. The toe area on both sides of the stairs was moist to wet. The previous inspection noted the area as dry. There was no visual seepage from this area.
5. The interior slope of the western road dike is in satisfactory condition except for one area. A slide area of the interior slope, about 15 yards long, has occurred. Repairs were being planned by plant personnel. The slide was presumed to be associated with the drawdown of the pond level. (Photo 4)
6. The drainage ditch along the exterior slope of the western road dike was unobstructed and protected from erosion with riprap.
7. The top of dike road was in good condition with no evidence of significant dike settlement or misalignment.
8. The southeast end of the pond borders the landfill leachate collection pond and dike. The dike and toe area appeared in good condition. The siphon from the Leachate pond into the West pond was not operating.

ASSESSMENT OF RECENT INSTRUMENTATION DATA

Pond water levels were obtained from Plant personnel for the date of the inspection. These levels are summarized below along with water levels measured during previous annual inspections. The Plant performs quarterly inspections and records pond levels and facility conditions.

Pond Name	Pond Elev. Ft. 28Oct2009	Pond Elev. Ft. 13Jan2009	Pond Elev. Ft. 30Oct 2007	Pond Elev. Ft. 1Nov 2005	Pond Elev. Ft. 14 Dec 2004
Clearwater	1501	1501	1501.3	1501.3	1501.3
NBAP	dewatered	dewatered	dewatered	dewatered	dewatered
SBAP	1506.3 (full)	1506.3 (full)	1506.3 (full)	1506.3 (full)	1506.3 (full)
West	1528	1531.5	1531.5	1531.5	1531.5
Aux EAP	1515	- 1515	1511	- 1510	- 1513




FIGURE 1

Date: DEC 28, 2009
Weather: CLOUDY, MILD

Legend

- A Animal Hole
- G Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Tr/Br Trees & Brush

NO ITEMS TO NOTE.
SEE COMMENTS IN
THE REPORT.

SLOPE LINE

V's POINT
DOWN SLOPE


0 50 100 200 300

APPROXIMATE SCALE 1"=167 FT.

GLEN LYN PLANT: BOTTOM ASH POND
INSPECTION LOCATION PLAN

FIGURE 2

Date: *OCT 28, 2009*
Weather: *CLOUDY, MILD*



AUX FLY ASH DAM
WILL NO LONGER BE
USED FOR EMERGENCY
WET DISPOSAL.

NO ITEMS TO NOTE.
SEE COMMENTS IN
THE REPORT.

GLEN LYN PLANT: AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN




FIGURE 3

Date: OCT 28, 2019
Weather: CLOUDY, MILD

N 390500

WATER LEVEL
IS BEING LOWERED
BY PUMPING

GLEN LYN PLANT WEST POND
INSPECTION LOCATION PLAN

Legend

- A Animal Hole
- C Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Tr/Br Trees & Brush

S1- SLIDE OF INTERIOR SLOPE
15YD LONG - (BEING REPAIRED
BY PLANT).

APPENDIX A: BOTTOM ASH POND COMPLEX PHOTOGRAPHS



Photo #1 - Active south pond



Photo #2 - Inactive north pond; interior slopes




Photo #3 - South pond discharge structure




Photo #4 - Exterior dike of South pond



Photo #9 - Exterior slope of North dike

Photo #10 - Exterior slope of North dike



Photo #11 - Exterior slope of North dike

APPENDIX B: AUXILIARY FLY ASH POND PHOTOGRAPHS



Photo #1 - North dike, looking east



Photo #2 - East dike, looking north



Photo #3 - Exterior slope of south dike, looking west




Photo #4 - Interior of Aux fly ash pond

APPENDIX C: WEST POND PHOTOGRAPHS



Photo #1 - Skimmer structure/water level




Photo #2 - Exterior slope main dike



Photo #3 - Exterior slope of main dike



Photo #4 - Interior slope of road dike

FOR INFORMATIONAL PURPOSES ONLY

**DAM & DIKE INSPECTION REPORT
BOTTOM ASH POND COMPLEX
AUXILIARY FLY ASH POND
WEST POND**

**GLEN LYN PLANT
GLEN LYN, VIRGINIA**

INSPECTION DATE November 18, 2010

PREPARED BY *Gary F. Zych*
Gary F. Zych, P.E.

DATE *11/24/2010*


REVIEWED BY *Behrad Zand*
Behrad Zand, P.E.

DATE *12/6/2010*

APPROVED BY *Pedro Jose Amaya*
Pedro Amaya, P.E.
Director, Civil Engineering

DATE *12/7/2010*

QA/QC DOCUMENT NO.
GERS-10-049



**PROFESSIONAL ENGINEER
SEAL & SIGNATURE**

2010 ANNUAL INSPECTION REPORT
 BOTTOM ASH POND COMPLEX
 AUXILIARY FLY ASH POND
 WEST POND

GLEN LYN PLANT
 GLEN LYN, WEST VIRGINIA

INTRODUCTION	2
SUMMARY OF VISUAL OBSERVATIONS	2
General	2
Bottom Ash Pond Complex	3
Auxiliary Fly Ash Pond	4
West Pond	4
ASSESSMENT OF RECENT INSTRUMENTATION DATA	5
CONCLUSIONS	6
Bottom Ash Pond Complex	6
Auxiliary Pond	6
West Pond	6
RECOMMENDATIONS	6
Bottom Ash Pond Complex	6
Auxiliary Pond	6
West Pond	6
FIGURE 1: Bottom Ash Pond Inspection Location Plan	
FIGURE 2: Auxiliary Fly Ash Pond Inspection Location Plan	
FIGURE 3: West Pond Inspection Location Plan	
APPENDIX A: Bottom Ash Pond Photographs	
APPENDIX B: Auxiliary Fly Ash Pond Photographs	
APPENDIX C: West Pond Photographs	

INTRODUCTION

AEPSC Civil Engineering administers the company's Dam Inspection and Maintenance Program (DIMP). As part of DIMP, staff from the Geotechnical Engineering Section periodically conduct the dike and dam inspections. Mr. Gary F. Zych, P.E., conducted the inspection for the 2010 calendar year. This report has been prepared under the direction of Mr. Pedro J. Amaya, P.E. and presents a summary of the inspection and assessment of the condition of the facilities.

Mr. Frank Tanner, Process Supervisor, at the Glen Lyn Plant, was the project facility contact. The inspection was performed on November 18, 2010. Weather conditions were cloudy and cool. The temperature was 40° F. There was approximately 0.8 inches of rainfall during the seven days prior to the inspection, with more than fifty percent occurring within 48 hours before the inspection.

At the Glen Lyn Plant there are three ponds that are part of the annual dike and dam inspection. These ponds are the Bottom Ash Pond Complex, the Auxiliary Fly Ash Pond and the West Pond, and are depicted in plan in Figures 1, 2 and 3, respectively. The Bottom Ash Pond Complex consists of the North and South Bottom Ash Ponds and a Clear Water Pond. The New River and the East River border it. The Auxiliary Fly Ash Pond was a wet fly ash pond adjacent to the New River and used for a backup system to the dry handling system. The Plant discontinued the option to utilize this pond as a backup in early 2009 and hence the facility is dry, excluding direct precipitation. The West Pond is a stormwater runoff pond for the dry ash landfill, which is located west of the Auxiliary Fly Ash Pond and of the landfill.

SUMMARY OF VISUAL OBSERVATIONS

General

The summary of the visual observations uses terms to describe the general appearance or condition of an observed item, activity or structure. Their meaning of these terms is as follows:

Good:	A condition or activity that is generally better or slightly better than what is minimally expected or anticipated from a design or maintenance point of view.
Fair or Satisfactory:	A condition or activity that generally meets what is minimally expected or anticipated from a design or maintenance point of view.
Poor:	A condition or activity that is generally below what is minimally expected or anticipated from a design or maintenance point of view.
Minor:	A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is below what is normal

or desired, but which is not currently causing concern from a structure safety or stability point of view.

Excessive: A reference to an observed item (e.g., erosion, seepage, vegetation, etc.) where the current maintenance condition is above or worse than what is normal or desired, and which may have affected the ability of the observer to properly evaluate the structure or particular area being observed or which may be a concern from a structure safety or stability point of view.

Appendices A, B and C contain selected photographs taken during the inspection of the Bottom Ash Pond, Auxiliary Fly Ash Pond and West Pond, respectively.

Bottom Ash Pond Complex (refer to Figure 1)

1. The North Bottom Ash Pond was the active pond for receiving ash sluice water and other waste water streams. (Photo 1).
2. The South Bottom Ash Pond was inactive. It was completely drained and all bottom ash was excavated. (Photo 2)
3. The interior slopes of both the North and South Bottom Ash Ponds appeared stable and in good condition. The crest and slopes of the Splitter dike between the two ponds also appeared stable and in good condition.
4. Flow over the North Bottom Ash Pond discharge structure was smooth with no obstructions. The structures appeared in good condition. In particular, the South BA Pond discharge structure was fully visible and no issues were noted about its condition. (Photo 3)
5. The South Bottom Ash Pond exterior slope, adjacent to the discharge channel, was well vegetated and contained no visible animal burrows or areas of slope instability. (Photo 4)
6. The interior slopes of the Clearwater Pond were also well vegetated and in good condition. The riprap in the northeast corner of the pond was stable (Photo 5).
7. Visible portions of the Clearwater Pond concrete discharge structure, wood steps, wood railing, platform, and intake structure were in satisfactory condition. Lower portions of the interior slope adjacent to this area are very steep, however, there are no other signs of instability or sloughing. (Photo 6)
8. The Clearwater Pond outfall pipe (RCP 30-inch diameter), walkway and railing were in satisfactory condition. Discharge from the outfall pipe was unobstructed and there was no erosion or scour at the outlet. There was no visual evidence of significant settlement or depressions above the pipe alignment. There was no seepage from around the outside of the pipe. (Photo 7)

9. The inlet structure and distribution pipe at the Clearwater Pond was in good condition.
10. The dike roads are in good condition. There is no rutting along the surface.
11. The North Bottom Ash Pond exterior slope along the New River appeared stable and well protected with vegetation and riprap. There were no signs of movement or displacement of the riprap. (Photo 8)

Auxiliary Fly Ash Pond (refer to Figure 2)

1. This pond is no longer used as an emergency wet fly ash pond. The Plant, in early 2009, decided to eliminate any future use.
2. There was no standing water in the pond. (Photo 1)
3. The lower section of the north dike (exterior slope along the New River) is part of the natural river bank and has vegetation and tree cover. There was no indication from the top of the bench that any instability exists.
4. The upper section of the exterior slope along the New River is well vegetated. This slope appeared stable and there were no signs of surficial sloughing, movement or displacement. (Photo 2)
5. The old erosion slide at the far eastern corner of the exterior slope at the tree line was well vegetated.
6. The exterior slope of the east dike appeared satisfactory with no signs of apparent instability. There were no signs of rodent holes or erosion gullies.
7. The outlet of the pond's discharge pipe, wood steps and railing were inspected and found in good condition. There was no flow through the open valve from the outfall.
8. The exterior slope of the south side dike along Route 649 was also well vegetated. There were no signs of slope instability or any recent erosion gullies.
9. The interior slopes of all three dikes appeared stable and well vegetated. The slopes had a stand of tall grass. (Photo 3)

West Pond (refer to Figure 3)

1. The water level in the pond was approximately 4 feet below the platform over the discharge structure. There was no discharge from the structure. (Photo 1)

2. The NPDES Outfall No. 007 discharge pipe located at the west end of the pond was unobstructed and in satisfactory condition. There was a slight trickle of water from the outlet presumably from minor seepage into the conduit. The slopes and dike surface above the pipe did not exhibit any evidence of settlement or instability and the flow was clear. The wood steps and railing leading to the outfall were in good condition.
3. The main dike was well maintained. This section of dike appears to be stable and there are no signs of sloughing. (Photo 2-3)
4. The toe area on both sides of the stairs that is normally moist was dry.
5. The interior slope of the western road dike is in good condition. The slide area that was noted in 2009 was repaired. (Photo 4)
6. The drainage ditch along the exterior slope of the western road dike was unobstructed and protected from erosion with riprap.
7. The top of dike road was in good condition with no evidence of significant dike settlement or misalignment.
8. The southeast end of the pond borders the landfill Leachate collection pond and dike. The dike and toe area appeared in good condition. The siphon from the Leachate pond into the West pond was not operating.
9. The dike portion that extends eastward along the river was cleared of trees in late 2009. This section of dike forms the confining berm for the dry ash landfill. The dike has naturally revegetated and is in satisfactory condition. There are no signs of instability or seepage along this section of dike. (Photos 5-6)

ASSESSMENT OF RECENT INSTRUMENTATION DATA

Pond water levels were obtained from Plant personnel for the date of the inspection. These levels are summarized below along with water levels measured during previous annual inspections. The Plant performs quarterly inspections and records pond levels and facility conditions.

Pond	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.	Pond Elev. Ft.
Name	18Nov2010	22Oct2009	13Jan2009	30Oct 2007	1Nov 2005
Clearwater	1501	1501	1501	1501.3	1501.3
NBAP	1506.3 (full)	dewatered	dewatered	dewatered	dewatered
SBAP	dewatered	1506.3 (full)	1506.3 (full)	1506.3 (full)	1506.3 (full)

West	1528	1531.5	1531.5	1531.5	1531.5
Aux FAP	dry	1515	1511	1510	1513
New River	1493.1				

The water level in the New River was based on the USGS gage data. No other instrumentation data is available for the dikes at the Plant.

CONCLUSIONS

Bottom Ash Pond Complex

The Bottom Ash Pond Complex earthen embankments and structures are in good condition. The interior slopes of the embankments are well vegetated above the normal water level. The stone slope protection along the river was in good condition. The discharge structures were also in satisfactory condition. The facility is well maintained.

Auxiliary Pond

Overall, the earthen embankments forming the Auxiliary Fly Ash Pond are in good condition. The vegetation covering the slopes is well established and maintained.

West Pond

Overall, the earthen embankments forming the West Pond are in good condition. The vegetation covering the slopes is established and well maintained. The inlet and outlet of the discharge structure are in satisfactory condition.

RECOMMENDATIONS

Bottom Ash Pond Complex

1. Continue routine maintenance items as necessary.

Auxiliary Pond

1. Continue routine maintenance items as necessary.

West Pond

1. Continue routine maintenance items as necessary.

In general, routine inspections, monitoring and maintenance by plant personnel should continue. If you have any questions with regard to this report, please do not hesitate to contact Gary Zych at 614-716-2917 (audinet 260-2917).

FIGURES

FIGURE 1: BOTTOM ASH POND INSPECTION LOCATION PLAN

FIGURE 2: AUXILIARY FLY ASH POND INSPECTION LOCATION PLAN

FIGURE 3: WEST POND INSPECTION LOCATION PLAN




FIGURE 1

Date: 11/18/2010
Weather: CLOUDY - 40°F

Legend

- A Animal Hole
- G Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Tr/Br Trees & Brush

① INTERIOR SLOPES HAVE BEEN SLIGHTLY ERODED AT WATER LEVEL AND HAVE STEEPEND OVER THE YEARS.

• NO OTHER CONDITIONS TO REPORT

SLOPE LINE


V's POINT
DOWN SLOPE

0 50 100 200 300
feet
APPROXIMATE SCALE 1"=167 FT.

GLEN LYN PLANT: BOTTOM ASH POND
INSPECTION LOCATION PLAN

FIGURE 2

Date: 11/18/2010
Weather: CLOUDY - 40°F



GLEN LYLE PLANT: AUXILIARY FLY ASH
POND INSPECTION LOCATION PLAN

FIGURE 3

Date: 11/18/2010
Weather: CLOUDY - 40°F

N 330500

NEW RIVER
FLOW

DISCHARGE
STRUCTURE

SA INDIK

WSEL:
4 FT BELOW
1532.2

GRATING

AREA REPAIRED
IN 2009

GLEN LYN PLANT WEST POND
INSPECTION LOCATION PLAN

Legend

- A Animal Hole
- G Erosion Gully
- W Area of Wetness or Seepage
- S Slide Area
- Tr/Br Trees & Brush

TR- ALL TREES ALONG THIS
SECTION OF BERM
WERE REMOVED IN 2009

APPENDIX A: BOTTOM ASH POND PHOTOGRAPHS

Photo # 1

North pond - active.



Photo # 2

South pond - dewatered.




Photo # 3

Discharge structure from
North pond to Clearwater
pond.




Photo # 4

Exterior slope of South pond dike along the discharge canal.




Photo # 5

Interior slopes of Clearwater Pond and distribution pipe



Photo # 6

Steep internal slopes of Clearwater Pond near the outlet structure.



Photo # 7

Discharge from Clearwater
Pond into the East River.





Photo # 8

Exterior slope of North
bottom ash pond along the
New River.



APPENDIX 16: AUXILIARY FLY ASH POND PHOTOGRAPHS

Photo # 1

Overview of Aux fly ash pond. Pond is dry with some area of exposed fly ash.



Photo # 2

Exterior slope along the New River





Photo # 3

Interior slopes.



APPENDIX C: WEST POND PHOTOGRAPHS




Photo # 1 Pond outlet structure, skimmer and low water level.	
Photo # 2 Exterior slope of dike, looking east.	
Photo # 3 Exterior slope of dike, looking west.	

Photo # 4

Interior slope showing the 2009 repaired area.




Photo # 5

Exterior slope of berm for the ash landfill. Berm was cleared in 2009




Photo # 6

Exterior slope of berm for the ash landfill. Berm was cleared in 2009



FIG. NO. FIGURE 2

 AMERICAN ELECTRIC POWER	AEP SERVICES CORP. RIVERSIDE PLAZA COLUMBUS, OH 43260
---	--

• • • • •

DATE: 3 Oct 4

AUXILIARY FLY ASH POND

DATE NOTED: 3




AEP SERVICE CORP.
FANTASIE PLAZA
COLUMBUS, OH 43265


AEFGL000206

FOR INFORMATIONAL PURPOSES ONLY

GLEN LYN PLANT
FLY ASH POND
1" = 100 FT



FOR INFORMATIONAL PURPOSES ONLY



STABILITY ASSESSMENT REPORT

BOTTOM ASH POND

GLEN LYN POWER STATION

GLEN LYN, VA

PREPARED BY

Behrad Zand
Behrad Zand, Engineer

Date

03/16/2011

REVIEWED BY

Gary F. Zych
Gary F. Zych,
Section Manager, Geotechnical Engineering

Date

3/16/2011

APPROVED BY


Pedro J. Amaya
Pedro J. Amaya, P.E.
Director, Civil Engineering

Date

3/16/2011

QA/QC DOCUMENT NO.

GERS-11-006



PROFESSIONAL ENGINEER

SEAL & SIGNATURE

(THIS PAGE INTENTIONALLY LEFT BLANK)

GLEN LYN PLANT STABILITY ASSESSMENT OF BOTTOM ASH POND

March 14, 2011

Introduction

In this study the stability of the bottom ash dikes at Glen Lyn Power Station is assessed. The Glen Lyn plant, owned by Appalachian Power Company (APCO), a subsidiary of American Electric Power (AEP), is a coal burning power plant located near Glen Lyn, Virginia. The plant currently has two units, namely Unit 5 and Unit 6, with a total generation capacity of 335 MW. The bottom ash disposal facility consists of a perimeter dike, approximately 1000 ft long along the bank of New River, and two splitter dikes separating North Bottom Ash Pond (adjacent to the river), South Bottom Ash Pond, and Clear Water Pond (location map enclosed). The bottom ash produced in the two units of the plant is sluiced in either the north or the south pond while the other pond remains inactive. The bottom ash is excavated from the inactive pond periodically using a front loader for beneficial use. The over flow from the active pond is discharged into the clear water pond through an 18 in diameter corrugated metal pipe. The water from the clear water pond flows under a skimmer structure into a decant tower and is discharged into East River through a 30 inch diameter concrete pipe.

The original crest of the perimeter dike was at elevation 1525. The crest was later lowered to the approximate elevation of 1515 ft. Thus, the current crest elevation of the perimeter dike is approximately 1515 ft while the crest elevation of the splitter dikes is approximately 1511 ft. The original bottom of the north and south and the clear water ponds are approximately 1500 ft and 1499 ft, respectively. The outboard slope of the perimeter dike is approximately 3 horizontal to 1 vertical (3:1) in most places and the inboard slope is approximately 2:1. The maximum normal operating pool level of the north and south ponds is 1506 ft while that of the clear water pond is 1501.

In 1978 AEP retained Woodward-Clyde Consultants to conduct a safety inspection of this facility. As a part of 1978 inspection, the consultant reviewed all the pertinent documents and drawings that were available at the time to provide a summary on the history and design of the facility. The inspection program of this facility has continued ever since and currently it is inspected annually by a certified engineer. The visual inspections of the facility since 1978 have not indicated any adverse condition that would raise a concern on the stability and safety of the dikes.

Material Properties

An idealized section of the perimeter dike was developed (Figure 1) based on the available data (enclosed) from boring log HP-0525 drilled in 2005. The overburden foundation material consists of layers of clay shale, sand and gravel, and sandy clay. While the boring log HP-0525 shows bottom ash material throughout the embankment, the 1978 inspection report states that the dikes were constructed of local lean clay and shale mixture. The embankment; therefore, was assumed to be constructed of lean clay and bottom ash as shown in Figure 1. The original design drawings of the bottom ash dike is unavailable, however, the dike structure presented in Figure 1 is similar to the design of the original fly ash dikes. The material properties of the compacted lean clay were selected based on recommendations of NAVFAC DM-7.2, Foundations and Earth Structures, Design Manual 7.2, 1982. The general description and mechanical properties of the material are presented in Table 1




Figure 1. Idealized dike section

Material Type	Undrained Friction Angle (deg)	Undrained Cohesion (psf)	Effective Friction Angle (deg)	Effective Cohesion (psf)	Unit Weight (pcf)
Compacted lean clay, embankment	0	400	28	200	110
Compacted bottom ash, embankment	40	0	40	0	80
Embankment sand and shale fragments	34	0	34	0	120
Rip rap	40	0	40	0	130
Foundation lean sandy clay	0	300	22	0	90
Foundation sand and gravel	40	0	40	0	125
Weathered shale and rock	15	2000	15	2000	120

Table 1. Material properties

Stability Analysis

Stability factors of safety for the outboard and inboard slopes were calculated for static condition and pseudo-static seismic loading condition. Limit equilibrium analysis method of Morgenstern-Price was used for the assessment. Peak ground acceleration of 0.12g used in the seismic analysis was inferred from 2008 USGS map for 2% probability of exceedance in 50 years. Presented in Table 2 are the calculated factors of safety for the dike section. All the safety factors are within the acceptable range for this type of facility; that is a low head low hazard dike that has been in operation for several decades with no recorded safety or stability issue. Figures 2 through 6 show the calculated factors of safety along with corresponding failure surfaces.

Based on the results of this study the facility is believed to be performing as intended.

Slope	Loading condition	Calculated Safety Factor	Location of the critical failure surface
Downstream	Steady-state seepage, drained	1.73	Outboard slope near toe El 1510 to 1496 ft
	Maximum surcharge, undrained	1.72	Outboard slope near toe El 1509 to 1496 ft
	Seismic loading undrained	1.16	From inboard slope at El. 1513 ft to outboard slope El. 1501 ft
Upstream	Steady-state seepage, drained	1.60	From middle of crest to bottom of pond
	Seismic loading undrained	1.08	From edge of crest to inboard toe

Table 2. Calculated stability safety factors for the upstream and downstream slopes




Figure 2. Stability analysis of the outboard slope under steady-state condition.




Figure 5. Stability analysis of the inboard slope under steady-state condition.





Figure 6. Stability analysis of the inboard slope under seismic loading

GFZ

NAVFAC DM-7.2
MAY 1982

APPROVED FOR PUBLIC RELEASE



FOUNDATIONS AND EARTH STRUCTURES

DESIGN MANUAL 7.2

DEPARTMENT OF THE NAVY
NAVAL FACILITIES ENGINEERING COMMAND
200 STOVALL STREET
ALEXANDRIA, VA. 22332

US EPA ARCHIVE DOCUMENT

AEPGL000285

TABLE 1
Typical Properties of Compacted Soils

Group Symbol	Soil Type	Range of Maximum Dry Unit Weight, pcf	Range of Optimum Moisture, Percent	Typical Values of Compression			Typical Laboratory Characteristics				Range of CBR Values	Range of Subgrade Modulus, $\frac{\text{lb}}{\text{in}^2 \text{ in}}$
				Percent of Original Height			Cohesion (unconfined) pcf	Effective Stress (unconfined) pcf	Penetration $\frac{\text{mm}}{100}$			
				At 1.5 Sat (20 pcf)	At 3.0 Sat (50 pcf)	Percent of Original Height						
GM	Well graded clean gravels, gravel sand mixtures	125 - 135	11 - 8	6.1	0.5	0	0	0	0	50 - 60	300 - 500	
GP	Coarsely graded clean gravels, gravel-sand mix	115 - 125	14 - 12	5.9		0	0	0	0	30 - 50	250 - 400	
GZ	Silty gravels, poorly graded gravel-sand-silt	120 - 135	12 - 8	6.5	2.1					20 - 40	200 - 400	
GC	Clayey gravels, poorly graded gravel-sand-clay	115 - 140	14 - 9	5.7	1.0					20 - 50	100 - 200	
GD	Well graded clean sands, silty sands	110 - 120	16 - 9	6.6	1.7	0	0	0	0	20 - 40	250 - 300	
SW	Poorly graded clean sands, well-sorted silt	105 - 120	21 - 12	6.3	1.4	0	0	0	0	10 - 40	100 - 200	
SM	Silty sands, poorly graded sand-silt mix	110 - 125	16 - 11	6.5	1.6	2500	400	25	5	10 - 40	100 - 200	
SC	Sand-silt clay with slightly plastic fines	105 - 130	15 - 11	6.4	1.4	4000	300	22	2	5 - 20	100 - 200	
SE	Clayey sands, poorly graded sand-clay mix	105 - 125	16 - 11	5.1	1.2	3500	200	21	5	5 - 20	100 - 200	
ML	Low plasticity silty sand and clay	95 - 120	24 - 12	6.9	1.7	1400	100	27	0.62	15 or less	50 - 100	
MH	Mixture of fine-grained silt and clay	100 - 130	22 - 12	5.6	1.2	1300	400	22	0.62			
OL	Inorganic clay of low to medium plasticity	95 - 120	16 - 12	1.5	2.5	1000	270	29	0.54	15 or less	50 - 100	
OH	Organic silty and clayey, low plasticity	60 - 100	13 - 24									
ME	Inorganic clayey silty, plastic silty	75 - 95	16 - 19	2.0	1.8	1600	400	25	0.47	10 or less	50 - 100	
ML	Inorganic clay of high plasticity	75 - 105	16 - 19	2.5	1.9	2100	270	29	0.35	15 or less	50 - 100	
OH	Organic clayey and silty clay	55 - 100	25 - 21									

Notes:

- All properties are for condition of "Standard Proctor" testing. Density, percent values of 1 and 100 mean are for modified Proctor maximum density.
- Typical strength characteristics are for effective strength envelopes and are obtained from BOD data.
- Compression values are for vertical loading with complete lateral confinement.
- (1) Indicate that typical property is greater than the value shown.
- (2) Indicate insufficient data available for an estimate.

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES

GROUND ELEVATION SYSTEM STATE PLANE

Water Level, ft. DRY

TIME

DATE 2-1-95

BORING NO. 0501

DATE 2/7/11

SHEET 1 OF 2

BORING START 2/1/95

BORING FINISH 2/1/95

PIEZOMETER TYPE

WELL TYPE

HGT. RISE/12 ABOVE GROUND

DIA

DEPTH TO TOP OF WELL SCREEN

BOTTOM

WELL DEVELOPMENT

BACKFILL

CEMENT/BENTONITE

FIELD PARTY TJH=RLY

RHS

CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE	TOE LEVEL, FEET	RCD %	DEPTH IN FEET	GRAPHIC LOG	USCS	SUB / ROCK IDENTIFICATION	WELL	DRIER'S NOTES
1	SS	9.0	1.5	4-4-4	1.1				<u>BROWN CLAYEY SAND</u> moist, 100% v-fine grain.		
2	SS	1.5	3.0	3-3-2	.7				<u>BLACK ASH</u> Dry to moist with fine limestone gravel.		
3	SS	3.0	4.5	2-3-3	1.1						
4	SS	4.5	6.0	5-6-5	1.2	5					
5	SS	6.0	7.5	3-4-6	1.1						
6	SS	7.5	9.0	5-9-9	.8						
7	SS	9.0	10.5	5-5-3	1.2	10					
8	SS	10.5	12.0	6-7-9	1.1						
9	SS	12.3	13.8	6-6-10	.7	15					
10	SS	17.3	18.8	12-16-18	.7				<u>REDDISH BROWN CLAYEY SANDY GRAVEL</u> moist, 1/2" max size, angular		17.3 DRILLING THROUGH AREAS.

TYPE OF CASING USED

Continued Next Page

X	NO. 2 ROCK CORE
	6" x 3 25 HSA
	9" x 6 25 HSA
	1 1/2" CASING ADVANCER
	1 1/2" CASING
	5/8" CASING
	AIR HAMMER

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE SLOTTED SCREEN, G = GEONOR, P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER RLY

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO 9501

DATE 2/7/11

SHEET 2 OF 2

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 2/1/95

BORING FINISH 2/1/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS/6"	COR- RECTED LENGTH RECOVERY %	RQD %	DEPTH IN FEET	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO							
11	SS	27.2	23.6	3-3-3	2					

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES

GROUND ELEVATION

SYSTEM STATE/PLANE

Water Level, ft DRY

TIME

DATE 2-1-95

BORING NO 9502

DATE 2/7/11

SHEET 1 OF 2

BORING START 2/1/95

BORING FINISH 2/1/95

PIEZOMETER TYPE

WELL TYPE

HGT. RISER ABOVE GROUND

DIA

DEPTH TO TOP OF WELL SCREEN

BOTTOM

WELL DEVELOPMENT

BACKFILL

CEMENT/BENTONITE

FIELD PARTY TJH=RLY

RIG

CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE	TOTAL LENGTH FEET	%	DEPTH TO GRAPHIC IN FEET	USCS	SOIL / ROCK IDENTIFICATION	WELL	DIGLER'S NOTES
1	SS	0.0	1.5	12-13-13	1.3			BLACK ASH, LIMESTONE ROAD BASE BROWN CLAYEY SANDry		
3	SS	3.0	4.5	3-3-3	1.2			BLACK ASHmet to cry		
4	SS	4.5	6.0	4-6-6	1.1	5				
5	SS	6.0	7.5	2-2-2	1.2					
6	SS	7.5	9.0	2-2-4	1.1					
7	SS	9.0	10.5	2-3-4	1.3	10				
8	SS	10.5	12.0	4-7-8	1.1			TRACE OF LIMESTONE GRAVEL BROWN SANDY CLAYry.		
9	SS	12.5	14.0	9-25-20	1.1					
2	SS	15.0	16.5	4-5-5	1.1	15				
10	SS	17.5	18.5	17-50	1.0			RED BRICKS GRAY SANDY CLAY BLACK COAL AND WOOD FRAGMENTS		17.3 DRILLING THROUGH AREAS

TYPE OF CASING USED

X NO 2 ROCK CORP
6" x 3.25 HSA
9" x 6.25 HSA
11W CASING ADVANCER 4"
NW CASING 3"
SW CASING 6"
AIR HAMMER 5"

Continued Next Page

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE
SLOTTED SCREEN, G = GEONOR, P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER RLY

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO. 9502 DATE 2/7/11 SHEET 2 OF 2

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 2/1/95

BORING FINISH 2/1/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE BLOWS / 6"	ROD TOTAL LENGTH RECOVERED %	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
11	SS	22.5 24.0	13 7 7	8				BROWN SAND, dry with trace of limestone gravel size material		

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES

GROUND ELEVATION

SYSTEM STATE PLANE

Water Level, ft DRY

TIME

DATE 2-1-95

BORING NO. 9503

DATE 2/7/11

SHEET 1 OF 2

BORING START 2/1/95

BORING FINISH 2/1/95

PIEZOMETER TYPE

WELL TYPE

HGT. RISER ABOVE GROUND

DIA

DEPTH TO TOP OF WELL SCREEN

POTOM

WELL DEVELOPMENT

BACKFILL

CEMENT/BENTONITE

FIELD PARTY TJH=RLY

R/G

CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE	TOTAL LENGTH OF LOG	DEPTH IN FEET	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
1	SS	0.0	13-13-16	1.2		LIMESTONE GRAVEL ROAD BASE		
2	SS	1.5	4-4-4	1.1		BROWN CLAYEY SAND		
3	SS	3.0	4-4-3	9		BLACK ASH		
4	SS	4.5	4-3-3	1.2	5			
5	SS	6.0	2-2-3	1.3				
6	SS	7.5	2-2-2	.3				
7	SS	9.0	2-1-1	.3	10			
8	SS	10.5	2-2-1	2				
9	SS	12.5	14-14-12	1.3	15			DRILLED THROUGH INTERMITTANT FLOIDERS COBBLES TO 22.6
10	SS	17.5	16-50	1.0		BLUE GRAY SHALEY SANDSTONE		

TYPE OF CASING USED

NO. 2 ROCK CORE
6" x 3.25 HSA
9" x 6.25 HSA
HW CASING ADVANCER
NW CASING
SW CASING
APL JAMMER

4"
3"
6"
8"

Continued Next Page

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE SLOTTED SCREEN, G = GEONOR, P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER RLY

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING

JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING NO. 9503

DATE 2/7/11 SHEET 2 OF 2

BORING START 2/1/95

BORING FINISH 2/1/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS/6"	TOTAL LENGTH RECOVERY %	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL/ROCK IDENTIFICATION	WEL-	DRILLER'S NOTES
		FROM	TO								
11	SS	22.6	22.7	50	.1						

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER: 3031

COMPANY: APPALACHIAN POWER COMPANY

PROJECT: GLEN LYN BOTTOM ASH DIKE

COORDINATES:

GROUND ELEVATION:

SYSTEM: STATE PLANE

Water Level: ☒ DRY ☐

TIME:

DATE: 2-1-95

BORING NO. 9504 DATE 2/7/11 SHEET 1 OF 2

BORING START 2/1/95 BORING FINISH 2/1/95

PIEZOMETER TYPE: WELL TYPE:

HGT. RISER ABOVE GROUND: DIA:

DEPTH TO TOP OF WELL SCREEN: BOTTOM:

WELL DEVELOPMENT: BACKFILL: CEMENT/BENTONITE

FIELD PARTY: TJH=RLY RIG: CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE	TOUGH LENGTH RECOVERY %	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
1	SS	0.0 - 1.5	0-6-7	1.5				BROWN CLAYEY SAND Moist, 100% v-fine grain		
2	SS	1.5 - 3.0	3-3-3	8				BLACK ASH Dry to moist		
3	SS	3.0 - 4.5	2-2-2	1.1						
4	SS	4.5 - 6.0	2-2-1	1.1	5					
5	SS	6.0 - 7.5	1-2-1	1.2						
6	SS	7.5 - 9.0	2-2-2	1.1						
7	SS	9.0 - 10.5	2-2-3	1.3	10					
8	SS	10.5 - 12.0	20-20-21	1.2				LIGHT BROWN SANDY SHALE Broken into gravel and sand size material		
9	SS	12.5 - 14.0	7-5-3	1.1				BLACK ASH Dry to moist.		
10	SS	17.5 - 19.0	2-5-0	1.1	15					

TYPE OF CASING USED

NO 2 ROCK CORE
6" x 3.25 HSA
9" x 6.25 HSA
LW CASING ADVANCER
NW CASING
SW CASING
AIR LIFT PUMP

FLAILMETER TYPE: PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE
SLOTTED SCREEN, G = GEONOR, P = PNEUMATIC

WELL TYPE: OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER: RLY

Continued Next Page

17.3 DRILLING
THROUGH AREAS.

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO. 9504

DATE 2/7/11

SHEET 2 OF 2

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 2/1/95

BORING FINISH 2/1/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS / 6"	TOTAL LENGTH RECOVERED %	DEPTH IN FEET	GRAPHIC LOG	LCS	SOIL/ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO								
11	SS	22.5	24.0	9-13 4	7				BROWN SANDY CLAY Moist, 100% v-line grain with gravel and sand size fragments		

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES N 387,329.6 E 1,312,372.4

GROUND ELEVATION 1524.0 SYSTEM STATE PLANE

Water Level, ft 34.0

TIME

DATE 11-7-95

BORING NO HP-9524 DATE 2/7/11 SHEET 1 OF 3

BORING START 11/7/95 BORING FINISH 11/8/95

PIEZOMETER TYPE N/A WELL TYPE N/A

HGT. RISE/IN ABOVE GROUND N/A DIA

DEPTH TO TOP OF WELL SCREEN N/A BOTTOM N/A

WELL DEVELOPMENT SEE NOTE BACKFILL QUICK GROUT

FIELD PARTY TJH-REB RIG CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS / 5'	TOTAL LENGTH RECOVERED	DEPTH IN FEET	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO							
1	SS	2.0	4.1	9-9-11	2		CL	TIME PH COND. REDOX TEMP. 12:45 4.15 222 281 18.15C 12:53 7.20 227 258 16.62C 12:57 7.24 231 261 16.72C 1:02 7.21 234 233 16.98C 1:06 7.23 237 214 16.98C 1:08 SAMPLE TAKEN 1:13 7.18 238 208 17.25C BLACK SILTY CLAY Roots, moist.		Pump test one hour at approximately 5 GPM prior to test by plant personnel. Packer set between 36.5 and 40.0'.
2	SS	7.6	9.1	2-3-3	1.1			BOTTOM ASH Dry.		Water return at all times.
3	SS	12.0	14.1	1-2-2	1.2					Intermittent boulders all further noted.
4	SS	17.6	19.1	7-9-15	1.2		CL GW	BROWN SILTY CLAY Moist BROKEN FRAGMENT OF GRAVEL DARK GRAY May be concrete		

TYPE OF CASING USED

X NO. 2 ROCK CORE
 X 6" x 3.25 HSA
 9" x 3.75 HSA
 11W CASING ADVANCE R 4"
 NW CASING 3"
 SW CASING 5"
 AIR HAMMER 6"

Continued Next Page

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE SLOTTED SCREEN, G = GEONOR P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER REB

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO. HP-9524 DATE 2/7/11

SHEET 2 OF 3

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 11/7/95

BORING FINISH 11/8/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET FROM TO	STANDARD PENETRATION RESISTANCE BLOWS / 6"	TOTAL LENGTH RECOVERY %	ROD	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
5	SS	22.6 24.1	5-7-9	1.1		25		GP	BROKEN SAND AND GRAVEL SIZE FRAGMENT OF SANDSTONE AND SHALE		
6	SS	27.6 29.1	2-3-3	1.2		30		CI	BROWN SANDY CLAY moist, low plasticity		Approximately 27 G natural material
7	SS	32.6 34.1	7-15-26	1.0		35			GRAY BROWN SAND AND GRAVEL wet to saturated, 20% fines, 1 3/8" max size, rounded to sub-angular	Y	
8	SS	33.5 36.9	7-9-4	.4				GP	SAME AS SAMPLE NO. 7 SATURATED, ANGULAR, 40% FINES		
9	NC	35.0 40.0		3.0	48				GRAY SANDSTONE hard well cemented, fine grain with shale laminations		
		40.0 40.5				40					Used 2 15/16 roller bit to advance hole Aucors in a bind.
						45					

Continued Next Page

DRIVING START 11/7/95 DRIVING FIN SH 11/8/95

US EPA ARCHIVE DOCUMENT

AEFGL000299

KIG CME-76

US EPA ARCHIVE DOCUMENT

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING

JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO. HP-9626 DATE 2/7/11

SHEET 3 OF 3

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 11/14/95

BORING FINISH 11/14/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS / 6"	TOTAL LENGTH RECOVERY %	ROD IN LEFT	DEPTH IN LEFT	GRAPHING USLS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO								
						50					

BORING NO **HP-9526** DATE **2/7/11** SHEET **2** OF **3**
BORING START **11/14/95** BORING FINISH **11/14/95**

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING NO HP-9528

DATE 2/7/11

SHEET 2 OF 2

BORING START

11/15/95

BORING FINISH

11/15/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE BLOWS / 6"	TOTAL LENGTH RECOVERED %	DEPTH IN FEET	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
5	SS	22.5	24.0	7.15 17	11	GC		
					25			
6	NQ	27.0	26.8	1.6	56			
7	NQ	28.9	33.0	5.0	52			
					30			
8	NQ	33.5	38.9	5.0	94			
					35			
9	NO	38.9	40.0	9	89			
					40			

AEP CIVIL ENGINEERING LABORATORY

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES N 386,682.4 E 1,313,336.1

GROUND ELEVATION 1515.3 SYSTEM STATE PLANE

BORING NO. HP-9528 DATE 2/7/11 SHEET 1 OF 2

BORING START 11/15/95 BORING FINISH 11/15/95

PIEZOMETER TYPE N/A WELL TYPE N/A

HGT. REFER. ABOVE GROUND N/A DIA

DEPTH TO TOP OF WELL SCREEN N/A BOTTOM N/A

WELL DEVELOPMENT SEE NOTE BACKFILL QUICK GROUT

FIELD PARTY TJH-REB REG CME-75

Water Level, ft
TIME
DATE

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET FROM TO	STANDARD PENETRATION RESISTANCE BLOWS / FT	TOTAL LENGTH RECOVERY	RECOVER %	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
1	SS	2.5	4.0		0			CL	11-16-95 TIME Ph COND. REDOX TEMP. 9:42 7.42 275 318 19.81C 9:46 7.57 ? 293 19.67C 9:48 7.60 278 283 19.83C 9:51 7.59 280 270 19.83C 9:54 SAMPLE TAKEN 9:56 7.66 279 260 19.69 DARK BROWN SANDY CLAY moist to wet with trace of pea size gravel.		Pump test one hour at approximately 5 GPM prior to test by plant personnel. Packers set between 29.5 and 40'.
2	SS	7.5	9.0	2-3.5	1.1	5			BLACK MIXTURE OF CLAY AND BOTTOM ASH moist		Water return at all times
3	SS	12.5	14.0	4-5.5	0	10			BLACK BOTTOM ASH moist		
4	SS	17.5	18.0	4-4.5	1.1	15		SC	BROWN CLAYEY SAND moist to wet, slight to non plasticity.		Approximately 17.5 inches material

TYPE OF CASING USED

☒ NQ 2 ROCK CORE
☒ 6" x 3 25 HSA
☒ 9" x 6 25 HSA
☒ 1 1/2" CAS NQ ADVANCER
☒ NQ CAS NQ
☒ SW CASING
☒ AIR HAMMER

4"
3"
6"
8"

Continued Next Page

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE SLOTTED SCREEN, G = GEOMON, P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER REB

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING NO. HP-9627 DATE 2/7/11

SHEET 2 OF 2

BORING START 11/15/95

BORING FINISH 11/15/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS / FT	TOTAL LENGTH RECOVERED %	DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO								
5	SS	23.0	24.5	15-23-31	1.4	25		GP	BROWN SILTY SAND AND GRAVEL max size, saturated, rounded to sub rounded.	V	
6	NQ	29.6	31.7		4.3	30			BLACK SHALE -hard, calcareous, calcite lens, and stain on joints, high angle fracture, vertical fracture 28.4 to 30.8'.		
7	NQ	31.7	34.5		6.3	35			Vertical fracture 36'		
8	NQ	38.5	39.3		.1						
9	NQ	39.3	40.0		1	40					

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES N 386,671.1 E 1,313,251.0

GROUND ELEVATION 1515.7 SYSTEM STATE PLANE

Water Level ft 22.5

1 MP

DATE 11-15-95

BORING NO. HP-9527 DATE 2/7/11 SHEET 1 OF 2

BORING START 11/15/95 BORING FINISH 11/15/95

PEZOMETER TYPE N/A WELL TYPE N/A

HGT. RISER ABOVE GROUND N/A DIA

DEPTH TO TOP OF WELL SCREEN N/A BOTTOM N/A

WELL DEVELOPMENT SEE NOTE BACKFILL QUICK GROUT

FIELD PARTY TJH-REB RIG CME-76

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET	STANDARD PENETRATION RESISTANCE BLOWS/5'	TOTAL LENGTH RECOVERY %	ROD DEPTH IN FEET	GRAPHIC LOG	USCS	SOIL / ROCK IDENTIFICATION	DRILLER'S NOTES
1	SS	3.0	4.5	5-6-7	1.1			11-15-95 TIME Ph COND. REDOX TEMP. 1:45 6.55 200 360 16.72C 1:49 7.52 207 328 16.36C 1:52 7.70 207 310 16.26 1:54 7.79 207 298 16.36 1:57 SAMPLE TAKEN 1:59 7.82 211 290 16.33C BLACK BOTTOM ASH Dry	Pump test one hour at approximately 5 GPM prior to test by part personal Packers set between 29.5 and 40.0'
2	SS	8.0	9.5	3-4-4	1.0				Water return at all times
3	SS	13.0	14.5	7-7-7	1.1				
4	SS	18.0	19.5	8-8-0	1.0			DARK BROWN SILTY SAND AND GRAVEL Saturated, 1 3/8" max size, angular to sub-angular, 20% fines.	Approximately 18' of natural material

TYPE OF CASING USED

X NO-2 ROCK CORE
 X 5" x 3 25 JISA
 3" x 6 25 HSA
 HW CAS NG ADVANCER
 NW CAS NG
 SW CAS NG
 AIR HAMMER

4"
 5"
 6"
 5"

Continued Next Page

PEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE
 SLOTTED SCREEN, G = GEONOR, P = PNEUMATIC

WELL TYPE OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDED REB

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

BORING NO. HP-9526 DATE 2/7/11

SHEET 2 OF 2

PROJECT GLEN LYN BOTTOM ASH DIKE

BORING START 11/8/95

BORING FINISH 11/9/95

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE BLOWS / FT	CORAL LENGTH RECOVERY %	DEPTH IN FEET	GRAPHIC LOG USCS	SOIL/ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO							
5	NO	21.1	25.0		3.8	48		GRAY SANDSTONE with shale lens, hard, well cemented, iron stain on joints		
6	NO	25.0	30.0		4.9	54				
7	NO	30.0	34.0		3.9	63				

AMERICAN ELECTRIC POWER SERVICE CORPORATION
AEP CIVIL ENGINEERING LABORATORY
LOG OF BORING



JOB NUMBER 3031

COMPANY APPALACHIAN POWER COMPANY

PROJECT GLEN LYN BOTTOM ASH DIKE

COORDINATES N 387,441.9 E 1,312,324.2

GROUND ELEVATION 1508.9 SYSTEM STATE PLANT

Water Level ft 17.9
TIME 7:00
DATE 11-9-95

BORING NO HP-9526 DATE 2/7/11 SHEET 1 OF 2

BORING START 11/9/95 BORING FINISH 11/9/95

PIEZOMETER TYPE N/A WELL TYPE N/A

HGT. RISER ABOVE GROUND N/A DIA

DEPTH TO TOP OF WELL SCREEN N/A BOTTOM N/A

WELL DEVELOPMENT SEE NOTE BACKFILL QUICK GROUT

FIELD PARTY TJH-REB RIO CME-75

SAMPLE NUMBER	SAMPLE	SAMPLE DEPTH IN FEET		STANDARD PENETRATION RESISTANCE	TOTAL LENGTH RECOVERED	RECOVER %	DEPTH IN FEET	GRAPHIC LOG	V.S.C.S	SOIL / ROCK IDENTIFICATION	WELL	DRILLER'S NOTES
		FROM	TO	BLOWS / 5"								
1	SS	2.5	4.0	7-9-15	1.0				CL	11-9-95 TIME Ph COND. REDOX TEMP 11:35 6.65 278 330 17.36C 11:40 6.95 287 285 16.53C 11:42 7.02 286 262 16.45C 11:45 7.03 286 249 16.45C 11:47 SAMPLE TAKEN 11:50 7.03 285 227 16.49C BROWN SANDY CLAYTrace of gravel and brick dry		Pump test one hour at approximately 5 GPM prior to test by plant. Packer set between 23.5 and 34.3'
2	SS	7.5	8.0	16-22-26	1.1		5			CLMULTI-COLORED SANDY CLAYDry, with some sandstone and shale gravel size material		Augered through boulders and hard pan area
3	SS	12.5	14.0	5-8-10	1.1		10			CLBROWN SANDY CLAYHard, low plasticity with trace of wood		Approximately 12.5 natural material
4	SS	17.5	19.0	10-15-19	1.0		15		GP	BROWN SILTY SAND AND GRAVELVel to solution, rounded to sub rounded, 30% fines		

TYPE OF CASING USED


X NO 2 ROCK CORF
X 6" x 3.25 IUSA
9" x 6.25 IUSA
HW CASING ADVANCER 4"
NW CASING 3"
SW CASING 5"
AIR HAMMER 8"

Continued Next Page

PIEZOMETER TYPE PT = OPEN TUBE POROUS TIP, SS = OPEN TUBE SLOTTED SCREEN, C = GEONOR, P = PNEUMATIC

WELL TYPE: OW = OPEN TUBE SLOTTED SCREEN, GM = GEOMON

RECORDER REB



MONITORING WELL CONSTRUCTION DETAILS												
MONITOR WELL NO.	BORING NO.	DATE OF INSTALLATION	STATE PLANE COORDINATES	TOP OF CASING	GROUND ELEVATION	TOP OF BENTONITE SEAL	TOP OF GRAVEL PACK	TOP OF SCREEN	BOTTOM OF SCREEN	BOTTOM OF GRAVEL PACK	BOTTOM OF PIPE	TOTAL DEPTH
MW-0801	B-0801	10-13-08	N 387,230.00 E 1312,315.10	1514.80	1515.25	1489.25	1485.75	1483.55	1474.05	1472.15	1472.15	40.75
MW-0802	B-0802	10-07-08	N 387,245.20 E 1312,383.10	1515.15	1515.65	1488.65	1485.05	1482.95	1473.45	1471.95	1471.95	41.70
MW-0803	B-0803	10-23-08	N 387,245.20 E 1312,337.60	1508.48	1508.91	1486.91	1485.61	1483.51	1474.01	1472.41	1472.31	34.47
MW-0804	B-0804	10-23-08	N 387,238.00 E 1312,401.00	1516.67	1517.09	1487.79	1484.89	1482.79	1473.29	1471.69	1471.69	43.38
MW-0805	B-0805	10-15-08	N 387,239.20 E 1312,775.20	1518.08	1518.43	1485.13	1482.93	1482.93	1473.43	1471.43	1471.43	44.65

* TOTAL DEPTH = TOP OF CASING EL. - BOTTOM OF SCREEN EL.

GENERAL NOTES

LEGEND

- x509.5 SPOT ELEVATION
- INTERMEDIATE CONTOUR
- - - INDEX CONTOUR
- - - DEPRESSION CONTOUR
- TREES AND TREELINE
- STRUCTURE AND BUILDING
- x - FENCE
- o POLE
- == ROADS
- EDGE OF WATER
- o MANHOLES / CATCH BASIN
- o POWER POLE
- PIPES
- TOWER
- MW0802 NEW WELL LOCATION
- HP-9525 OLD WELL LOCATION

REFERENCES

DATE	NO.	DESCRIPTION	APPRO.
REVISIONS			
S: /GL/55/CIVIL/LSKETCH/SK01.009.DGN			
"THIS DRAWING IS THE PROPERTY OF THE AMERICAN ELECTRIC POWER SERVICE CORP. AND IS LOANED UPON CONDITION THAT IT IS NOT TO BE REPRODUCED OR COPIED, IN WHOLE OR IN PART, OR USED FOR FURNISHING INFORMATION TO ANY PERSON WITHOUT THE WRITTEN CONSENT OF THE AEP SERVICE CORP., OR FOR ANY PURPOSE DETRIMENTAL TO THEIR INTEREST, AND IS TO BE RETURNED UPON REQUEST."			
APPALACHIAN POWER COMPANY			
GLEN LYN PLANT			
GLEN LYN VIRGINIA			
BOTTOM ASH POND WELL LOCATION			
DWG NO: GSK-GL-56-012009			
SCALE: 1" = 40'			
DRI:	CHK:	SLIP:	ENG:
APPROVED BY:		X.X. XXXXXXX	
DATE:			

AMERICAN ELECTRIC POWER

AEP SERVICE CORP
1 RIVERSIDE PLAZA
COLUMBUS, OH 43215

APPENDIX B



Site Name:	Glen Lyn Plant	Date:	February 16, 2011
Unit Name:	Auxiliary Fly Ash Pond	Operator's Name:	Appalachian Power
Unit I.D.:	NID: VA07101	Hazard Potential Classification:	High ☐ Significant ☐ Low ☒
Inspector's Name:		Scott Clarke, P.E. and Lorainne Ramos Nieves, P.E., CFM	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

Note: Comments regarding each issue number have been listed below as needed.

Issue #	Yes	No	Issue #	Yes	No
1. Frequency of Company's Dam Inspections?	✓		18. Sloughing or bulging on slopes?		✓
2. Pool elevation (operator records)?		✓	19. Major erosion or slope deterioration?		✓
3. Decant inlet elevation (operator records)?	✓		20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		N/A	Is water entering inlet, but not exiting outlet?		N/A
5. Lowest dam crest elevation (operator records)?	✓		Is water exiting outlet, but not entering inlet?		N/A
6. If instrumentation is present, are readings recorded (operator records)?	✓		Is water exiting outlet flowing clear?		N/A
7. Is the embankment currently under construction?		✓	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		✓	From underdrain?		✓
9. Trees growing on embankment? (If so, indicate largest diameter below)	✓		At isolated points on embankment slopes?		✓
10. Cracks or scarps on crest?		✓	At natural hillside in the embankment area?		✓
11. Is there significant settlement along the crest?		✓	Over widespread areas?		✓
12. Are decant trashracks clear and in place?		N/A	From downstream foundation area?		✓
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		✓	"Boils" beneath stream or ponded water?		✓
14. Clogged spillways, groin or diversion ditches?		✓	Around the outside of the decant pipe?		✓
15. Are spillway or ditch linings deteriorated?		✓	22. Surface movements in valley bottom or on hillside?		✓
16. Are outlets of decant or underdrains blocked?		✓	23. Water against downstream toe?	✓	
17. Cracks or scarps on slopes?		✓	24. Were Photos taken during the dam inspection?	✓	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Issue #	Comments
1.	Impoundments are inspected quarterly by the plant personal and annually through an outside consultant.
2.	The Auxiliary Fly Ash Pond is currently inactive and on the day of the assessment had no significant pooling behind the dike; no normal pool elevations were available for this impoundment.
3.	The invert at the Auxiliary Fly Ash Pond outlet is $\pm 1502.0'$
5.	A quarterly inspection report indicates a lowest crest elevation of 1540.0' for the the Auxiliary Fly Ash Pond. Plan view hard copies of pond surveys completed in 2007 confirm listed elevations.
6.	According to the plant owner, instrumentation at either impoundment was installed with the intent of being temporary; no continual record of readings is kept for piezometers or observation wells at either impoundment. The



	only readings recorded as part of the quarterly reports are pond elevations, as previously noted.
9.	Between the toe of the northeastern embankment and the New River there is significant tree growth; largest tree size ranged from 12"- 18" diameter. Several tree saplings ranging from 2.0" to 2.5" diameter were observed along the northeastern inside groin. Virginia DCR requires a 25 ft clear zone (i.e. no trees) beyond the toe of all impounding structures.
20.	The second impoundment, Auxiliary Fly Ash Pond, is currently inactive and had no pooling behind the dike; no discharge could be seen leaving impoundment through the outlet.
23.	The Auxiliary Fly Ash Pond has Adair Run along the southeastern embankment and the New River along the northeastern embankment.
*	Three animal burrows were observed along the northeastern embankment of the Auxiliary Fly Ash Pond. The first was located at the north end of the toe of the embankment. The remaining burrows were flagged for maintenance by the plant personal; one located midway up the embankment towards the midpoint of the pond and the other located about three quarters of the way up the embankment between the midpoint and southern end of the embankment.



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit VA 0000370 / Outfall 006 **INSPECTOR** Scott Clarke, P.E. and Lorainne Ramos Nieves, P.E., CFM

Date February 16, 2011
Impoundment Name Auxiliary Fly Ash Pond (Inactive)

Impoundment Company AEP, Appalachian Power
EPA Region 3

State Agency Virginia Department of Conservation & Recreation, Division of Dam Safety and
(Field Office) Address Floodplain Management; 8 Radford St., Suite 201 Christiansburg, VA 24073
Name of Impoundment Auxiliary Fly Ash Pond (Inactive)

(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New ☒

Update ☐

Yes

No

Is impoundment currently under construction?

☐
☒

Is water or ccw currently being pumped into the impoundment?

☐
☒

IMPOUNDMENT FUNCTION: Settling pond for fly ash disposal.

Nearest Downstream Town Name: Hinton, West Virginia.

Distance from the impoundment: 20.5 mi.

Location:

Latitude 37 Degrees 22 Minutes 42.8 Seconds **N**

Longitude 80 Degrees 52 Minutes 32.1 Seconds **W**

State Virginia

County Giles

Yes

No

Does a state agency regulate this impoundment?

☒
☐

If So Which State Agency?


Virginia DCR, Division of Dam Safety and
Floodplain Management / Virginia DEQ

**HAZARD POTENTIAL** *(In the event the impoundment should fail, the following would occur):*

- ☐ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.
- ☒ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.
- ☐ **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.
- ☐ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

Auxiliary Fly Ash Pond is located along the left bank of the New River and portion of the left bank of Adair Run near its confluence with the New River. A failure of this facility would be limited to the New River and/or Adair Run with no probable loss of human life and relatively low economic and/or environmental losses. Virginia DCR, Division of Dam Safety and Floodplain Management, currently regulate this facility as a low hazard impoundment.

**CONFIGURATION:**

Cross-Valley



Side-Hill



Diked



Incised (form completion optional)



Combination Incised/Diked





Embankment Height (ft) 43 ft**Embankment Material** Sand, clay and fly ash.**Pool Area (ac)** 10 acre-ft**Liner** 1"-3" thick**Current Freeboard (ft)** N/A**Liner Permeability** Clay

**TYPE OF OUTLET** (Mark all that apply)☐ **Open Channel Spillway**☐ Trapezoidal☐ Triangular☐ Rectangular☐ Irregular

depth (ft)

average bottom width (ft)


top width (ft)

TRAPEZOIDALTRIANGULARRECTANGULARIRREGULAR☒ **Outlet (Inactive)**

24" inside diameter

Material

- ☒ corrugated metal
- ☐ welded steel
- ☐ concrete
- ☐ plastic (hdpe, pvc, etc.)
- ☐ other (specify):



Yes

No

Is water flowing through the
outlet?☐ No Outlet☐ Other Type of Outlet
(specify):The Impoundment was Designed By **AEP Engineers**



Yes

No

Has there ever been a failure at this site?

☐☒

If So When?

If So Please Describe :



Yes

No

Has there ever been significant seepages
at this site?

☐☒

If So When?

If So Please Describe :



Yes

No

Has there ever been any measures undertaken to monitor/lower Phreatic water table levels based on past seepages or breaches at this site?

☐☒

If so, which method (e.g., piezometers, gw pumping,...)?

If So Please Describe :

**ADDITIONAL INSPECTION QUESTIONS**

Concerning the embankment foundation, was the embankment construction built over wet ash, slag, or other unsuitable materials? If there is no information just note that.

No plans or information were available at the time of the site visit regarding embankment foundation. Information has been requested from AEP and will be provided after clearing AEP legal.

Did the dam assessor meet with, or have documentation from, the design Engineer-of-Record concerning the foundation preparation?

The AEP Senior Civil Engineer and the AEP Geotechnical Engineer for the Glen Lyn Plant were both present during the site visit, however no plans or information were available at the time of the site visit regarding the design foundation preparation. Information has been requested from AEP and will be provided after clearing AEP legal.

From the site visit or from photographic documentation, was there evidence of prior releases, failures, or patchwork on the dikes?

No evidence of prior releases, failures, or patchwork on dikes could be noted at the time of the site visit.



Site Name:	Glen Lyn Plant	Date:	February 16, 2011
Unit Name:	Bottom Ash Pond	Operator's Name:	Appalachian Power
Unit I.D.:	NID: VA07102	Hazard Potential Classification:	High ☐ Significant ☐ Low ☒
Inspector's Name:		Scott Clarke, P.E. and Lorainne Ramos Nieves, P.E., CFM	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

Note: Comments regarding each issue number have been listed below as needed.

Issue #	Yes	No	Issue #	Yes	No
1. Frequency of Company's Dam Inspections?	✓		18. Sloughing or bulging on slopes?		✓
2. Pool elevation (operator records)?	✓		19. Major erosion or slope deterioration?	✓	
3. Decant inlet elevation (operator records)?		✓	20. Decant Pipes:		
4. Open channel spillway elevation (operator records)?		N/A	Is water entering inlet, but not exiting outlet?		✓
5. Lowest dam crest elevation (operator records)?	✓		Is water exiting outlet, but not entering inlet?		✓
6. If instrumentation is present, are readings recorded (operator records)?		✓	Is water exiting outlet flowing clear?	✓	
7. Is the embankment currently under construction?		✓	21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below):		
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		✓	From underdrain?		✓
9. Trees growing on embankment? (If so, indicate largest diameter below)	✓		At isolated points on embankment slopes?		✓
10. Cracks or scarps on crest?		✓	At natural hillside in the embankment area?		✓
11. Is there significant settlement along the crest?		✓	Over widespread areas?		✓
12. Are decant trashracks clear and in place?	✓		From downstream foundation area?		✓
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		✓	"Boils" beneath stream or ponded water?		✓
14. Clogged spillways, groin or diversion ditches?		✓	Around the outside of the decant pipe?		✓
15. Are spillway or ditch linings deteriorated?		✓	22. Surface movements in valley bottom or on hillside?		✓
16. Are outlets of decant or underdrains blocked?	✓		23. Water against downstream toe?	✓	
17. Cracks or scarps on slopes?		✓	24. Were Photos taken during the dam inspection?	✓	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Issue #	Comments
1.	Impoundments are inspected quarterly by the plant personal and annually through an outside consultant.
2.	A quarterly inspection report, titled Dike Inspection Checklist, indicates normal pool elevations at 1505.5', 1506.3' and 1501.3' for the North Bottom Ash Pond, South Bottom Ash Pond and Clearwater Pond, respectively.
5.	A quarterly inspection report indicates a lowest crest elevation of 1515.0' for the Bottom Ash Pond. Plan view hard copies of pond surveys completed in 2007 confirm listed elevations.
6.	According to the plant owner, instrumentation at either impoundment was installed with the intent of being temporary; no continual record of readings is kept for piezometers or observation wells at either impoundment. The only readings recorded as part of the quarterly reports are pond elevations, as previously noted.



9.	Several tree saplings ranging from 1.0"-1.5" diameter were observed protruding from riprap armor along the northern embankment of the Bottom Ash Pond (adjacent to the New River). Additional tree clusters were also observed on either end of the riprap armor, largest tree size ranged from 18"- 24" diameter. The eastern embankment of the Bottom Ash Pond (adjacent to the East River) had plentiful tree cover, largest tree size ranged from 12"- 18" diameter.
16.	The Bottom Ash Pond outlet to East River was partially obstructed with sediment.
19.	The northeastern groin area of the cleanwater pond cell of the Bottom Ash Pond has been armored with riprap to prevent further slope deterioration due to erosion. In addition, some slope deterioration of the interior slope is noted along the eastern embankment of the bottom ash clear water pond cell, near the access walkway to outlet structure.
23.	The Bottom Ash Pond has the New River along the downstream toe of the northern embankment and the East River along the downstream toe of the eastern embankment.


**Coal Combustion Waste (CCW)
Impoundment Inspection****Impoundment NPDES Permit** VA 0000370/ Outfall
004**INSPECTOR** Scott Clarke, P.E. and Lorainne Ramos
Nieves, P.E., CFM**Date** February 16, 2011
Impoundment Name Bottom Ash Pond**Impoundment Company** AEP, Appalachian Power
EPA Region 3**State Agency** Virginia Department of Conservation & Recreation, Division of Dam Safety and
(Field Office) Address Floodplain Management; 8 Radford St., Suite 201 Christiansburg, VA 24073
Name of Impoundment Bottom Ash Pond*(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)***New** ☒**Update** ☐**Yes****No****Is impoundment currently under construction?**☐☒**Is water or ccw currently being pumped into the impoundment?**☒☐**IMPOUNDMENT FUNCTION:** Settling pond for bottom ash disposal.**Nearest Downstream Town Name:** Hinton, West Virginia.**Distance from the impoundment:** 20.5 mi.**Location:****Latitude** 37 Degrees 22 Minutes 21.4 Seconds **N****Longitude** 80 Degrees 51 Minutes 55.6 Seconds **W****State** Virginia**County** Giles**Yes****No****Does a state agency regulate this impoundment?**☒☐**If So Which State Agency?**Virginia DCR, Division of Dam Safety and
Floodplain Management / Virginia DEQ

**HAZARD POTENTIAL** *(In the event the impoundment should fail, the following would occur):*

- ☐ **LESS THAN LOW HAZARD POTENTIAL:** Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.
- ☒ **LOW HAZARD POTENTIAL:** Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.
- ☐ **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.
- ☐ **HIGH HAZARD POTENTIAL:** Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

Bottom Ash Pond is located along the left bank of the New River and portion of the right bank of the East River near its confluence with the New River. A failure of this facility would be limited to the New River and/or East River with no probable loss of human life and relatively low economic and/or environmental losses. Virginia DCR, Division of Dam Safety and Floodplain Management, currently regulate this facility as a low hazard impoundment.

**CONFIGURATION:**

Cross-Valley



Side-Hill



Diked



Incised (form completion optional)



Combination Incised/Diked





Embankment Height (ft) 27 ft**Embankment Material** Clayey Shale**Pool Area (ac)** 5.8 acre-ft**Liner** None**Current Freeboard (ft)** 17.5 ft / 17.5 ft / 21.7 ft
(Normal Freeboard)**Liner Permeability** None

**TYPE OF OUTLET** (Mark all that apply)☐ **Open Channel Spillway**☐ Trapezoidal☐ Triangular☐ Rectangular☐ Irregular

depth (ft)


average bottom width (ft)

top width (ft)

TRAPEZOIDALTRIANGULARRECTANGULARIRREGULAR☒ **Outlet**

30" 30" inside diameter (Clearwater Pond)

18" inside diameter (North/South Pond)

Material☒ corrugated metal (North/South Pond)☐ welded steel☒ Concrete (Cleanwater Pond)☐ plastic (hdpe, pvc, etc.)☐ other (specify):

Yes

No

Is water flowing through the
outlet?☐ No Outlet☐ Other Type of Outlet
(specify):



The Impoundment was Designed By **AEP Engineers**

Yes

No

Has there ever been a failure at this site?

☐☒

If So When?

If So Please Describe :



Yes

No

Has there ever been significant seepages
at this site?

☐☒

If So When?

If So Please Describe :



Yes

No

Has there ever been any measures undertaken to monitor/lower Phreatic water table levels based on past seepages or breaches at this site?

☐☒

If so, which method (e.g., piezometers, gw pumping,...)?

If So Please Describe :

**ADDITIONAL INSPECTION QUESTIONS**

Concerning the embankment foundation, was the embankment construction built over wet ash, slag, or other unsuitable materials? If there is no information just note that.

No plans or information were available at the time of the site visit regarding embankment foundation. Information has been requested from AEP and will be provided after clearing AEP legal.

Did the dam assessor meet with, or have documentation from, the design Engineer-of-Record concerning the foundation preparation?

The AEP Senior Civil Engineer and the AEP Geotechnical Engineer for the Glen Lyn Plant were both present during the site visit, however no plans or information were available at the time of the site visit regarding the design foundation preparation. Information has been requested from AEP and will be provided after clearing AEP legal.

From the site visit or from photographic documentation, was there evidence of prior releases, failures, or patchwork on the dikes?

No evidence of prior releases, failures, or patchwork on dikes could be noted at the time of the site visit.