

US EPA ARCHIVE DOCUMENT

Report of Dam Safety Assessment of Coal
Combustion Surface Impoundments
Alliant Energy
M.L. Kapp Power Station
Clinton, IA

AMEC Project No. 3-2106-0183.0002

Prepared By:

AMEC Earth & Environmental, Inc.
690 Commonwealth Center
11003 Bluegrass Parkway
Louisville, KY 40299

Prepared For:

U.S. Environmental Protection
Agency
Office of Solid Waste and
Emergency Response
Office of Resource Conservation
and Recovery
1200 Pennsylvania Ave., NW
MC: 5304P
Washington, DC 20460

December 2010

I certify that the management units referenced herein:

Alliant Energy's M.L. Kapp Power Station Emergency Ash Settling Ponds (Primary and Secondary) and Main Ash Settling Ponds (Primary and Secondary) were assessed on October 27, 2010.

Signature _____
Don Dotson, PE
Senior Geotechnical Engineer

List of AMEC Participants who have participated in the assessment of the management units and in preparation of the report:

- Chris Eger
CADD Technician
- Daniel Conn
GIS Specialist
- Mary Sawitzki, PE
Civil/Environmental Engineer
- Shea Carr, PE
Civil Engineer

DRAFT

TABLE OF CONTENTS

SECTION	PAGE NO.
1.0 INTRODUCTION AND PROJECT DESCRIPTION.....	1
1.1 Introduction.....	1
1.2 Project Background.....	1
1.2.1 Coal Combustion Dam Inspection and Checklist Forms	1
1.2.2 State Issued Permits	2
1.3 Site Description and Location	2
1.4 Ash Ponds	2
1.4.1 Main Ash Settling Area	3
1.4.2 Emergency Ash Settling Area	3
1.5 Previously Identified Safety Issues.....	4
1.6 Site Geology	4
1.7 Inventory of Provided Materials.....	4
2.0 FIELD ASSESSMENT	5
2.1 Visual Observations	5
2.2 Visual Observations - Emergency Ash Primary and Secondary Settling Ponds ...	5
2.2.1 Emergency Ash Primary and Secondary Settling Ponds - Embankments and Crest.....	6
2.2.2 Emergency Ash Primary and Secondary Settling Ponds - Outlet Control Structures	6
2.3 Visual Observations - Main Primary and Secondary Ash Ponds	6
2.3.1 Main Primary and Secondary Ash Ponds - Embankments and Crest.....	7
2.3.2 Main Primary and Secondary Ash Ponds - Outlet Control Structures.....	7
2.4 Monitoring Instrumentation.....	7
3.0 DATA EVALUATION	8
3.1 Design Assumptions	8
3.2 Hydrologic and Hydraulic Design	8
3.2.1 Long Term Hydrologic Design Criteria	8
3.2.2 Hydrologic Design Criteria - Main Ash Settling Ponds.....	9
3.2.3 Hydrologic Design Criteria - Emergency Ash Ponds	11
3.3 Structural Adequacy & Stability	11
3.3.1 MAIN ASH POND - Structural Adequacy & Stability	13
3.3.2 Emergency Ash Pond - Structural Adequacy & Stability	14
3.4 Foundation Conditions	16
3.5 Operations and Maintenance	17
3.5.1 Safety Assessments	17
3.5.2 Instrumentation.....	18
3.5.3 State or Federal Inspections	18
4.0 COMMENTS AND RECOMMENDATIONS	19
4.1 Acknowledgement of Management Unit Conditions	19
4.2 Recommendations	19
4.2.1 Hydrologic and Hydraulic.....	20
4.2.2 Geotechnical and Stability Recommendations	20
4.2.3 Inspection Recommendations.....	21
5.0 CLOSING.....	22

TABLES

Table 1. Site Visit Attendees 1
Table 2. Ash Settling Pond Size and Storage Data 4
Table 3. M.L. Kapp Rainfall Data 5
Table 4. MSHA* Minimum Long Term Hydrologic Design Criteria 8
Table 5. Summary of 2010 Main Settling Pond Area Hydrologic Calculations 10
Table 6. Minimum Stability Factors of Safety 11
Table 7. Soil Properties for Emergency Ash Pond (Boring B-1)..... 12
Table 8. Soil Properties for Main Ash Pond (Boring B-2)..... 13
Table 9. Factors of Safety for Main Ash Pond at Critical Section..... 14
Table 10. Factors of Safety for Emergency Ash Pond at Critical Section..... 16
Table 11. Emergency and Main Ash Settling Area Foundation Soils 17

FIGURES

Site Location and Vicinity Map Figure 1
Aerial Site Plan Figure 2
Critical Infrastructure Map Figure 3
Topographic Site Map Figure 4
Main Ash Settling Pond - Original (1965) Plan and Typical Cross Sections..... Figure 5
Emergency Ash Settling Ponds - Original and Current Configuration Figure 6
2010 Stability Analyses - Analyzed Sections Figure 7

APPENDICES

EPA Coal Combustion Dam Inspection Checklists and Coal Combustion
Waste Impoundment Inspection Forms Data - October 2010 Appendix A
Site Photo Log Map and Site Photos..... Appendix B
Inventory of Provided Materials Appendix C

1.0 INTRODUCTION AND PROJECT DESCRIPTION

1.1 Introduction

AMEC was contracted by the United States Environmental Protection Agency (EPA) contract BPA EP09W001702, to perform assessments of selected coal combustion byproducts surface impoundments. As part of this contract with EPA, AMEC was assigned to perform an assessment of Alliant Energy's M.L. Kapp Power Station (M.L. Kapp), which is located in Clinton, Iowa as shown on Figure 1, the Site Location and Vicinity Map.

A site visit to M.L. Kapp was made by AMEC on October 27, 2010. The purpose of the visit was to perform visual observations, to inventory coal combustion waste (CCW) surface impoundments, assess the containment dikes, and to collect relevant historical impoundment documentation.

AMEC engineers, Don Dotson, PE and Mary Sawitzki, PE, were accompanied during the site visit by the individuals listed on Table 1.

Table 1. Site Visit Attendees

Company or Organization	Name and Title
Alliant Energy	Greg Hudson, Plant Manager
Alliant Energy	Kurt Hubbart, Environmental and Safety Specialist
Alliant Energy	William Skalitzky, Senior Environmental Specialist

1.2 Project Background

Coal fired power plants, like Alliant Energy's M.L. Kapp Power Station, produce CCW as a result of the power production process. At M.L. Kapp, impoundments (dams) were designed and constructed to provide storage and disposal for the CCW that is produced. CCW impoundment areas at the M.L. Kapp facility are referred to as the Main Ash Settling and the Emergency Ash Settling areas. Each settling area contains a Primary and a Secondary Settling Pond. The Emergency Ash Settling Ponds do not receive CCW waste on a regular basis, but serve as an alternative sluicing destination when required. The ponds in both Ash Settling Areas were commissioned in 1965. Modifications were made to the Emergency and Main Ash Settling Areas in 2000 and 2002, respectively.

The National Inventory of Dams (NID), administered by the U.S. Army Corps of Engineers (USACE), provides a hazard rating for many dams within the United States. The Ash Settling Ponds at M.L. Kapp are not included in the NID.

1.2.1 Coal Combustion Dam Inspection and Checklist Forms

As part of the observations and evaluations performed at M.L. Kapp, AMEC completed EPA's Coal Combustion Dam Inspection Checklists and CCW Impoundment Inspection Forms. Inspection forms for each pond are presented in Appendix A. The Impoundment Inspection Forms include a section that assigns a "Hazard Potential" that is used to indicate what would occur following failure of an impoundment. "Hazard Potential" choices include "Less than Low,"

“Low,” “Significant,” and “High.” As defined on the Inspection Form, dams assigned a “Significant Hazard Potential” are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. “Significant Hazard Potential” classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.” “Low Hazard Potential” classification definition is reserved for dams where “failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner’s property.” “Less than Low Hazard Potential” classification is reserved for dams where “failure or misoperation results in no probable loss of human life and no economic or environmental losses.” Based on the site visit evaluation of the impoundments, AMEC engineers assigned a “Significant Hazard” potential to the Emergency Ash Secondary Settling Pond and a “Low Hazard” potential to each of the other three ponds. The Emergency Ash Secondary Settling Pond was assigned a “Significant Hazard” rating due to its proximity to Mill Creek and the Mississippi River.

1.2.2 State Issued Permits

The Iowa Department of Natural Resources issued an Iowa National Pollution Discharge Elimination System (NPDES) Permit to Alliant Energy. The current permit identification number is Iowa 2326103. This NPDES Permit authorizes Alliant Energy to discharge decant from the Main Ash Secondary Settling Pond through Outfall 003, as well as from the Emergency Ash Secondary Settling Pond through Outfall 004, to the Mississippi River. The effective date of the permit is July 16, 1999. Although the permit date of expiration was July 15, 2004, and a permit renewal request was submitted, Alliant Energy has been instructed to discharge under the previously issued permit because the State of Iowa is in the process of working through a backlog of NPDES permit renewals.

1.3 Site Description and Location

The M.L. Kapp Power Station is located in the city of Clinton, Clinton County, Iowa. While Beaver Slough, a spur of the Mississippi River, is located directly adjacent to and east of the facility buildings and the Emergency Ash Settling Ponds, the remaining sides of the facility are surrounded by industry. The Main Ash Settling Pond area is located apart from the Emergency Ponds and facility buildings. The Aerial Site Plan, included as Figure 2, provides a view of the pond areas and their proximity to the creek and river.

Figure 3, the Critical Infrastructure Map, provides an aerial view of the region and indicates the location of the M.L. Kapp ash ponds in relation to schools, hospitals, and other critical infrastructure that is located within approximately 5 miles down gradient of the impoundments. A table that provides names and coordinate data for the infrastructure is included on the map. A Topographic Site Map is included as Figure 4.

1.4 Ash Ponds

M.L. Kapp utilizes coal in the production of electricity. In this process, two types of ash are generated: fly ash and bottom ash. Bottom ash, the heavier and coarser of the two, as well as fly ash, are typically sluiced into the Main Ash Primary Settling Pond, but can, if necessary, be sluiced to the Emergency Ash Primary Settling Pond. Decant water from each Primary Pond is gravity discharged into the neighboring Secondary Pond. Settled decant is pumped from each Secondary Pond and discharged through permitted NPDES outfalls as described previously.

The ash handling summary detailed above was based on review of provided documentation as well as communication with Westar personnel who are knowledgeable concerning the facility's operational processes.

A May 22, 2009 document, written by Alliant Energy in response to EPA's Request for Information under Section 104(e) of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA), 42 U.S.C 9604(e), provided the following general background for the ash ponds.

- Both ponds in the Main Ash Settling Area temporarily or permanently contain fly ash, bottom ash, pyrites, and other materials including ash transport water, boiler water wash, air heater wash (fly ash), and site storm water runoff.
- Both ponds in the Emergency Ash Settling Area temporarily or permanently contain fly ash, bottom ash, pyrites, coal pile stormwater runoff, ash transport waters, boiler water wash, air heater wash (fly ash), turbine cleans, steam grade water production wastewaters, plant area storm water runoff, ash weir overflow, plant floor drains, and boiler chemical cleans.
- All Main and Emergency Settling Ponds were designed by and constructed under the supervision of a professional engineer.
- The Main or Emergency Settling Ponds are not presently inspected or monitored by a professional engineer.

Alliant Energy's March 18, 2009 response to EPA's Request for Information and other provided documentation, as well as recent communications with Alliant Energy personnel, provided the following additional information that is specific to each ash pond. Current descriptive information resulting from the site visit, as well as photographic references, are provided in Section 2 of this Assessment Report.

1.4.1 Main Ash Settling Area

The Main Ash Settling Area is located approximately 0.5 miles northwest of the main facility buildings and Emergency Ash Settling Ponds. This area was commissioned in 1965 as a single pond and received sluiced CCW from the facility. Discharge from the original pond was by gravity flow to Mill Creek through a discharge structure located on the north berm perimeter. As illustrated on Figure 5, the original berm was designed to have a crest width of 10 feet and an embankment height of 11 feet.

In 2002, dewatered ash in the pond was dredged to create the interior two pond system that currently exists. CCW from the facility is sluiced into the eastern corner of Main Ash Primary Settling Pond through a 10-inch pipeline. Decant from the Primary Pond flows by gravity to the Main Ash Secondary Settling Pond, entering into its west corner. Flow is discharged from the Secondary Pond by pump to permitted NPDES outfall 003 or to the plant facility for beneficial reuse. Table 2 provides a summary of surface area, height, storage capacity, and stored material volumes for these ponds.

1.4.2 Emergency Ash Settling Area

The Emergency Ash Settling Area, also commissioned in 1965, is located directly adjacent to the main facility buildings and the coal pile. It was necessary to enlarge the coal pile in 2001, which in turn required modification of the Emergency Settling Ponds. Figure 6 illustrates the

layout of the ponds prior to 2001 and the modified layout that currently exists. Discharge from the original pond was by gravity to Mill Creek through a discharge structure located on the north embankment of the Emergency Ash Secondary Settling Pond. The northern embankment of the Secondary Pond is diked, all other perimeter locations are incised. Flow discharges from the Primary Pond into the Secondary Pond by gravity through a culvert pipe located in the berm that separates the two ponds. Discharge from the Secondary Pond is by pump to permitted NPDES outfall 004. Table 2 provides a summary of surface area, height, storage capacity and stored material volumes for these ponds.

Table 2. Ash Settling Pond Size and Storage Data

Area	Surface Area (acre)	Maximum Height of Management Unit (feet)	Storage Capacity (cubic yards)	Store Material Volume (cubic yards)
Main Ash Settling Ponds				
Primary	6.9	25	167,000*	66,7001*
Secondary	2.3	10	37,000*	14,800*
Emergency Ash Settling Ponds				
Primary	0.74	2	4,770**	1,190***
Secondary	0.54	10	3,460**	865***

*Measured in 2006.

**Measured in 2000.

***Measured in May 2009.

1.5 Previously Identified Safety Issues

Discussions with plant personnel and review of provided documentation indicate that there are no current or previously identified safety issues from the previous 5 years at the M.L. Kapp Power Station.

1.6 Site Geology

The M.L. Kapp Power Station is located at the interface of the lowan Surface geologic formation and the Mississippi Alluvial Plain formation. These two formations consist of alluvial deposits of silt, clays, sands and gravels. The underlying bedrock of Clinton County is Niagara Limestone and dolomite of the Silurian System. The limestone's chemical composition is a carbonate of lime and magnesium, with a small amount of silica and alumina, colored yellow by the hydrated oxide of iron. Most of the surface rock is a porous, disintegrated limestone with frequent pockets of crystals of dolomite. Ledges at greater depths are apt to be more fine-grained and compact.

1.7 Inventory of Provided Materials

Alliant Energy provided several documents to AMEC that pertained to the design and operation of the M.L. Kapp Power Station. These documents were used in the preparation of this report and are listed in Appendix C, Inventory of Provided Materials.

2.0 FIELD ASSESSMENT

2.1 Visual Observations

AMEC performed visual assessments of M.L. Kapp's Ash Ponds, including the Main Primary and Secondary and Emergency Primary and Secondary, on October 27, 2010. Assessment of the ash ponds was completed in general accordance with FEMA's *Federal Guidelines for Dam Safety, Hazard Potential Classification System for Dams*, April 2004. The EPA Coal Combustion Dam Inspection Checklist and Coal Combustion Waste (CCW) Impoundment Inspection Form were completed for each ash pond during the site visit and provided to EPA via email within five business days following the site visit. Appendix A contains copies of the completed checklist forms. A Photo Location Map (B-1), as well as descriptive photos, can be found in Appendix B. Rainfall data for the Clinton, Iowa area was collected for thirty days prior to the site visit. Table 3, below, summarizes the rainfall data for the days and month immediately preceding AMEC's site visit.

Table 3. M.L. Kapp Rainfall Data

Rainfall Prior to Site Visit	
Date	Rainfall (in.)
October 19, 2010	0.00
October 20, 2010	0.00
October 21, 2010	0.00
October 22, 2010	0.00
October 23, 2010	0.49
October 24, 2010	0.24
October 25, 2010	0.00
October 26, 2010	0.79
October 27, 2010	0.00
Total (9 days prior to visit)	1.52
October Rainfall	1.52
Total (30 days prior to visit)	1.52

2.2 Visual Observations - Emergency Ash Primary and Secondary Settling Ponds

The Emergency Ash Primary and Secondary Ponds are located within the fenced facility building area and adjacent to the coal pile (Photo EP-2). Land use for the area outside of the fenced facility is primarily industrial and includes a sewage treatment plant that is located northeast of these ponds, directly across Mill Creek. Bottom ash and other CCW material enter the Emergency Primary Pond on its west boundary (Photo EP-3). A storm drain pipe, located

on the southeast portion of the pond edge, provides a path for runoff from the coal pile to enter the pond (EP-4).

2.2.1 Emergency Ash Primary and Secondary Settling Ponds - Embankments and Crest

Emergency Primary Pond

This pond is incised and contains an internal dike on its northeast side that separates it from the Emergency Secondary Pond (EP-5). Upstream slopes are fairly evenly graded and covered by riprap in some locations (Photo EP-5); however, other locations are unevenly graded with a weedy, unmaintained grass cover (Photos EP-1, EP-3, and EP-4). The crest of the dividing dike is soil covered and has an approximate width of 15 feet (Photo EP-5).

Emergency Secondary Pond

The internal divider dike that separates the Primary and Secondary Ponds is located on the Secondary Pond's southwest side (EP-5). The crest of this pond has an approximate width of 15 feet and is primarily soil covered. As with the Primary Pond, the upstream embankment faces in the Secondary Pond are sometimes fairly evenly graded and covered with riprap (Photo EP-10) or, are steep and unevenly graded with sparse grass cover (Photos EP-6 and EP-7). The Secondary Pond is incised on its northwest and southeast sides; however, an approximately 10 to 12 foot embankment exists on its northeast side. The downstream embankment face was noted to be covered in overgrown, weedy vegetation and to contain animal burrows (Photos EP-11, EP-12, EP-13, and EP-15). The land at the downstream embankment toe is the floodplain for Mill Creek and the Mississippi River.

2.2.2 Emergency Ash Primary and Secondary Settling Ponds - Outlet Control Structures

Emergency Primary Pond

The Emergency Primary Pond discharges flow to the Emergency Secondary Pond by gravity through a connector pipe located in the internal divider dike (Photos EP-5 and EP-6).

Emergency Secondary Pond

Flow is discharged from the Emergency Secondary Pond by pump (Photos EP-7 and EP-9) to a permitted NPDES outfall. Originally, flow from this pond was discharged by gravity through a now abandoned box weir structure located in the northeast embankment wall (Photos EP-8, EP-10, and EP-14).

2.3 Visual Observations - Main Primary and Secondary Ash Ponds

The Main Ash Settling Pond area is located approximately 0.4 miles to the northwest of the main facility building and the Emergency Ash Settling Ponds. The Main Pond area is bordered by roadway along its western and southern perimeter and by Mill Creek floodplain land to its north and east.

The existing two pond series system in the Main Ash Settling Pond area was originally constructed as a single settling pond. In 2002, the two ponds were created within the boundary of the original pond through dredging operations that utilized in-place, dried CCW material to form new internal divider and perimeter embankments. The resulting two ponds are smaller

than the original single pond. Figure 2, the Aerial Site Plan, illustrates the extent of the current two pond configuration, as well as the location of the existing, original embankment.

Sluiced bottom ash from the plant facility enters the southeast corner of the Main Primary Pond via approximately 1,750 feet of 10-inch pipe from the plant facility (Photos MP-3, MP-4, and M-10).

2.3.1 Main Primary and Secondary Ash Ponds - Embankments and Crest

There is a sizeable amount of dredged and stacked ash throughout the areas outside the ponds. Grass and natural ground cover exists in most areas outside the ponds. The dividing dike located between the ash ponds is not grass covered and appears to be dried CCW material (Photo MP-7 and MP-11). Upstream embankments of both the Primary and Secondary Ponds, having been created from dredged ash, vary somewhat in slope, and are not uniformly covered by grass, and feature bushy type vegetation in places (Photos MP-2, MP-6, MP-9, and MP-11).

The original pond embankment remains in-place; however, it does not directly support the ash ponds since the ponds themselves are situated well inside this original embankment. The narrowest distance between a pond boundary and the original downstream embankment face appears to be at the Secondary Pond discharge pump house, which is located at the eastern end of the pond. The original embankment has not been maintained and is covered in trees and vegetation (MP-15 through MP-18). An animal burrow was noted at the top of the northeastern embankment (Photo MP-14).

2.3.2 Main Primary and Secondary Ash Ponds - Outlet Control Structures

Flow is discharged from the northwest corner Primary Pond into the southwest corner of the Secondary Pond through a drop inlet (Photos MP-5 and MP-8)). The drop inlet was noted to be adjustable using extension pieces located nearby (Photo MP-7). The southwest corner of the Secondary Pond, where flow from the Primary Pond enters, was overgrown with grass and weeds and did not appear to have been active in some time (Photo MP-8).

The original, abandoned, single pond configuration outlet structure, a gravity flow weir box, is located on the western portion of the original, northern embankment. The discharge piping is located through the embankment and daylights at the downstream embankment toe, in the Mill Creek floodplain (Photos M-12 and M-13).

2.4 Monitoring Instrumentation

There is no geotechnical or groundwater monitoring instrumentation located at the M.L. Kapp Power Station.

3.0 DATA EVALUATION

3.1 Design Assumptions

AMEC has reviewed provided documentation related to design assumptions regarding both hydraulic adequacy and dike stability. However, some design assumptions were not available in the documentation, and have been listed as not provided where necessary.

3.2 Hydrologic and Hydraulic Design

3.2.1 Long Term Hydrologic Design Criteria

The Mine Safety and Health Administration provides minimum hydrologic criteria relevant to CCW impoundments in Impoundment Design Guidelines of the Mining Safety and Health Administration (MSHA) Coal Mine Impoundment Inspection and Plan Review Handbook (Number PH07-01) published by the U.S. Department of Labor, Mine Safety and Health Administration, Coal Mine Safety and Health, October 2007.

When detailing impoundment design storm criteria, MSHA states that dams need “to be able to safely accommodate the inflow from a storm event that is appropriate for the size of the impoundment and the hazard potential in the event of failure of the dam.” Additionally, MSHA notes that sufficient freeboard, adequate factors of safety for embankment stability, and the prevention of significant erosion to discharge facilities, are all design elements that are required for dam structures under their review. Additional impoundment and design storm criteria are as shown in Table 4, MSHA Minimum Long Term Hydrologic Design Criteria.

Table 4. MSHA* Minimum Long Term Hydrologic Design Criteria

Hazard Potential	Impoundment Size	
	< 1000 acre-feet < 40 feet deep	≥ 1000 acre-feet ≥ 40 feet deep
Low - Impoundments located where failure of the dam would result in no probable loss of human life and low economic and/or environmental losses.	100 - year rainfall**	½ PMF
Significant/Moderate - Impoundments located where failure of the dam would result in no probably loss of human life but can cause economic loss, environmental damage, or disruption of lifeline facilities.	½ PMF	PMF
High - Facilities located where failure of the dam will probably cause loss of human life.	PMF	PMF

*Mining Safety and Health Administration (MSHA) Coal Mine Impoundment Inspection and Plan Review Handbook (Number PH07-01) published by the U.S. Department of Labor, Mine Safety and Health Administration, Coal Mine Safety and Health, October 2007

**Per MSHA, the 24-hour duration shall be used with the 100-year frequency rainfall.

The definition of design freeboard, according to the MSHA Guidelines, is “the vertical distance between the lowest point on the crest of the embankment and the maximum water surface elevation resulting from the design storm.” Additionally, the Handbook states that “Sufficient documentation should be provided in impoundment plans to verify the adequacy of the

freeboard.” Recommended items to consider when determining freeboard include “potential wave run-up on the upstream slope, ability of the embankment to resist erosion, and potential for embankment foundation settlement.” Lastly, the Handbook states, “Without documentation, and absent unusual conditions, a minimum freeboard of 3 feet is generally accepted for impoundments with a fetch of less than 1 mile.”

The CCW impoundments at the M.L. Kapp Power Station fall within the smallest storm event designation category on Table 4. Using MSHA long term hydrologic criteria, design for the 100-year, 24-hour rainfall event would be recommended.

3.2.2 Hydrologic Design Criteria - Main Ash Settling Ponds

AMEC was provided with a draft *Original Ash Settling Basin Drainage and Capacity* hydrologic design summary (2010 Drainage and Capacity Summary). This draft Summary, which included calculations, was completed by Sargent & Lundy, L.L.C. for Alliant Energy and was dated November 12, 2010. The “Original Ash Settling Basin” refers to what is currently called the Main Ash Settling Pond area.

Design input included:

- A current topographical map of the Main Ash Settling Pond area, completed in November 2010 by Hinkle Engineering and Surveying L.L.C.;
- The current topographical map was utilized by Sargent & Lundy to delineate surface areas that are tributary to the Primary and Secondary Ponds in the Main Ash Settling Pond area;
- A 100-year, 24-hour storm event rainfall of 6.25 inches was used in the runoff calculations. The chosen rainfall amount was based on maps of the area provided in the Precipitation Frequency Atlas of the United States, National Oceanic and Atmospheric Administration (NOAA), Atlas 14, Volume 2, Version 3;
- Runoff volumes were calculations using the Soil Conservation Service (SCS) curve number method from Technical Release 55 (TR55); and,
- Discharge from the Secondary Pond is achieved by pump. Three, 550 gallon per minute (gpm) pumps are located in the pump house on the Pond’s eastern boundary.

Design assumptions included:

- Two of the three Secondary Pond discharge pumps (rated at 550 gpm each) are sufficient to discharge flow at a rate higher than that of incoming sluiced CCW materials; and,
- Based on pumping capacity, the typical operating water surface elevation in the Secondary Pond does not exceed elevation 585.00 feet;

The total area inside the original Ash Settling area was noted to be 28.4 acres. However, only 18.4 acres of that total acreage currently drains into the Primary and Secondary Ponds. That area was further subdivided and assigned differing runoff curve numbers based on hydrologic soil groups that included:

- Gravel surface of main dike - CN = 90;
- Pond water surface - CN = 100; and,
- Ash and poorly vegetated areas - CN = 85.

As outlined in the SCS curve number method found in TR55, the maximum retention, S, in inches, as well as the runoff depth, D, in inches were calculated. The calculated runoff depth was applied to the surface area tributary to the Secondary Pond and a resulting water surface elevation was determined. Table 5, as presented in the 2010 Drainage and Capacity Summary, provides a summary of the hydrologic calculations.

Table 5. Summary of 2010 Main Settling Pond Area Hydrologic Calculations

Description	Value
Drainage Area, including pond area, A (acre)	18.39
100-year, 24-hour Rainfall (inch)	6.25
Potential Maximum Retention, S (inch)	1.1
Runoff Depth, D (inch)	5.1
Runoff Volume = A x D/12 (acre-feet)	7.82
Pond Capacity* (acre-feet)	8.66
*Note: Discharge pond connected with pump house (Secondary Pond) is assumed pumping the incoming waste water at elevation 585.00 feet. The storage volume for storm water is considered above elevation 585.50 feet (surface area 2.12 acre) to 589.00 feet (surface area 2.83 acre). Secondary Pond capacity = (2.12+2.83)/2 x (589.00 feet-585.50 feet)=8.66 acre-feet.	

Sargent & Lundy further determined that a runoff volume of 7.82 acre-feet would produce a water surface elevation of 588.66 feet in the Secondary Pond, just 0.38 feet below the lowest surveyed crest elevation of 589.04 feet. It was noted that it would be necessary for the additional pump to operate and, at 550 gpm, a total of 3.2 days would be required to evacuate the volume of stormwater runoff (7.82 acre-feet) from the pond.

The fact that the Secondary Pond could contain the stormwater runoff volume was noted. However, it was recognized that the resulting freeboard of 0.38 feet was not consistent with appropriate minimum design conditions. Sargent & Lundy provided the following two recommendations to increase the resulting freeboard.

- Raise the dike height to approximate elevation 590 feet (1 foot above existing), or
- Increase the Secondary Ponds available storage area by connecting the Secondary Pond area to the lower lying area to its north. Earthwork would be required for this option, but the survey indicated the low lying area totals approximately 4.1 acres.

Another concern was noted in the draft *Original Ash Settling Basin Drainage and Capacity* hydrologic design summary. Sargent & Lundy reported that an area of exposed ash exists south of the Secondary Pond that is higher than the original embankment crest height. Stormwater carrying this ash drains out of the containment area and into a swale, located along the southern and western site boundary that drains into Mill Creek. Recommendations to keep the ash within the embankment boundary were provided that included “providing permanent stabilized surfacing for the area, raising the perimeter dike, or redirecting the drainage to the [Secondary] Pond.”

Sargent and Lundy noted that both the stormwater storage capacity and elevated exposed ash issues require more investigation.

AMEC believes the hydrologic methodology and calculations presented by Sargent & Lundy are acceptable. However, it was not clear what portion of the runoff would impact the Main Primary Settling Pond and what volume, if any, that pond could provide in balancing the storage requirement using the detention time available within that pond. A hydraulic evaluation of the entire pond system, namely the Primary Pond, Secondary Pond, and discharge pumps, should be completed to evaluate the minimum freeboard available during the storm event. The evaluation may show that the Primary Pond provides storage volume and detention time such that the peak runoff affecting the Secondary Pond has passed, allowing the Secondary Pond to process runoff from the Primary Pond while maintaining an acceptable freeboard depth.

AMEC is in agreement with Sargent & Lundy that both the stormwater storage capacity and elevated exposed ash issues require more investigation.

3.2.3 Hydrologic Design Criteria - Emergency Ash Ponds

Hydrologic and hydraulic criteria were not provided for the Emergency Ash Settling Ponds.

3.3 Structural Adequacy & Stability

Two well regarded sources for embankment design and evaluation criteria include The United States Army Corps of Engineers (USACE) and the United States Mine Safety and Health Administration (MSHA). Minimum recommended factors of safety for different loading conditions can be found in those agency publications, as shown in Table 6 below.

Table 6. Minimum Stability Factors of Safety

Loading Condition	MSHA ¹	USACE ²
Rapid Drawdown	1.3	1.1 ³ - 1.3 ⁴
Long-Term Steady Seepage	1.5	1.5
Earthquake Loading	1.2	--- ⁵

¹ Coal Mine Impoundment Inspection and Plan Review Handbook, 2007, US Mine Safety and Health Administration

² Slope Stability Publication, EM1110-2-1902, 2003, US Army Corps of Engineers, Table 3-1: New Earth and Rock-Fill Dams

³ Applies to drawdown from maximum surcharge pool

⁴ Applies to drawdown from maximum storage pool

⁵ Referred to USACE Engineer Circular "Dynamic Analysis of Embankment Dams" document that is still in preparation

To consider the structural adequacy and stability of the ash ponds at the M.L Kapp Power Station, AMEC reviewed stability analysis material provided by Westar Energy with respect to the load cases shown in Table 6. Factors of safety documented in the provided material were compared with those factors outlined in the table to help determine whether the impoundments meet the requirements for acceptable stability.

AMEC reviewed the November 11, 2010 report entitled *Slope Stability Analyses - Ash Settling Pond* prepared by Sargent & Lundy for the M.L. Kapp Power Station prepared for Interstate Power and Light (Alliant Energy). The recently completed stability analyses are summarized in Section 3.3.1 and 3.3.2. The Sargent & Lundy analysis included the existing Main Ash Pond dike, which is within the Original Ash Settling Basin, and the Emergency Ash Pond dike. The report presented a summary of guidance documents and data that were reviewed, the geotechnical exploration that was performed by Huntingdon Engineering & Environmental, Inc, as well as the results of the structural stability analyses that were completed for two cross sections (one for each pond). It was noted that the study was not complete and a final report

with analyses would be submitted at later time. Factors of safety documented in the provided material were compared with those factors outlined in the table to help determine whether the impoundments meet the requirements for acceptable stability.

Sargent & Lundy evaluated the overall stability of the dams by reviewing cross sections and previously collected drilling data for their study, as shown on Figure 7. Sargent & Lundy notes the cross sections selected for analysis “were estimated to present the most critical stability conditions for dike stability around the ponds”. The slope stability analyses were performed using SLOPE/W program version 5.211. Minimum acceptable factor of safety (FS) values for the static, seismic and the rapid drawdown conditions analyzed in this calculation were 1.5, 1.15 and 1.1 to 1.3, respectively. Sargent & Lundy stated in their report:

Since the original Ash Settling Basin has been filled with ash, the interior slope of the perimeter dike is not exposed and there is no potential for rapid drawdown condition to affect the overall stability of the interior slope. Also, since the top width of the Main Ash Pond dike (within the original Ash Settling Basin) is more than 65 feet, there is no potential for a rapid drawdown within the Main ash Pond to affect the overall stability of the interior slope of the original Settling Basin and allow materials to disperse outside the limits of the original Ash Settling Basin.”

Therefore, Sargent & Lundy’s slope stability analyses included static and seismic (pseudo-static) conditions only for the downstream (exterior) dike face for the Main Ash Pond, and the study included static and seismic (pseudo-static) conditions for the downstream dike face and rapid drawdown condition for the interior face for the Emergency Ash Pond. For their study, Sargent & Lundy utilized the soil borings, B-1 and B-2 performed in 1994 by Huntingdon Engineering & Environmental, located adjacent to the Emergency Ash Pond and Main Ash Pond dikes, respectively. Table 7 and Table 8 provide a summary of the soil properties utilized in Sargent & Lundy’s report. We understand the two borings utilized by Sargent & Lundy for the basis of their slope stability analyses were drilled adjacent to the existing dikes; therefore, we understand the information utilized for the dike material was based on available construction documents.

Table 7. Soil Properties for Emergency Ash Pond (Boring B-1)

Material	Unit Weight γ (lb/ft ³)	Friction Angle, σ' (Degrees)	Cohesion, c' (lb/ft ²)
Consolidated Ash Fill	100	25	0
Dike Fill (Cohesive)	125	25	250
Clayey Silt	120	28	50
Silty Lean Clay	125	24	150
Bedrock	160	0	10,000

Table 8. Soil Properties for Main Ash Pond (Boring B-2)

Material	Unit Weight γ (lb/ft ³)	Friction Angle, σ' (Degrees)	Cohesion, c' (lb/ft ²)
Sluiced Ash	90	15	0
Consolidated Ash Fill	100	25	0
Dike Fill (Cohesive)	125	25	250
Clayey Silt	120	28	50
Silty Lean Clay (1)	125	24	150
Silty Lean Clay (2)	125	25	150
Silty Lean Clay (3)	125	20	150
Sand	110	26	0

3.3.1 MAIN ASH POND - Structural Adequacy & Stability

Static Analysis - Main Ash Pond

The Main Ash Pond was analyzed for static and seismic conditions utilizing soil strengths estimated from the single boring located in this area (Boring B-2). We have not been provided with laboratory data from this boring; therefore, we have assumed the soil parameters utilized were based on published correlations. Sargent & Lundy provided, as Figure 2 of their report, the cross-section which outlines their estimated soil profiles along with their corresponding soil parameters. The cross-section utilized for the Main Ash Pond has a top of dike elevation of 592 feet with a top of Main Ash Pond elevation of 600.5 feet (approximately 8.5 feet above the Main Ash Pond dike. In their analysis, a surcharge load of 1,000 pounds per square foot (psf) was considered. Their report stated that the surcharge load was to represent the weight of the equipment that operates in this area to remove the ash and the stockpiled load of the ash prior to be transported to a different location. Their analysis also included the phreatic surface within the consolidated ash. This surface was shown to begin at elevation 596 feet, drop to elevation 585 feet within the existing ash fill, and then drop again through the perimeter dike to elevation 580 feet. The latter elevation corresponds to the elevation of the water in the existing exterior ditch.

Sargent & Lundy's stability analyses indicated a factor of safety of 1.707 for the exterior face of the perimeter dike.

Seismic Analysis - Main Ash Pond

The seismic analysis was performed utilizing a horizontal load coefficient of 2 percent of gravity for the dike and ash fill materials as well as the subsoil layers. Sargent & Lundy chose to evaluate the seismic conditions in a pseudo-static condition and their report stated:

This value represents the lateral force generated during an earthquake on the dike as a fraction of the weight of the material in the cross-section analyzed, and is assumed to act at the same intensity during the earthquake (i.e., pseudo-static condition). In pseudo-static analyses, typically $\frac{2}{3}$ to $\frac{3}{4}$ of the peak acceleration is applied to the soil mass as an average value during earthquake since the acceleration history during an earthquake goes through a large number of acceleration cycles, all but one less than the peak acceleration. However, bedrock motions can also amplify, attenuate, or remain approximately at the same levels as the earthquake waves travel upward from the rock toward the soil surface. Recognizing the potential for some amplification through the in-situ

soils, the peak bedrock acceleration obtained from the above references was conservatively applied at the soil surface without any reduction.

'Effective Stress' strength parameters for the dike material and the in-situ soils were used in the analysis. . . since the earthquake acceleration levels for the site are very small and will not be capable of generating any significant excess porewater pressures (beyond hydrostatic pressure) within the portion the dike below the phreatic surface which would cause a reduction in the soil strength during an earthquake.

Sargent & Lundy's report indicated the factor of safety obtained during their pseudo-static conditions for the downstream face of the dike to be 1.623. The calculated factors of safety for the critical cross section for the Main Ash Pond are shown in Table 9.

Table 9. Factors of Safety for Main Ash Pond at Critical Section

Analysis	Factors of Safety	
	Long Term	Earthquake Loading
Required Minimum Safety Factor	1.5 ¹	1.2 ¹
Existing Condition	1.707	1.623

¹ Based on the MSHA guidelines, Coal Mine Impoundment Inspection and Plan Review Handbook, 2007, US Mine Safety and Health Administration

The required minimum safety factor for earthquake loading is 1.2 per Coal Mine Impoundment Inspection and Plan Review Handbook, 2007, US Mine Safety and Health Administration; however, Sargent & Lundy set their required minimum safety factor for earthquake loading at 1.15. Minimum factors of safety were again included in the table by Sargent & Lundy for comparative purposes. Factors of safety for the critical section were determined to be greater than MSHA specified minimums, therefore the structural integrity of the dam was considered to be satisfactory.

3.3.2 Emergency Ash Pond - Structural Adequacy & Stability

Static Analysis - Emergency Ash Pond

The Main Ash Pond was analyzed for static and seismic conditions utilizing soil strengths estimated from the single boring located in this area (Boring B-1). We have not been provided with laboratory data from this boring; therefore, we have assumed the soil parameters utilized were based on either empirical data or published correlations. Sargent & Lundy provided, as Figure 5 of their report, the cross-section which outlines their estimated soil profiles along with their corresponding soil parameters. The cross-section utilized for the Emergency Ash Pond has a top of dike elevation of 590 feet and their report noted the top of the berm (dike) was designed to be 10 feet in width; however, during their site examination of October 28, 2010 the width of the dike appeared to be 25 feet in width. Sargent & Lundy estimated that approximately 15 feet of ash fill has been placed adjacent to the existing interior face of the dike thereby extending the existing dike width from 10 to 25 feet. Sargent & Lundy noted in their report that, with the exception of the ash located adjacent to the interior face of the dike, the remainder of the pond is full of water. Sargent & Lundy also noted that no seepage was observed during their October 28, 2010 site visit; therefore, they assumed the phreatic surface was configured during their analysis to be contained within the body of the dike.

Sargent & Lundy's stability analyses indicated a factor of safety of 1.861 for the exterior (downstream) face of the perimeter dike; and, they also noted the ash berm located on the interior face of the dike had no effect on the dike's exterior face stability.

Seismic Analysis - Emergency Ash Pond

The November 11, 2010 report does not outline the parameters utilized for the seismic (pseudo-static) analysis of the Emergency Ash Pond; however, AMEC has assumed the parameter were similar to those utilized in the Main Ash Pond (i.e., a horizontal load coefficient of 2 percent of gravity for the dike and ash fill materials as well as the subsoil layers, effective stress strength parameters for the soil, etc.). Sargent & Lundy's report and its corresponding Figure 6 indicated the factor of safety for the downstream face of the dike to be 1.768.

Rapid Drawdown Analysis - Emergency Ash Pond

Given the current CCW storage configuration of the Main Ash Pond, rapid drawdown at that location was not considered as a possibility. Rapid drawdown analysis was performed only for the Emergency Ash Pond. Sargent & Lundy stated in their report,

A rapid lowering of the water level inside the pond due to controlled or uncontrolled operational conditions may create potential instability for the interior slope of the dike. The basic mechanism that causes the instability condition is the loss of support from the hydrostatic pressure from water against the interior slope whereas the porewater pressures within the body of the dike cannot dissipate rapidly by drainage due to limited hydraulic conductivity of the dike material. The net result is increased weight of the soil (no longer buoyant, but still saturated) creating an increased downward pull of the dike materials whereas the shear strength of the soil remains essentially unchanged due to lack of drainage within the dike. This causes a reduction in the slope FS relative to the full pond condition.

Under normal conditions, the pond water levels are generally stable due to the controlled discharge through a pump structure. A very fast drop in the pond water levels, in all likelihood, would be a result of a dike failure under static or earthquake condition. During rapid drawdown, the phreatic surface within the dike will gradually drop, and the time-rate of this drop will be a function of the hydraulic conductivity of the dike material. In rapid drawdown analyses, the phreatic surface is conservatively assumed to remain constant within the dike. The purpose of the rapid drawdown analyses is to investigate the potential for additional dike failures caused by such drops in the pond water levels.

It is likely that the ash placed along the interior slope of the dike will drain partially as the water level within the pond drops during the rapid drawdown. This drainage should increase the stability of the ash as well as the dike. However, the extent of the internal drainage that takes place during the drawdown is difficult to estimate (permeability of the ash and the time-rate of drop in the water level will be required), and therefore, no drainage condition is conservatively considered within the ash as well as the dike fill.

Sargent & Lundy's analyses included the 15-foot wide ash berm (as previously described in Section 3.3.1 *Static Analysis - Emergency Ash Pond*) located on the interior face of the 10-foot dike. The report indicated the factor of safety for this ash berm to be less than 1.0; thereby indicating the ash berm will likely result in a sliding instability in the event in a rapid drawdown.

However, their report noted that the instability is not likely to affect the main body of the dike, and the factor of safety for a rapid drawdown condition for the Emergency Ash Pond was indicated to be 1.576.

The calculated factors of safety for the critical cross section for the Emergency Ash Pond are summarized in Table 10.

Table 10. Factors of Safety for Emergency Ash Pond at Critical Section

Analysis	Factors of Safety		
	Long Term	Earthquake Loading	Rapid Drawdown
Required Minimum Safety Factor	1.5 ¹	1.2 ¹	1.3 ¹
Existing Condition	1.861	1.768	1.576

¹ Based on the MSHA guidelines, Coal Mine Impoundment Inspection and Plan Review Handbook, 2007, US Mine Safety and Health Administration

The required minimum safety factor for earthquake loading is 1.2 per Coal Mine Impoundment Inspection and Plan Review Handbook, 2007, US Mine Safety and Health Administration; however, Sargent & Lundy set their required minimum safety factor for earthquake loading at 1.15. Minimum factors of safety, were again included in the table by Sargent & Lundy for comparative purposes. Factors of safety for the critical section were determined to be greater than MSHA specified minimums, therefore the structural integrity of the dam was considered to be satisfactory.

Sargent & Lundy noted that based on their results, for the present conditions, the perimeter dikes around the Main Ash Pond, Original Ash Pond, and the Emergency Ash Pond meet the minimum FS requirements and are considered stable.

3.4 Foundation Conditions

Documentation was provided that describes the results of borings that were advanced into downstream embankment locations at both the Main Ash Settling Pond area and the Emergency Ash Settling Pond area. These two borings were completed by Huntingdon Engineering & Environmental on August 5, 1994 and described in a Geotechnical Exploration Test Boring Logs summary letter, dated August 9, 1994.

Boring B-1 was advanced into the northwestern downstream embankment toe of the Emergency Ash Settling Pond area. Boring B-2 was advanced into the eastern downstream embankment toe of the Main Ash Settling Pond area. Foundation soils encountered at these locations are as shown in Table 11.

Table 11. Emergency and Main Ash Settling Area Foundation Soils

Soil Description	Depth Range (feet)	Soil Description	Depth Range (feet)
Emergency Ash Settling Pond Area		Main Ash Settling Pond Area	
FINE-TO-COURSE SANDY CLAYEY SILT with some gravel, medium gray, medium stiff to rather stiff, moist (ML) - POSSIBLE FILL	0 - 4	CLAYEY SILT with fine gravel, dark gray, medium stiff (ML) -FILL	0 - 1
LEAN CLAY, medium reddish brown, medium stiff, moist (CL)	4 - 7	CLAYEY SILT, dark gray, medium stiff, with a trace of organics, moist (ML) - ALLUVIUM	1 - 5
SILTY LEAN CLAY, medium to dark brownish gray, medium stiff, moist (CL) - ALLUVIUM	7 - 13	SILTY LEAN CLAY, dark gray, medium stiff, moist (CL) - ALLUVIUM	5 - 7 ½
LEAN CLAY, mottled light gray and reddish brown, medium stiff, wet - ALLUVIUM	13 - 22 ½	SILTY LEAN CLAY, medium grayish brown, rather stiff, moist (CL) - ALLUVIUM	7 ½ - 10
AUGER REFUSAL @ 22 ½ FT Weathered Rock		Same, dark gray	10 - 13 ½
		SILTY LEAN CLAY, medium grayish brown, soft to medium stiff, wet (CL) - ALLUVIUM	13 ½ - 18 ½
		Same, with some gravel, soft - ALLUVIUM	18 ½ - 23
		MEDIUM-TO-COARSE SAND, gray and brown, very loose, wet (SP) - ALLUVIUM	23 - 26
		No reported auger refusal	

3.5 Operations and Maintenance

3.5.1 Safety Assessments

Alliant Energy personnel performed and recorded surface pond visual inspections of the Main and Emergency Ash Settling Ponds in March 2009 and March 2010. Each inspection report includes information concerning dike integrity, specifically the presence of animal activity, seepage, erosion, trees/vegetation, ponding, leakage from valving or piping, or damage due to heavy equipment use. Outfall structures are also inspected for the presence of many of the same issues. The dike walls and discharge structures are also checked for the presence of any settled ash.

Visual inspections performed in 2009 noted the presence of trees on the berm of the Main and Emergency Settling Ash Ponds. The provided recommendation was to cut the trees down and trim the area.

Visual inspections performed in 2010 on the Emergency Settling Ash Ponds noted animal activity in the northern dike, and some soft soil and erosion issues. Resulting actions included contacting local animal trapping services and operations to add acceptable soil material to the berm area. Build up of settled ash was also noted in the Emergency Pond area and plans for

removal were reported. Visual inspections performed in 2010 on the Main Settling Ash Ponds noted the presence of weedy vegetation, as well as build up of settled ash. Recommendations were provided for removal of each.

3.5.2 Instrumentation

There is no geotechnical or groundwater monitoring instrumentation located at the M.L. Kapp Power Station.

3.5.3 State or Federal Inspections

No State or Federal inspections have taken place at the M.L. Kapp Power Station.

DRAFT

4.0 COMMENTS AND RECOMMENDATIONS

Condition assessment definitions, as accepted by the National Dam Safety Review Board, are as follows:

SATISFACTORY

No existing or potential dam safety deficiencies are recognized. Acceptable performance is expected under all loading conditions (static, hydrologic, seismic) in accordance with the applicable regulatory criteria or tolerable risk guidelines.

FAIR

No existing dam safety deficiencies are recognized for normal loading conditions. Rare or extreme hydrologic and/or seismic events may result in a dam safety deficiency. Risk may be in the range to take further action.

POOR

A dam safety deficiency is recognized for loading conditions which may realistically occur. Remedial action is necessary. POOR may also be used when uncertainties exist as to critical analysis parameters which identify a potential dam safety deficiency. Further investigations and studies are necessary.

UNSATISFACTORY

A dam safety deficiency is recognized that requires immediate or emergency remedial action for problem resolution.

NOT RATED

The dam has not been inspected, is not under state jurisdiction, or has been inspected but, for whatever reason, has not been rated.

4.1 Acknowledgement of Management Unit Conditions

I certify that the management units referenced hereinafter were personally assessed by me and was found to be in the following condition:

Main Ash (Primary and Secondary) Settling Ponds: Poor

Emergency Ash (Primary and Secondary) Settling Ponds: Poor

4.2 Recommendations

The management units above were rated poor due to lack of documentation; specifically,

- 1) Completion of the hydrologic and hydraulic study for the Main Ash Ponds,
- 2) Hydrologic and hydraulic information for the Emergency Ash Ponds, and
- 3) More complete stability analyses.

4.2.1 Hydrologic and Hydraulic

Main Ash Settling Ponds

Although hydrologic and hydraulic documentation was provided for the Main Settling Ash Ponds, the conclusions presented in the documentation indicated the Main Ash Secondary Pond could not provide sufficient freeboard for the 100-year, 24-hour storm event. The Main Ash Primary Settling Pond, although contributing runoff volume, did not appear to have been taken into account with respect to runoff volume detention. In Section 3.2.2, AMEC provided a recommendation regarding the completion of a hydraulic study utilizing the entire two pond system, before evaluating available freeboard. Whatever the outcome, the Main Ponds must be operated in such a way that an acceptable freeboard depth is available during the 100-year, 24-hour storm event.

Emergency Ash Settling Ponds

AMEC recommends that an appropriate design storm rainfall and freeboard depth in accordance with MSHA guidelines be applied to each impoundment's watershed to assess whether the dam and decant system can safely store, control, and discharge the design flow. Based on the size and rating for the Emergency Ponds, the MSHA recommended design storm would be the 100-year, 24-hour event. Hydraulic calculations should also be completed to determine the rate at which the discharge system could pass the design storm, if necessary, or draw down elevated water surfaces following such an event. The analysis should consider all critical stages over the life of the pond including full pond conditions.

4.2.2 Geotechnical and Stability Recommendations

In the opinion of the assessing professional engineer, the criteria for minimum safety factors should be in accordance with USACE EM 1110-2-1902 with a minimum seismic safety factor of 1.2 as recommended by 2007 *MSHA Coal Mine Impoundment Inspection and Plan Review Handbook*, page 88. Likewise, if the dam does not meet the above seismic factor of safety, then the stability of the embankment should be analyzed and the amount of embankment deformation or settlement that may occur should be evaluated to assure that sufficient section of the crest will remain intact to prevent a release from the impoundment.

A November 2010 report by Sargent & Lundy, titled *Slope Stability Analyses - Ash Settling Pond Dikes*, for the M.L. Kapp Generating Station presents stability analyses for Main Ash Pond and the Emergency Ash Pond. Two cross sections were analyzed for static, seismic (pseudo-static condition, and rapid drawdown (for Emergency Ash Pond only). The locations of the cross sections were selected to represent the "most critical" areas within the perimeter berms. Sargent & Lundy's report references two borings located "adjacent" to the existing dikes; however, laboratory data was not provided at the time of this report.

In the opinion of the assessing professional engineer, the analysis should consider all critical stages over the life of the pond including pond full conditions. These conditions would need to be determined in conjunction with the hydraulic recommendations above. The hydrologic and hydraulic analysis will provide maximum water levels in the pond and a phreatic surface through the embankment. A rapid-drawdown should be performed for downstream embankment in relation to flooding of the Mississippi River. Since Sargent & Lundy's borings did not penetrate the CCW material, and documentation pertaining to the CCW's degree of compaction is not known, the friction angle value used for the CCW in the analysis appears to be slightly high for

ash material (friction angle of 25 was utilized). Typical ash friction values are 28 degrees for compacted, 24 degrees for loosely compacted, and 11 degrees for uncompacted material. Consideration should be given for lowering strength values to account for inconsistencies within the fill or foundation materials. The analyses presented appear limited to a circular surface; different types of failure surfaces should be analyzed and optimized.

4.2.3 Inspection Recommendations

Annual visual inspections of each management unit should be performed by a Professional Engineer. Inspection reports should be maintained by the facility. Additionally, routine inspections (daily or weekly) performed by facility O&M personnel should be supported by an inspection checklist that could also serve as documentation of the inspection.

Vegetation on the impoundments should continue to be aggressively managed. We further recommend that vegetation be managed based on guidance in (a) Corps of Engineers EM 1110-2-301, *Guidelines for Landscape Planting and Vegetation Management at Floodwalls, Levees, and Embankment Dams* and (b) FEMA 534, *Technical Manual for Dam Owners: Impacts of Plants on Earthen Dams*. Additionally, animal impact should be mitigated based on guidance in FEMA 473, *Technical Manual for Dam Owners: Impacts of Animals on Earthen Dams*.



5.0 CLOSING

This report is prepared for the exclusive use of the Environmental Protection Agency for the site and criteria stipulated herein. This report does not address regulatory issues associated with storm water runoff, the identification and modification of regulated wetlands, or ground water recharge areas. Further, this report does not include review or analysis of environmental or regional geo-hydrologic aspects of the site, except as noted herein. Questions or interpretation regarding any portion of the report should be addressed directly by the geotechnical engineer.

Any use, reliance on, or decisions to be made based on this report by a third party are the responsibility of such third parties. AMEC accepts no responsibility for damages, if any, suffered by any third party as a result of decisions made or actions based on this report.

The conclusions and recommendations given in this report are based on visual observations, our partial knowledge of the history of Dolet Hills impoundments, and information provided to us by others. This report has been prepared in accordance with normally accepted geotechnical engineering practices. No other warranty is expressed or implied.

FIGURES



AMEC Earth & Environmental

800 Commonwealth Center
11003 Bluegrass Parkway
Louisville, Ky 40228
(502) 267-0700



CLIENT LOGO



CLIENT

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

PROJECT
ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

TITLE
ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON, IA
SITE LOCATION & VICINITY MAP

DWN BY: CAE

CHK'D BY: MOS

PROJECTION:

DATUR:

REV. NO.:


SCALE: AS SHOWN

DATE: 11/15/10

PROJECT NO.: 3-2108-0183.0002

FIGURE: 1

Legend
 Existing Original Embankment



UNITED STATES
 ENVIRONMENTAL PROTECTION AGENCY

DWN BY: DJC

CKD BY: MS

Datum: NAD 83

Projection: UTM 15

Scale: As Shown

ASSESSMENT OF DAM SAFETY OF
 COAL COMBUSTION SURFACE IMPOUNDMENTS

REV. No.: A

Date: 11-9-10

Project No: 3-2106-0183-0002

AMEC Earth & Environmental
 690 Commonwealth Business Center
 11003 Bluegrass Parkway
 Louisville, KY 40299




ALLIANT ENERGY
 ML KAPP POWER STATION, CLINTON, IA
 AERIAL SITE PLAN

Figure No: 2

Id	NAME	Longitude	Latitude
1	Camanche High School	-90.26235111	41.78753053
2	Camanche Elementary School	-90.25568432	41.79169716
3	Sodus School (historical)	-90.33596427	41.75642004
4	Church of the Visitation	-90.26262894	41.79447496
5	Immanuel Lutheran Church	-90.26235105	41.78419739
6	First Baptist Church	-90.25651754	41.7819752
7	Saint Marks United Methodist Church	-90.25457309	41.78253067
8	Camanche Public Library	-90.25707313	41.77919743
9	Camanche Historical Museum	-90.25873993	41.78586399
10	Camanche Fire Department	-90.25790661	41.78808613
11	Camanche Police Department	-90.25818443	41.78614182

Legend

-  School
-  Church
-  Public Building
-  Railroad




AMEC Earth & Environmental
690 Commonwealth Business Center
11003 Bluegrass Parkway
Louisville, KY 40299


UNITED STATES
ENVIRONMENTAL PROTECTION AGENCY



DRAWN BY: DJC
CHKD BY: MS
DATUM: NAD83
PROJECTION: UTM 15
SCALE: AS SHOWN
DATE: 11/9/2010

ASSESSMENT OF DAM SAFETY OF
COAL COMBUSTION SURFACE IMPOUNDMENTS


ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON, IA
CRITICAL INFRASTRUCTURE



0 1 Miles
0 1 Kilometers

Notes: Critical infrastructure data provided by ESRI

FIGURE
3



AMEC Earth & Environmental

800 Commonwealth Center
11000 Bluegrass Parkway
Louisville, Ky 40228
(502) 267-0700



CLIENT LOGO



CLIENT

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

PROJECT
ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

DWN BY: CAE

DATUR:

DATE: 11/15/10

TITLE
ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON, IA
TOPOGRAPHIC SITE MAP

CHKD BY: MOS




REV. NO.:

PROJECT NO: 3-2108-0183.0002

PROJECTION:

SCALE: AS SHOWN

FIGURE: 4



NOTE: THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH THE AMEC EARTH & ENVIRONMENTAL REPORT

CLIENT LOGO



CLIENT:

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

AMEC Earth & Environmental
 690 Commonwealth Center
 11009 Shagbush Parkway
 Louisville, KY 40259
 (502) 287-0700



DRAWN BY: CAE

CHECKED BY: MOS

DATE:

PROJECT:

SCALE: AS SHOWN

PROJECT: ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

TITLE: ALLIANT ENERGY

ML KAPP POWER STATION, CLINTON, IA


MAIN ASH SETTLING POND - ORIGINAL (1965) PLAN AND TYPICAL CROSS SECTIONS

DATE: 11/22/10

PROJECT NO: 3-2108-0183.0002

REV. NO: FIGURE NO: 5

**ORIGINAL CONFIGURATION
(PRE 2001)**



NOTE: THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH THE AMEC EARTH & ENVIRONMENTAL REPORT

CLIENT LOGO



CLIENT:

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

AMEC Earth & Environmental

680 Commonwealth Center
11003 Bluegrass Parkway
Louisville, KY 40299
(502) 267-0700



DWN BY:

CAE

PROJECT

ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

CHK'D BY:

MOS

DATE:

PROJECT NO:

3-2106-0183.0002

SCALE:

AS SHOWN

TITLE

**ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON, IA
EMERGENCY ASH SETTLING PONDS - ORIGINAL AND
CURRENT CONFIGURATION**

DATE:

11/29/30


REV. NO.:

3-2106-0183.0002

FIGURE NO.


6

EXISTING CONFIGURATION



NOTE:
FLOW PATH

SCALE: 1" = 100'



NOTE: THIS DRAWING SHOULD BE READ IN CONJUNCTION WITH THE AMEC EARTH & ENVIRONMENTAL REPORT

CLIENT LOGO



CLIENT:

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

AMEC Earth & Environmental

690 Commonwealth Center
11003 Bluegrass Parkway
Louisville, KY 40299
(502) 267-0700



DWN BY:

CAE

PROJECT

ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

CHK'D BY:

MOS

DATE:

TITLE

**ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON, IA
2010 STABILITY ANALYSES - ANALYZED SECTIONS**

DATE:

11/29/30

PROJECT NO.:

3-2106-0183.0002

REV. NO.:

7

FIGURE NO.:

7

APPENDICES

APPENDIX A
Waste Impoundment Inspection Forms



Site Name: M.L. Kapp	Date: October 27, 2010
Unit Name: Emergency Primary Ash Settling Pond	Operator's Name: Alliant Energy, Inc.
Unit I.D.:	Hazard Potential Classification: High Significant Low
Inspector's Name: Don Dotson/AMEC and Mary Sawitzki/AMEC	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	See note			18. Sloughing or bulging on slopes?			X
2. Pool elevation (operator records)?	Not provided			19. Major erosion or slope deterioration?			X
3. Decant inlet elevation (operator records)?	Not provided			20. Decant Pipes:			
4. Open channel spillway elevation (operator records)?	N/A			Is water entering inlet, but not exiting outlet?			X
5. Lowest dam crest elevation (operator records)?	590.0 ft			Is water exiting outlet, but not entering inlet?			X
6. If instrumentation is present, are readings recorded (operator records)?	N/A			Is water exiting outlet flowing clear?			No flow
7. Is the embankment currently under construction?		X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below): See Note			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	X			From underdrain?			
9. Trees growing on embankment? (If so, indicate largest diameter below)		X		At isolated points on embankment slopes?			
10. Cracks or scarps on crest?		X		At natural hillside in the embankment area?			
11. Is there significant settlement along the crest?		X		Over widespread areas?			
12. Are decant trashracks clear and in place?	N/A			From downstream foundation area?			
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X		"Boils" beneath stream or ponded water?			
14. Clogged spillways, groin or diversion ditches?	N/A			Around the outside of the decant pipe?			
15. Are spillway or ditch linings deteriorated?	N/A			22. Surface movements in valley bottom or on hillside?		N/A	
16. Are outlets of decant or underdrains blocked?		X		23. Water against downstream toe?		N/A	
17. Cracks or scarps on slopes?		X		24. Were Photos taken during the dam inspection?		X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

Inspection Issue #	Comments
1. Annually by Alliant Energy	
21. Pond is incised.	

US EPA ARCHIVE DOCUMENT



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # Iowa 2326103 Date October 27, 2010

INSPECTOR Don Dotson/Mary Sawitzki (AMEC)

Impoundment Name M.L. Kapp Emergency Primary Ash Settling Pond Impoundment Company Alliant Energy

EPA Region 7 State Agency (Field Office) Address

901 N. 5th Street Kansas City, KS 66101

Name of Impoundment M.L. Kapp Emergency Primary Ash Settling Pond (Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update

Is impoundment currently under construction? Yes No X
Is water or ccw currently being pumped into the impoundment? X

IMPOUNDMENT FUNCTION: Alternative receiving location for CCW and related materials.

Nearest Downstream Town : Name Camanche, IA

Distance from the impoundment approx. 2 miles

Impoundment


Location: Longitude -90 Degrees 13 Minutes 59.1 Seconds Latitude 41 Degrees 48 Minutes 32.5 Seconds State IA County Clinton

Does a state agency regulate this impoundment? YES NO X

If So Which State Agency?

US EPA ARCHIVE DOCUMENT

CONFIGURATION:



Cross-Valley
 Side-Hill
 Diked
 Incised (form completion optional)
 Combination Incised/Diked

Embankment Height 0-2 feet Embankment Material Sandy Clayey Silt
 Pool Area 0.74 acres Liner No
 Current Freeboard* 4-5 feet Liner Permeability N/A

*Water level lower during excavation


TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway


- Trapezoidal
- Triangular
- Rectangular
- Irregular

- depth
- bottom (or average) width
- top width
-


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR




 Outlet

- inside diameter

Material

- corrugated metal
- welded steel
- concrete
- plastic (hdpe, pvc, etc.)
- other (specify) _____



Is water flowing through the outlet? YES* X NO _____
*connection is open

 No Outlet

 X **Other Type of Outlet** (specify) 18" - 24" pipe into emergency secondary ash pond – emergency primary and secondary ponds are hydraulically connected.

The Impoundment was Designed By Sargent & Lundy



Site Name: M.L. Kapp	Date: October 27, 2010
Unit Name: Emergency Secondary Ash Settling Pond Operator's Name: Alliant Energy, Inc.	
Unit I.D.:	Hazard Potential Classification: High Significant Low
Inspector's Name: Don Dotson/AMEC and Mary Sawitzki/AMEC	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	See note			18. Sloughing or bulging on slopes?	See Note		
2. Pool elevation (operator records)?	Not provided			19. Major erosion or slope deterioration? See Note	X		
3. Decant inlet elevation (operator records)?	Not provided			20. Decant Pipes: See Note			
4. Open channel spillway elevation (operator records)?	N/A			Is water entering inlet, but not exiting outlet?			
5. Lowest dam crest elevation (operator records)?	590.0 ft			Is water exiting outlet, but not entering inlet?			
6. If instrumentation is present, are readings recorded (operator records)?	N/A			Is water exiting outlet flowing clear?			
7. Is the embankment currently under construction?		X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below): See Note			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	X			From underdrain? N/A			
9. Trees growing on embankment? (If so, indicate largest diameter below)		X		At isolated points on embankment slopes?			
10. Cracks or scarps on crest?		X		At natural hillside in the embankment area?			
11. Is there significant settlement along the crest?		X		Over widespread areas?			
12. Are decant trashracks clear and in place?	N/A			From downstream foundation area?			
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X		"Boils" beneath stream or ponded water?			
14. Clogged spillways, groin or diversion ditches?	N/A			Around the outside of the decant pipe? N/A			
15. Are spillway or ditch linings deteriorated?	N/A			22. Surface movements in valley bottom or on hillside?	See Note		
16. Are outlets of decant or underdrains blocked?		X		23. Water against downstream toe?	See Note		
17. Cracks or scarps on slopes?	See note			24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

<u>Inspection Issue #</u>	<u>Comments</u>
1.	Annual by Alliant Energy, beginning in 2009
9.	No trees, but embankments were covered by thick vegetation.
17.-18.	Could not determine due to heavy vegetation.
19.	Oversteepened slopes evident, possibly caused by drawdown.
20.	Water is pumped from impoundment, pumps were not operating on day of visit.
21, 22 & 23.	Pond is primarily incised; however it is diked along entire northeast portion; heavy vegetation did not allow assessment for seepage or presence of water.

US EPA ARCHIVE DOCUMENT



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # Iowa 2326103
Date October 27, 2010

INSPECTOR Don Dotson/Mary Sawitzki (AMEC)

Impoundment Name M.L. Kapp Emergency Ash Secondary Settling Pond
Impoundment Company Alliant Energy
EPA Region 7
State Agency (Field Office) Address 901 N. 5th Street, Kansas City, KS 66101

Name of Impoundment M.L. Kapp Emergency Ash Secondary Settling Pond
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update

Is impoundment currently under construction? Yes No
Is water or ccw currently being pumped into the impoundment? X

IMPOUNDMENT FUNCTION: Receives decant from Emergency (Alternative) Primary Ash. Pond and discharges to NPDES outfall 004

Nearest Downstream Town : Name Camanche, IA
Distance from the impoundment approx. 2 miles

Impoundment Location: Longitude -90 Degrees 13 Minutes 58.2 Seconds
Latitude 41 Degrees 48 Minutes 33.8 Seconds
State IA County Clinton

Does a state agency regulate this impoundment? YES NO X

If So Which State Agency?

US EPA ARCHIVE DOCUMENT

HAZARD POTENTIAL (In the event the impoundment should fail, the following would occur):

 LESS THAN LOW HAZARD POTENTIAL: Failure or misoperation of the dam results in no probable loss of human life or economic or environmental losses.

 LOW HAZARD POTENTIAL: Dams assigned the low hazard potential classification are those where failure or misoperation results in no probable loss of human life and low economic and/or environmental losses. Losses are principally limited to the owner's property.

 X **SIGNIFICANT HAZARD POTENTIAL:** Dams assigned the significant hazard potential classification are those dams where failure or misoperation results in no probable loss of human life but can cause economic loss, environmental damage, disruption of lifeline facilities, or can impact other concerns. Significant hazard potential classification dams are often located in predominantly rural or agricultural areas but could be located in areas with population and significant infrastructure.


 HIGH HAZARD POTENTIAL: Dams assigned the high hazard potential classification are those where failure or misoperation will probably cause loss of human life.

DESCRIBE REASONING FOR HAZARD RATING CHOSEN:

(1) Directly adjacent to and above flood plain/creek located 100 yards from
Mississippi River,

(2) Failure of Emergency Secondary Pond would cause portion of liquid/CCW
stored in the Emergency Primary Pond to exit as well since the two ponds are
hydraulically connected.

CONFIGURATION:



- Cross-Valley
- Side-Hill
- Diked
- Incised (form completion optional)
- Combination Incised/Diked

Embankment Height 10 feet Embankment Material Sandy Clayey Silt; Lean Clay; and Silty Lean Clay
 Pool Area 0.54 acres Liner No
 Current Freeboard* 4-5 feet Liner Permeability N/A

*Water level lower during excavation
 ** Pumped discharge - pump operation checked daily


TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway


- Trapezoidal
- Triangular
- Rectangular
- Irregular

- depth
- bottom (or average) width
- top width
-


TRAPEZOIDAL




TRIANGULAR



RECTANGULAR



IRREGULAR




 Outlet

- inside diameter

Material

- corrugated metal
- welded steel
- concrete
- plastic (hdpe, pvc, etc.)
- other (specify) _____



Is water flowing through the outlet? YES _____ NO* X

*Pumps were not operating during assessment visit

 No Outlet

 X **Other Type of Outlet** (specify) Pumped to NPDES Outfall 004

The Impoundment was Designed By Sargent & Lundy



Site Name: M.L. Kapp	Date: October 27, 2010
Unit Name: Main Ash Primary Settling Pond	Operator's Name: Alliant Energy, Inc.
Unit I.D.:	Hazard Potential Classification: High Significant Low
Inspector's Name: Don Dotson/AMEC and Mary Sawitzki/AMEC	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?				See note			
2. Pool elevation (operator records)?				Not provided			
3. Decant inlet elevation (operator records)?				Not provided			
4. Open channel spillway elevation (operator records)?				N/A			
5. Lowest dam crest elevation (operator records)?				590.0 ft			
6. If instrumentation is present, are readings recorded (operator records)?				N/A			
7. Is the embankment currently under construction?			X				
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?		X					
9. Trees growing on embankment? (If so, indicate largest diameter below) See Note			X				
10. Cracks or scarps on crest?			X				
11. Is there significant settlement along the crest?			X				
12. Are decant trashracks clear and in place?				N/A			
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?			X				
14. Clogged spillways, groin or diversion ditches?				N/A			
15. Are spillway or ditch linings deteriorated?				N/A			
16. Are outlets of decant or underdrains blocked?			X				
17. Cracks or scarps on slopes?				See note			
18. Sloughing or bulging on slopes?							See Note
19. Major erosion or slope deterioration? See Note						X	
20. Decant Pipes: See Note							
Is water entering inlet, but not exiting outlet?							
Is water exiting outlet, but not entering inlet?							
Is water exiting outlet flowing clear?							
21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below): See Note							
From underdrain? N/A							
At isolated points on embankment slopes?							
At natural hillside in the embankment area?							
Over widespread areas?							
From downstream foundation area?							
"Boils" beneath stream or ponded water?							
Around the outside of the decant pipe? N/A							
22. Surface movements in valley bottom or on hillside?							See Note
23. Water against downstream toe?							See Note
24. Were Photos taken during the dam inspection?						X	

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

<u>Inspection Issue #</u>	<u>Comments</u>
1.	Annual inspections by Alliant Energy, beginning in 2009
9.	Heavy vegetation
17.-18.	Could not determine due to heavy vegetation
19.	Oversteepened slopes evident, possibly caused by drawdown.
20.	Pond level was below vertical inlet into secondary pond; could not determine
21., 22., and 23.	Could not determine due to heavy vegetation.

US EPA ARCHIVE DOCUMENT



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # Iowa 2326103
Date October 27, 2010

INSPECTOR Don Dotson/Mary Sawitzki (AMEC)

Impoundment Name M.L. Kapp Main Ash Primary Settling Pond
Impoundment Company Alliant Energy
EPA Region 7

State Agency (Field Office) Address

Iowa Department of Natural Resources USEPA Region 7
502 E. 9th Street 901 N. 5th Street
Des Moines, IA 50319 Kansas City, KS 66101

Name of Impoundment Alliant Energy M.L. Kapp Main Ash Primary Settling Pond
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update

Is impoundment currently under construction? Yes No
Is water or ccw currently being pumped into the impoundment? X

IMPOUNDMENT FUNCTION: Primary receiving location for CCW and related materials.

Nearest Downstream Town : Name Camanche, IA
Distance from the impoundment approx. 2 miles

Impoundment


Location: Longitude -90 Degrees 14 Minutes 22.3 Seconds
Latitude 41 Degrees 48 Minutes 40.3 Seconds
State IA County Clinton

Does a state agency regulate this impoundment? YES NO X

If So Which State Agency?

US EPA ARCHIVE DOCUMENT

CONFIGURATION:



Cross-Valley
 Side-Hill
 Diked
 Incised (form completion optional)
 Combination Incised/Diked


Embankment Height 11 feet Embankment Material Clayey Silt and Silty Lean Clay
 Pool Area 6.9 acres Liner No
 Current Freeboard* 4-5 feet Liner Permeability N/A

TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway

- Trapezoidal
- Triangular
- Rectangular
- Irregular

TRAPEZOIDAL




TRIANGULAR

Top Width
Depth

- depth
- bottom (or average) width
- top width

RECTANGULAR



IRREGULAR


Average Width
Avg
Depth

 Outlet

- inside diameter

Material

- corrugated metal
- welded steel
- concrete
- plastic (hdpe, pvc, etc.)
- other (specify) _____



Is water flowing through the outlet? YES _____ NO X*

*Water level below level of pipe culvert discharge

 No Outlet

 Other Type of Outlet (specify) discharges into Main Secondary Pond through a pipe culvert, not provided culvert diameter, appeared to be at least 18 inches.
Culvert invert is adjustable using stacking pipe connectors

The Impoundment was Designed By Sargent & Lundy



Site Name: M.L. Kapp	Date: October 27, 2010
Unit Name: Main Ash Secondary Settling Pond	Operator's Name: Alliant Energy, Inc.
Unit I.D.:	Hazard Potential Classification: High Significant Low
Inspector's Name: Don Dotson/AMEC and Mary Sawitzki/AMEC	

Check the appropriate box below. Provide comments when appropriate. If not applicable or not available, record "N/A". Any unusual conditions or construction practices that should be noted in the comments section. For large diked embankments, separate checklists may be used for different embankment areas. If separate forms are used, identify approximate area that the form applies to in comments.

		Yes	No			Yes	No
1. Frequency of Company's Dam Inspections?	See note			18. Sloughing or bulging on slopes?	See Note		
2. Pool elevation (operator records)?	Not provided			19. Major erosion or slope deterioration? See Note	X		
3. Decant inlet elevation (operator records)?	Not provided			20. Decant Pipes: See Note			
4. Open channel spillway elevation (operator records)?	N/A			Is water entering inlet, but not exiting outlet?			
5. Lowest dam crest elevation (operator records)?	590.0 ft			Is water exiting outlet, but not entering inlet?			
6. If instrumentation is present, are readings recorded (operator records)?	N/A			Is water exiting outlet flowing clear?			
7. Is the embankment currently under construction?		X		21. Seepage (specify location, if seepage carries fines, and approximate seepage rate below): See Note			
8. Foundation preparation (remove vegetation, stumps, topsoil in area where embankment fill will be placed)?	X			From underdrain? N/A			
9. Trees growing on embankment? (If so, indicate largest diameter below)	X			At isolated points on embankment slopes?			
10. Cracks or scarps on crest?		X		At natural hillside in the embankment area?			
11. Is there significant settlement along the crest?		X		Over widespread areas?			
12. Are decant trashracks clear and in place?	N/A			From downstream foundation area?			
13. Depressions or sinkholes in tailings surface or whirlpool in the pool area?		X		"Boils" beneath stream or ponded water?			
14. Clogged spillways, groin or diversion ditches?	N/A			Around the outside of the decant pipe? N/A			
15. Are spillway or ditch linings deteriorated?	N/A			22. Surface movements in valley bottom or on hillside?	See Note		
16. Are outlets of decant or underdrains blocked?		X		23. Water against downstream toe?	See Note		
17. Cracks or scarps on slopes?	See note			24. Were Photos taken during the dam inspection?	X		

Major adverse changes in these items could cause instability and should be reported for further evaluation. Adverse conditions noted in these items should normally be described (extent, location, volume, etc.) in the space below and on the back of this sheet.

<u>Inspection Issue #</u>	<u>Comments</u>
1.	Annual inspections by Alliant Energy, beginning in 2009
9.	Heavy vegetation and trees 18" - 24"
17.-18.	Could not determine due to heavy vegetation
19.	Oversteepened slopes evident, possibly due to drawdown.
20.	Water is pumped from impoundment; pumps were not operating on day of visit.
21, 22 & 23.	Heavy vegetation did not allow assessment for seepage, surface movement, or presence of water at toe.

US EPA ARCHIVE DOCUMENT



Coal Combustion Waste (CCW) Impoundment Inspection

Impoundment NPDES Permit # Iowa 2326103
Date October 27, 2010

INSPECTOR Don Dotson/Mary Sawitzki (AMEC)

Impoundment Name M.L. Kapp Main Ash Secondary Settling Pond

Impoundment Company Alliant Energy

EPA Region 7

State Agency (Field Office) Address
USEPA Region 7
901 N. 5th Street
Kansas City, KS 66101

Name of Impoundment Alliant Energy M.L. Kapp Main Ash Secondary Settling Pond
(Report each impoundment on a separate form under the same Impoundment NPDES Permit number)

New X Update

Is impoundment currently under construction? Yes No
Is water or ccw currently being pumped into the impoundment? X

IMPOUNDMENT FUNCTION: Receives decant from Main Primary Ash Pond and discharges to NPDES outfall 003

Nearest Downstream Town : Name Camanche, IA

Distance from the impoundment approx. 2 miles

Impoundment


Location: Longitude -90 Degrees 14 Minutes 21.7 Seconds
Latitude 41 Degrees 48 Minutes 43.5 Seconds
State IA County Clinton

Does a state agency regulate this impoundment? YES NO X

If So Which State Agency?

US EPA ARCHIVE DOCUMENT

CONFIGURATION:



- Cross-Valley
- Side-Hill
- Diked
- Incised (form completion optional)
- Combination Incised/Diked

Embankment Height 10 feet
 Pool Area 2.3 acres
 Current Freeboard* 4-5 feet

Embankment Material Clayey Silt and Silty Lean Clay
 Liner No
 Liner Permeability N/A


*Pump discharge – daily pump operation check

TYPE OF OUTLET (Mark all that apply)

 Open Channel Spillway

- Trapezoidal
- Triangular
- Rectangular
- Irregular

TRAPEZOIDAL




TRIANGULAR

Top Width

Depth

- depth
- bottom (or average) width
- top width

RECTANGULAR



IRREGULAR

Average Width


Avg
Depth

 Outlet

 inside diameter

Material

- corrugated metal
- welded steel
- concrete
- plastic (hdpe, pvc, etc.)
- other (specify) _____



Is water flowing through the outlet? YES _____ NO* X
*Pump not operating during site assessment


 No Outlet

 X **Other Type of Outlet** (specify) pumped to NPDES outfall 003

The Impoundment was Designed By Sargent & Lundy

APPENDIX B
Site Photo Log Map and Site Photos

Legend
 Photo Location



UNITED STATES
 ENVIRONMENTAL PROTECTION AGENCY

DWN BY: DJC

CKD BY: MS

Datum: NAD 83

Projection: UTM 15

Scale: As Shown

ASSESSMENT OF DAM SAFETY OF
 COAL COMBUSTION SURFACE IMPOUNDMENTS

REV. No.: A

Date: 11-9-10

Project No: 3-2106-0183-0002

Figure No: B-1

AMEC Earth & Environmental
 690 Commonwealth Business Center
 11003 Bluegrass Parkway
 Louisville, KY 40299



ALLIANT ENERGY
 ML KAPP POWER STATION, CLINTON, IA
 PHOTO LOCATION MAP

B-1



EP-1
LOOKING NORTHWEST ACROSS EMERGENCY ASH PRIMARY
AND SECONDARY SETTLING PONDS



EP-2
LOOKING SOUTH AT COAL PILE ADJACENT
TO OPERATIONS/OFFICE BUILDING

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2106-0183.0002	
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-2	



EP-3
LOOKING WEST AT BOTTOM ASH INFLUENT PIPE
INTO EMERGENCY ASH PRIMARY SETTLING POND



EP-4
UPSTREAM END OF STORM DRAIN PIPE FROM COAL PILE
AREA INTO EMERGENCY ASH PRIMARY SETTLING POND

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-3	



EP-5
LOOKING AT UPSTREAM END OF EMERGENCY ASH PRIMARY
AND SECONDARY SETTLING PONDS CONNECTION PIPE



EP-6
LOOKING SOUTHWEST AT DOWNSTREAM END OF EMERGENCY
ASH PRIMARY AND SECONDARY PONDS CONNECTION PIPE

AMEC Earth & Environmental 890 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40289 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-4	



EP-7
LOOKING WEST AT EMERGENCY ASH SECONDARY
POND OUTFALL PUMP HOUSE



EP-8
EMERGENCY ASH SECONDARY POND ABANDONED
ORIGINAL DISCHARGE BOX STRUCTURE

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-5



EP-9
INFLUENT WELL AT EMERGENCY SECONDARY POND PUMP HOUSE



EP-10
LOOKING EAST FROM PUMPHOUSE AT ABANDONED ORIGINAL DISCHARGE BOX STRUCTURE

AMEC Earth & Environmental 890 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-6	



EP-11

ANIMAL BURROW OUTSIDE NORTH FENCE CORNER AT TOP OF EMERGENCY SECONDARY POND DOWNSTREAM EMBANKMENT SLOPE



EP-12

LOOKING SOUTHEAST ALONG CREST OF EMERGENCY SECONDARY POND DOWNSTREAM EMBANKMENT-MISSISSIPPI RIVER IN BACKGROUND

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700				CLIENT LOGO 		CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY			
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS				DWN BY: CAE		DATUM:		DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS				CHK'D BY: MOS		REV. NO.:		PROJECT NO: 3-2108-0183.0002	
				PROJECTION:		SCALE: AS SHOWN		APPENDIX: B-7	



EP-13
OUTLET OF ANIMAL BURROW SHOWN IN PHOTO EP-11



EP-14
DOWNSTREAM PIPE OUTLET OF ABANDONED ORIGINAL DISCHARGE BOX STRUCTURE

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-8	



**EP-15
ANIMAL BURROW IN DOWNSTREAM EMBANKMENT**

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40239 (502) 267-0700		CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS	DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA EMERGENCY POND SITE PHOTOS	CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
	PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-9	



**MP-1
INFLUENT WELL AT MAIN SECONDARY
POND DISCHARGE PUMP HOUSE**



**MP-2
LOOKING WEST ALONG MAIN ASH SECONDARY
POND FROM DISCHARGE PUMP HOUSE**

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700		CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS	DWN BY: CAE	DATUM:	DATE: 11/15/10
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS	CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2106-0183.0002
	PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-10



MP-3
LOOKING EAST AT CCW INFLUENT PIPE
FROM MAIN ML KAPP FACILITY



MP-4
CCW INFLUENT PIPE-CONNECTION POINT OF
NEW SECTION OF BASALT LINED CAST IRON

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700			CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS		DWN BY: CAE	DATUM:	DATE: 11/15/10
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS		CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2106-0183.0002
		PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-11



MP-5
BOTTOM SECTION OF DROP INLET IN MAIN PRIMARY
POND LEADING TO MAIN SECONDARY POND



MP-6
LOOKING EAST FROM WEST CREST
ACROSS MAIN ASH PRIMARY POND

AMEC Earth & Environmental 890 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700		CLIENT LOGO 	CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS	DWN BY: CAE	DATUM:	DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS	CHK'D BY: MOS	REV. NO.:	PROJECT NO: 3-2108-0183.0002	
	PROJECTION:	SCALE: AS SHOWN	APPENDIX: B-12	



MP-7
DROP INLET EXTENSION PIECES SITTING UPSLOPE
FROM DROP INLET IN MAIN ASH PRIMARY POND



MP-8
VEGETATION SURROUNDING PIPE DISCHARGE FROM
MAIN ASH PRIMARY POND INTO SECONDARY POND

AMEC Earth & Environmental

690 Commonwealth Center
 11003 Bluegrass Parkway
 Louisville, Ky 40299
 (502) 267-0700



CLIENT LOGO



CLIENT

UNITED STATES
ENVIRONMENTAL
PROTECTION AGENCY

PROJECT
ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

DWN BY: CAE

DATUM:

DATE: 11/15/10

TITLE
ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON IA
MAIN POND SITE PHOTOS

CHK'D BY: MOS

REV. NO.:

PROJECT NO:
3-2106-0183.0002

PROJECTION:

SCALE:
 AS SHOWN

APPENDIX:
B-13



MP-9
LOOKING NORTHEAST ALONG SOUTH EMBANKMENT
AND CREST OF MAIN SECONDARY POND



MP-10
LOOKING SOUTHEAST AT CCW PIPE INFLUENT
INTO MAIN ASH PRIMARY POND

AMEC Earth & Environmental

690 Commonwealth Center
 11003 Bluegrass Parkway
 Louisville, Ky 40299
 (502) 267-0700



CLIENT LOGO



CLIENT

UNITED STATES
ENVIRONMENTAL
PROTECTION AGENCY

PROJECT
ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

DWN BY: CAE

DATUM:

DATE: 11/15/10

TITLE
ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON IA
MAIN POND SITE PHOTOS

CHK'D BY: MOS

REV. NO.:

PROJECT NO: 3-2106-0183.0002

PROJECTION:

SCALE:
 AS SHOWN

APPENDIX: B-14



MP-11
LOOKING SOUTHWEST ALONG NORTH EMBANKMENT
AND CREST OF MAIN PRIMARY POND



MP-12
TOP OF ABANDONED MAIN POND OUTLET STRUCTURE

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700				CLIENT LOGO 		CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS				DWN BY: CAE		DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS				CHK'D BY: MOS		PROJECT NO: 3-2106-0183.0002	
				PROJECTION:		SCALE: AS SHOWN	
						APPENDIX: B-15	



MP-13
DOWNSTREAM END OF ABANDONED MAIN POND OUTLET
STRUCTURE AT TOE OF SLOPE OF ORIGINAL EMBANKMENT



MP-14
ANIMAL BURROW LOCATED AT NORTHEAST
CORNER OF ORIGINAL POND EMBANKMENT

AMEC Earth & Environmental

690 Commonwealth Center
 11003 Bluegrass Parkway
 Louisville, Ky 40299
 (502) 267-0700



CLIENT LOGO



CLIENT

UNITED STATES
ENVIRONMENTAL
PROTECTION AGENCY

PROJECT
ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS

DWN BY:
CAE

DATUM:

DATE: 11/15/10

TITLE
ALLIANT ENERGY
ML KAPP POWER STATION, CLINTON IA
MAIN POND SITE PHOTOS

CHK'D BY:
MOS

REV. NO.:

PROJECT NO:
3-2106-0183.0002

PROJECTION:

SCALE:
AS SHOWN

APPENDIX:
B-16



MP-15
LOOKING EAST ALONG DOWNSTREAM SLOPE OF ORIGINAL EMBANKMENT AT TREES/VEGETATION



MP-16
LOOKING WEST ALONG DOWNSTREAM SLOPE OF ORIGINAL EMBANKMENT AT TREES/VEGETATION

AMEC Earth & Environmental 890 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700				CLIENT LOGO 		CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY	
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS				DWN BY: CAE		DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS				CHK'D BY: MOS		PROJECT NO: 3-2108-0183.0002	
				PROJECTION:		SCALE: AS SHOWN	
						APPENDIX: B-17	



MP-17
LOOKING SOUTHWEST ALONG SOUTHERN
PORTION OF ORIGINAL EMBANKMENT



MP-18
LOOKING NORTHEAST ALONG SOUTHERN
PORTION OF ORIGINAL EMBANKMENT

AMEC Earth & Environmental 690 Commonwealth Center 11003 Bluegrass Parkway Louisville, Ky 40299 (502) 267-0700				CLIENT LOGO 		CLIENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY			
PROJECT ASSESSMENT OF DAM SAFETY OF COAL COMBUSTION SURFACE IMPOUNDMENTS				DWN BY: CAE		DATUM:		DATE: 11/15/10	
TITLE ALLIANT ENERGY ML KAPP POWER STATION, CLINTON IA MAIN POND SITE PHOTOS				CHK'D BY: MOS		REV. NO.:		PROJECT NO: 3-2106-0183.0002	
				PROJECTION:		SCALE: AS SHOWN		APPENDIX: B-18	

APPENDIX C
Inventory of Provided Materials

Hoosier Energy Provided Documents

1. Interoffice memorandum Frank E. Ratts Generating Station Bottom Ash Pond (Pond #1), dated May 11, 1994;
2. Interoffice memorandum Ash Pond Maintenance 1996, dated December 27, 1996;
3. Levee Repair Petersburg Generating Station, prepared by Koester Contracting Corp, dated August 17, 1997;
4. Application for Approval of Construction in a Floodway, dated March 16, 1984;
5. Frank E. Ratts Generating Station Ash Disposal System Modifications, Site and Grading Plan, prepared by R.W. Beck and Associates dated March 19, 1975;
6. Interoffice memorandum Ash Pond Survey, dated September 14, 1995;
7. Construction Permit New Settling Pond (Pond 3), dated February 7, 1983;
8. Fly Ash Pond Closure Plan, prepared by Burns & McDonnell, dated January 28, 1997;
9. Frank E. Ratts Generating Station Ash Management Plan for Pond Closure, prepared by Burns & McDonnell, dated April 22, 1998;
10. Site Observation Trip Coal Ash Storage Pond, prepared by ATC Associates Inc., site inspection performed on August 6, 1997.
11. Frank E. Ratts Generating Station Ash Disposal System Modifications, Site and Grading Plan, prepared by R.W. Beck and Associates dated March 19, 1975. Same as item 5, with notes pertaining to active/inactive areas in Bottom Ash Pond and Pond 1.
12. Compliance Plan for the Frank E. Ratts ash pond system, dated October 31, 2007;
13. Certificate for Approval of Construction in a Floodway, dated July 2, 1984;
14. Floodplain Analysis and Regulatory Assessment, dated October 15, 2007;
15. Interoffice memorandum Ratts Subsurface Investigation, dated October 31, 1997;
16. EPA Information Request under Section 104(e) of the Comprehensive Response, Compensation, and Liability Act, dated March 9, 2009;
17. Pictures of 1997 seepage;
18. Attachment 2, Piezometer Water Level Measurements;
19. Floodplain Analysis and Regulatory Assessment, dated October 15, 2007 (same as item 14);
20. Construction Permit Application (Pond 3) ,dated September 14, 1982;
21. Approved Construction Permit (Pond 4), dated May 11, 1984;
22. Construction Permit Application (Pond 4) ,dated March 16, 1984;
23. Property Land Descriptions (Ponds 2 and 3);
24. Property Descriptions;
25. Site Aerial;
26. Ratts Generating station dike Evaluation, prepared by Fuller Mossbarger Scott & May Engineers, dated September 22, 2006;
27. Record of Well Water, Indiana Department of Natural Resources, dated July 13, 1988;
28. Request for 100-Year Flood Elevation Determination, dated March 5, 2007;
29. From Indiana Department of Environmental Management, signed agreed order issued to Hoosier Energy concerning the ash pond failure, dated September 18, 2007
30. 2007 Ash Pond Dike Improvements, Ratts Generating Station, Pike County, Indiana, prepared by Stantec Consulting Services Inc., dated April 2, 2009;
31. Ash Pond Dike Improvements, Ratts Generating Station, Pike County, Indiana, prepared by Stantec Consulting Services Inc., dated January 15, 2009;
32. Attachment 1 Subsurface Investigation Test Results, includes piezometer logs and lab test results, provided by ATC Associates Inc. dated January 7, 1998;
33. Report of Slope Stability Evaluation, Permitter Dikes for Ash Pond 003 Ratts Generating Station, Pike County, Indiana, prepared by Fuller Mossbarger Scott & May Engineers, dated January 31, 2007;

34. Interoffice memorandum Ratts Station Ash Management, dated December 18, 1995;
35. Technical Specification for Ash Pit Dike Upgrade Ratts Generating Station Hoosier Energy Rec, Inc. Petersburg, IN. dated June 30, 1998;
36. Hoosier Energy, various work orders and property inspection forms;
37. Monroe City Quadrangle, prepared by the United States Department of the Interior Geological Survey;
38. Hoosier Energy Ratts Generating Station Ash Pond and Dike Cross-Sections, prepared by Bernardin Lochmueller & Assoc., Inc, dated December 22, 1997;
39. Bottom Ash Pond Closure Plan, Exhibit 1B, prepared by Burns & McDonnell, dated March 26, 1998;
40. Phase I & Phase II Dike Plan, Exhibit 2A, prepared by Burns & McDonnell, dated January 28, 1997;
41. Partial Development of Phase I Cell, Exhibit 2B, Burns & McDonnell, dated April 9, 1998;
42. Ash Pond Sections, Exhibit 3, prepared by Burns & McDonnell, dated January 28, 1997;
43. The Hoosier Energy Division, Indiana Statewide R.E.C Inc Units No. 1&2 – Petersburg, Indiana, Proposed Ash Pit #4, prepared by Laramore, Douglass and Popham Engineers – Constructors, date illegible;
44. New Settling Pond for Ratts Station, prepared by Hoosier Energy, dated September 14, 1982;
45. Hoosier Energy – Frank E. Ratts Generating Station, 10 Year Ash Management Plan, prepared by Time Goad, dated May 13, 1998;
46. Flue Gas Desulfurization Retrofit Conceptual Design Report;
47. Letter from the Department of the Army Operations and Readiness Division Regulatory Branch, indicating the plant is not within a floodplain, dated August 1, 1994;
48. Specifications and Contract Documents Contract I, Ash Pond, The Hoosier Energy Division Indiana Statewide R.E.C., Inc. Bloomington, Indiana;
49. Addendum to Report of Slope Stability Evaluation, Perimeter Dikes for Ash Pond 003, prepared by FMSM Engineers, dated March 2, 2007;
50. Addendum to Report of Slope Stability Evaluation, Perimeter Dikes for Ash Pond 003 Drawings 1 through 3, prepared by FMSM Engineers, dated February, 2007;

-  2002 Main Ash Pond Design Drawing.pdf
-  2010 Ash Pond Inspection.tif
-  alliant-mlkapp_RRFI.pdf
-  Ash Line Drawing B-322.pdf
-  Ash Pond - B323.pdf
-  Ash Pond Berm Earthwork 1993.pdf
-  Ash Pond Berm Soil Borings 1994.pdf
-  Ash Pond Berm Soil Specs 1965.pdf
-  Ash Pond Berm Soil Specs 1993.pdf
-  Ash Pond Drawing B321.pdf
-  Ash Pond Work 1965.pdf
-  E Ash Pond Redesign.pdf
-  EPA Ash Assessment KAPP Cover Ltr 102010.pdf
-  Genco Standard Guide for Pond Inspections Revision 0.pdf
-  Kapp Hydraulic Analysis.pdf
-  Kapp NPDES Permit 1999.pdf
-  Kapp Site Photo.pdf
-  Kapp Water Flow Diagram.pdf
-  M1 Conceptual Design.tif
-  Main and E Pond Piping.pdf
-  Main Ash Pond Drawing B320.pdf
-  ML Kapp Ash Pond Inspection 2009.pdf
-  Outdoor Piping.pdf
-  SLOPE STABILITY KAPP PONDS .pdf