

RIP MOBILE PAINTS

Active Ingredients
Cuprous Oxide
Inert Ingredients
Total



DUB-L-COP

ONE COAT

COPPER PAINT NAVY 16-X 473-74

MO

E PAINT

CAUTION!

HARMFUL IF SWALLOWED
KEEP OUT OF REACH OF CHILDREN

ONE GALLON



.....	42.5%
.....	57.5%
.....	100.0%

Jack
Tar

Marine Finishes

DUB-L-COP

ONE-COAT

COPPER PAINT NAVY 16-X 473-74

PAINT MFG. CO., INC. MOBILE, ALABAMA

CAUTION!

**HARMFUL IF SWALLOWED
KEEP OUT OF REACH OF CHILDREN**
See other cautions on back panel

ONE GALLON

This paint is intended for
surface marine life. Do
not for any settled pig-
mentations of the liquid

Surface: Hull should be
blasting to remove all
following the direction
473-74 allowing a minim
returning to water.

Notes: If old surface
When dry apply 1 coat of
of Jack Tar Copper Paint
least overnight before
Jack Tar Wash Primer 401

Expendable: Use No. 1000
cloth saturated with Me
Apply one very thin coa
Copper Paint Navy 16-X

NOTE: DO NO

and, any fr
and are
flood repeat
contents to
reuse empty
discard in a

Do not conta

DO NOT USE,

Use with de

XABWIT

This paint is intended to protect steel, wood, and fiberglass boats from fouling by barnacles and similar marine life. Disperse thoroughly before each use by pouring most of the liquid off and working any settled pigment into a smooth paste using a stiff paddle. Continue by adding small portions of the liquid to the paste until paint is completely mixed.

Steel: Hull should be cleaned by scraping, chipping and mechanical wire brushing or by sand-blasting to remove all rust and scale. Prime by applying 3 coats of Anti-Corrosive Primer 409-68 following the directions on the can. When dry apply 2 coats of Jack Tar Copper Paint Navy 16-X 473-74 allowing a minimum of 4 hours between coats. Allow to dry at least overnight before returning to water.

Wood: If old surface, scrape clean and hose off with high pressure water and stiff brush. When dry apply 1 coat of BLP Jack Tar Wash Primer 409-42 on bare spots. When dry apply 2 coats of Jack Tar Copper Paint Navy 16-X 473-74 allowing a minimum of 4 hours between coats and at least overnight before returning to water. If new work prime the surface with 1 coat of BLP Jack Tar Wash Primer 409-42. When dry apply 2 coats of Jack Tar Copper Paint Navy 16-X 473-74.

Fiberglass: SAND THOROUGHLY with medium-fine grit sandpaper. Wash sanded surface with a CLEAN cloth saturated with Methyl Isobutyl Ketone to remove all traces of "mold release compound". Apply one very thin coat of BLP Jack Tar Wash Primer 409-42 followed by 2 coats of Jack Tar Copper Paint Navy 16-X 473-74.

NOTE: DO NOT use Linseed Oil to thin. Use BLP MoPaxOL 75-1 if necessary.

CAUTION! COMBUSTIBLE

Keep away from heat and open flame. Avoid prolonged contact with skin or eyes and breathing of vapor or spray mist. In case of contact with eyes, flood repeatedly with water. CALL PHYSICIAN IMMEDIATELY! Do not transfer contents to unlabeled containers. Close container after each use. Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place away from water supply.

Do not contaminate water by cleaning of equipment, or disposal of wastes.

DO NOT USE, POUR, SPILL, OR STORE NEAR HEAT OR OPEN FLAME.

ONE GALLON

XABWIT

Use with adequate ventilation.

KEEP OUT OF REACH OF CHILDREN

EPA EST. 1719-AL-1

EPA REG. NO. 1719-15