

CCEPTED

4-9-71

POR ECONON . PUISON ED UNDER NO.

U. S. D. A. REGISTRATION 3482-27

GP Form

502-371

## DIRECTIONS FOR USE

Previously painted bottoms on which the old paint is in good condition. and firmly attached may be recoated after sanding off all loose dirt. Where old paint is loose and flaking in large areas, strip it off and proceed as for new unpainted work.

NEW AND STRIPPED WORK

TOA BLI This copper paint can be applied directly to wood bettoms after sanding smooth. To insure adhesion to fiberglass bottoms, they should be primed with one coat of 15370 or 375 Epoxy Primer, in accordance with directions for that material, before applying copper paint. Prime steel bottoms with two coats 407 Shiple from Primer, and aluminum bottoms with two coats 410 or 415 Primer before using copper paint.

Stir copper paint thoroughly with a flat paddle between sing and during application. Apply two coats to clean, dry surface and a lev at least 4 hours. drying time between coats and before 'ameting. Thin only if absolutely becessiry to restore free brushing consistency. A 1 the turpentine or paint thinner, well started in, can be used for this purpose and for cleaning brushes and so apment. Add no other materials

## CAUTION - FLAMMABLE

Keep awas from heat and open Flame

THIS PAINT CONTAINS COPPER AND OTHER COMPOUNDS HARMFUL if swallowed and it is sold for use ONLY on ship and boat bottoms for the prevention of marine forlang. Do not use it in any house hold application. Avoid breathing vapor or spray mist and contact with skin Wash immediately with soap and water in use of contact with skin-Use protective mask when dry-sarding. Avoid contam nation of feed and foodstuffs.

Keep's intainer closed when not it as Keep out to a confidence of the USE WITH ADEQUATE VENTILATION.

GLOUCESTER PAINTS, INC., GLOUCESTEF, MASS. 01930