ACTIVE INGRED' NTS: METALLIC COPPER 26.7% TRIBUTYLTIN FLUORIDE 4.7% INERT INGREDIENTS 68.6% (COPPER AS METALLIC 26.7%)





May be fatal if swallowed. Read precautions on right hand side of label.




ı

i

9-25-72

absorbed through the skin. Do not get on skin, in eyes or on clothing. May cause eye damage. Do not breathe vapor er spray mist. In case of contact wash skin with soap and water (for eyes flush with water and call physician immediately). Wash eputaminated clothing before reuse. Do not take internally, Avoid storage near food or feed products. Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place. KEEP OUT OF THE REACH OF CHILDREN.

WARNING FLAMMABLE: Keep away from heat, sparks or open flame. Keep container closed when not in use.



A hard anti-fouling copper-bronze bottom coating for racing hulls, as well as others. Designed for fiberglass and wood. Contains effective anti-fouling ingredients in addition to the high percentage of pure metal flake. Should be applied by liberal brushing. Will not lift old enamels in good condition. For use in both salt and fresh water. DO NOT USE FOR ANY APPLICATION OTHER THAN BOAT BOTTOMS.

PREPARATION OF SURFACE:

Over Bare Wood or Fiberglass

Be sure surface is sound and dry, free of wax, grease and other surface contaminants. Fiberglass should be washed with wax and grease remover, then sanded with medium grit (150) sandpaper. For even better adhesion, P-619 Primer, used as directed on the label, is recommended on fiberalass.

Over Old Enamel

sand with medium grit sandpaper.

APPLICATION:

Apply by brush at package consistency or thinned 10-15% with Z-Spar #10 Thinner. For best protection, apply 2 coats. Allow 4 hours or more between coats, dependent upon drying conditions. Allow final coat to dry at least 4 hours before launching.

DO NOT USE ON ALUMINUM OR STEEL BOATS.



B-60 RACING BRONZE ANTI-FOULING

DIRECTIONS

Be sure old enamel is firm and paintable. Wash with wax and grease remover and

Soft anti-fouling bottom paints should be completely removed.

SPECIAL NOTE

