

panel

For use
emulsion

45 lb net

Slime
water

Active Ingredients...

Inert Ingredients....

1 lb Dope	70%
* Metastriate	15%
Sodium phosphite	15%
	100%

(X) POIS

DANGER

KEEP OUT OF REACH

(See side panel for additio
dote statement)

INFORM

ations

COTEY CHEMICAL CORPORA
P. O. Box 2039 Ph:
LUBBOCK, TEXAS 79408

96

ACCEPTED

JUL 17 1968

FOR ALL FEDERAL AND STATE
DEPARTMENT OF AGRICULTURE
ECONOMIC POISON REGISTER
REGISTER NO. 2292 SUBJECT
ATTACHED COMMENTS.

(Side panel)

WARNING!

Causes severe burns to skin and damage to eyes. Do not get in contact with skin, eyes, and clothing. Do not take internally. May be fatal if swallowed. In case of contact, immediately flush skin with plenty of water and wash with vinegar; for eyes, flush with plenty of water for at least 15 minutes and get medical attention. See physician.

(Side panel)

DIRECTIONS

1. Use about 1/4 lb of WELGICIDE CLEANER per gallon of water inside the casing.
2. Dissolve the required amount in water and pour the solution between casing and column pipe. Pour several gallons of the mixed solution down discharge pipe. Add the chemical carefully to the water as considerable heat will be generated when WELGICIDE CLEANER is dissolved in water.
3. Agitate occasionally with the pump. Leave the chemical in the well for 24 hours or longer.
4. Pump the first water after treatment to waste.

Do not use on aluminum, magnesium or zinc.

Do not reuse container. Destroy when empty.