

GIBSON

PAINTS

If It's Gibson's, It's Good

Copper bottom paint

KEEP OUT OF REACH OF CHILDREN
DANGER

EPA Registration No. 11026-3
EPA Establishment No. 11026-CA-1

SEE BACK PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS

ACTIVE INGREDIENTS:	Tributyltin fluoride	1%
	Cuprous oxide	27%
INERT INGREDIENTS:	72%

CONTAINS PETROLEUM DISTILLATE

NET CONTENTS ONE U. S. GALLON (3.79 l)

PRECAUTIONARY STATEMENTS
Hazards to Humans and Domestic Animals

DANGER

Corrosive. Causes irreversible eye damage and burns. Harmful if absorbed through skin, swallowed, or inhaled. Do not get on skin, in eyes, or on clothing. Wear goggles or safety glasses. Wear protective clothing such as long-sleeved cotton shirt, long pants, hat and gloves. Wash thoroughly with soap and water after handling. Remove contaminated clothing and wash before reuse. Avoid breathing spray mist or chips from sanding. Use with adequate ventilation. While spraying and/or sanding boat surface, wear a mask or a respirator jointly approved by the Mining Enforcement and Safety Administration and the National Institute for Occupational Safety and Health.

PRACTICAL TREATMENT

If Swallowed: Drink promptly a large quantity of milk, egg whites, gelatin solution or, if these are not available, drink large quantities of water. Avoid alcohol. Get medical attention. NOTE TO PHYSICIAN: Probable mucosal damage may contraindicate the use of gastric lavage.

If in Eyes: Flush with plenty of water. Get medical attention.

If on Skin: Wash paint off with mineral spirits (paint thinner), and then wash with plenty of soap and water. If skin is irritated, get medical attention.

If Inhaled: Remove victim to fresh air. If not breathing, give artificial respiration, preferably mouth to mouth. Get medical attention.

ENVIRONMENTAL HAZARDS

This material is toxic to fish. Do not apply directly to water by cleaning of equipment or disposal of wastes. Do not allow chips or dust generated during paint removal to enter water. Dispose of paint debris in an approved landfill, or by depositing with a licensed garbage collector.

PHYSICAL OR CHEMICAL HAZARDS

Combustible: Do not use or store near heat or open flame.

DIRECTIONS FOR USE

IT IS A VIOLATION OF FEDERAL LAW TO USE THIS
PRODUCT IN A MANNER INCONSISTENT WITH ITS LABELING 11026-3

GIBSON'S COPPER BOTTOM PAINT is an antifouling coating used for the prevention of marine fouling such as algae, tubeworms and barnacles. Prepare the surface as follows:

- Previously painted surfaces -- Scrape, scale and remove old failing paint.
- Bare wood -- Pretreatment with copper naphthenate wood preservative or priming with red lead paint, or both, is recommended; but it is not mandatory.
- Unpainted steel -- Remove any rust and prime with 2 coats of metal primer.
- Unpainted fiberglass -- Prime with an epoxy fiberglass primer.

Mix the paint thoroughly by stirring and pouring back and forth into another can. The paint may be applied by brush, roller or spray. If too heavy, thin as needed with mineral spirits (paint thinner). Surfaces to be coated must be clean and dry. Apply at least 2 coats of Copper Bottom Paint, allowing at least 1 hour between coats. Allow last coat to dry at least 1 hour before launching. Coverage is 300 to 400 square feet per gallon. Wash equipment with paint thinner (mineral spirits).

STORAGE OR DISPOSAL

Do not contaminate water, food or feed by storage or disposal. Open dumping is prohibited. Unused paint and containers must be disposed of in accordance with applicable Federal, State or local procedures; or wrap container and place in trash collection.

MANUFACTURED BY GIBSON PAINT CO., OAKLAND, CA 94606