



Overhead door, eastern side of boiler room, recently boarded up.

Photo P02010701



Severe erosion of mortar (pointing) in smoke stack.

Photo P02010702



Staining of brick on south side of building.

Photo P02010703



Cracking in southeast corner, under granite sill of third floor window.

Photo P02010704



Cracking southeast corner of building, third floor.

Photo P02010705



Mortar erosion eastern end of building.

Photo P02010706



Fire escape, northern side of building, note rust holes in structural member.

Photo P02010707



Mortar erosion and cracking on northern side of building.

Photo P02010708



Cracking and mortar erosion, Northern side parapet at three story to two story transition.

Photo P02010709



Cracking on boiler room wall, Southern side of Aerovox.

Photo P02010710



Ceiling collapsing in boiler room lockers area.

Photo P02010711



Column out of plumb in shipping department, first floor.

Photo P02010712



Column in shipping area off plumb and cracking.

Photo P02010713



Ceiling collapse in first floor storage area (below cardboard box room).

Photo P02010714



Unauthorized entry point to first floor storage area.

Photo P02010715



Water damage at second floor roof drain, Assembly area.

Photo P02010716



Ceiling and floor water damage third floor Special Projects room.

Photo P02010717



Water damage to third floor; photo does not adequately document condition, heaving of flooring approximately a foot in places.

Photo P02010718



Interior paint peeling and efflorescence due to water penetration, northeastern stairwell.

Photo P02010719