

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of the rental Geoprobe unit sampling in the former "oxbow" area, between Brook Village and Centredale Manor buildings, adjacent to the Woonasquatucket River. Photograph taken facing northwest.

FRAME NUMBER: 13 **DATE:** 29 June 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 10:45 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of high visibility fencing installed at 562 Woonasquatucket Avenue. Note Allendale Pond in background. Photograph taken facing west.

FRAME NUMBER: 14 **DATE:** 1 July 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 14:30 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of high visibility fencing installed at 562 Woonasquatucket Avenue. Allendale Pond is located in the background. Photograph taken facing west.

FRAME NUMBER: 15 **DATE:** 1 July 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 14:33 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of high visibility fencing installed on the NEC greenway. The Woonasquatucket River is located on the extreme left. Photograph taken facing south.

FRAME NUMBER: 16 **DATE:** 20 July 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 09:00 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of sediment sampling (by Geologic, Inc) at the Allendale Dam (sample location AD-03). Note residential properties in the background. Photograph taken facing east.

FRAME NUMBER: 17 **DATE:** 20 July 1999


TIME: 09:50 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of sediment sampling (by Geologic, Inc.) at the Allendale Dam (sample location AD-03). Photograph taken facing west.

FRAME NUMBER: 18 **DATE:** 20 July 1999

TIME: 10:55 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk


WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island

TOP



SCENE: View of vandalized warning post, after an apparent arson attempt. Photograph taken facing east.

FRAME NUMBER: 20 DATE: 3 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 13:30 SKY CONDITION: Sunny
WITNESS(ES): None
FILM TYPE: 35-mm FILM ROLL: BC300355



SCENE: View of completed cedar fence installation, with the Centredale Manor apartment in the background. Note the site trailers to the extreme right. Photograph taken facing southeast.

FRAME NUMBER: 21 DATE: 23 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta SETTING: Automatic

TIME: 12:50 SKY CONDITION: Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm FILM ROLL: BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of completed cedar fence installation. The Brook Village apartment building is in the background. Photograph taken facing north.

FRAME NUMBER: 22 **DATE:** 24 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:51 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of completed cedar fence installation. Note site office trailers located at the extreme left. Photograph taken facing southwest.

FRAME NUMBER: 23 **DATE:** 24 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 12:53 **SKY CONDITION:** Cloudy
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of chain-link fence installed between drainage swale/wetlands area and the Centredale Manor building. Note shed in far right background. Photograph taken facing south.

FRAME NUMBER: 24 **DATE:** 24 August 1999

TIME: 13:00 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300355



SCENE: View of installed chain-link fencing at 41 Steere Avenue. The drainage swale/wetlands area is located behind the fence to the left. Photograph taken facing north.

FRAME NUMBER: 00 **DATE:** 24 August 1999

TIME: 13:05 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300355

PHOTOGRAPHY LOG SHEET

Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of chain-link fencing installed across the dead end at Steere Avenue. The Centredale Manor building is located behind the fence. Photograph taken facing west.

FRAME NUMBER: 01 **DATE:** 24 August 1999

TIME: 13:06 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300356



SCENE: View of chain-link fencing installed at 45 Grover Street. Note the red sample flags in foreground. The site wetlands area is located behind the fence. Photograph taken facing northwest.

FRAME NUMBER: 03 **DATE:** 24 August 1999

TIME: 13:10 **SKY CONDITION:** Sunny

PHOTOGRAPH BY: Renata Wynnyk

WITNESS(ES): None

CAMERA: Minolta **SETTING:** Automatic

FILM TYPE: 35-mm **FILM ROLL:** BC300356


PHOTOGRAPHY LOG SHEET
Centredale Manor Restoration Project • North Providence, Rhode Island



SCENE: View of chain-link fence installed across the dead end of Grover Street. Photograph taken facing west.

FRAME NUMBER: 04 **DATE:** 24 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:11 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300356



SCENE: View of chain-link fencing installed at the vacant property at 41 Grover Street. Note residential property at 42 Redfern Street in the background. Photograph taken facing south.

FRAME NUMBER: 05 **DATE:** 24 August 1999
PHOTOGRAPH BY: Renata Wynnyk
CAMERA: Minolta **SETTING:** Automatic

TIME: 13:12 **SKY CONDITION:** Sunny
WITNESS(ES): None
FILM TYPE: 35-mm **FILM ROLL:** BC300356