

APPENDIX A

SITE PHOTOGRAPHS



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF NORTH CHANNEL LOOKING IN EAST DIRECTION
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF NORTH CHANNEL LOOKING TO THE WEST
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
HEADWALL OF CULVERT ON NORTH SIDE OF LANDFILL.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF A DEPRESSION IN THE ASPHALT ABOVE THE NORTHERN CULVERT'S
HEADWALL.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF ENDWALL OF CULVERT FOR NORTHERN DRAINAGE CHANNEL.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF MONITORING WELL 2WMW45S WHICH IS INCLUDED IN SITE 2 GROUNDWATER
MONITORING PROGRAM AND IS LOCATED NORTH OF DEPLOYED PARKING AREA.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF MONITORING WELL 2LMW17D. THE WELL WAS MISSING A COVER AND LID.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF A LONGITUDINAL (NORTH-SOUTH) CRACK IN THE ASPHALT AT
APPROXIMATELY THE MIDDLE OF THE COVER AREA.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
CLOSE UP VIEW OF THE LONGITUDINAL CRACK IN THE ASPHALT LAYER.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF A HOLE IN THE ASPHALT LAYER FROM THE FIRST QUARTER AREA OF THE
COVER. BELIEVED TO BE CAUSED FROM HEAVY EQUIPMENT PARKED ON ASPHALT.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF EQUIPMENT STORED AND SITE 4–RUBBLE FILL AREA AT BUNKER A-86
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 2 – AREA A LANDFILL AND WETLAND
VIEW OF DEPRESSION IN RIP RAP AT TOE OF LANDFILL AT NORTHEASTERN END OF
CAP. POSSIBLE LOCATION OF PIPING OF FINES FROM BENEATH RIP RAP.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
TREES USED FOR PLANTING DURING RESTORATION AFTER REMEDIAL ACTION.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF STREAM 2 AND LOWER POND LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
HEADWALL OF STREAM 2 LOOKING WEST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
LOWER POND LOOKING SOUTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF STREAM 3 LOOKING NORTHWEST.
CULVERT TO STREAM 5 SHOWN AT DISTANCE.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF UPPER POND TOWARD STREAM 4 LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF OBDA POND LOOKING EAST TOWARD OBDA.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF SEEP ON SOUTHERN BANK OF OBDA POND.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF STREAM 1 LEAVING OBDA POND LOOKING WEST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF HEADWATERS OF STREAM 4 LOOKING SOUTHEAST.
AREA WHERE PESTICIDE CONTAMINATION WAS CAPPED AND LEFT IN PLACE.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF STREAM 5 LOOKING WEST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF NEWLY DISCOVERED DISPOSAL AREA ON HILLSIDE TO THE NORTH OF
STREAM 5.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 3 – AREA A DOWNSTREAM/OBDA
VIEW OF OBDA POND AND UPPER POND LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 6 – DRMO
VIEW OF THE SITE FROM THE BUILDING 479 LOOKING NORTH.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 6 – DRMO
VIEW OF THE SITE LOOKING NORTHWEST FROM BUILDING 479.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 6 – DRMO
AREA OF SETTLEMENT APPROXIMATELY 50 FEET SOUTHWEST OF THE SOUTHWEST
CORNER OF BUILDING 491.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 6 – DRMO
VIEW OF MONITORING WELL 6MW11D AND DEDICATED SAMPLE COLLECTION TUBING.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 6 – DRMO
VIEW OF THE “DO NOT DIG” SIGN LOCATED AT THE SOUTHERN GATE ENTRANCE.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 7 – TORPEDO SHOPS
VIEW OF BUILDING 325 LOOKING EAST.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 7 – TORPEDO SHOPS
VIEW OF BUILDING 450 LOOKING WEST.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 7 – TORPEDO SHOPS
VIEW OF BUILDING 477, SHED USED FOR SOLVENT STORAGE.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 8 – GOSS COVE LANDFILL
VIEW OF INSTALLATION OF LANDFILL COVER LOOKING WEST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 8 – GOSS COVE LANDFILL. VIEW OF SITE LOOKING SOUTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 8 – GOSS COVE LANDFILL
VIEW OF SITE LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 8 – GOSS COVE LANDFILL
VIEW OF NORTHERN-MOST END OF LANDFILL LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 – GOSS COVE LANDFILL
CAP CONSTRUCTION
APRIL 19, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0275



SITE 8 - GOSS COVE LANDFILL
FINAL CAP SURFACE LOOKING SOUTH
AUGUST 9, 2001
NSB - NLON, GROTON, CONECTICUT. CTO 0816



SITE 8 - GOSS COVE LANDFILL
SITE ENTRANCE AND FINAL CAP SURFACE LOOKING WEST
AUGUST 9, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 9 - FORMER WASTE OIL TANK OT-5
VIEW OF SITE LOOKING NORTHWEST
AUGUST 9, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 9 - FORMER WASTE OIL TANK OT-5
VIEW OF SITE LOOKING SOUTHEAST
AUGUST 9, 2001
NSB-NLON, GROTON, CONNECTICUT. CTOP 0816



SITE 10 – FUEL STORAGE TANKS AND TANK 54-H
VIEW OF SITE LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 11 – POWER PLANT OIL TANKS
VIEW OF SITE LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 13 – BUILDING 79 WASTE OIL PIT
VIEW OF THE SITE LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 14 – OBDANE
VIEW OF THE SITE LOOKING NORTH.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 14 – OBDANE
CLOSE UP VIEW OF THE SITE LOOKING NORTH. YELLOW STICK-UP CASING FOR
MONITORING WELL 14MW1S EVIDENT IN PICTURE.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 14 - OBDANE
VIEW OF THE SITE AFTER REMOVAL ACTION LOOKING NORTH
AUGUST 9, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 15 – SPENT ACID STORAGE AND DISPOSAL AREA
VIEW OF THE SITE LOOKING NORTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 16A – HOSPITAL INCINERATOR
VIEW OF SITE LOOKING SOUTHWEST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 16B – HOSPITAL INCINERATOR
VIEW OF SITE LOOKING NORTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 17 – HAZARDOUS MATERIALS/SOLVENT STORAGE AREA – BUILDING 31
VIEW OF SITE LOOKING NORTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 18 – SOLVENT STORAGE AREA – BUILDING 33
VIEW OF SITE LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 18 – SOLVENT STORAGE AREA – BUILDING 33
VIEW OF SITE LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 19 – SOLVENT STORAGE AREA – BUILDING 316
VIEW OF SITE LOOKING SOUTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 20 – AREA A WEAPONS CENTER
VIEW OF SITE LOOKING NORTHEAST. AREA TO BE REMEDIATED.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 20 – AREA A WEAPONS CENTER.
VIEW OF SOUTHERN DRAINAGE DITCH LOOKING NORTHEAST. AREA TO BE
REMEDIED.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 20 – AREA A WEAPONS CENTER
VIEW OF WESTERN DRAINAGE DITCH LOOKING NORTHEAST.
AREA TO BE REMEDIATED.
APRIL 11, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 21 – BERTH 16
VIEW OF SITE LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 21 – BERTH 16
CLOSE UP VIEW OF DAMAGED MONITORING WELL 20MW5.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 21 – BERTH 16
CLOSE UP VIEW OF MONITORING WELL 20MW6.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 22 – PIER 33
VIEW OF SITE LOOKING SOUTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 23 – TANK FARM
VIEW OF SITE LOOKING EAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 23 - TANK FARM
VIEW OF SITE LOOKING WEST
AUGUST 9, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 24 – CENTRAL POINT ACCUMULATION AREA – BUILDING 174
VIEW OF SITE LOOKING NORTHEAST.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816



SITE 25 – CLASSIFIED MATERIAL INCINERATOR.
VIEW OF SITE LOOKING NORTH.
APRIL 10, 2001
NSB-NLON, GROTON, CONNECTICUT. CTO 0816