



Hole in fence looking towards site.

Photographer: J. Ehret

Date: 8/16/00

Time: 13:45

Frame No: 1

Site Location: PSY

Direction: East

Comments: _____

Checklist
Reference: _____



Hole in fence from concrete pad.

Photographer: J. Ehret

Date: 8/16/00

Time: 13:55

Frame No: 2

Site Location: PSY

Direction: Southwest

Comments: _____

Checklist
Reference: _____



Photographer: J. Ehret

Date: 8/16/00

Time: 13:55

Frame No: 3

Site Location: PSY

Direction: South

Comments: _____

Checklist
Reference: _____

Southwest corner of site.



Photographer: J. Ehret

Date: 8/16/00

Time: 14:10

Frame No: 4

Site Location: PSY

Direction: Northeast

Comments: _____

Checklist
Reference: _____

Northeast side of site with MW 8 cluster in foreground. B. Pinette's garage in background



MW-5 cluster with northern fence line in background.

Photographer: J. Ehret

Date: 8/16/00

Time: 14:25

Frame No: 5

Site Location: PSY

Direction: North

Comments: _____

Checklist
Reference: _____



MW-7 cluster.

Photographer: J. Ehret

Date: 8/16/00

Time: 14:30

Frame No: 6

Site Location: PSY

Direction: Southwest

Comments: _____

Checklist
Reference: _____



Photographer: J. Ehret

Date: 8/16/00

Time: 14:50

Frame No: 7

Site Location: PSY

Direction: Northeast

Comments: _____

Checklist
Reference: _____

MW-1 cluster area (wells obscured by tall grass).



Photographer: J. Ehret

Date: 8/16/00

Time: 15:00

Frame No: 8

Site Location: PSY

Direction: Southwest

Comments: _____

Checklist
Reference: _____

Looking toward the site through large (~30') break in northwest corner of fence



MW-9 cluster, wells broken at grade.

Photographer: J. Ehret

Date: 8/16/00

Time: 15:10

Frame No: 9

Site Location: PSY

Direction: N/A

Comments: _____

Checklist
Reference: _____



Well risers and surface seals stockpiled by Roger Pinetta

Photographer: J. Ehret

Date: 8/16/00

Time: 15:20

Frame No: 10

Site Location: PSY

Direction: N/A

Comments: _____

Checklist
Reference: _____

Pinette's Salvage Yard Superfund Site - Five Year Review
 EPA Contract Number 68-W6-0042
 Work Assignment Number 054-FRFE-0134
 PHOTOGRAPHIC RECORD



Photographer: J. Ehret

Date: 8/16/00

Time: 15:35

Frame No: 11

Site Location: PSY

Direction: North

Comments: _____

Checklist
 Reference: _____

Roger Pinette's garage with old site sign used as siding.



Photographer: J. Ehret

Date: 8/16/00

Time: 15:55

Frame No: 12

Site Location: PSY

Direction: N/A

Comments: _____

Checklist
 Reference: _____

DMW-4 destroyed.

Pinette's Salvage Yard Superfund Site - Five Year Review
EPA Contract Number 68-W6-0042
Work Assignment Number 054-FRFE-0134
PHOTOGRAPHIC RECORD



MW-3 cluster well destroyed.

Photographer: J. Ehret

Date: 8/16/00

Time: 16:15

Frame No: 13

Site Location: PSY

Direction: N/A

Comments: _____

Checklist
Reference: _____



Site fence from main gate looking down Gardner Creek road, Rita Pinette's residence in background.

Photographer: J. Ehret

Date: 8/16/00

Time: 16:25

Frame No: 14

Site Location: PSY

Direction: Northeast

Comments: _____

Checklist
Reference: _____

Pinette's Salvage Yard Superfund Site - Five Year Review
EPA Contract Number 68-W6-0042
Work Assignment Number 054-FRFE-0134
PHOTOGRAPHIC RECORD

Photographer: J. Ehret

Date: 8/16/00

Time: 16:40

Frame No: 15

Site Location: PSY

Direction: Northwest

Comments: _____

Checklist

Reference: _____



Main site gate.