Volume III Table of Contents

Section		Pages	Date
	Purpose and Overview of the Quality Assurance Handbook	3	1-04-85
3.0	General Aspects of Quality Assurance for Stationary Source Emissions Testing Programs		
3.0.1 3.0.2	Planning the Test Program General Factors Involved in Stationar	12 y 9	5-01-79 5-01-79
3.0.3	Source Testing Chain-of-Custody Procedure for Source Sampling	7	5-01-79
3.0.4	Procedure for NBS Traceable Certification of Compressed Cas Worki Standards Used for Calibration and Au	dit	- 6 09 0 7
	of Continuous Source Emission Monitor	ing	
3.0.5	Revised Traceability Protocol No. 1 Specific Procedures to Assess Accurac of Reference Methods Used for SPNSS	у 58	9-23-85
3.0.6	Specific Procedures to Assess Accurac of Reference Methods Used for NESHAP	y 14	9-23-85
3.0.7	Calculation and Interpretation of Accuracy for Continuous Emission Monitoring Systems (CEMS)	14	11-05-85
3.0.8	Audit Materials Available from U.S.E.P.A.	7	11-04-85
3.0.9	Continuous Emission Monitoring System (CEMS) Good Operating Practices	s 47	6-01-86
3.0.10	Guideline for Developing Quality Control Procedures for Gaseous Continuous Emission Monitoring Systems	11	11-26-85
3.1	Method 2-Determination of Stack Gas Velocity and Volumetric Flow Rate		
3.1.1 3.1.2	Procurement of Apparatus and Supplies Calibration of Apparatus	15 21	1-15-80 1-15-80
3.1.3	Presampling Operations	7	1-15-80
3.1.4	On-Site Measurements	12	1-15-80
3.1.5	Postsampling Operations	3	1-15-80
3.1.6	Calculations	4	1-15-80
3 1.7	Maintenance	1	1-15-80
3.1.8	Auditing Procedure	5	1-15-80
3.1.9 —	Recommended Standards for Establishin Traceability	g 1	1-15-80
3.1.10	Reference Method	11	1-15-80
3.1.11	References	. 2	1-15-80
3.1.12	Data Forms	8	1-15-80

Section	. P	ages	Date
3.2	Method 3Determination of Carbon Dioxide. Oxygen Excess Air. and Dry Molecular Weight		
3.2.1 3.2.2 3.2.3 3.2.4 3.2.5	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations	15 4 6 12	1-15-80 1-15-80 1-15-80 1-15-80 1-15-80
3.2.6 3.2.7 3.2.8 3.2.9	Calculations Maintenance Auditing Procedure Recommended Standards for Establishing Traceability	3 1 5 1	1-15-80 1-15-80 1-15-80 1-15-80
3.2.10 3.2.11 3.2.12	Reference Method References Data Forms	3 1 6	1-15-80 1-15-80 1-15-80
3.3	Method 4-Determination of Moisture in Stack Gases		
3.3.1 3.3.2 3.3.3 3.3.4 3.3.5	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations	9 19 7 10 4	1-15-80 1-15-80 1-15-80 1-15-80
3.3.6 3.3.7 3.3.8 3.3.9	Calculations Maintenance Auditing Procedure Recommended Standards for Establishing Traceability Reference Method	8 3 4 1	1-15-80 1-15-80 1-15-80 1-15-80
3.3.11		1 14	1-15-80 1-15-80 1-15-80
3.4	Method 5-Determination of Particulate Emissions from Stationary Sources		
3.4.1 3.4.2 3.4.3 3.4.4 3.4.5 3.4.6 3.4.7	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance	15 22 20 19 15 10	1-15-80 1-15-80 1-15-80 1-15-80 1-15-80 1-15-80 1-15-80
3.4.8 3.4.9	Auditing Procedure Recommended Standards for Establishing Traceability Reference Method	7 1 6	1-15-80 1-15-80 1-15-80
3.4.11	References Data Forms	2 21	1-15-80 1-15-80
3.5 Method 6-Determination of Sulfur Dioxide Emissions from Stationary Sources			
3.5.1 3.5.2 3.5.3 3.5.4 3.5.5 3.5.6 3.5.7 3.5.8 3.5.9	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure Recommended Standards for Establishing	6 6 3 7 7 2 1 6	5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 9-23-85 5-01-79
	Traceability		

Sec	tion	F	ages	Date
_ 3	3.5.10 3.5.11 3.5.12	Reference Method References Data Forms	4 1 13	5-01-79 5-01-79 5-01-79
3	3.6	Method 7-Determination of Nitrogen Oxide Emissions from Stationary Source	∌ 8	
3 3 3 3 3 3	3.6.1 3.6.2 3.6.3 3.6.4 3.6.5 5.6.6 3.6.7	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure Recommended Standards for Establishing Traceability	5 5 8 5 4 1 6	5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 9-23-85 5-01-79
3	6.6.10 6.11 6.6.12	Reference Method References Data Forms	5 1 13	5-01-79 5-01-79 5-01-79
3	.7	Method 8-Determination of Sulfuric Mis and Sulfur Dioxide Emissions from Stationary Sources	st .	
3 3 3 3 3 3	7.1 .7.2 .7.3 .7.4 .7.5 .7.6 .7.7 .7.8	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure Recommended Standards for Establishing Traceability	7 10 4 10 9 6 2 3	5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 5-01-79 5-01-79
3	.7.10 .7.11 .7.12	Reference Method References Data Forms	5 1 17	5-01-79 5-01-79 5-01-79
3	.8	Method 10-Determination of Carbon Monoxide Emissions from Stationary Sources		
3 3 3 3 3 3	.8.1 .8.2 .8.3 .8.4 .8.5 .8.6 .8.7 .8.8	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure Recommended Standards for Establishing Traceability	13 18 6 12 5 3 2 7	1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82
3	.8.10 .8.11 .8.12	Reference Method References Data Forms	3 2 11	1-04-82 1-04-82 1-04-82

Section	:	Pages	Date
3.9	3.9 Method 13B-Determination of Total Fluoride Emissions from Stationary Sources (Specific-Ion Electrode Method)		
3.9.1 3.9.2 3.9.3 3.9.5 3.9.5 3.9.6 3.9.6 3.9.7	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure	25 6 21 19 7 3	1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82
3.9.10 3.9.11 3.9.12	Recommended Standards for Establishin Traceability Reference Method References Data Forms	2 1 22	1-04-82 1-04-82 1-04-82 1-04-82
3.10	Method 13A-Determination of Total Fluoride Emissions from Stationary Sources (SPADNS Zirconium Lake Method)	
3.10.1 3.10.2 3.10.3 3.10.4 3.10.5 3.10.6 3.10.7	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance	5 3 3 18 7 2	1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82
3.10.11	Auditing Procedure Recommended Standards for Establishin Traceability Reference Method References Data Forms	1 g 1 5 1 6	1-04-82 1-04-82 1-04-82 1-04-82 1-04-82
3.11	Method 17-Determination of Particulat Emissions from Stationary Sources (In-Stack Filtration Method)		1-04-62
3.11.1 3.11.2 3.11.3 3.11.4 3.11.5 3.11.6 3.11.7 3.11.8 3.11.9	Procurement of Apparatus and Supplies Calibration of Apparatus Presampling Operations On-Site Measurements Postsampling Operations Calculations Maintenance Auditing Procedure Recommended Standards for Establishin	2 3 6 1 2 2	1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82 1-04-82
3.11.11	Traceability Reference Method References Data Forms	11 1 1	1-04-82 1-04-82 1-04-82
3.12	Method 9-Visible Determination of the Opacity Emissions from Stationary Sources		
3.12.1 3.12.2 3.12.3	Certification and Training of Observe Procurement of Apparatus and Supplies Preobservation Operations		4-20-83 4-20-83 4-20-83

Section	F	ages	Date
3.12.4 3.12.5 3.12.6 3.12.7		18 2 7 2	4-20-83 4-20-83 4-20-83 4-20-83
3.12.8	Reference Method	5	4-20-83
3.12.9 3.12.10	References and Bibliography Data Forms	1 9	4-20-83 4-20-83
3.13	Methods 6A and 6B-Determinations of Sulfur Dioxide. Moisture. and Carbo Dioxide Emissions from Fossil Fuel Combustion Sources	on	
3.13.1	Procurement of Apparatus and Supplies	18	7-01-86
3.13.2	Calibration of Apparatus	14	7-01-86
3.13.3 3.13.4	Presampling Operations On-Site Measurements	6 2 5	7-01-86
3.13.5		25 15	7-01-86 7-01-86
3.13.6		9	7-01-86
	Maintenance	3	7-01-86
3.13.8		11	7-01-86
3.13.9		, 1	7-01-86
	Reference Method	5	7-01-86
	References	2	7-01-86
3.13.12	Data Forms	18	7-01-86
3.14	Method 7A-Determination of Nitrogen Oxide Emissions from Stationary Sources (Grab Sampling-Ion Chromatographic Method)		
3.14.1	Procurement of Apparatus and Supplies	10	7-01-86
3.14.2	Calibration of Apparatus	14	7-01-86
3.14.3	Presampling Operations	6	7-01-86
3.14.4	On-Site Measurements	7	7-01-86
3.14.5	Postsampling Operations	11	7-01-86
3.14.6	Calculations	6	7-01-86
3.14.7	Maintenance	2	7-01-86
3.14.8		6	7-01-86
3.14.9	Recommended Standards for Establishing Traceability	1	7-01-86
	Reference Method	3	7-01-86
	References Data Forms	2	7-01-86
3.15	Method 7D-Determination of Nitrogen Oxide Emissions from Stationary Sources (Alkaline-Permanganate-Ion Chromatographic Method)	12	7-01-86
3.15.1	Procurement of Apparatus and Supplies	18	7-01-86
3.15.2	Calibration of Apparatus	20	7-01-86
3.15.3	Presampling Operations	6	7-01-86
3.15.4	On-Site Measurements	10	7-01-86
3.15.5	Postsampling Operations	13	7-01-86
3.15.6 3.15.7	Calculations Maintenance	5.	7-01-86
3.15.7	Auditing Procedure	3	7-01-86
3.15.9	Recommended Standards for Establishing Traceability	6	7-01-86 7-01-86

Section		Pages	Date
3.16	Method 18-Measurement of Gaseous Organic Compound Emissions by Gas Chromatography		
3.16.1	Summary and Method Highlights Procurement of Apparatus and Supplies	22 16	6-30-88 6-30-88
3.16.2	Calibration of Apparatus	15	6-30-88
3.16.3		44	6-30-88
3.16.4		33	6-30-88
3.16.5		39	6-30-88
	Calculations Maintenance	6	-30-88
	Auditing Procedure	3 8	6-30-88
	Recommended Standards for	8 1	6-30-88 6-30-88
3.10.5	Establishing Traceability	1	6-30-66
3.16.10	Reference Methods	22	6-30-88
	References	5	6-30-88
3.16.12	Data Forms	21	6-30-88
3.17	Method 25-Determination of Total Gaseous Nonmethane Organic Emissions as Carbon from Stationary Sources	•	
	Summary and Method Highlights	5	-31 -91
3.17.1	Procurement of Apparatus and Supplies	25	5-31-91
3.17.2	Calibration of Apparatus	9	5-31-91
3.17.3	Presampling Operations	9	5-31-91
	On-site Measurements/	14	5-31-91
	Postsampling Operations	30	5-31-91
	Calculations	11	5-31-91
	Maintenance	2	5-31-91
	Auditing Procedure	9	5-31-91
3.17.9	Recommended Standards for Establishing Traceability	1	5-31-91
3.17.10	Reference Methods	25	5-31-91
3.17.11	References	1	5-31-91
3.18	Method 23- Not Yet Available		
3.19	Method 101A-Determination of		
	Particulate and Gaseous Mercury		
	Emissions from Stationary Sources		
	Summary and Method Highlights	3	9-3-92
3.19.1	Procurement of Apparatus and	18	9-3-92
	Supplies		
3.19.2	Calibration of Apparatus	25	9-3-92
3.19.3	Presampling Operations	7	9-3-92
3.19.4 3.19.5	On-site Measurements Postsampling Operations	19 29	9-3-92
3.19.5	Calculations	29 10	9-3 -92 9-3 -92
3.19.7	Maintenance	4	9-3-92
	Auditing Procedure	4	9-3-92
3.19.9	Recommended Standards for	i	9-3-92
- -	Establishing Traceability	-	-
	Reference Methods	18	9-3-92
3.19.11	References	2	9-3-92