PETTIT

marine paint

UNEPOXY

ACTIVE INGREDIENTS	
Cuprous Oxide	45.00%
Bis (tributyltin) Oxide	1.30%
INERT INGREDIENTS	53.70%
	100.00%

COPPER AS METALLIC 40.00%

This product contains petroleum distillates.

ANTI FOULING
1224 BLUE
PACIFIC FORMULA

32 FL.OZ. (1 QT.) 946 mL

KEEP OUT OF REACH OF CHILDREN.

DANGER! SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS.

PETTIT PAINT CO., INC. BOROUGH OF ROC

PETTIT

marine paint

UNEPOXY

ANTI FOULING
1224 BLUE
PACIFIC FORMULA

ACTIVE INGREDIENTS	
Cuprous Oxide	45.00%
Bis (tributyltin) Oxide	1.30%
INERT INGREDIENTS	53.70%
	100.00%

COPPER AS METALLIC 40.00%

This product contains petroleum distillates.

(1 QT.) 946 mL

KEEP OUT OF REACH OF CHILDREN.

DANGER! SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS.

ETTIT PAINT CO., INC. BOROUGH OF ROCKAWAY, N.J. 07866 - SPRING VALLEY, CALIF. 92077

[illegible]

[illegible] such as gloves, [illegible] shirt, [illegible] pants, [illegible] hat. [illegible] eye irritation. [illegible] be fatal if swallowed. Material is absorbed through skin [illegible] inhaled. [illegible] this product may be a dermal sensitizer. Avoid contact with skin, eyes, [illegible] clothing. Avoid breathing vapor; spray mist; dust or chips from [illegible]. Wash the exposed skin with soap and water after handling and before [illegible] ventilation.

[illegible]

[illegible] available, [illegible] water [illegible]

[illegible]

[illegible]

[illegible]

[illegible] "generate during paint removal [illegible] enter [illegible] dispose of paint chips in an approved landfill."

PHYSICAL & CHEMICAL HAZARDS

[illegible] open flame.

(continued on right hand panel)

BEST DOCUMENT AVAILABLE

(continued from left hand panel)

DIRECTIONS FOR USE

It is a violation of federal law to use this product in a manner inconsistent with its labeling.
NOTE - When product is used in confined areas or applied by spraying, wear a respirator jointly approved by the Mining Enforcement and Safety Administration (formerly the U.S. Bureau of Mines) and by the National Institute for Occupational Safety and Health under the provisions of 30 CFR 11.

GENERAL DESCRIPTION

Epoxy is an anti-fouling protective coating resistant to algae, barnacles and other marine fouling.

STORAGE & DISPOSAL

Pesticide, spray mixture, or rinse water that cannot be used according to label instructions must be disposed of according to Federal or approved state procedures under Subtitle C of the Resource Conservation and Recovery Act.

Container Disposal

[illegible] reconditioning, [illegible] dispose [illegible] their approved [illegible] procedures.

E.P.A. REG. NO. .....[illegible]-25
E.P.A. EST. NO. .....390-[illegible]-1

BEST DOCUMENT AVAILABLE

[illegible] is a hard [illegible] antifouling paint for use on [illegible] bottoms [illegible] paint adhesion.

PREPARATION OF SURFACE: The surface to be painted should be dry, clean, and oil free. It should be properly prepared by solvent cleaning and/or sanding before any primers or paints are applied. Follow the recommended systems below. When sanding an antifouling paint, wear a face mask to prevent the inhalation of sanding dust.

APPLICATION AND TEMPERATURE: Unepoxy can be applied by brush, roller or spray. The work should be done between 9:00 a.m. and 4:00 p.m. under good drying conditions. The temperature range of application is 40° to 90° F. Two coats [illegible].

PREPARATION OF PAINT: [illegible] with cuprous oxide. As a result [illegible] there [illegible] settling to occur especially if the paint has been on the shelf for several months. It is necessary to thoroughly mix the paint before use. If possible shake the can of paint on a mechanical paint shaker. [illegible] check the sides and bottom of the can to [illegible]. If mixing is going to be done with a wooden paddle [illegible], pour off half of the liquid from the [illegible] then properly mix in any settled pigment; then return the [illegible].

THINNER: Use Pettit's [illegible] for thinning the Unepoxy on a warm [illegible] day [illegible]. Do not over thin Unepoxy or inadequate [illegible] Thinner for spray application.

DRY TIMES: [illegible] between two to four hours minimum before applying the second coat. After the second coat is applied, let the paint dry at least eight hours or preferably overnight before immersing the boat. Under adverse drying conditions let the boat dry overnight to make sure all the solvent is out of the paint film. Maximum immersion time is two months.

COVERAGE: Unepoxy covers approximately 400 square feet per gallon.

MAINTENANCE OF ANTIFOULING PAINT: No antifouling paint can be effective under all conditions of exposure. Manmade pollution and natural occurrences can adversely affect antifouling paint performance. Extreme hot and cold water temperatures, silt, dirt, oil, brackish water, and even electrolysis can ruin an antifouling paint. Therefore, we strongly suggest that the boat be checked several times a month to make sure it is clean and that no growth is occurring. Lightly scrub the bottom with a soft brush to remove anything from the anti-fouling paint surface.

PAINT SYSTEMS

BEST DOCUMENT AVAILABLE

FIBERGLASS: Wash the fiberglass with Pettit's 12120 Brushing Thinner or 15095 Dewaxer to remove parting agent, grease, and dirt. Sand thoroughly with 80-120 grit sandpaper to dull the glossy fiberglass surface. Rewash the sanded surface and then apply two coats of Unepoxy. To skip the sanding operation after the hull has been washed, apply a coat of Pettit's 6004 Skip Sand primer. Then apply two coats of Unepoxy.

BLISTERED GELCOTE: Remove all antifouling paint by sanding or using Pettit's 9030 Fiberglass Paint & Varnish Remover. Sand the gelcote and fill any voids with Pettit's 7190 Polyester Mender. Sand smooth, apply a coat of Pettit's 4169 Polypoxy Undercoater/4027 Polypoxy Brush Hardener. Let dry 24 hours minimum, sand lightly and then apply two coats of Unepoxy.

[illegible] N HULLS: [illegible] be thoroughly sanded or scraped [illegible] wood, apply one coat of Pettit's [illegible] Lead Primer and let dry for 24 hours. Sand lightly and apply two coats of Unepoxy.

STEEL HULLS, UNDERWATER METAL PARTS, LEAD KEELS: To remove old rust and scale [illegible] the metal surface scrape or sandblast with wire brush. Wash the surface [illegible] Pettit's 12120 Brushing [illegible] remove grease and dirt. Apply one [illegible] of Pettit's Metal Primer [illegible] metal and let dry four hours. Follow [illegible] two coats of Pettit's [illegible] bottom and let dry two hours between coats and [illegible] hours before applying two coats of Unepoxy.

DO NOT USE THIS [illegible] ALUMINUM HULLS AND OUTDRIVES.