**RECOMMENDED FOR:**
**ALL WOOD, PLYWOOD, FIBERGLASS AND PROPERLY PRIMED METAL BOATS.**

THE SPECIAL WATER RESISTANT ACRYLIC RESINS IN COMBINATION WITH TBTF PROVIDE EFFECTIVE PROTECTION AGAINST BARNACLES, TEREDOS, ALGAE, AND OTHER MARINE FOULING ORGANISMS

**FEATURES:**

**• TBTF (Tributyltin Fluoride) has been proven a most effective anti-fouling toxicant • The water resistant acrylic base develops a hard, medium gloss finish, yet allows proper release of TBTF to retard most growth or attachment • Formulated in "fade resistant" rich, bright colors. • TBTF remains effective . . . even if boat is pulled from water and relaunched frequently.**

**DIRECTIONS FOR USE: IT IS A VIOLATION OF FEDERAL LAW TO USE THIS PRODUCT IN A MANNER INCONSISTENT WITH ITS LABELING.**

**DO NOT SPRAY! WEAR MASK WHILE SANDING TO AVOID BREATHING PAINT DUST.**

**BEFORE YOU PAINT:** Surface should be clean and sound. Check adhesion of old paint with a knife blade before painting over previously painted surfaces. If old paint lifts easily or is in generally poor condition it should be removed. Previous coats of "soft" or "semi-hard" bottom paints identifiable by a chalky or powdery feel should be completely removed. Use Sears PAINT AND VARNISH REMOVER (except on fiberglass) or power sanding to remove old paint.

**OLD PAINT IN GOOD CONDITION:** Sand thoroughly to remove gloss, then wipe with Sears EPOXY and LACQUER THINNER. Apply two or three coats unthinned.

**NEW OR UNFINISHED WOOD:** Sand thoroughly, caulk seams and cracks. Apply first coat thinned 25% with Sears EPOXY and LACQUER THINNER and allow to dry several hours. Sand lightly before applying two or three coats unthinned.

**FIBER GLASS:** Sand thoroughly to remove gloss. Wash surface with Sears *EPOXY* and *LACQUER THINNER* to remove grease, wax and mold release agent. Apply two or three finish coats unthinned.

**METALS:** (Steel and Aluminum) Preparation of metal below the water line is extremely critical. *Complete insulation from water is necessary to prevent pitting and other permanent damage. Remove all* rust and corrosion with steel wool or by sanding until the metal is bright. Sand pit marks smooth. Finish sand with very fine emery cloth to remove protruding metal slivers. Wipe surface with Sears EPOXY and LACQUER THINNER *to remove traces of oil, grease or wax. Prime with Sears MARINE* METAL PRIMER following the instructions given on the label of that product. Apply two or three finish coats unthinned.

**APPLICATION:**

*For boats used in fresh water apply a minimum of two coats of Sears ANTI-FOULING BOTTOM PAINT.* At least three coats should be used for boats in salt water. For best results, avoid painting in direct sunlight. Stir paint thoroughly before and during application. Flow on paint generously with good quality bristle brush or enamel roller. *Allow at least four hours drying time between coats. Allow at least* forty-eight hours after application of last coat before boat is launched. Clean brushes and other tools with Sears EPOXY and LACQUER THINNER immediately after using. *NOT RECOMMENDED FOR USE ON STYROFOAM.*

**NOTE:** Scratches and gouges that penetrate the paint to bare metal should be repaired to avoid damage from corrosion or "galvanic action". Sand damaged areas to bare metal and follow above directions for painting metals.

**COVERAGE:** Approximately 100 sq. ft. (9.3 sq. meters) per quart.

**Manufactured for Sears by**
**DeSoto, Inc., 1700 South Mt. Prospect Rd., Box 5050, DesPlaines, IL. 60017**

# MARINE

EASY

# ANTI-FOULING BOTTOM PAINT

with TBTF for salt or fresh water

MY6365H

DES0

## PRECAUTIONARY STATEMENTS:

**DANGER: HAZARDS TO HUMANS AND DOMESTIC ANIMALS**

Corrosive: Causes irreversible eye damage and skin burns. Harmful if absorbed through skin. Avoid getting in eyes or on skin or on clothing. Wear protective eyeglasses or safety glasses. Wear protective clothing such as long sleeved shirt and long pants, hat and gloves. Wash thoroughly with soap and water after handling. Remove contaminated clothing and wash before reuse. Avoid breathing vapor, dust or mists from sanding. To avoid overexposure to solvent vapors, open windows and doors or use other means to ensure fresh air entry during application and drying. If you experience eye watering, headaches or dizziness, increase fresh air or wear respiratory protection (NIOSH/MSHA TC-23C or equivalent), or leave the area. Do not take internally. Close container after each use.

**NOTICE:** Reports have associated repeated and prolonged occupational overexposure to solvents with permanent brain and nervous system damage. Intentional misuse by deliberately concentrating and inhaling the contents may be harmful or fatal.

**STATEMENT OF PRACTICAL TREATMENT**

If swallowed: Drink promptly a large quantity of milk, egg whites or gelatin solution. If these are not available, drink large quantities of water. Avoid alcohol. Get medical attention.

**ENVIRONMENTAL HAZARDS**

[illegible] Avoid contamination of [illegible] and dust generated during paint removal to enter water. Dispose of [illegible] as an approved waste.

**PHYSICAL OR CHEMICAL HAZARDS:**

**COMBUSTIBLE.** Do not use or store near heat, sparks and flame. Use with adequate ventilation.

**NOTE:** While sanding final surface wear a respirator jointly approved by the Mine Safety Appliances Company and the National Institute for Occupational Safety and Health.

**STORAGE AND DISPOSAL:**

Securely wrap original container in several layers of newspaper and discard in trash.

**KEEP OUT OF REACH OF CHILDREN**

KEEP OUT OF REACH OF CHILDREN
DANGER
See Side Panel for Additional Precautionary Statements

30 6365 GOLD BRONZE

NET CONTENTS 32 FL OZ (1 QT)

EPA REG. NO. 10182-
EPA EST. NO. 8[illegible]-[illegible]

[illegible] 1 1980

Un[illegible]
Fungi[illegible]
as amended, for the
registered under
EPA Reg. No. 10182-