DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION

Interim Final 2/5/99

RCRA Corrective Action
Environmental Indicator (EI) RCRIS code (CA725)

Current Human Exposures Under Control

Facility Name: __ **Century Brass Products, Inc. (Retained Parcel)**___
Facility Address: ____**Silver Street, Waterbury, Connecticut**
Facility EPA ID #: _CTD060008307__

1. Has **all** available relevant/significant information on known and reasonably suspected releases to soil, groundwater, surface water/sediments, and air, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

   ___**x**__ If yes - check here and continue with #2 below.

   _____ If no - re-evaluate existing data, or

   _____ if data are not available skip to #6 and enter"IN" (more information needed) status code.

BACKGROUND

Definition of Environmental Indicators (for the RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Current Human Exposures Under Control" EI

A positive "Current Human Exposures Under Control" EI determination ("YE" status code) indicates that there are no "unacceptable" human exposures to "contamination" (i.e., contaminants in concentrations in excess of appropriate risk-based levels) that can be reasonably expected under current land- and groundwater-use conditions (for all "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Current Human Exposures Under Control" EI are for reasonably expected human exposures under current land- and groundwater-use conditions ONLY, and do not consider potential future land- or groundwater-use conditions or ecological receptors. The RCRA Corrective Action program's overall mission to protect human health and the environment requires that Final remedies address these issues (i.e., potential future human exposure scenarios, future land and groundwater uses, and ecological receptors).

Duration / Applicability of EI Determinations

EI Determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

RDMS DOC ID 105984

2. Are groundwater, soil, surface water, sediments, or air **media** known or reasonably suspected to be **"contaminated"**[1] above appropriately protective risk-based "levels" (applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action (from SWMUs, RUs or AOCs)?

	Yes	No	?	Rationale / Key Contaminants
Groundwater	X			
Air (indoors)[2]		X		
Surface Soil (e.g., <2 ft)	X			
Surface Water		X		
Sediment	X			
Subsurf. Soil (e.g., >2 ft)	X			
Air (outdoors)		X		

_____ If no (for all media) - skip to #6, and enter "YE," status code after providing or citing appropriate "levels," and referencing sufficient supporting documentation demonstrating that these "levels" are not exceeded.

__X__ If yes (for any media) - continue after identifying key contaminants in each "contaminated" medium, citing appropriate "levels" (or provide an explanation for the determination that the medium could pose an unacceptable risk), and referencing supporting documentation.

_____ If unknown (for any media) - skip to #6 and enter "IN" status code.

Rationale and Reference(s): In 2005, CTDEP hired a contractor to perform a site wide investigation of this parcel. The results of the soil, sediment, surface water and groundwater sampling and analysis are summarized in **Attachment 1.**

Footnotes:

[1] "Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriately protective risk-based "levels" (for the media, that identify risks within the acceptable risk range).

[2] Recent evidence (from the Colorado Dept. of Public Health and Environment, and others) suggest that unacceptable indoor air concentrations are more common in structures above groundwater with volatile contaminants than previously believed. This is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration necessary to be reasonably certain that indoor air (in structures located above (and adjacent to) groundwater with volatile contaminants) does not present unacceptable risks.

3. Are there **complete pathways** between "contamination" and human receptors such that exposures can be reasonably expected under the current (land- and groundwater-use) conditions?

Summary Exposure Pathway Evaluation Table

	Potential **Human Receptors** (Under Current Conditions)						
"Contaminated" Media	Residents	Workers	Day-Care	Construction	Trespassers	Recreation	Food[3]
Groundwater	NO	NO	NO	NO			NO
~~Air (indoors)~~	___	___	___				
Soil (surface, e.g., <2 ft)	NO	NO	NO	NO	YES	NO	NO
~~Surface Water~~	___	___			_____		
Sediment	NO	NO			YES	NO	NO
Soil (subsurface e.g., >2 ft)				NO			NO
~~Air (outdoors)~~	___	___	___	___	___		

Instructions for Summary Exposure Pathway Evaluation Table:

1. Strike-out specific Media including Human Receptors' spaces for Media which are not "contaminated") as identified in #2 above.

2. enter "yes" or "no" for potential "completeness" under each "Contaminated" Media -- Human Receptor combination (Pathway).

Note: In order to focus the evaluation to the most probable combinations some potential "Contaminated" Media - Human Receptor combinations (Pathways) do not have check spaces ("___"). While these combinations may not be probable in most situations they may be possible in some settings and should be added as necessary.

_____ If no (pathways are not complete for any contaminated media-receptor combination) - skip to #6, and enter "YE" status code, after explaining and/or referencing condition(s) in-place, whether natural or man-made, preventing a complete exposure pathway from each contaminated medium (e.g., use optional Pathway Evaluation Work Sheet to analyze major pathways).

_**X**__ If yes (pathways are complete for any "Contaminated" Media - Human Receptor combination) - continue after providing supporting explanation.

_____ If unknown (for any "Contaminated" Media - Human Receptor combination) - skip to #6 and enter "IN" status code

Rationale and Reference(s):___**See Attachment 2**_____

[3] Indirect Pathway/Receptor (e.g., vegetables, fruits, crops, meat and dairy products, fish, shellfish, etc.)

4 Can the **exposures** from any of the complete pathways identified in #3 be reasonably expected to be **"significant"**[4] (i.e., potentially "unacceptable" because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable "levels" (used to identify the "contamination"); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable "levels") could result in greater than acceptable risks)?

___**X**_ If no (exposures can not be reasonably expected to be significant (i.e., potentially "unacceptable") for any complete exposure pathway) - skip to #6 and enter "YE" status code after explaining and/or referencing documentation justifying why the exposures (from each of the complete pathways) to "contamination" (identified in #3) are not expected to be "significant."

_____ If yes (exposures could be reasonably expected to be "significant" (i.e., potentially "unacceptable") for any complete exposure pathway) - continue after providing a description (of each potentially "unacceptable" exposure pathway) and explaining and/or referencing documentation justifying why the exposures (from each of the remaining complete pathways) to "contamination" (identified in #3) are not expected to be "significant."

_____ If unknown (for any complete pathway) - skip to #6 and enter "IN" status code

Rationale and Reference(s):___**See Attachment 3**_____

[4] If there is any question on whether the identified exposures are "significant" (i.e., potentially "unacceptable") consult a human health Risk Assessment specialist with appropriate education, training and experience.

5 Can the "significant" **exposures** (identified in #4) be shown to be within **acceptable** limits?

_____ If yes (all "significant" exposures have been shown to be within acceptable limits) - continue and enter "YE" after summarizing and referencing documentation justifying why all "significant" exposures to "contamination" are within acceptable limits (e.g., a site-specific Human Health Risk Assessment).

_____ If no (there are current exposures that can be reasonably expected to be "unacceptable")- continue and enter "NO" status code after providing a description of each potentially "unacceptable" exposure.

_____ If unknown (for any potentially "unacceptable" exposure) - continue and enter "IN" status code

Rationale and Reference(s):

6. Check the appropriate RCRIS status codes for the Current Human Exposures Under Control EI event code (CA725), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (and attach appropriate supporting documentation as well as a map of the facility):

__X__ YE - Yes, "Current Human Exposures Under Control" has been verified. Based on a review of the information contained in this EI Determination, "Current Human Exposures" are expected to be "Under Control" at the **Century Brass Products Inc. Retained** facility, EPA ID # CTD060008307, located at **Silver St., Waterbury, CT** under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

____ NO - "Current Human Exposures" are NOT "Under Control."

____ IN - More information is needed to make a determination.

Completed by (signature)  Date 09/28/05
(print) **David Ringquist**
(title) Sanitary Engineer 3

Supervisor (signature) _____ Date 09/28/05
(print) **Diane Duva**
(title) Supervising Sanitary Analyst
(EPA Region or State) **Connecticut**

Locations where References may be found:

Connecticut Department of Environmental Protection, 79 Elm St., Hartford Connecticut 06106

Contact telephone and e-mail numbers

(name) **David Ringquist**
(phone #)**860-424-3573**
(e-mail) **david.ringquist@po.state.ct.us**

FINAL NOTE: THE HUMAN EXPOSURES EI IS A QUALITATIVE SCREENING OF EXPOSURES AND THE DETERMINATIONS WITHIN THIS DOCUMENT SHOULD NOT BE USED AS THE SOLE BASIS FOR RESTRICTING THE SCOPE OF MORE DETAILED (E.G., SITE-SPECIFIC) ASSESSMENTS OF RISK.

Attachment 1

Are groundwater, soil, surface water, sediments, or air **media** known or reasonably suspected to be **"contaminated"**[1] above appropriately protective risk-based "levels?

Groundwater

Groundwater at the site is contaminated as shown by various monitoring wells at the site. See the attached Drawing 3 showing the location of the groundwater monitoring wells and the results of the monitoring. From a report completed by Loureiro Engineering Associates, Inc.: "Groundwater collected from the Site as part of this subsurface investigation was evaluated for the presence of VOCs, SVOCs, PCBs, [Connecticut's Extractable Total Petroleum Hydrocarbons] (CT ETPH), cyanide, and various metals. Concentrations of several VOCs including PCE, TCE, 11DCA, cDCE, and VC, and several metals were reported in groundwater collected from the areas of the Site at concentrations indicative of one or more release(s) resulting from historical site activities such as the former dry cleaning operation/exterior drum storage area and metal hydroxide sludge landfill. The presence in groundwater of chlorinated hydrocarbons that may be degradation products of PCE (e.g. vinyl chloride, TCE), particularly in the vicinity of the metal hydroxide sludge area, indicates that natural degradation of chlorinated VOCs may be occurring in groundwater at the Site; however, such degradation may be occurring to a lesser degree on the northernmost portion of the Site. With the exception of copper and zinc, the concentrations of metals reported in groundwater do not exceed respective SWPC; however, the elevated concentrations of various metals (including copper and zinc) suggest that site groundwater has been impacted by one or more releases at the Site…….In several instances, the concentrations of zinc and to a lesser degree, PCE and copper, exceed respective SWPC".

Air (indoors)

There are no buildings on the site, nor are there any within approximately 500 feet of the property boundary. This media is therefore not applicable to the site.

Soil (surface, e.g., <2 ft)

Soil at the site is contaminated as shown by recent analysis of soil samples at the site. See the attached Drawing 2 showing the location of the soil samples and the analytical results. From a report completed by Loureiro Engineering Associates, Inc.:

"Soil samples collected from the Site as part of the subsurface investigation were evaluated for the presence of VOCs, SVOCs, PCBs, CT ETPH, cyanide, and various metals, depending on proximity to certain potential or confirmed release areas,……. Generally, shallow soil at the Site was found to contain elevated concentrations of several metals, particularly copper, lead, and zinc; SVOCs; and VOCs. The presence of these contaminants in shallow soil support the CSM developed for the Site, in that historical operations including metal working, exterior storage of waste materials in drums, and dry cleaning operations, have resulted in an impact to underlying soil. Further, the presence of elevated SVOCs and metals at the Site correlates to the presence of relatively shallow deposits of fill materials including coal, ash, and slag. The concentrations of these constituents of concern exceed one or more of the [Connecticut Remediation Standard Regulations] (RSR) default, numeric criteria for soil (RDEC, IDEC, and GB PMC)".

RDEC = Residential Direct Exposure Criteria
IDEC = Industrial/Commercial Direct Exposure Criteria
GB PMC = Pollutant Mobility Criteria for areas where the groundwater is classified as "GB", i.e. not suitable for drinking without treatment.

Surface Water

The Mad River, bisecting the site, was tested by LEA and the results are presented as Attachement 7. These results show that the surface water is not contaminated above human health standards.

Sediment

Sediment in the Mad River is contaminated as shown by recent analysis of sediment samples. See the attached Drawing 2 showing the location of the samples and the analytical results. From a report completed by Loureiro Engineering Associates, Inc.:

"As part of the subsurface investigation completed at the Site, six sediment samples were collected from portions of the Mad River that transect the Site. Based on the presence of two select metals (copper and zinc) at elevated concentrations, it appears that groundwater discharging to surface water and potentially historical discharges from a former on-site tail race may have resulted in an impact to sediment quality in the river."

Subsurf. Soil (e.g., >2 ft)

Soil at the site is contaminated as shown by recent analysis of soil samples at the site. See the attached Drawing 2 showing the location of the soil samples and the analytical results.

The following six paragraphs are from the Loureiro Engineering Associates, Inc. report:

"Subsurface soil samples were compared against the default, numeric direct exposure criteria (RDEC and IDEC), and pollutant mobility criteria for a GB groundwater classification area (GB PMC), as tabulated in the RSRs.

Direct Exposure Criteria

Metals were detected at concentrations exceeding the tabulated RDEC and IDEC criteria at two locations at the Site. Specifically, concentrations of arsenic and lead exceeded the RDEC and IDEC at one or more of the following locations: MW-012 (arsenic) and SB-011 (arsenic and lead).

CT ETPH were detected at concentrations exceeding the RDEC in borings MW-010 and MW-012. These two locations are located on the northern portion of the Site. Boring MW-010 is located within the Building 5 Former Drum Storage Area. Boring MW-012 is located within an area identified as a former head race, east of Building 5 at the Site.

SVOCs were detected at concentrations above the RDEC and IDEC at one location at the Site. Concentrations of the following SVOCs exceeded the noted default, numeric criteria tabulated in the RSRs: benzo(a)anthracene (RDEC and IDEC), benzo(b)fluoranthene (RDEC and IDEC), benzo(a)pyrene(RDEC and IDEC), indeno(1,2,3-c,d)pyrene (RDEC).

The compound PCE was detected at concentrations above the RDEC in locations SB-007 and SB-008. Both of these locations are located in the Building 5 Former Drum Storage Area.

Pollutant Mobility Criteria

SVOCs were detected at concentrations above the GB PMC at only one location at the Site, MW-010. Specifically, benzo(a)anthracene, benzo(b)fluoranthene, benzo(a)pyrene, indeno(1,2,3-c,d)pyrene, carbazole, and chrysene, exceeded their respective criteria as tabulated in the RSRs. Boring MW-010 is located within the Building 5 Former Drum Storage Area. VOCs were detected at concentrations exceeding the GB PMC in two locations. Specifically, PCE and TCE were both detected at a concentration exceeding the GB PMC in boring SB-007. PCE was also detected at a concentration exceeding the GB PMC in boring SB-008. Both of these sampling locations are located within the Building 5 Former Drum Storage Area."

Air (outdoors)

There are no on-going processes or sources of soil contamination at the site that would produce significant air emissions. Although ambient air was not monitored, CTDEP made the judgment that it is not reasonably suspected to be contaminated above appropriately protective risk-based levels.

Attachment 2

Are there **complete pathways** between "contamination" and human receptors such that exposures can be reasonably expected under the current (land- and groundwater-use) conditions?

Groundwater

There are no pathways between contaminated groundwater and any of the possible receptors under current conditions. The site is located in Waterbury where city water is provided to the residential properties adjacent to the site, therefore groundwater is not used as a drinking water source. In addition, contaminants in the groundwater that originate at the site are unlikely to migrate offsite since the groundwater discharges to the Mad River, as discussed in the Loureiro report: "*Based on an evaluation of groundwater elevation data, groundwater along the eastern portion of the Site appears to discharge to the Mad River, which transects the Site from south to north. Based on the near proximity of certain well locations to the Mad River and the interpreted groundwater flow direction, it appears that groundwater data collected as part of this subsurface investigation is representative of groundwater discharging into the Mad River."* (See Drawing 3, groundwater contour map).

Soil (surface, e.g., <2 ft), Surface Water, Sediment

Because this is an abandoned site that has a poorly maintained perimeter fence and no trespassing signs, the only potential human receptors under current conditions are trespassers.

Soil (subsurface e.g., >2 ft)

There are no pathways between contaminated subsoil and the intermittent trespasser, the only potential human receptor. These people are unlikely to excavate soil that would result in an exposure to contaminants in soil greater than two feet deep. In fact, in the past 15 years since the site has been abandoned, there has been no observed evidence of this activity at the site.

Attachment 3

Can the **exposures** from any of the complete pathways identified in #3 (of the checklist) be reasonably expected to be **"significant"**[4] (i.e., potentially "unacceptable" because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable "levels" (used to identify the "contamination"); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable "levels") could result in greater than acceptable risks)?

Soil (surface, e.g., <2 ft), Surface Water, Sediment

Because this is an abandoned site, the only potential human receptors under current conditions are trespassers. Exposures from complete pathways between contaminated surface soil, surface water (Mad River), sediment (Mad River) and trespassers are not reasonably expected to be significant due to the very low exposure frequency resulting from:

- The limited exposure time. Trespassers are generally on foot or bicycle. They pass through the site and spend very little time at the site. Motorcycles and all-terrain vehicles have been observed at the site. This appears to occur infrequently as there are no worn trails, a common characteristic of high-use areas;
- The local law enforcement agency makes an effort to keep people out of the site;
- There are a limited number of areas at the site (as shown on Drawing 2) that are contaminated to levels that exceed risk-based criteria.
- It is unlikely that trespassers would use the Mad River for swimming or fishing. These activities have never been observed or reported during the 15 years the CTDEP has been overseeing this site. The Mad River at this location is not an attractive location for either of these uses.
- The site has a perimeter fence and warning signs that, while not in perfect condition, are able to keep people from trespassing to some degree.

Attachment 4

Has the **migration** of contaminated groundwater **stabilized** (such that contaminated groundwater is expected to remain within "existing area of contaminated groundwater" as defined by the monitoring locations designated at the time of this determination)?

Based on the data presented on Drawing 3 (attached) of the Loureiro report, we can conclude that contaminated groundwater is expected to remain within the existing area of contaminated groundwater because the groundwater discharges to the Mad River. This conclusion is supported by: 1) the groundwater contours on the eastern side of the Mad River, 2) comparison of VOC concentrations on the eastern side of the river to the western side, and 3) the elevated level of metals found in the Mad River sediments.

The groundwater contours, as shown on Drawing 3 of the Loureiro report (attached), show that the flow is toward the west and northwest, i.e. toward the river. The Loureiro report states: "Groundwater elevations for the Site (on the eastern side of the Mad River) exhibit a decreasing trend from southeast to northwest, indicating an overall flow direction of shallow groundwater towards the northwest and the Mad River. Based on an evaluation of the topographic and geologic maps, as well as the thickness and distribution of the unconsolidated deposits in the vicinity of the Site, it is possible that groundwater from deeper zones in the overburden aquifer beneath the Site migrates beneath the Mad River without directly discharging to the river in the immediate vicinity of the Site. However, the bedrock high located west and north of the Site would limit migration of overburden groundwater in that direction, and it is more likely that deeper groundwater from the Site follows the general trend of the Mad River Valley to the north."

The VOC concentrations at monitoring well D3 (eastern side of river) show elevated levels of vinyl chloride, perchloroethylene, and trichloroethylene. These same constituents are all non-detect at well MW-11D, located on the opposite side and down stream of the river. Both wells are screened at similar depths.

The sediment contains elevated levels of lead and copper. This could be the result of either surface water run-off or the discharge of contaminated groundwater into the Mad River, or both.

Attachment 5

Is the **discharge** of "contaminated" groundwater into surface water likely to be **"insignificant"** (i.e., the maximum concentration[3] of each contaminant discharging into surface water is less than 10 times their appropriate groundwater "level," and there are no other conditions (e.g., the nature, and number, of discharging contaminants, or environmental setting), which significantly increase the potential for unacceptable impacts to surface water, sediments, or eco-systems at these concentrations)?

The discharge of contaminated groundwater into surface water is insignificant, based on a recent analysis of surface water samples that show no exceedances of the human or ecological risk-based standards. The surface water data can be found at Attachment 7. The surface water sample locations can be found on Drawing 1, attached.

Attachment 6
Bibliography

Loureiro Engineering Associates, Inc., 2005, Subsurface Investigation Report, Former Centruy Brass Products, Waterbury, Connecticut

Attachment 7

Surface Water Analytical Data

	Sample Date	9/19/2005	9/19/2005	9/19/2005	9/19/2005
	Sample Time	10:15	11:15	13:50	14:25
	Laboratory	Spec	Spec	Spec	Spec
	Lab. Number	SA34453-10	SA34453-12	SA34453-14	SA34453-16
Date Metals Analyzed	Units	9/23/2005	9/23/2005	9/23/2005	9/23/2005
Arsenic	mg/l	<0.004	<0.004	<0.004	<0.004
Barium	mg/l	0.0227	0.0192	0.0185	0.0183
Cadmium	mg/l	<0.0012	<0.0012	<0.0012	<0.0012
Chromium, Total	mg/l	<0.0025	<0.0025	<0.0025	<0.0025
Copper	mg/l	0.0025	<0.0025	0.0028	0.0044
Lead	mg/l	<0.0038	<0.0038	<0.0038	<0.0038
Mercury	mg/l	<0.0002	<0.0002	<0.0002	<0.0002
Nickel	mg/l	<0.0025	<0.0025	<0.0025	0.0051
Selenium	mg/l	<0.0075	<0.0075	<0.0075	<0.0075
Silver	mg/l	<0.005	<0.005	<0.005	<0.005
Zinc	mg/l	<0.04	<0.04	0.0427	<0.04
Date VOCs Analyzed	Units	9/22/2005	9/22/2005	9/22/2005	9/22/2005
cis-1,2-dichloroethylene	ug/l	ND	ND	ND	5.5
Naphthalene	ug/l	ND	ND	ND	1.2
Tetrachloroethylene	ug/l	ND	ND	ND	4.8

Location	
SW-001	Upstream of site, at confluence of unnamed brook and Mad River.
SW-002	90' West of location MW-003.
SW-003	75' Northwest of location MW-007.
SW-004	Furthest downstream, collected beneath Silver St Express overpass.

LEGEND

- ASBESTOS SAMPLES
- MONITORING WELL
- SEDIMENT SAMPLE
- SOIL BORING
- SOIL SAMPLE
- SURFACE WATER SAMPLE
- MH MANHOLE
- FORMER BUILDING OUTLINE (APPROXIMATE)
- STRUCTURES
- EDGE OF PAVED ROAD
- EDGE OF GRAVEL ROAD
- FENCE
- PROPERTY LINE (APPROXIMATE)
- WATERCOURSE (APPROXIMATE)

HAMILTON PARK

METAL HYDROXIDE SLUDGE LANDFILL

SILVER STREET EXPRESS

ST. JOSEPH'S CEMETERY

INTERSTATE 84

MAD RIVER

MAD RIVER

FORMER HEAD RACE

FORMER TAIL RACE

FORMER TRANSFORMER BANK

BUNKERS

A-22 BUNKER

APPROXIMATE FORMER UST AREA

VAULT

MH/MH

SS-023 SS-022 SS-020 SS-019 SS-021 SS-017 SS-016

SS-009R SS-008R SS-014 SS-013 SS-012 SS-011 SS-010 SS-007R SS-006R SS-005R SS-004R SS-003R SS-002R SS-001R SS-001T SS-015

MW-001 MW-002 MW-003 MW-004 MW-005 MW-006 MW-007 MW-009 MW-010 MW-011D MW-013

SB-009 SB-012 SB-004 SB-013 SB-011 SB-014 SB-008a SB-015 SB-008 SB-007 SB-005 SB-006 SB-016 SB-001 SB-002 SB-003

SW-001 SW-002 SW-003 SW-004

SD-01 SD-02 SD-03 SD-04 SD-05 SD-06

U-1 EW-1 D2 D3 D4

A-01 A-02 A-03 A-04 A-05 A-06 A-07 A-08 A-09 A-10 A-11 A-12 A-13 A-14 A-15 A-16 A-17 A-18 A-19 A-20 A-21 A-23 A-24

DRAFT

30 0 30 60 90
SCALE IN FEET

REV.	DESCRIPTION OF REVISION	DATE	APPR.

Loureiro Engineering Associates, Inc.
100 Northwest Drive • Plainville, Connecticut 06062
An Employee Owned Company

SCALE	COMM. NO.	DATE	DATE
SHOWN	18HW501.001	8/16/05	8/16/05
DRAWN BY		APP. BY	
J.A.M.		K.M.C.	

SUBSURFACE INVESTIGATION - FORMER CENTURY BRASS PRODUCTS SITE, WATERBURY, CT

SITE PLAN

An Employee Owned Company

DRAWING 1

SHEET NO. 1 NO. OF SHEETS 1

© \AUTOCAD\PROJECTS\18HW501\18HW501-D1.DWG Tab: D1 Saved: 9/29/2005 11:04 AM Plotted: 9/29/2005 11:04 AM

ASBESTOS SAMPLES

A-01	7/5/2005
Constituent	ND
Asbestos	ND
As	2.27
A-02	7/5/2005
Constituent	ND
Asbestos	ND
A-03	7/5/2005
Constituent	ND
Asbestos	ND
A-04	7/5/2005
Constituent	ND
Asbestos	ND
A-05	7/5/2005
Constituent	ND
Asbestos	ND
A-06	7/5/2005
Constituent	ND
Asbestos	ND
A-07	7/5/2005
Constituent	ND
Asbestos	ND
A-08	7/5/2005
Constituent	ND
Asbestos	ND
A-09	7/5/2005
Constituent	–
Asbestos, Chrysotile	.60%
A-10	7/5/2005
Constituent	–
Asbestos, Chrysotile	.60%
A-11	7/5/2005
Constituent	ND
Asbestos	ND
A-12	7/5/2005
Constituent	ND
Asbestos	ND
A-13	7/5/2005
Constituent	ND
Asbestos	ND
A-14	7/5/2005
Constituent	ND
Asbestos	ND
A-15	7/5/2005
Constituent	–
Asbestos, Chrysotile	.20%
A-16	7/5/2005
Constituent	ND
Asbestos	ND
A-17	7/5/2005
Constituent	ND
Asbestos	ND
A-18	7/5/2005
Constituent	ND
Asbestos	ND
A-19	7/5/2005
Constituent	ND
Asbestos	ND
A-20	7/5/2005
Constituent	ND
Asbestos	ND
A-21	7/5/2005
Constituent	ND
Asbestos	ND
A-22	7/5/2005
Constituent	–
Asbestos, Chrysotile	.20%
A-23	7/5/2005
Constituent	ND
Asbestos	ND
A-24	7/5/2005
Constituent	ND
Asbestos	ND

SEDIMENT SAMPLES

SD-01	7/11/2005
Constituent	0' – 0.25'
METAL	–
As	2.21
Cd	ND;0.402
Cr	5.00;5.87
Cu	2.7;5.27.4
Pb	8.97;144
Ni	6.42;7.06
Zn	43.4;50.1
Depth of Boring	0.25'
SD-02	7/11/2005
Constituent	0' – 0.25'
METAL	–
Ba	12.7
Cr	8.76
Cu	152
Pb	28
Ni	14
Zn	73.7
Depth of Boring	0.25'
SD-03	7/11/2005
Constituent	0' – 0.25'
METAL	–
Ba	16.2
Cd	0.42
Cr	8.78
Cu	13.6
Pb	12.7
Ni	5.2
Zn	58.7
Depth of Boring	0.25'
SD-04	7/11/2005
Constituent	0' – 0.25'
METAL	–
Ba	14.4
Cr	6.65
Cu	10.2
Pb	7.46
Ni	3.41
Zn	42.7
Depth of Boring	0.25'
SD-05	7/11/2005
Constituent	0' – 0.25'
METAL	–
Ba	10.2
Cr	5.22
Cu	7.54
Pb	5.37
Ni	2.71
Zn	37.2
Depth of Boring	0.25'
SD-06	7/11/2005
Constituent	0' – 0.25'
METAL	–
Ba	11
Cr	2.62
Cu	5.45
Pb	3.19
Ni	2.72
Zn	43.7
Depth of Boring	0.25'

SOIL SAMPLES

MW-001	7/7/2005
Constituent	0' – 2'
METAL	–
As	2.21
Cd	0.668;0.601
Cr	52.9;48.4
Cu	287;253
Pb	95.9;70.5
Ni	13.8;12.6
Zn	254;254
METALS	–
Cr (SPLP)	0.0095
SVOCs	ND;ND
VOC	ND;ND
Depth of Boring	16.00'
Depth of Groundwater	~8.23'
MW-002	7/8/2005
Constituent	0' – 2'
METAL	–
Ba	94.3
Cd	1.19
Cr	18.1
Cu	66.6
Pb	51.4
Ni	18.3
Zn	130
PHYSIC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9-C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
VOCs	ND
Depth of Boring	24.00'
Depth of Groundwater	~11.41'
MW-003	7/7/2005
Constituent	0' – 2'
METAL	–
Ba	58.3
Cd	1.88
Cr	14.7
Cu	125
Pb	256
Ni	40.8
Zn	662
PHYSIC	–
CT ETPH	118;NO
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9-C36, NOS	102
Jet Fuel #4 ;#5	ND
Oil, Other	102
CT ETPH	102
TPH (As Motor Oil)	ND
TPH, Unidentified	102
SVOCs	–
BA	285
BBF	293
BAP	462
BGP	352
BKF	243
CRYS	349
FA	852
IP	377
PHN	284
PAH	4238
PYR	541
VOCs	ND
Depth of Boring	18.00'
Depth of Groundwater	~16.68'
MW-004	7/8/2005
Constituent	0' – 2'
METAL	–
Ba	32
Cd	4.68
Cr	88.3
Cu	3620
Pb	228
Hg	0.24
Ni	362
Ag	1.58
Zn	1970
METALS	–
Cr (SPLP)	0.0104
Cu (SPLP)	0.359
Pb (SPLP)	0.0247
Zn (SPLP)	0.272
SVOCs	ND
VOCs	–
ACT	116
Depth of Boring	20.03'
Depth of Groundwater	~15.65'

MW-004	7/8/2005	
Constituent	0' – 2'	6' – 8'
METAL	–	–
Ba	32	15.8
Cd	4.68	1.01
Cr	88.3	11
Cu	3620	28.3
Pb	228	4.2
Hg	0.24	ND
Ni	362	30.1
Ag	1.58	ND
Zn	1970	234
METALS	–	–
Cr (SPLP)	0.0104	–
Cu (SPLP)	0.359	–
Pb (SPLP)	0.0247	–
Zn (SPLP)	0.272	–
SVOCs	ND	ND
VOCs	–	–
ACT	116	–
Depth of Boring	20.03'	–
Depth of Groundwater	~15.65'	–

MW-005	7/9/2005
Constituent	0' – 2'
METAL	–
As	3.97
Ba	244
Cd	2.25
Cr	58.9
Cu	36600
Pb	4650
Hg	1.04
Ni	159
Zn	3070000
METALS	–
TCLP (SPLP)	0.159
Cr (SPLP)	0.0026
SVOCs	–
PCB-1254	1660
PCB-1260	935
PCB	2,595
PCBs (SPLP)	ND
PHYSIC	–
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9-C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	77
TPH (As Motor Oil)	ND
TPH, Unidentified	77
SVOCs	–
BA	465
PAH	465
VOCs	–
PCB	273
TB010cacc	273
Depth of Boring	12.50'
Depth of Groundwater	~13.19'

MW-006	7/13/2005		
Constituent	0' – 2'	2' – 4'	12' – 14'
METAL	–	–	–
Ba	80.2;92.8		57.3
Cr	14.6;17.4		13.7
Cu	18.9;25.6		17.6
Pb	ND;3.53		1.2
Ni	12.8;15.8		21.5
Zn	37.0;45.9		82.5
PHYSC	ND;ND		
Fuel Oil No. 2	ND;ND		
Fuel Oil No. 4	ND;ND		
Fuel Oil No. 6	ND;ND		
Gasoline	ND;ND		
C9-C36, NOS	ND;ND		
Jet Fuel #4 ;#5	ND;ND		
Oil, Other	ND;ND		
CT ETPH	ND;ND		
TPH (As Motor Oil)	ND;ND		
TPH, Unidentified	ND;ND		
SVOCs	ND;ND	–	
CRYS		827	
A-MLNE		627	
PHN		747	
PAH	ND;ND	3100	
PYR		1530	
B-MLNE		2160	
VOCs	ND;–	ND	
ACT	ND;151		
Depth of Boring	17.50'		
Depth of Groundwater	~14.03'		

MW-007	7/7/2005	
Constituent	0' – 2'	14' – 16'
METAL	–	–
Ba	64.2	29.7
Cr	15.4	8.76
Cu	19.8	24.2
Pb	3.48	ND
Ni	18.5	35.1
Zn	41.8	40.5
PHYSC	ND	ND
Fuel Oil No. 2	ND	ND
Fuel Oil No. 4	ND	ND
Fuel Oil No. 6	ND	ND
Gasoline	ND	ND
C9-C36, NOS	ND	ND
Jet Fuel #4 ;#5	ND	ND
Oil, Other	ND	ND
CT ETPH	ND	ND
TPH (As Motor Oil)	ND	ND
TPH, Unidentified	ND	ND
SVOCs	ND	ND
VOCs	ND	ND
Depth of Boring	24.00'	
Depth of Groundwater	~17.41'	

SB-016	7/7/2005	
Constituent	0' – 4'	6' – 8'
METAL	–	–
Ba	5.79	57.3
Cr	6.26	13.9
Cu	14.4	20.2
Ni	20.2	35.8
Zn	49.7	68.6
PHYSC	ND	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	ND	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	ND	
TPH (As Motor Oil)	ND	
TPH, Unidentified	ND	
SVOCs	ND	
VOCs	ND	
Depth of Boring	24.00'	
Depth of Groundwater	~17.41'	

MW-009	7/8/2005	
Constituent	2' – 4'	6' – 8'
METAL	–	–
Ba	30.9	35.3
Cd	0.643	ND
Cr	8.64	9.88
Cu	1380	13.8
Pb	36.9	ND
Hg	0.42	ND
Ni	214	48.9
Ag	3.67	ND
Zn	258	76.4
PHYSC	ND	ND
Fuel Oil No. 2	ND	ND
Fuel Oil No. 4	ND	ND
Fuel Oil No. 6	ND	ND
Gasoline	ND	ND
C9-C36, NOS	ND	ND
Jet Fuel #4 ;#5	ND	ND
Oil, Other	ND	ND
CT ETPH	ND	ND
TPH (As Motor Oil)	ND	ND
TPH, Unidentified	ND	ND
SVOCs	ND	ND
VOCs	ND	ND
Depth of Boring	20.00'	

MW-010	7/5/2005	
Constituent	0' – 4'	6' – 8'
METAL	–	–
As	5.44	ND;ND
Ba	45	111;69.7
Cd	0.946	0.636;0.429
Cr	10.8	24.3;12.8
Cu	1450	98.0;33.6
Pb	102	ND;6.75
Hg	0.644	ND;ND
Ni	157	101;70.8
Ag	4.89	ND;ND
Zn	488	204;142
PHYSC	–	ND;ND
Fuel Oil No. 2	ND	ND;ND
Fuel Oil No. 4	ND	ND;ND
Fuel Oil No. 6	ND	ND;ND
Gasoline	–	ND;ND
C9-C36, NOS	35	ND;ND
Jet Fuel #4 ;#5	ND	ND;ND
Oil, Other	ND	ND;ND
CT ETPH	35	ND;ND
TPH (As Motor Oil)	ND	ND;ND
TPH, Unidentified	35	ND;ND
SVOCs	ND	ND;ND
ACNE	1710	ND;ND
BA	12000	ND;ND
BBF	8530	ND;ND
BAP	7520	ND;ND
BGP	3470	ND;ND
BKF	8230	ND;ND
CHRYS	8170	ND;ND
CRYS	10600	ND;ND
FA	26900	ND;ND
FLE	1710	ND;ND
IP	3080	ND;ND
A-MNE	2690	ND;ND
PHN	32700	ND;ND
PAH	156000	ND;ND
PYR	28000	ND;ND
ACN	2570	ND;ND
ANTH	6510	ND;ND
DBF	4210	ND;ND
B-MLNE	2290	ND;ND
VOCs	–	–;–
NAP	566	ND;ND
TCA	57.5	ND;ND
CDCE	1420	6.4;12.2
PCE	8570	78.9;110
TCE	581	ND;6.5
TB010cacc	10630	85.3;130
Depth of Boring	14.00'	
Depth of Groundwater	~12.77'	

MW-110	7/14/2005	
Constituent	0' – 2'	8' – 10'
METAL	–;–	–
As	12.0;10.3	
Ba	116;63.1	
Cd	8.94;0.433	
Cr	6.08;6.12	
Cu	261;143	
Pb	55.2;34.2	
Ni	23.2;8.81	
Zn	575;131	
PHYSC	~;ND	
Fuel Oil No. 2	ND;ND	
Fuel Oil No. 4	ND;ND	
Fuel Oil No. 6	ND;ND	
Gasoline	ND;ND	
C9-C36, NOS	118;ND	
Jet Fuel #4 ;#5	ND;ND	
Oil, Other	ND;ND	
CT ETPH	118;ND	
TPH (As Motor Oil)	ND;ND	
TPH, Unidentified	118;ND	
SVOCs	~;~	ND
ACNE	2270;ND	
BA	3730;ND	
BBF	3920;ND	
BAP	3070;ND	
BGP	891;ND	
BKF	2850;ND	
CRYS	3780;371	
FA	6590;ND	
IP	1350;ND	
NAP	3030;ND	
PHN	2400;486	
PAH	57000;857	ND
PYR	2340;ND	
ANTH	783;ND	
DBF	604;ND	
B-MLNE	1190;310	
VOCs	~;ND	ND
NAP	137;ND	ND
Depth of Boring	28.00'	
Depth of Groundwater	~11.08'	

MW-012	7/7/2005	
Constituent	2' – 4'	
METAL	–	
As	12.1	
Ba	143	
Cd	4.42	
Cr	8.85	
Cu	269	
Pb	32.2	
Ni	32.6	
Zn	208	
PHYSC	–	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	735	
Jet Fuel #4 ;#5	ND	
Oil, Other	735	
CT ETPH	735	
TPH (As Motor Oil)	ND	
TPH, Unidentified	735	
SVOCs	–	
BAN	209	
VOCs	–	
NAP	209	
Depth of Boring	12.00'	
Depth of Groundwater	~9.10'	

MW-013	7/13/2005	
Constituent	0' – 2'	
METAL	–	
As	8.53	
Ba	152	
Cd	2.37	
Cr	47.6	
Cu	29.50	
Pb	205	
Hg	0.241	
Ni	67.8	
Ag	1.49	
Zn	1890	
PHYSC	–	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	368	
TPH (As Motor Oil)	ND	
TPH, Unidentified	368	
SVOCs	–	
ACNE	1650	
BA	1680	
BBF	1600	
BAP	1710	
BGP	725	
BKF	1330	
CRYS	2100	
FA	5170	
IP	853	
PHN	2690	
PAH	22800	
PYR	2340	
ANTH	706	
VOCs	ND	
Depth of Boring	20.00'	
Depth of Groundwater	~16.60'	

SB-001	7/14/2005		
Constituent	0' – 2'	4' – 6'	
METAL	–	–	
As	4.48	5.72	
Ba	86.2	50.7	
Cd	11.8	1.86	
Cr	21.8	16.1	
Cu	447.0	233	
Pb	374	50.1	
Hg	0.298	ND	
Ni	143	27.7	
Zn	13900	610	
PCB	–	–	
PCB-1254	61.8	ND	
PCB-1260	99.5	33.9	
PCB	71.8	33.9	
PHYSC	–	ND	
Fuel Oil No. 2	ND	ND	
Fuel Oil No. 4	ND	ND	
Fuel Oil No. 6	ND	ND	
Gasoline	ND	ND	
C9-C36, NOS	96.2	ND	
Jet Fuel #4 ;#5	ND	ND	
Oil, Other	96.2	ND	
CT ETPH	96.2	ND	
TPH (As Motor Oil)	ND	ND	
TPH, Unidentified	96.2	ND	
SVOCs	–	–	
FA	289	365	
PAH	557	717	
PYR	268	352	
VOCs	–	–	
CDCE	ND	6.6	
PCE	16.1	89.3	
TCE	ND	14.4	
TB010cacc	16.1	110.3	
Depth of Boring	16.00'		

SB-002	7/14/2005		
Constituent	0' – 2'	6' – 8'	
PHYSC	–	ND	
Fuel Oil No. 2	ND	ND	
Fuel Oil No. 4	ND	ND	
Fuel Oil No. 6	ND	ND	
Gasoline	ND	ND	
C9-C36, NOS	954	ND	
Jet Fuel #4 ;#5	ND	ND	
Oil, Other	ND	ND	
CT ETPH	954	ND	
TPH (As Motor Oil)	ND	ND	
TPH, Unidentified	954	ND	
SVOCs	ND	ND	
VOCs	ND	ND	
Depth of Boring	16.00'		

SB-005	7/14/2005	
Constituent	2' – 4'	
METAL	–	
Ba	20.5	
Cr	14.5	
Cu	19.6	
Pb	1.31	
Ni	38.5	
Zn	49.3	
PHYSC	ND	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	ND	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	ND	
TPH (As Motor Oil)	ND	
TPH, Unidentified	ND	
SVOCs	–	
PCE	13.8	
TB010cacc	13.8	
Depth of Boring	9.00'	

SB-008a	7/14/2005		
Constituent	2' – 4'		
METAL	–		
Ba	2.01		
Cr	17.87		
Cu	23.4		
Pb	2.91		
Ni	10.1		
Zn	27.8		
PHYSC	ND		
CN (Tot)	ND		
Fuel Oil No. 2	ND		
Fuel Oil No. 4	ND		
Fuel Oil No. 6	ND		
Gasoline	ND		
C9-C36, NOS	ND		
Jet Fuel #4 ;#5	ND		
Oil, Other	ND		
CT ETPH	ND		
TPH (As Motor Oil)	ND		
TPH, Unidentified	ND		
SVOCs	ND		
VOCs	–		
PCE	5		
TB010cacc	5		
Depth of Boring	16.00'		

SB-013	7/12/2005		
Constituent	0' – 2'	4' – 6'	8' – 9'
METAL	–	–	–
As	2.01		
Ba	37.9		
Cd	0.502		
Cr	6.24		
Cu	1.25		
Pb	7.39		
Ni	1.40		
Zn	150		
PCB	ND		
PHYSC	–		
Fuel Oil No. 2	ND		
Fuel Oil No. 4	ND		
Fuel Oil No. 6	ND		
Gasoline	ND		
C9-C36, NOS	64.8		
Jet Fuel #4 ;#5	ND		
Oil, Other	ND		
CT ETPH	64.8		
TPH (As Motor Oil)	ND		
TPH, Unidentified	64.8		
SVOCs	ND	ND	ND
VOCs	–	ND	ND
PCE	56.6	ND	ND
TB010cacc	56.6	ND	ND
Depth of Boring	9.00'		

SB-014	7/12/2005	
Constituent	6' – 8'	
METAL	–	
Ba	34.5	
Cd	0.632	
Cr	17	
Cu	85.5	
Ni	18.8	
Zn	225	
PHYSC	–	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	ND	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	53	
TPH (As Motor Oil)	ND	
TPH, Unidentified	53	
SVOCs	ND	
VOCs	–	
TCA	179	
CDCE	1500	
PCE	42000;60500	
TCE	2550	
TB010cacc	47000;60500	
Depth of Boring	16.00'	

SB-008	7/8/2005		
Constituent	2' – 4'		8' – 10'
METAL	–		–
Ba	108		22
Cd	2.28		ND
Cr	19.5		4.92
Cu	1550		12.2
Pb	75.1		ND
Hg	0.355		ND
Ni	413		17.1
Ag	14.7		ND
Zn	849		54
PCB	–		–
PCB-1260	117		ND
PHYSC	–		ND
Fuel Oil No. 2	ND		ND
Fuel Oil No. 4	ND		ND
Fuel Oil No. 6	ND		ND
Gasoline	ND		ND
C9-C36, NOS	229		ND
Jet Fuel #4 ;#5	ND		ND
Oil, Other	ND		ND
CT ETPH	229		ND
TPH (As Motor Oil)	ND		ND
TPH, Unidentified	229		ND
SVOCs	–		ND
BA	500		ND
BAP	460		ND
CRYS	523		ND
FA	1030		ND
IP	427		ND
PHN	675		ND
PAH	4500		ND
PYR	760		ND
VOCs	–		–
NAP	76.9		ND
CDCE	159		52.4
PCE	18700		ND
TCE	745		ND
MC	ND		66.6
TB010cacc	19000		119
Depth of Boring	16.00'		

SB-011	7/12/2005		
Constituent	2' – 4'		8' – 10'
METAL	–		–
As	19.2		ND
Ba	147		57.6
Cd	1.01		0.647
Cr	10.7		25.2
Cu	1330		46.2
Pb	5410		ND
Hg	4.59		ND
Ni	611		36.7
Ag	16		ND
Zn	1350		122
METALS	–		–
Pb (SPLP)	0.114		
Hg (SPLP)	0.00189		
Ni (SPLP)	0.28		
PHYSC	–		ND
Fuel Oil No. 2	ND		ND
Fuel Oil No. 4	ND		ND
Fuel Oil No. 6	ND		ND
Gasoline	ND		ND
C9-C36, NOS	402		ND
Jet Fuel #4 ;#5	ND		ND
Oil, Other	ND		ND
CT ETPH	402		ND
TPH (As Motor Oil)	ND		ND
TPH, Unidentified	402		ND
SVOCs	ND		ND
VOCs	–		ND
CDCE	77.6		ND
PCE	102		ND
TCE	121		ND
TB010cacc	501		ND
Depth of Boring	16.00'		

SB-012	7/14/2005	
Constituent	0' – 2'	
SVOCs	ND	
VOCs	ND	
Depth of Boring	9.00'	

SS-001R	7/19/2005	
Constituent	0'	
METAL	–	
Ba	26.3	
Cd	0.608	
Cr	15.7	
Cu	366	
Pb	258	
Ni	29.7	
Zn	238	
SVOCs	ND	
VOCs	–	
PCE	13.3	
TB010cacc	13.3	

SS-006R	7/19/2005	
Constituent	0'	
METAL	–	
Ba	48.3	
Cd	0.65	
Cr	12.2	
Cu	998	
Pb	111	
Ni	33.5	
Zn	590	
PHYSC	–	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	60.4	
Jet Fuel #4 ;#5	ND	
Oil, Other	60.4	
CT ETPH	ND	
TPH (As Motor Oil)	ND	
TPH, Unidentified	60.4	
SVOCs	ND	
VOCs	ND	

SS-007R	7/19/2005	
Constituent	0'	
METAL	–	
As	2.45	
Ba	174	
Cd	6.62	
Cr	19.6	
Cu	852.0	
Pb	431	
Hg	0.982	
Ni	479	
Ag	9.02	
Zn	3200	
PHYSC	ND	
CN (Tot)	ND	
SVOCs	ND	
VOCs	–	
PCE	203	
TB010cacc	203	

SS-008R	7/19/2005	
Constituent	0'	
METAL	–	
As	21.6	
Ba	135	
Cd	4.6	
Cr	43.9	
Cu	2460	
Pb	1120	
Hg	0.416	
Ni	97.6	
Ag	8.76	
Zn	337	
PHYSC	–	
CN (Tot)	ND	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	111	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	111	
TPH (As Motor Oil)	ND	
TPH, Unidentified	111	
SVOCs	–	
BA	611	
BBF	577	
CRYS	914	
FA	2050	
PHN	872	
PAH	5710	
PYR	4660	
VOCs	ND	

SS-001R	7/19/2005	
Constituent	0'	
METAL	–	
As	4.41	
Ba	406	
Cd	5.24	
Cr	111	
Cu	3560	
Pb	883	
Hg	1.2	
Ni	406	
Ag	11.8	
Zn	2560	
PHYSC	–	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	524	
Jet Fuel #4 ;#5	ND	
Oil, Other	ND	
CT ETPH	524	
TPH (As Motor Oil)	ND	
TPH, Unidentified	524	
SVOCs	–	
FA	2260	
PAH	2260	
VOCs	ND	

SS-002R	7/19/2005	
Constituent	0'	
METAL	–	
Ba	1100	
Cd	4.75	
Cr	72.3	
Cu	913.0	
Pb	1720	
Hg	1.88	
Ni	111	
Ag	3.83	
Zn	3530	
SVOCs	ND	
VOCs	ND	

SS-003R	7/19/2005	
Constituent	0'	
METAL	–	
Ba	61.2	
Cd	1.16	
Cr	14.4	
Cu	265	
Pb	62.3	
Hg	0.406	
Ni	28.6	
Ag	3	
Zn	208	
PHYSC	ND	
CN (Tot)	ND	
SVOCs	ND	
VOCs	–	
ACT	343	
BZ	13.6	
TB020cacc	13.6	

SS-004R	7/19/2005	
Constituent	0'	
METAL	–	
Ba	50.9	
Cd	2.79	
Cr	50.4	
Cu	2800	
Pb	1400	
Hg	0.223	
Ni	195	
Ag	2.87	
Zn	1830	
PHYSC	–	
CN	ND	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	232	
Jet Fuel #4 ;#5	ND	
Oil, Other	232	
CT ETPH	232	
TPH (As Motor Oil)	ND	
TPH, Unidentified	232	
SVOCs	–	
ACNE	532	
BA	927	
BBF	768	
BAP	673	
BKF	590	
CRYS	1130	
FA	3170	
PHN	1900	
PAH	11700	
PYR	1330	
ANTH	712	
VOCs	–	
PCE	14.6	
TCE	14.2	
TB010cacc	28.8	

SS-009R	7/19/2005	
Constituent	0'	
METAL	–	
As	0.61	
Ba	26	
Cd	20	
Cr	21.1	
Cu	247.00	
Pb	116	
Hg	0.39	
Ni	91.70	
Ag	1020	
Zn	10100	
PHYSC	–	
CN (Tot)	ND	
Fuel Oil No. 2	ND	
Fuel Oil No. 4	ND	
Fuel Oil No. 6	ND	
Gasoline	ND	
C9-C36, NOS	7660	
Jet Fuel #4 ;#5	ND	
Oil, Other	7660	
CT ETPH	7660	
TPH (As Motor Oil)	ND	
TPH, Unidentified	7660	
SVOCs	ND	
VOCs	ND	

SS-010R	7/19/2005	
Constituent	0'	
METAL	–	
As	8.76	
Cd	0.608	
Cr	15.7	
Cu	366	
Pb	258	
Ni	29.7	
Zn	238	
SVOCs	ND	
VOCs	–	
PCE	13.3	
TB010cacc	13.3	

SS-005R	7/19/2005	
Constituent	0'	
METAL	–

EW-1	7/19/2005
Constituent	–
As	2.21
Ba (unfiltered)	0.0728
Cu (unfiltered)	0.0162
Zn (unfiltered)	0.0118
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ; #5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	–
CDCE	6.4
TCE	2.7
TB010calc	9.1
Depth of Groundwater	~9.09'

MW-001	7/19/2005
Constituent	–
METAL	–
Ba (unfiltered)	0.053
Zn (unfiltered)	0.0148
SVOCs	ND
VOCs	ND
Depth of Boring	16.00'
Depth of Groundwater	~8.23'

MW-002	7/19/2005
Constituent	3.50' – 13.50
METAL	–
Ba	0.0615
Cu	0.0025
Ni	0.0711
Zn	0.0319
SVOCs	ND
VOCs	ND
Depth of Boring	13.80'
Depth of Groundwater	~10.21'

MW-003	7/19/2005
Constituent	9.00' – 18.00
METAL	–
Ba (unfiltered)	0.0221;0.0226
Cu (unfiltered)	0.0025;ND
Ni (unfiltered)	0.0418;0.0425
Zn (unfiltered)	0.422;0.427
PHYSC	ND;ND
Fuel Oil No. 2	ND;ND
Fuel Oil No. 4	ND;ND
Fuel Oil No. 6	ND;ND
Gasoline	ND;ND
C9–C36, NOS	ND;ND
Jet Fuel #4 ; #5	ND;ND
Oil, Other	ND;ND
CT ETPH	ND;ND
TPH (As Motor Oil)	ND;ND
TPH, Unidentified	ND;ND
SVOCs	ND;ND
VOCs	ND;ND
Depth of Boring	18.00'
Depth of Groundwater	~16.68'

MW-004	7/19/2005
Constituent	11.00' – 20.0
METAL	–
Ba	0.0256
Cu	0.013
Ni	0.0256
Zn	0.126
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ; #5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	ND
Depth of Boring	20.03'
Depth of Groundwater	~15.65'

MW-005	7/19/2005
Constituent	3.20' – 12.20
METAL	–
Cu (unfiltered)	0.201
Cu (unfiltered)	0.0034
Ni (unfiltered)	0.0278
Zn (unfiltered)	6.35
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ; #5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND;ND
VOCs	ND;ND
Depth of Boring	12.30'
Depth of Groundwater	~13.19'

MW-006	7/19/2005
Constituent	–
METAL	–
Ba (unfiltered)	0.0364
Fe	9.55
Mn	1.32
Ni (unfiltered)	0.0163
Na	13.5
Zn (unfiltered)	0.084
PHYSC	–
Chloride (As Cl)	30.5
Fluoride – Total	ND
Nitrate Nitrogen (As N)	ND
Specific Conductivity	342
Sulfate (As SO4)	20.4
pH	6.5
SVOCs	ND
VOCs	–
CDCE	5.6
VC	2.3
TB010calc	7.9
Depth of Boring	17.30'
Depth of Groundwater	~14.03'

MW-007	7/18/2005
Constituent	13.00' – 22.0
METAL	–
Ba (unfiltered)	0.0329
Cu (unfiltered)	0.0037
Ni (unfiltered)	0.0278
PCB	ND
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ; #5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	–
CBZ	1
PCE	1.6
TB010calc	2.6
TB020calc	1
Depth of Boring	24.00'
Depth of Groundwater	~17.41'

MW-009	7/18/2005
Constituent	6.00' – 15.00
METAL	–
Cu (unfiltered)	0.0078
Ni (unfiltered)	0.0683
PCB	ND
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	–
TCA	11.2
PCE	33.2
TCE	7.8
TB010calc	52.2
Depth of Boring	16.00'
Depth of Groundwater	~11.71'

MW-010	7/18/2005
Constituent	4.00' – 14.00
METAL	–
Cu (unfiltered)	0.0157
Ni (unfiltered)	0.0769
Zn (unfiltered)	0.122
PCB	ND
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	–
CDCE	93
PCE	53.5
TCE	6
TB010calc	152.5
Depth of Boring	14.00'
Depth of Groundwater	~12.77'

MW-11D	7/20/2005
Constituent	19.00' – 28.0
METAL	–
Ba	0.0423
SVOCs	ND
VOCs	ND
Depth of Boring	28.00'
Depth of Groundwater	~11.08'

MW-012	7/18/2005
Constituent	2.00' – 12.00
METAL	–
Ba (unfiltered)	0.0534
Cu (unfiltered)	0.0167
Ni (unfiltered)	0.05
Zn (unfiltered)	0.243
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	ND
Depth of Boring	12.00'
Depth of Groundwater	~9.10'

MW-013	7/19/2005
Constituent	11.00' – 20.0
METAL	–
Ba	0.0225
Cu	0.0031
Ni	0.0136
Zn	0.0377
PHYSC	ND
Fuel Oil No. 2	ND
Fuel Oil No. 4	ND
Fuel Oil No. 6	ND
Gasoline	ND
C9–C36, NOS	ND
Jet Fuel #4 ;#5	ND
Oil, Other	ND
CT ETPH	ND
TPH (As Motor Oil)	ND
TPH, Unidentified	ND
SVOCs	ND
VOCs	ND
Depth of Boring	20.00'
Depth of Groundwater	~16.60'

U-1	6/30/2005
Constituent	–
Cd	0.0057
Cu	0.0438
Fe	0.375
Mn	0.153
Ni	0.0221
Na	15
Zn	0.629
PHYSC	–
Chloride (As Cl)	18.4
Fluoride - Total	ND
Nitrate Plus Nitrite Nitrogen (As N)	0.64
Specific Conductivity	218
Sulfate (As SO4)	13.6
pH	5.84
SVOCs	ND
VOCs	ND
Depth of Groundwater	~10.32'

D-2	6/30/2005
Constituent	–
Ba	0.0597
Cu	0.194
Fe	10.8
Mn	0.889
Ni	0.106
Na	16
Zn	0.885
PHYSC	–
Chloride (As Cl)	27.9
Fluoride - Total	ND
Nitrate Plus Nitrite Nitrogen (As N)	0.21
Specific Conductivity	305
Sulfate (As SO4)	17.5
pH	5.99
SVOCs	ND
VOCs	–
11DCA	4.2
CDCE	4.6
PCE	8.3
TCE	3.2
TB010calc	18.3
Depth of Groundwater	~18.14'

D-3	6/30/2005	-	
Constituent	–	–	
Cr	0.003	0.003	
Cu	0.0356	0.0346	
Fe	1.48	1.75	
Mn	2.37	2.55	
Ni	0.0212	0.021	
Na	25.3	23.8	
Zn	0.098	0.105	
PHYSC	–	–	
Chloride (As Cl)	44	42.7	
Fluoride - Total	ND	ND	
Nitrate Plus Nitrite Nitrogen (As N)	ND	ND	
Specific Conductivity	381	397	
Sulfate (As SO4)	22.9	23.1	
pH	6.04	6.08	
SVOCs	ND	ND	
VOCs	–	–	–
11DCA	ND	1	
CDCE	108	132	
VC	12.8	18	
PCE	227.206	267	344
TCE	25.7	31.8	
TB010calc	374	450	344
Depth of Groundwater	~19.09'		

Groundwater Elevations – Subsurface Investigation
Century Brass, Hamilton Avenue, Waterbury, Connecticut – 18HW501.001
July 18, 2005

Monitoring Well ID	Reference Elevation – Top of Road Box (Feet – NGVDa)	Reference Elevation – Top of PVC Casing (Feet – NGVDa)	Well Construction	Screened Interval (feetb)	Measured Depth to Water (Feetb)	Well Depth (Feetb)	Water Level Elevation (Feet – NGVDa)
MW-001	220.25316	219.96133	0.5" PVC	5 to 15	8.22	15.25	211.74
MW-002	219.34983	219.07346	0.5" PVC	3.5 to 13.5	8.02	13.00	211.05
MW-003	219.15540	217.90357	0.5" PVC	9 to 18	13.88	20.41	204.02
MW-004	215.75604	215.55750	0.5" PVC	11 to 20	12.70	21.47	202.86
MW-005	211.25823	210.81179	0.5" PVC	3.16 to 12.16	9.74	13.79	201.07
MW-006	212.53560	212.08792	0.5" PVC	11 to 21	14.00	22.81	198.09
MW-007	210.42703	210.21833	0.5" PVC	13 to 22	15.31	23.82	194.91
EW-1	212.43250	212.07905	Unknown	Unknown	NM	NM	––
MW-009	202.39728	202.18246	0.5" PVC	6 to 15	9.26	17.00	192.92
MW-010	202.27731	201.95504	1.5" PVC	4 to 14	9.37	17.75	192.59
MW-011D	201.61656	201.40536	0.5" PVC	19 to 28	NM	NM	––
MW-012	200.73310	200.68864	1.5" PVC	2 to 12	7.10	14.40	193.59
MW-013	214.99471	214.78949	0.5" PVC	11 to 20	14.09	21.79	200.70
U-1	214.09737	213.98210	2" PVC	6 to 16	10.69	17.75	203.29
D-2	212.96427	212.80780	2" PVC	5.5 to 15.5	18.23	26.38	194.58
D-3	213.95294	213.82914	2" PVC	8 to 18	19.21	30.00	194.62
D-4	213.93838	213.42810	2" PVC	7 to 17	dry	13.80	––

o NGVD – National Geodetic Vertical Datum of 1929.
b Depths in feet below ground surface.
NM = Not Measured



DRAFT

LEGEND

- MH — MANHOLE
- MONITORING WELL
- FORMER BUILDING OUTLINE (APPROXIMATE)
- EDGE OF PAVED ROAD
- EDGE OF GRAVEL ROAD
- FENCE
- PROPERTY LINE (APPROXIMATE)
- WATERCOURSE (APPROXIMATE)
- 211 — GROUNDWATER CONTOUR (DASHED IS INFERRED)
- GROUNDWATER FLOW DIRECTION

DATA BLOCK LEGEND

LOCATION IDENTIFIER
SAMPLE DATE

CA–80	06/19/2002
Constituent	98.50' – 103.'
METALS	–
Cd	0.0115
Cu	3.00
Pb	0.2068
Ni	0.466
Zn	1.67
VOCs	–
CPM	0.6 L
TCE	3.3
Depth of Boring	103.50'
Depth to Groundwater	~ 11.64'

- SCREENED INTERVAL
- DASH INDICATES DETECT(S) IN CONSTITUENT GROUP (SPECIFIC COMPOUNDS IDENTIFIED BELOW)
- ITALICIZED AND RED COLORED CONSTITUENT CONCENTRATION INDICATES AN EXCEEDANCE OF ONE OR MORE CRITERIA IDENTIFIED IN THE CONNECTICUT REMEDIATION STANDARD REGULATIONS
- "L" IS A CONSTITUENT CONCENTRATION QUALIFIER
- DEPTH AS MEASURED ON SAMPLE DATE

NOTES:

1. THE RESPECTIVE UNITS FOR GROUNDWATER IN WHICH QUANTIFIABLE CONCENTRATIONS ARE DETECTED ARE AS FOLLOWS: VOCs, SVOCs – MICROGRAMS PER LITER (ug/L); TPH AND METALS – MILLIGRAMS PER LITER (mg/L).
2. VOCs CATEGORY REFERS TO COMPOUNDS DETECTED USING EPA METHOD 8260.
3. GROUNDWATER CONTOURS GENERATED FROM DEPTH MEASUREMENTS TAKEN ON JULY 18, 2005

GENERAL NOTES:

1. IN THE CASE OF A DUPLICATE SAMPLE AND CONSTITUENT DETECTS OR NON–DETECTS (ND), THEY ARE SEPARATED BY A SEMICOLON WITHIN THE SAMPLING INTERVAL WHERE THE DUPLICATION OCCURS.
2. ONLY DETECTED METALS (FILTERED OR UNFILTERED) ARE SHOWN ON THE DATA BLOCKS.
3. YELLOW HIGHLIGHTED AREA INDICATES EXCEDANCE OF MARCH 2003 PROPOSED REVISION TO RSRs FOR RESIDENTIAL VOLATILIZATION CRITERIA.

LEGEND

- MONITORING WELL (MW)
- SAMPLE W/ DETECT BUT NO EXCEEDANCES
- SAMPLE ANALYZED BUT NO DETECTS

GROUNDWATER EXCEEDANCES

INDUSTRIAL / COMMERCIAL VOLATILIZATION CRITERIA (IVC)
RESIDENTIAL VOLATILIZATION CRITERIA (RVC)
SURFACE WATER PROTECTION CRITERIA (SWPC)
GROUNDWATER PROTECTION CRITERIA (GWPC)

METALs

As	ARSENIC	Hg	MERCURY
Ba	BARIUM	Ni	NICKEL
Cd	CADMIUM	Se	SELENIUM
Cr	CHROMIUM (TOTAL)	Ti	TITANIUM
Cu	COPPER	Zn	ZINC
Pb	LEAD		

CONSTITUENT ABBREVIATIONS

MISC.

TPH	TOTAL PETROLEUM HYDROCARBONS
PCB	POLYCHLORINATED BIPHENYL
PHYSC	PHYSICAL ANALYSES

CONSTITUENT CONCENTRATION QUALIFIERS

ND	NONE DETECTED; LESS THAN DETECTION LIMIT
J	ESTIMATED VALUE: COMPOUND PRESENT AT A CONCENTRATION BELOW THE METHOD DETECTION LIMIT
J1	ESTIMATED VALUE: % DIFFERENCE OF DAILY CALIBRATION STANDARDS OUTSIDE CONTROL LIMITS
L	ESTIMATED VALUE: CONSTITUENT DETECTED ABOVE THE METHOD DETECTION LIMIT, BUT BELOW THE QUANTIFICATION LIMIT.
H	ESTIMATED VALUE: CONSTITUENT DETECTED ABOVE THE CALIBRATION RANGE. B CONSTITUENT DETECTED IN THE BLANK.

REV.	DESCRIPTION OF REVISION	DATE	APPR.

Loureiro Engineering Associates, Inc.
100 Northwest Drive • Plainville, Connecticut 06062
An Employee Owned Company

SCALE: SHOWN
COMM. NO.: 18HW501.001
DRAWN BY: A.C.L. DATE: 09/06/05
APP. BY: K.M.C. DATE: 09/06/05

SUBSURFACE INVESTIGATION – FORMER CENTURY BRASS PRODUCTS SITE, WATERBURY, CT
GROUNDWATER SAMPLING LOCATIONS & GROUNDWATER CONTOUR MAP

An Employee Owned Company

DRAWING 3

SHEET NO. 1 NO. OF SHEETS 1

G:\AUTOCAD\PROJECTS\18HW501\18HW501-03.DWG TAB: 03 SAVED: 9/14/2005 3:01 PM PLOTTED: 9/16/2005 1:34 PM