DOCUMENTATION OF ENVIRONMENTAL INDICATOR DETERMINATION

Interim Final 2/5/99

RCRA Corrective Action
Environmental Indicator (EI) RCRIS code (CA725)

Current Human Exposures Under Control

Facility Name: Tinker Air Force Base
Facility Address: 7701 Arnold Street, Suite 204
Facility EPA ID #: OK1571724391

1. Has **all** available relevant/significant information on known and reasonably suspected releases to soil, groundwater, surface water/sediments, and air, subject to RCRA Corrective Action (e.g., from Solid Waste Management Units (SWMU), Regulated Units (RU), and Areas of Concern (AOC)), been **considered** in this EI determination?

   ✓ If yes - check here and continue with #2 below.

   _____ If no - re-evaluate existing data, or

   _____ if data are not available skip to #6 and enter "IN" (more information needed) status code.

BACKGROUND

Definition of Environmental Indicators (for the RCRA Corrective Action)

Environmental Indicators (EI) are measures being used by the RCRA Corrective Action program to go beyond programmatic activity measures (e.g., reports received and approved, etc.) to track changes in the quality of the environment. The two EI developed to-date indicate the quality of the environment in relation to current human exposures to contamination and the migration of contaminated groundwater. An EI for non-human (ecological) receptors is intended to be developed in the future.

Definition of "Current Human Exposures Under Control" EI

A positive "Current Human Exposures Under Control" EI determination ("YE" status code) indicates that there are no "unacceptable" human exposures to "contamination" (i.e., contaminants in concentrations in excess of appropriate risk-based levels) that can be reasonably expected under current land- and groundwater-use conditions (for all "contamination" subject to RCRA corrective action at or from the identified facility (i.e., site-wide)).

Relationship of EI to Final Remedies

While Final remedies remain the long-term objective of the RCRA Corrective Action program the EI are near-term objectives which are currently being used as Program measures for the Government Performance and Results Act of 1993, GPRA). The "Current Human Exposures Under Control" EI are for reasonably expected human exposures under current land- and groundwater-use conditions ONLY, and do not consider potential future land-or groundwater-use conditions or ecological receptors. The RCRA Corrective Action program's overall mission to protect human health and the environment requires that Final remedies address these issues (i.e., potential future human exposure scenarios, future land and groundwater uses, and ecological receptors).

Duration / Applicability of EI Determinations

EI Determinations status codes should remain in RCRIS national database ONLY as long as they remain true (i.e., RCRIS status codes must be changed when the regulatory authorities become aware of contrary information).

2. Are groundwater, soil, surface water, sediments, or air **media** known or reasonably suspected to be **"contaminated"**[1] above appropriately protective risk-based "levels" (applicable promulgated standards, as well as other appropriate standards, guidelines, guidance, or criteria) from releases subject to RCRA Corrective Action (from SWMUs, RUs or AOCs)?

	Yes	No	?	Rationale / Key Contaminants
Groundwater	✓			chlorinated solvents, chromium
Air (indoors) [2]		✓		
Surface Soil (e.g., <2 ft)		✓		
Surface Water		✓		
Sediment		✓		
Subsurf. Soil (e.g., >2 ft)		✓		
Air (outdoors)		✓		

_____ If no (for all media) - skip to #6, and enter "YE," status code after providing or citing appropriate "levels," and referencing sufficient supporting documentation demonstrating that these "levels" are not exceeded.

_✓_ If yes (for any media) - continue after identifying key contaminants in each "contaminated" medium, citing appropriate "levels" (or provide an explanation for the determination that the medium could pose an unacceptable risk), and referencing supporting documentation.

_____ If unknown (for any media) - skip to #6 and enter "IN" status code.

Rationale and Reference(s):

There has been extensive data collected for all media at Tinker Air Force Base. Risk assessments have been conducted at several sites. The list below shows contaminants that have been detected above MCLs.

Groundwater: Cis 1,2-Dichloroethylene, Trichloroethylene, 1,2-Dichloroethane, Tetrachloroethylene, BTEX, Chromium, Carbon Tetrachloride

Reference: Draft Basewide Non-NPL Groundwater Phase II RFI for Appendix I and II SWMUs Addendum I (May 1999)

Footnotes:

[1] "Contamination" and "contaminated" describes media containing contaminants (in any form, NAPL and/or dissolved, vapors, or solids, that are subject to RCRA) in concentrations in excess of appropriately protective risk-based "levels" (for the media, that identify risks within the acceptable risk range).

[2] Recent evidence (from the Colorado Dept. of Public Health and Environment, and others) suggest that unacceptable indoor air concentrations are more common in structures above groundwater with volatile contaminants than previously believed. This is a rapidly developing field and reviewers are encouraged to look to the latest guidance for the appropriate methods and scale of demonstration necessary to be reasonably certain that indoor air (in structures located above (and adjacent to) groundwater with volatile contaminants) does not present unacceptable risks.

3. Are there **complete pathways** between "contamination" and human receptors such that exposures can be reasonably expected under the current (land- and groundwater-use) conditions?

Summary Exposure Pathway Evaluation Table

Potential **Human Receptors** (Under Current Conditions)

"Contaminated" Media	Residents	Workers	Day-Care	Construction	Trespassers	Recreation	Food[3]
Groundwater	yes	no	no	no			no
~~Air (indoors)~~	___	___	___				
~~Soil (surface, e.g., <2 ft)~~	___	___	___	___	___	___	___
~~Surface Water~~	___	___			___	___	___
~~Sediment~~	___	___			___	___	___
~~Soil (subsurface e.g., >2 ft)~~				___			___
~~Air (outdoors)~~	___	___	___	___	___		

Instructions for Summary Exposure Pathway Evaluation Table:

1. Strike-out specific Media including Human Receptors' spaces for Media which are not "contaminated" as identified in #2 above.

2. Enter "yes" or "no" for potential "completeness" under each "Contaminated" Media -- Human Receptor combination (Pathway).

Note: In order to focus the evaluation to the most probable combinations some potential "Contaminated" Media - Human Receptor combinations (Pathways) do not have check spaces ("___"). While these combinations may not be probable in most situations they may be possible in some settings and should be added as necessary.

_____ If no (pathways are not complete for any contaminated media-receptor combination) – skip to #6, and enter "YE" status code, after explaining and/or referencing condition(s) in-place, whether natural or man-made, preventing a complete exposure pathway from each contaminated medium (e.g., use optional Pathway Evaluation Work Sheet to analyze major pathways).

_✓_ If yes (pathways are complete for any "Contaminated" Media - Human Receptor combination) - continue after providing supporting explanation.

_____ If unknown (for any "Contaminated" Media - Human Receptor combination) - skip to #6 and enter "IN" status code.

Rationale and Reference(s):

Residents located to the immediate southwest of Tinker have private water supply wells.

[3] Indirect Pathway/Receptor (e.g., vegetables, fruits, crops, meat and dairy products, fish, shellfish, etc.)

4. Can the **exposures** from any of the complete pathways identified in #3 be reasonably expected to be **"significant"**, (i.e., potentially "unacceptable" because exposures can be reasonably expected to be: 1) greater in magnitude (intensity, frequency and/or duration) than assumed in the derivation of the acceptable "level' (used to identify the "contamination"); or 2) the combination of exposure magnitude (perhaps even though low) and contaminant concentrations (which may be substantially above the acceptable "levels") could result in greater than acceptable risks)?

√ If no (exposures can not be reasonably expected to be significant (i.e., potentially "unacceptable") for any complete exposure pathway) – skip to #6 and enter "YE" status code after explaining and/or referencing documentation justifying why the exposures (from each of the complete pathways) to "contamination" (identified in #3) are not expected to be "significant."

____ If yes (exposures could be reasonably expected to be "significant" (i.e., potentially "unacceptable") for any complete exposure pathway) – continue after providing a description (of each potentially "unacceptable" exposure pathway) and explaining and/or referencing documentation justifying why the exposures (from each of the remaining complete pathways) to "contamination" (identified in #3) are not expected to be "significant."

____ If unknown (for any complete pathway) – skip to #6 and enter "IN' status code

Rationale and Reference(s):

One of the residential water supply wells to the immediate southwest of Tinker has been contaminated with trichloroethylene at 13.7 parts-per-billion (the MCL is 5). The contamination is in a shallow aquifer situated hundreds of feet above the aquifer used as a major source of drinking water (a.k.a., the Production Zone). No contamination has been detected in the Production Zone. However, the residential well was constructed in a shallow aquifer and screened in a manner which allows contamination in the upper aquifer to enter the well. A twenty-well pump and treat system was installed as an interim corrective measure. Grunfos pumps were installed in 2002 to replace the original reciprocal piston pumps. The newer "smart" pumps have doubled the original extraction volume of the extraction system which is extracting the contaminated groundwater and treating it.

In addition, the Air Force is constructing a 500-foot long, 100-foot deep zero-valent iron permeable reactive barrier (PRB) across the contaminant plume to remove the trichloroethylene before it can migrate off-site. The construction of the PRB will be completed in August 2004.

.If there is any question on whether the identified exposures are "significant" (i.e., potentially "unacceptable"0 consult a human health Risk Assessment specialist with appropriate education, training and experience.

5. Can the "significant" **exposures** (identified in #4) be shown to be within **acceptable** limits?

_____ If yes (all "significant" exposures have been shown to be within acceptable limits) – continue and enter "YE" after summarizing and referencing documentation justifying why all "significant" exposures to "contamination" are within acceptable limits (e.g., a site-specific Human Health Risk Assessment).

_____ If no (there are current exposures that can be reasonably expected to be "unacceptable")- continue and enter "NO" status code after providing a description of each potentially "unacceptable" exposure.

_____ If unknown (for any potentially "unacceptable" exposure) - continue and enter "IN" status code.

Rationale and Reference(s):

6. Check the appropriate RCRIS status codes for the Current Human Exposures Under Control EI event code (CA725), and obtain Supervisor (or appropriate Manager) signature and date on the EI determination below (and attach appropriate supporting documentation as well as a map of the facility):

__√__ YE - Yes, "Current Human Exposures Under Control" has been verified. Based on a review of the information contained in this EI Determination, "Current Human Exposures" are expected to be "Under Control" at the Tinker Air Force Base facility, EPA ID # OK1571724391, located at 7701 Arnold Street. Suite 204 under current and reasonably expected conditions. This determination will be re-evaluated when the Agency/State becomes aware of significant changes at the facility.

____ NO - "Current Human Exposures" are NOT "Under Control."

____ IN - More information is needed to make a determination.

Completed by (signature) [signature] Date 12/30/05
(print) Robert Replogle
(title) Environmental Protection Specialist

Supervisor (signature) [signature] Date 1/5/06
(print) Donald Hensch
(title) Engineering Manager
(EPA Region or State) ODEQ

Locations where References may be found:

Oklahoma Department of Environmental Quality
Land Protection Division
707N. Robinson Avenue
Oklahoma City, OK 73102

Integrated Environmental Team Library
7701 Arnold Street, Suite 213
Tinker AFB, Oklahoma 73160-9100

Contact telephone and e-mail numbers
(name) Robert Replogle
(phone #) 405-702-5118
(e-mail) robert.replogle@deq.state.ok.us

FINAL NOTE: THE HUMAN EXPOSURES EI IS A QUALITATIVE SCREENING OF EXPOSURES AND THE DETERMINATIONS WITHIN THIS DOCUMENT SHOULD NOT BE USED AS THE SOLE BASIS FOR RESTRICTING THE SCOPE OF MORE DETAILED (E.G., SITE-SPECIFIC) ASSESSMENTS OF RISK.