
SUNRISE MOUNTAIN LANDFILL
(ATTACHMENT 5)
DIVERSION BERM LOCATIONS
AND SLOPES > 10%
March 21, 2008
Exponent
0 400 800 1200 1600 2000
Dam
Eastern Perimeter Ditch
Channel 2
Rockfall Channel
Channel 3
Berm 11
Berm 12
Dam Outlet Channel
See Attachment 6
for Top Deck Area
Channel 1
Western Ridge Ditch
Berm 9
Berm 1
Berm 2
Berm 10
Berm 10A
Berm 8
Berm 7
Berm 6
Swale
Berm 4
Berm 3
Berm 5
Berm 13
Background Topo Based on:
KENNY AERIAL MAPPING, INC.
Flight Date: North Half March 24, 1999
South Half August 03, 1999
N.E. Canyon Updated
May 22, 2002
Client: Republic Services
LEGEND - EXISTING FEATURES
ROAD
LEASE BOUNDARY
WASTE LIMITS
EXISTING UNLINED CHANNEL
ROADWAY BERM
CONCRETE HEADWALL
PIPE DOWNDRAIN
DRIVEOVER
ROCK OR CONCRETE LINED DITCH/CHANNEL
LANDFILL GAS HEADERS AND LATERALS
DRAINAGE AREA BOUNDARY
E15 DRAINAGE AREA NAME
Greater than 10% Slope
Diversion Berm (~ 9,000 feet)
Perimeter Berm
Concentrated Run-On Flow Locations