

# PETTIT

marine  paint

# UNEPOXY

## ANTI FOULING

1226

BLUE INLANE FORMULA

1 QT. 32 FL.OZ. (1 QT.)

**CAUTION** KEEP OUT OF THE REACH OF CHILDREN.  
OTHER WARNINGS ON BACK PANEL

# PETTIT PAINT CO., INC.

# SAN LEANDRO, CALIF. BELLEVILLE, N. J.

### ACTIVE INGREDIENTS

Cuprous Oxide	41.40%
Bis (tri-n-butyltin) Oxide	2.00%
<b>INERT INGREDIENTS</b>	<b>56.60%</b>
	<b>100.00%</b>

USDA REG. #390-96

### UNEPOXY COLOURS

Unepoxy is an effective hard racing finish for boats. It is a non-antifouling hard racing finish that is easy to apply and dries to a hard, durable finish. It is suitable for use on aged hard racing finishes, bare metal, wood, fiberglass or semi-hard antifouling paint. It is applied in two coats between coats. After the first coat, the surface should be sanded and the second coat applied. The maximum life is 2 months maximum.

**FIBERGLASS:** Wash fiberglass with PETTIT'S #1210 BRUSHING THINNER and dirt. Sand thoroughly with medium grit sandpaper. Wash with water. Apply a coat of 9399 SATELLITE PRIMER. After the primer has dried, apply the first coat of Unepoxy. The second coat is applied to the first coat with 24 hours drying.

**WOODEN HULLS:** Old antifouling paint should be removed. The new non-antifouling hard racing finishes should be sanded thoroughly. If the hull is bare, apply 1 coat of PETTIT'S RED LEAD PRIMER and let dry for 24 hours. Sand.

**STEEL HULLS:** To remove old rust and scale from the metal surface, use a wire brush. Wash the surface with PETTIT'S #1210 BRUSHING THINNER. Wash with water. Apply 1 coat of PETTIT'S VINYL METAL PRIMER to bare metal and let dry 4 hours. Follow with 2 coats of RED UNDERCOATER and let dry 2 hours between coats and 4 hours before applying Unepoxy.

**CLEANING AND THINNING:** Use PETTIT'S #1210 BRUSHING THINNER.

DO NOT USE THIS PRODUCT ON ALUMINUM HULLS. USE PAINT THAT IS HIGHLY BONDING TO ALUMINUM.

### CAUTION

**HARMFUL OR FATAL IF SWALLOWED. MAY CAUSE SKIN IRRITATION**

CONTAINS COPPER AND TIN COMPOUNDS AND AROMATIC HYDROCARBONS. DO NOT SWALLOW. Drink milk. Do not breathe spray mist. Do not get in eyes or on skin. In case of skin contact, remove contaminated clothing and immediately wash with soap and water. In case of skin contact, remove contaminated clothing and immediately wash with soap and water. Flush eyes with water. Get medical attention if swallowed. Do not eat, drink, or use food or feed products. Do not apply to surface that will be used by children. Destroy it by perforation or crushing. Bury or discard in safe place.

Use with adequate ventilation.

ONE QUART U.S. STANDARD

IMPERIAL MEASURE

ACCEPTED WITH COMMENTS

UNDER THE FEDERAL INSECTICIDE ACT

July 28, 1971

391-016