

Stauffer
CHEMICALS

POLE-FUME[®]

**A FUMIGANT FOR CONTROLLING DECAY
AND INSECTS IN WOOD POLES**

CAUTION

**Keep Out of Reach
of Children**

**HARMFUL IF INHALED OR SWALLOWED.
IRRITATING TO EYES, NOSE, THROAT AND SKIN.**

AVOID BREATHING VAPOR.

DO NOT GET IN EYES, ON SKIN, OR ON CLOTHING.

In case of contact, immediately remove contaminated clothing or shoes and flush skin with plenty of water, and apply soothing lotion; for eyes, flush with water for at least 15 minutes and get medical attention.

Wash and dry clothing and shoes before re-use.

When applying in enclosed areas, wear a mask or respirator of a type passed by the U.S. Bureau of Mines for Vapam[®] protection.

1 GAL. NET

Made in USA By

STAUFFER CHEMICAL COMPANY

WESTPORT, CT 06880

DIRECTIONS FOR USE

When a pole is detected with rot or insect damage, dig the soil away from the base of the pole to a depth of 12 inches.

Drill 9/16 inch holes in each quarter of the pole at ground line and one 9/16 inch hole 2 feet above the ground line, preferably above the decay pocket. These holes should be at a 45° angle downward and to a depth equal to, or slightly greater than the radius of the pole.

Inject equal amounts of POLE-FUME into all holes using a total of 1 pint per pole. In severely diseased poles use 2 pints per pole.

Plug the holes with treated wood plugs, using the precaution of wearing safety goggles to avoid splashing any of the liquid POLE-FUME into the eyes.

When the POLE-FUME treatment is for the control of insects, the pole should be wrapped over the treated area with 48-inch laminated kraft paper. Staple and seal the seam and top edge with 1-inch masking tape.

FOR THE CONTROL OF DECAY IN POLES, NO WRAPPING IS NECESSARY.

Backfill and tamp the excavated area to form a seal against the kraft paper. The kraft paper should be removed and disposed of, when convenient, after 2 months.

DISPOSAL

Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place away from water supplies.