


BALTIMORE
RED COPPER PAINT
PIGMENT 47.7 %
VEHICLE 52.3 %
Pigment
Cuprous Oxide 41.5 %
Red Iron Oxide C.P. 15.5 %
Calcium Carbonate 15.5 %
Magnesium Silicate 27.5 %
Vehicle
Pine Tar 35.0 %
Phenolic Resin 18.0 %
Este Gum 12.6 %
Mineral Spirits 34.4 %
ACTIVE INGREDIENT
Cuprous Oxide 19.9 %
(Copper, as Metallic 17.6 %)
INERT INGREDIENTS 80.1 %

USDA REG. NO. 2568-23

## DIRECTIONS

STIR THOROUGHLY BOTH BEFORE AND DURING APPLICATION, AND LILOW 4-6 HOURS' DRYING TIME BETWEEN COATS AND BEFORE LAUNCHING. IT IS NOT ADVISABLE TO DELAY LAUNCHING LONGER THAN 6 HOURS. APPLY TO BARE WOOD OR TO A SURFACE PROPERLY PREPARED BY SANDING, WIRE BRUSHING AND CLEANING. FOR BEST RESULTS TWO COATS SHOULD BE APPLIED, AND ON NEW WORK NO LESS THAN THREE COATS. NO OTHER PRIMER SHOULD BE USED. NO THINNING IS NORMALLY NEEDED . . . TURPENTINE MAY BE USED TO WASH BRUSHES OR REPLACE SOLVENT LOST BY EVAPORATION.

CAUTION! COMBUSTIBLE! Keep away from heat, sparks, and open flame. CONTAINS LEAD OR OTHER COMPOUNDS HARMFUL IF EATEN. Do not apply on any interior surfaces of a dwelling, or a place used for the care of children, or on window sills, toys, cribs and other furniture which might be chewed by children. Avoid breathing vapor or spray mist and prolonged contact with skin. Wash thoroughly after handling and before eating or smoking. Keep container closed when not in use. Keep out of reach of children. I se with adequate ventilation. Do not take internally.





(OLIVER REEDER & SON., INC. PROPRIETORS.)

QUART ::

BALTIMORE, MD. 21230 U.S.A.

AGAINST THE ATTACHMENTS OF

BARNACLES, SHELLS AND ALGAE (SEA GRASSES)

RALTIMORE RED COPPER PAINT PIGMENT . . . . . . . 47.7% VEHICLE ..... Pigment Cuprous Oxide Red from Oxide C.P. Red Iron Ovide C.P. 15.5% Calcium Carborate 15.5% Magne-lum Silicate 27.5% Ventele Pine Tar ... 35 0% Phenolic Resin ... 18.0% Ester Gues Mineral Spirits ACTIVE INGREDIENT Copper, as Metallic 17 60, 1 INERT INGREDIENTS No 1% USDA REG NO 2568 23

19.9%

80.1%

## DIRECTIONS

STIR THOROUGHLY BOTH BEFORE AND DURING APPLICATION, AND ALLOW 4-6 HOURS' DRYING TIME BETWEEN COATS AND BEFORE LAUNCH-ING. IT IS NOT ADVISABLE TO DELAY : AUNCHING LONGER THAN 6 HOURS. APPLY TO BARE WOOD OR TO A SURFACE PROPERLY PREPARED BY SANDING, WIRE BRUSHING AND CLEANING, FOR BEST RESULTS TWO COATS SHOULD BE APPLIED, AND ON NEW WORK NO LESS THAN THREE COATS. NO OTHER PRIMER SHOULD BE USED. NO THINNING IS NORMALLY NEEDED . . . TURPENTINE MAY BE USED TO WASH BRUSHES OR REPLACE SOLVENT LOST BY EVAPORATION.

CAUTION! COMBUSTIBLE! Keep away from heat, sparks, and open flame CONTAINS LEAD OR OTHER COMPOUNDS HARMFUL IF EATEN. Do not apply on any interior surfaces of a dwelling, or a place used for the care of children, or on window sills, toys, cribs and other furniture which might be chewed by children. Avoid breathing vapor or spray mist and prolonged contact with skin. Wash thoroughly after hancling and before eating or smoking Keep container closed when not in use. Keep out of reach of children. Use with adequate ventilation. Do not take internally.

· 4363 - 4