



NET WEIGHT 5 MEASURE



GLOUCESTER

SEA JACKET®



MARINE

PAINTS


3482-34

ACTIVE INGREDIENT	
Cuprous Oxide*	70.2%
INERT INGREDIENTS	29.8
	100.0%
*Total copper metal (from cuprous oxide)	60.4%




ACCEPTED
 Sept 23 1972
 UNDER THE FEDERAL INSECTICIDE
 FUNGICIDE AND FERTILIZER ACT
 FOR ECONOMIC PEST CONTROL REGISTERED
 ED UNDER NO. 100-1000000000
 TO AFFILIATE

Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place.



PREMIUM QUALITY SHIPBOTTOM

ANTIFOULING PAINT



515 SPECIAL RED

CAUTION KEEP OUT OF REACH OF CHILDREN
SEE BACK PANEL FOR ADDITIONAL CAUTIONS

This is a hard-finish paint which has not only remarkable antifouling properties, but excellent adhesion, erosion resistance, and long life as well. These characteristics recommend it for boats of high speed requiring superior adhesion and erosion resistance; boats in the water year-round, where long life is important; and sailing and other craft where smoothness and least frictional resistance is desired.

DIRECTIONS FOR USE

This paint is sold for use ONLY on ship and boat bottoms for the prevention of marine fouling. Do not use it in any household application.

Previously painted bottoms on which the old paint is in good condition and firmly attached may be recoated after sanding off all loose dirt. Where old paint is loose and flaking in large areas, strip it off and proceed as for new unpainted work.

NEW AND STRIPPED WORK

This copper paint can be applied directly to wood bottoms after sanding smooth. To insure adhesion to fiberglass bottoms, they should be primed with one coat of B370 Epoxy Primer, in accordance with directions for that material, before applying copper paint. Prime steel bottoms with two coats 407 Shipbottom Primer, and aluminum bottoms with two coats 410 Q. D. Green, before using copper paint. Steel or aluminum can also be primed with 415 Primer.

Stir copper paint thoroughly with a flat paddle before using and during application. Apply two coats to clean, dry surface and allow at least 4 hours drying time between coats and before launching. Thin only if absolutely necessary to restore free brushing consistency. Use denatured alcohol for thinning if required, and for cleaning brushes and equipment. Add no other materials.

CAUTION - FLAMMABLE

Do not use, pour, spill or store near heat or open flame.

THIS PAINT CONTAINS COPPER AND OTHER COMPOUNDS HARMFUL if swallowed. Avoid breathing vapor or spray mist and contact with skin. Wash immediately with soap and water in case of contact with skin. Use protective mask when dry-sanding. Avoid contamination of feed and foodstuffs.

Keep container closed when not in use. Keep out of reach of children.

USE WITH ADEQUATE VENTILATION.

U.S.D.A. Registration No. 3482-34

GP Form 515-172

GLOUCESTER PAINTS, INC., GLOUCESTER, MASS., U.S.A.

