

Stir GRACO Creosote thoroughly before using. Never dilute. If you do, its effectiveness is reduced. Do not boil as this results in unnecessary loss of material. For best results follow these directions: Heat Creosote to a little above water boiling temperature, say 220° F. However, in hot weather, you can use it just as it is on

dry, seasoned wood and get good results. Although Creosote when hot penetrates deeper and is more effective, it may be applied cold with satisfactory results.

HOW TO APPLY AS A WOOD PRESERVATIVE

Brushing: Apply liberally, with brush or mop, hot Creosote, flooding surface so as to fill completely ali cross cuts, mortises, tenons, checks and other defects. After an interval of 24 hours, or after first application has dried, apply a second coat in the same manner, to achieve the best results. This is absolutely essential for all material to be used under or lying on the ground.

Spraying: Spray GRACO Creosote hot, with a spray gun or paint machine. Creosote cools quickly when sprayed. Spraying effectively drives Creosote into cracks and crevices, but is not recommended in severely cold weather. After an interval of 24 hours, or after first application has dried, apply a second coat in the same manner, to achieve the best results. This is absolutely essential for all material to be used under or lying on the ground.

Dipping: Immerse that portion of timber to be treated in a bath of hot Creosote for a period of one to two hours. It is especially necessary that all wood to be treated be completely peeled and well seasoned.

FILLED BY

THE WARNER-GRAHAM CO. BALTIMORE, MARYLAND, U.S.A.

Open Tank Method: Immerse the timber in a bath of GRACO Creosote. Keep the temperature at 200° F, for two hours and then allow to cool before removing timber. If you want to use two baths, place the timber removed from the first bath into a second tank in which the Creosote is not heated, and keep it there for two hours more. This treatment gives the best penetration.



To Prevent Decay and to Control Termites



 \Box

Ш

EPT

いじ

4

ACTIVE INGREDIENTS: 98.5% REFINED COAL TAR CREOSOTE

INERT INGREDIENTS: 1% Water (Maximum) 0.5% Free Carbon (Maximum)

CAUTION

MAY CAUSE SKIN IRRITATION. USE ONLY WITH ADEQUATE VENTILATION. AVOID PRO-LONGED OR REPEATED CONTACT WITH SKIN. AVOID PROLONGED BREATHING OF VAPOR. HARMFUL IF SWALLOWED.

KEEP OUT OF REACH OF CHILDREN.

USDA REG NO 7342-1

FILLED BY THE WARNER-GRAHAM CO. BALTIMORE, MARYLAND, U.S.A.