

[LOGO] Betz PaperChem, Inc. slime-trol[R] DP-580 Slime Control Agent

(FIRST PANEL)

PRECAUTIONARY STATEMENTS[14bf]

HAZARDS TO HUMANS AND[12bf]
DOMESTIC ANIMALS[12bf]

DANGER[18bf]

HARMFUL OR FATAL IF SWALLOWED OR ABSORBED THROUGH THE SKIN. Causes eye damage and skin irritations. Do not inhale vapor or mist. Use with adequate ventilation. Do not get into eyes, on skin or on clothing. Wear rubber gloves, goggles and face shield when handling. Immediately remove and wash contaminated clothing and wash before reuse. Wash thoroughly after handling.

ACCEPTED
APR 02 1987
Under the Federal Insecticide, Fungicide, and Rodenticide Act, as amended, for the pesticide registered under EPA Reg. No. 45017-24

ENVIRONMENTAL HAZARDS[14bf]

This pesticide is toxic to fish and wildlife. Do not discharge effluent containing this product into lakes, ponds, estuaries, oceans, or public waters unless this product is specifically identified and addressed in an NPDES permit. Do not discharge effluent containing this product to sewer systems without previously notifying the sewage treatment plant authority. For guidance contact your State Water Board or Regional Office of the EPA.

PHYSICAL AND CHEMICAL HAZARDS[12bf]

Corrosive. Do not use, pour or store near heat or open flame.


DIRECTIONS FOR USE[14bf]

It is a violation of Federal law to use this product in a manner inconsistent with its labeling.

PULP AND PAPER MILL SYSTEMS[12bf]

BETZ PaperChem Slime-trol DP-580 aids in the control of objectionable bacteria and fungi in pulp, paper mill and the additive system, and for the preservation of pulp, pigment slurries, alum, emulsions, adhesives, defoamers, polymers, and paper products. Additions can be made on a continuous or intermittent basis, depending upon the

BEST AVAILABLE COPY



severity of the contamination.

3ADLY FOULED SYSTEMS must be cleaned before treatment is begun.

(Directions for Use continued on third panel.)

PAPCH059 3612

Business Phone: 904-733-7110 BETZ Paper- [Cont'd at bottom of second panel.]

(SECOND PANEL)

Contents: LIQUID

Active Ingredients:

Dodine(dodecylguanidine acetate).....4.8%

Methylenebis (thiocyanate).....4.9%

Inert Ingredients*.....90.3%


Total.....100.0%

*Inert ingredients include solubilizing and dispersing agents.

EPA Reg. No. 45017-24

WEIGHT PER GALLON OF PRODUCT
8.2 Pounds (60F)

NET WEIGHT OR VOLUME
AS MARKED ON CONTAINER



KEEP OUT OF REACH OF CHILDREN[12bF]

DANGER[13bF]


STATEMENT OF PRACTICAL TREATMENT[14bF]

In case of contact with skin, wash immediately with soap and plenty of water. Immediately contact physician.

In case of contact with eyes, flush promptly and thoroughly with clear water for at least 15 minutes. Immediately contact physician.

In case of ingestion, immediately contact physician.

A Material Safety Data Sheet containing more detailed information relative to



this product is available upon request.

See left panel for additional Precautionary Statements.

Chem, Inc. JACKSONVILLE, FLORIDA 32216 [Cont'd at bottom of third panel.]

(THIRD PANEL)

FOR SLIME CONTROL

Slime-trol DP-580 should be added directly to the pulp and paper mill systems. Apply at a point in the system where the product will be uniformly mixed.

INTERMITTENT OR SLUG METHOD

INITIAL DOSE: When the system is noticeably fouled, add Slime-trol DP-580 at the rate of 0.1 to 1.0 pound per ton of pulp or paper produced. Addition of Slime-trol DP-580 to the additive system should be made directly at the rate of 0.5 to 4.0 pounds (60 to 480 ppm) per 1000 gallons. Repeat until control is achieved.

SUBSEQUENT DOSE: When microbial control is evident, add Slime-trol DP-580 at the rate of 0.1 to 0.3 pound per ton of pulp or paper produced. Treat the system as needed to maintain control. Addition of Slime-trol DP-580 to the additive system may be reduced to 0.25 to 2.0 pounds (30 to 240 ppm) per 1000 gallons.

CONTINUOUS FEED METHOD

INITIAL DOSE: When the system is noticeably fouled, add Slime-trol DP-580 at the rate of 0.1 to 1.0 pound per ton of pulp or paper produced. Addition of Slime-trol DP-580 to the additive system should be made directly at the rate of 0.5 to 4.0 pounds (60 to 480 ppm) per 1000 gallons. Continue until control is achieved.


SUBSEQUENT DOSE: Maintain the following level by continuous feed of Slime-trol DP-580 at the rate of 0.1 to 0.3 pound per ton of pulp and paper produced. Addition of Slime-trol DP-580 to the additive system should be made at the rate of 0.1 to 1.5 pounds (12 to 180 ppm) per 1000 gallons.

FOR PRESERVATION(1254)

Slime-trol DP-580 should be added directly to the material to be preserved prior to manufacturing into the finished product, i.e.,

ACCEPTED
APPROVED
45017-24

BEST AVAILABLE COPY



pulp, broke, polymers, defoamers, alum, emulsions, adhesives, paper mill coatings, pigment slurries, and paper products. The dosage rate will depend upon the material to be preserved and the storage time. The usual additions should be 200 to 300 ppm and under extreme conditions of spoilage the dosage rate should be increased to 250 to 800 ppm. The above recommendations are based on a maximum storage time of 2 weeks. For storage time greater than 2 weeks, the maximum concentration of Slime-trol DP-530 should be increased to 1000 ppm.

Emergency (Health or Accident): 215-355-3300

(FOURTH PANEL)

STORAGE AND DISPOSAL[12bf]

STORAGE: Keep container tightly closed. Protect from freezing. Store in a dry place. Do not store at elevated temperatures.

DISPOSAL: Do not contaminate water, food or feed by storage or disposal.

PESTICIDE DISPOSAL:


Pesticide wastes are acutely hazardous and/or toxic. Improper disposal of excess pesticide, spray mixture, or rinsate is a violation of Federal law. If these wastes cannot be disposed of by use according to label instructions, contact your State Pesticide or Environmental Control Agency or the Hazardous Waste representative at the nearest EPA Regional Office for guidance.

CONTAINER DISPOSAL:

Metal and Plastic Containers[bf]: Triple rinse (or equivalent). Then offer for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or incinerate or burn if allowed by state and local authorities. If burned, stay out of smoke.

Fiber Drums with Liners[bf]: Completely empty liner by shaking and tapping sides and bottom to loosen clinging particles. Empty residue into application equipment. Then dispose of liner and drum in a sanitary landfill or incinerate if allowed by state and local authorities. Do not reuse empty drum and liner.

FOR INDUSTRIAL USE ONLY. Technical advice regarding specific site problems is avail-



BEST AVAILABLE COPY

able from BETZ PaperChem, Inc.

1 17/5

BEST AVAILABLE COPY

5 2
9 3
0 2