

**PRECAUTIONARY STATEMENTS
HAZARDS TO HUMANS
(& DOMESTIC ANIMALS)**

• **WARNING** •

CAUSES EYE IRRITATION. Harmful if absorbed through skin. Avoid contact with skin, eyes, or clothing. Wear protective clothing such as gloves, long sleeved cotton shirt, long pants and hat. May be harmful if inhaled. Do not breathe vapor or spray mist while spraying paint or sanding boat surfaces. Wear a mask or respirator partly approved by The Mining Safety and Health Administration and The National Institute of Occupational Safety and Health. Remove contaminated clothing and wash before reuse. Wash thoroughly with soap and water after handling.

ENVIRONMENTAL HAZARDS

This Material is Toxic to Fish. Do not apply directly to water by dumping or disposal of wastes. Do not allow ships and their gear during paint removal to enter water. Disposal of paint debris is an approved method.

PHYSICAL or CHEMICAL HAZARDS
Do Not Use or Store Near An Open Flame.

DIRECTIONS FOR USE

IT IS A VIOLATION OF FEDERAL LAW TO USE THIS PRODUCT IN A MANNER INCONSISTENT WITH ITS LABELING.

STORAGE AND DISPOSAL

STORAGE

Do not contaminate water, food or feed by storage or disposal. Open dumping is prohibited. Store in a cool, dry area away from heat or open flame.

DISPOSAL

Prior to spray machine or roller use that cannot be used or according to label various items must be disposed of according to applicable Federal, state or local procedures.

Container - Triple rinse (or equivalent). Then allow for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or by other approved state and local procedures.

**QUALITY PRODUCTS
FOR THE COMMERCIAL WATERMAN**

RAPPAHANNOCK

**Copper Paint
No. 2**

**ACTIVE INGREDIENTS
CUPROUS OXIDE
(Copper as Metallic)**
INERT INGREDIENTS
TOTAL

25.00%
25.00%
74.00%
100.00%

25.00%
25.00%
74.00%
100.00%

"This Product Contains petroleum Distillates"

Keep Out of Reach of Children

• **WARNING** •

STATEMENT OF PRACTICAL TREATMENT

IF SWALLOWED. Drink promptly a large quantity of milk, egg whites, gelatin solution or if these are not available, drink large quantities of water. Avoid Alcohol. Get Medical Attention.

IF INHALED. Remove victim to fresh air. If not breathing, give artificial respiration, preferably mouth to mouth. Get Medical Attention.

IF ON SKIN. Wash with plenty of soap and water. Get Medical Attention.

IF IN EYES. Flush with plenty of water. Get Medical Attention.

SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS

MFD. BY: Rappahannock Copper Paint Co., Inc.
Virginia Beach, Virginia

Establishment No.

EPA Registration No.

NET CONTENTS - ONE GALLON

JAN 23 1985

51647-2

**DIRECTIONS FOR USE
FOR COMMERCIAL USE ONLY**

This is a superior oxide pigment coating formulated especially to prevent the attachment of both plant and animal fouling on vessels immersed in both seawater and "brackish" water.

When used over steel or aluminum surfaces, a primer coating is required to prevent accelerated corrosion. The coating requires no primer when used directly over fiberglass or wood. For optimum performance, two (2) coats are recommended. The theoretical coverage of this product is at least 600 square feet per gallon, when applied to the recommended dry film thickness.

To prepare the surface for coating, remove all old coating and fouling residues by either washing with high pressure water, scraping or by shot blasting. Be sure to use the proper protective equipment to prevent inhalation or ingestion of the paint dust generated.

A clean dry surface, free of oil, corrosion, dirt, grease, oil, marine fouling, or other foreign matter will provide the optimum performance of this coating, when used for either complete coating or for touch-up. Inadequate surface preparation will result in unsatisfactory performance. Be sure to remove all dust, debris and other surface contaminants that are generated by the cleaning process, prior to painting.

Mix the coating with either a high speed mixer, or a paint shaker for a minimum of five (5) minutes to ensure complete pigment reencapsulation. Then in the event that the coating is too thick to apply easily. Thin with mineral spirits or kerosene. Clean up with mineral spirits or kerosene.

Apply by either brush, roller, or spray. Be sure to follow mixing instructions and apply the correct thickness. Allow a minimum of four (4) hours between coats and a minimum of two (2) hours before undercoating vessel.

40 00 11

Rev. 2

Oct. 81

00 00 11

BEST AVAILABLE COPY