

Tecumseh Redevelopment Inc. (Formerly: Bethlehem Steel Corp.)

**Foot of Campbell Street
Williamsport, PA 17701
Congressional District 10
EPA ID #: PAD003053758
Facility Property Area: 46 acres
Last Updated: 4/29/2014**

Current Progress at the Site

This facility is one of EPA Region III's high priority RCRA corrective action sites and EPA, working with PADEP has determined that both the Human Exposure and Groundwater Environmental Indicators continue to be met at this facility.

On March 30, 1999, EPA determined that both the Human Exposures and Groundwater Environmental Indicators have been met. The facility is now managed by Tecumseh Redevelopment, a realty management arm of International Steel Group (ISG). ISG purchased Bethlehem Steel in a bankruptcy proceeding in 2003.

Site Description

The Bethlehem Steel Corp. (now Tecumseh Development) facility is located at the foot of Campbell Street in Williamsport, Lycoming County, Pa. Bethlehem Steel Corp. previously manufactured wire rope and strand at the facility. Sludge, including spent liquor sludge, from the plant's wastewater treatment facility accumulated in three surface impoundments. The impoundments were closed as disposal impoundments under a RCRA closure plan approved by the State. The impoundments were certified closed on November 5, 1990 and a RCRA Post Closure Permit was issued in April 1994. Bethlehem Steel Corp. is conducting monitoring and maintenance at the disposal impoundments as required by the Post Closure Permit. The most recent sampling showed that groundwater contaminant levels remain below applicable water quality standards. Changes to certain monitoring requirements were made to the post closure permit on March 27, 2002. The most recent inspection by PADEP, which included sampling of all monitoring wells was conducted on June 25, 2003 by PADEP Williamsport personnel.

Site Responsibility

RCRA Corrective Action activities at this facility are being conducted under the direction of PADEP through a post-closure permit that addresses the corrective action obligation at the facility.

Institutional Controls

Institutional controls are not required at this time.

Government Contact

Maureen Essenthier
Office of Pennsylvania Remediation - 3LC30
U.S. Environmental Protection Agency - Region III
1650 Arch Street
Philadelphia, PA 19103-2029
Phone: (215) 814-3416
Email: essenthier.maureen@epa.gov

PADEP
Mr David Garg
dgarg@state.pa.us

Facility Contact

Mr. Keith Nagel
Tecumseh Redevelopment, Inc./ISG
Manager Environmental Affairs
3250 interstate Drive
Richfield, Ohio 44286-9000
Phone: (330) 659-7434
Email: knagel@intlsteel.com

For more information about EPA's corrective action webpage, including Environmental Indicators, please visit our site at: www.epa.gov/reg3wcmd/correctiveaction.htm