

Summary of Waterbody Assessment and TMDL Status in Massachusetts

Woburn, MA

ID	Waterbody Name	Watershed Name	Category	Acres		Miles		Cause	TMDL
				In Town - Total	Total	In Town - Total	Total		
MA71-01_2008	Aberjona River	Boston Harbor:	5			4.6	9.2	Cause Unknown Metals Nutrients Organic enrichment/Low DO Other habitat alterations* Pathogens Unionized Ammonia	
MA71-10_2008	Cummings Brook	Boston Harbor:	3			2.1	2.1		
MA71-11_2008	Shaker Glen Brook	Boston Harbor:	3			1.5	1.5		
MA92-04_2008	Maple Meadow Brook	Ipswich	4c			0.0	4.2		
MA71019_2008	Horn Pond	Boston Harbor:	5	107.81	107.81			Noxious aquatic plants Nutrients Organic enrichment/Low DO	

1) Adapted from Final Massachusetts Year 2008 Integrated List of Waters (CN 281.1, 12/2008); available at <http://www.mass.gov/dep/water/resources/08list2.pdf>
 2) For additional information on TMDLs and to view reports, see: <http://www.mass.gov/dep/water/resources/tmdls.htm>
 3) For Massachusetts Surface Water Quality Standards, and waterbody classes and uses, see: <http://www.mass.gov/dep/service/regulations/314cmr04.pdf>

Assessment of Waterbody Segment

Category 2 - Attaining some uses; other uses not assessed
 Category 3 - Insufficient information to make assessments for any use
 Category 4a - TMDL is completed
 Category 4c - Impairment not caused by a pollutant
 Category 5 - Impaired or threatened for one or more uses and requiring a TMDL

Note: The accuracy of mileage and acreage estimates is limited for waterbodies that serve as or span municipal boundaries