

Superfund Records Center

SITE: New Bedford

BREAK: 5.3

OTHER: 462545

Karen Vilandry Comments II 09-07-09

To: Elaine Stanley
Remedial Project Manager
New Bedford Harbor Superfund
Site

Regarding the "Explanation of Significant Differences between the remedial action being undertaken and the remedial action set forth in the Record of Decision, (ROD), and the reasons such changes are being made, I have some questions regarding the material used for the liner to store the toxic sediment.

What is the liner made of, how thick is it, and what type of hazardous waste material is it designed for? Specifically, is it made to hold a combination of PCBs, trichloroethylene and heavy metals? How long can these sediments be stored without that material breaking down?

Thank you.

Sincerely,
Karen A. Vilandry
Environmental Activist
Greater New Bedford
34 Huttleston Avenue
Fairhaven, MA 02719-3115
Tel. 508-951-1184
Email: kav704@yahoo.com

