

4.2



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02254-9149



SDMS DocID **46289**

REPLY TO  
ATTENTION OF

April 16, 1991

Programs/Project Management

MAY 03 91

Ms. Mary Sanderson  
Environmental Protection Agency  
Waste Management Division  
J.F. Kennedy Building (HANCAN 2)  
Boston, Massachusetts 02203-2211

Superfund Records Center  
SITE: New Bedford  
BREAK: 04.02  
OTHER: 76289

Dear Ms. Sanderson:

I have enclosed a summary of the groundwater monitoring that has been performed in and around the New Bedford Harbor confined disposal facility. The results do not show a significant change from pre-operational conditions except that PCBs were detected in wells F and G during the most recent sampling effort (October 90).

I have also attached the results of a sampling effort carried out to determine PCB levels in the sediment within the CDF. These samples were taken in November 1990 to assist in the development of the health and safety specifications for the site preparation contract.

Please give me a call at 647-8895 if there are any questions or if additional information is needed.

Sincerely,

Mark J. Otis  
Project Manager

Encls

CF:  
Paul Craffey (MA DEP)  
Mr. Otis, 113s