

**From:** Colarusso, Phil  
**To:** ["Chet Myers"](#)  
**Subject:** RE: NBMCT Blasting curtains  
**Date:** Thursday, September 26, 2013 10:09:00 AM  
**Attachments:** [image001.jpg](#)  
[image002.png](#)  
[image003.png](#)

---

Chet,

Cindy Catri asked me to tell you that the silt curtain placement details be reflected in the Blasting Operation Plan to be submitted to EPA.

Thanks  
Phil

---


**From:** Chet Myers [mailto:[cmyers@apexcos.com](mailto:cmyers@apexcos.com)]  
**Sent:** Wednesday, September 25, 2013 8:47 AM  
**To:** Colarusso, Phil  
**Subject:** RE: NBMCT Blasting curtains

Hi Phil,

It sounds like that is going to work. We will need to check with MassDOT to confirm (since they own the bridge), but HDC is on board, so I think we may have a viable plan.

We will keep you up to date on the details as events proceed.

Thanks,



**Follow Apex on and Like us on**

**Privacy Notice:** This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

---

**From:** Colarusso, Phil [mailto:[colarusso.phil@epa.gov](mailto:colarusso.phil@epa.gov)]  
**Sent:** Tuesday, September 24, 2013 3:02 PM  
**To:** Chet Myers  
**Subject:** RE: NBMCT Blasting curtains

If that's possible, that would be my preference.

---

**From:** Chet Myers [mailto:[cmyers@apexcos.com](mailto:cmyers@apexcos.com)]  
**Sent:** Tuesday, September 24, 2013 3:00 PM

**To:** Colarusso, Phil  
**Subject:** RE: NBMCT Blasting curtains

Hi Phil,

We couldn't connect the northwest tip of Fish Island with the shore, because Maritime Terminal is on the west side of the passage and Bridge Terminal is on the north side of Fish Island. They have a thriving cargo business, and would oppose us putting a barrier to navigation in that location.

However, we could probably put the silt curtain under the bridge on the New Bedford side between Fish Island and the shoreline. The fish may then just head south along the west side, then cross over and go north until they went around Fish Island.

So, the silt curtain would be closer to 90 degrees to shore than 45 degrees as we had previously discussed, but it could be a good option (we could secure the silt curtain to the bridge, which would help to stabilize it to keep it in place).

Thanks,



**Follow Apex on and Like us on**

**Privacy Notice:** This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

---

**From:** Colarusso, Phil [<mailto:colarusso.phil@epa.gov>]  
**Sent:** Tuesday, September 24, 2013 2:45 PM  
**To:** Chet Myers  
**Subject:** RE: NBMCT Blasting curtains

Chet,

Been kicking this around with some colleagues. Is there any potential to use the area around Fish Island? I don't know how much navigation occurs on the west side of the island and the shoreline, but that seems like a natural chokepoint. If one could use the island and prevent them from making their passage on the west side they may follow the channel the rest of the way. The good thing is that by the time this happens, hopefully the peak of the outward migration will have already passed.

Phil

---

**From:** Chet Myers [<mailto:cmyers@apexcos.com>]  
**Sent:** Tuesday, September 24, 2013 11:42 AM

**To:** Colarusso, Phil  
**Subject:** NBMCT Blasting curtains

Hi Phil,

Attached are a few locations that we could place curtains at a 45 degree angle to shore to help encourage fish to migrate toward the center of the Harbor.

We are trying to avoid blocking navigational traffic and/or putting structures into the Federal Channel and/or Federal Turning Basin.

Give me a call after you get a chance to look at this and we can discuss.

Thanks,

	<b>Chet Myers</b> <b>Apex Companies, LLC</b> 125 Broad Street, 5th Floor Boston, MA 02110 O) 617-728-0070 x113 M) 617-908-5778
---	--

**Follow Apex on and Like us on**

**Privacy Notice:** This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

---

**From:** Michael Tumolo  
**Sent:** Tuesday, September 24, 2013 11:40 AM  
**To:** Chet Myers  
**Subject:** NBMCT Blasting curtains

Let me know if you need any changes.

Mike T

	<b>Michael Tumolo</b> Engineer III <b>Apex Companies, LLC</b> 125 Broad Street, 5th Floor Boston, MA 02210 O) 617-728-0070
---	---

**Follow Apex on and Like us on**

**Privacy Notice:** This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg  
which may be a computer program. This attached computer program could  
contain a computer virus which could cause harm to EPA's computers,  
network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced  
into the EPA network. EPA is deleting all computer program attachments  
sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you  
should contact the sender and request that they rename the file name  
extension and resend the Email with the renamed attachment. After  
receiving the revised Email, containing the renamed attachment, you can  
rename the file extension to its correct name.

For further information, please contact the EPA Call Center at  
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg  
which may be a computer program. This attached computer program could  
contain a computer virus which could cause harm to EPA's computers,  
network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced  
into the EPA network. EPA is deleting all computer program attachments  
sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you  
should contact the sender and request that they rename the file name  
extension and resend the Email with the renamed attachment. After  
receiving the revised Email, containing the renamed attachment, you can  
rename the file extension to its correct name.

For further information, please contact the EPA Call Center at  
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*