

## EPA Official Record

---

**Notes ID:** B0F40B60CFDCE14686257A380067EAD3

**From:** Chet Myers <cmyers@apexcos.com>

**To:** Ann Williams/R1/USEPA/US@EPA; "Davis, Gary (DCR)" <gary.davis@state.ma.us>

**Copy To:** Carl Dierker/R1/USEPA/US@EPA; Jay Borkland <jborkland@apexcos.com>; Cynthia Catri/R1/USEPA/US@EPA; Phil Colarusso/R1/USEPA/US@EPA; Mike Marsh/R1/USEPA/US@EPA; "paul.j.sneeringer@usace.army.mil" <paul.j.sneeringer@usace.army.mil>; Jackie Leclair/R1/USEPA/US@EPA; Carl Deloi/R1/USEPA/US@EPA; William Walshrogalski/R1/USEPA/US@EPA

**Delivered Date:** 06/26/2012 06:53 PM EDT

**Subject:** RE: Follow up questions re New Bedford/South Terminal

Hi Ann,

As you requested, we will be sending over information as it is available. Attached please find the revised plans for the expanded Winter Flounder Mitigation Area (plus cross-sections), Revised OU-3 Capping Area (plus cross-sections), and the revised Mooring Mitigation Areas (plus cross-sections).

Please note that these plans are draft.

With regard to EPA's Question 6: After EPA's initial questions regarding tackifiers/polymer emulsions, EPA's second, third, and fourth questions appear to be asking for the justification/backup for the SER Performance Standards. Is this correct? We want to clarify, primarily because MassDEP will need to be involved to answer these questions, but also because EPA has previously accepted the SER Performance Standards during in-water work over the last two phases of Navigational Dredging, and this is the first time that these questions have come up.

Thanks!

<a href="#">[IMAGE]</a>	<b>Chet Myers</b>
	<b>Apex Companies, LLC</b>
	184 High Street, Suite 502
	Boston, MA 02210
	O) 617-728-0070      M) 617-908-5778

**Privacy Notice:** This message and any attachment(s) hereto are intended solely for the individual(s) listed in the masthead. This message may contain information that is privileged or otherwise protected from disclosure. Any review, dissemination or use of this message or its contents by persons other than the addressee(s) is strictly prohibited and may be unlawful. If you have received this message in error, please notify the sender by return e-mail and delete the message from your system. Thank you.

**From:** Ann Williams [mailto:Williams.Ann@epamail.epa.gov]  
**Sent:** Tuesday, June 26, 2012 10:03 AM  
**To:** Davis, Gary (DCR)  
**Cc:** Carl Dierker; Chet Myers; Jay Borkland; Cynthia Catri; Phil Colarusso; Mike Marsh; paul.j.sneeringer@usace.army.mil; Jackie Leclair; Carl Deloi; William Walshrogalski  
**Subject:** RE: Follow up questions re New Bedford/South Terminal

Dear Gary:

Attached are the Region's questions following our review of the Commonwealth's June 18, 2012 submission. These questions all pertain to evaluations we are making in order to prepare a draft decision. Therefore we would appreciate responses as soon as possible. If some answers are available sooner than others, we encourage the Commonwealth to provide those early responses right away rather than waiting until all of the responses are complete. In addition to the attached questions, we have also asked for information about the "Readiness Plan" in a June 20, 2012 email to you.

Please call me at 617-918-1097 if you have any questions about the attached.

Sincerely,

Ann

Ann H. Williams  
Senior Assistant Regional Counsel  
U.S. EPA Region 1  
5 Post Office Square - Suite 100  
Mail Code ORA18-1  
Boston, MA 02109-3912  
617-918-1097 (phone)  
617-918-0097 (fax)  
[williams.ann@epa.gov](mailto:williams.ann@epa.gov)

*(See attached file: EPA questions 6.25.12.docx)*

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*

This Email message contained an attachment named  
image001.jpg

which may be a computer program. This attached computer program could contain a computer virus which could cause harm to EPA's computers, network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses introduced into the EPA network. EPA is deleting all computer program attachments sent from the Internet into the agency via Email.

If the message sender is known and the attachment was legitimate, you should contact the sender and request that they rename the file name extension and resend the Email with the renamed attachment. After receiving the revised Email, containing the renamed attachment, you can rename the file extension to its correct name.

For further information, please contact the EPA Call Center at (866) 411-4EPA (4372). The TDD number is (866) 489-4900.

\*\*\*\*\* ATTACHMENT NOT DELIVERED \*\*\*\*\*



- P-2.8.pdf



- P-5.1.pdf



- P-5.2.pdf



- X-2.4.pdf



- X-5.1.pdf