

Welcome to the online source for the California Code of Regulations

16 CA ADC § 3340.41

16 CCR § 3340.41

Cal. Admin. Code tit. 16, § 3340.41

BARCLAYS OFFICIAL CALIFORNIA CODE OF REGULATIONS
TITLE 16. PROFESSIONAL AND VOCATIONAL REGULATIONS
DIVISION 33. BUREAU OF AUTOMOTIVE REPAIR
CHAPTER 1. AUTOMOTIVE REPAIR DEALERS AND OFFICIAL STATIONS AND ADJUSTERS
ARTICLE 5.5. MOTOR VEHICLE INSPECTION PROGRAM

This database is current through 7/10/09, Register 2009, No. 28
§ 3340.41. Inspection, Test, and Repair Requirements.

(a) A licensed station shall give a copy of the test report printed from the emissions inspection system to the customer. The report shall be attached to the customer's invoice.

(b) No person shall enter into the emissions inspection system any access or qualification number other than as authorized by the bureau, nor in any way tamper with the emissions inspection system.

(c) No person shall enter into the emissions inspection system any vehicle identification information or emission control system identification data for any vehicle other than the one being tested. Nor shall any person knowingly enter into the emissions inspection system any false information about the vehicle being tested.

(d) The specifications and procedures required by Section 44016 of the Health and Safety Code shall be the vehicle manufacturer's recommended procedures for emission problem diagnosis and repair or the emission diagnosis and repair procedures found in industry-standard reference manuals and periodicals published by nationally recognized repair information providers. Smog check stations and smog check technicians shall, at a minimum, follow the applicable specifications and procedures when diagnosing defects or performing repairs for vehicles that fail a smog check test.

(e) A smog check station shall not perform an initial test, except for an official pre-test, on or issue a certificate of compliance to any vehicle that has been directed to a test-only station for its biennial smog check pursuant to Sections 44010.5 or 44014.7 of the Health and Safety Code, unless the station is licensed as a test-only station pursuant to subdivision (b) of Section 44014 of the Health and Safety Code. The reinspection and certification of a test-only directed vehicle that has failed an initial test at a test-only station and has undergone subsequent repairs to correct the cause of the failure, may be performed by a test-only station, or by a test-and-repair station that performs those repairs and that is also certified as a Gold Shield station pursuant to Section 44014.2 of the Health and Safety Code and Article 10 (commencing with section 3392.1) of this chapter.

Image 1 (8.5" X 6.5") Not available for Offline Print to STP or FAX

Image 2 (8.5" X 6.5") Not available for Offline Print to STP or FAX



Image 3 (8.5" X 6.25") Not available for Offline Print to STP or FAX




Image 4 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 5 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 6 (8.5" X 6.25") Not available for Offline Print to STP or FAX




Image 7 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 8 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 9 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 10 (8.5" X 6.5") Not available for Offline Print to STP or FAX




Image 11 (8.5" X 6.5") Not available for Offline Print to STP or FAX

Image 12 (8.25" X 6.5") Not available for Offline Print to STP or FAX

Image 13 (6" X 6.5") Not available for Offline Print to STP or FAX

 [Click to View]

Image 14 (7.5" X 6.5") Not available for Offline Print to STP or FAX

 [Click to View]

Image 15 (8.25" X 6.5") Not available for Offline Print to STP or FAX

 [Click to View]

Image 16 (8.25" X 6.25") Not available for Offline Print to STP or FAX

 [Click to View]

Image 17 (8.25" X 6.5") Not available for Offline Print to STP or FAX

 [Click to View]

Image 18 (8.25" X 6.5") Not available for Offline Print to STP or FAX

Note: Authority cited: Sections 44002, 44016 and 44030, Health and Safety Code; and Section 9882, Business and Profession Code. Reference: Sections 44010.5, 44012, 44014, 44014.2, 44014.7, 44016, 44030, 44036(a) and (b), 44050 and 44051.5, Health and Safety Code.

HISTORY

1. Amendment of section heading filed 8-24-88; operative 9-23-88 (Register 88, No. 37).
2. Amendment filed 4-16-90; operative 4-16-90 (Register 90, No. 19).
3. Editorial correction of printing error correcting section heading (Register 91, No. 6).
4. Amendment of subsection (c) filed 8-18-92; operative 9-17-92 (Register 92, No. 37).
5. New section heading, new subsection (d) and amendment of Note filed 7-26-96 as an emergency; operative 7-26-96 (Register 96, No. 30). A Certificate of Compliance must be transmitted to OAL by 11-25-96 or emergency language will be repealed by operation of law on the following day.
6. Editorial correction of subsection (d) (Register 97, No. 2).
7. Certificate of Compliance as to 7-26-96 order transmitted to OAL 11-19-96 and filed 1-6-97 (Register 97, No. 2).
8. New subsection (e) and new Forms T1-T6 filed 2-1-2001; operative 2-1-2001

pursuant to Government Code section 11343.4(c) (Register 2001, No. 5).

9. Amendment of subsections (a)-(c) filed 6-9-2003; operative 7-9-2003 (Register 2003, No. 24).

10. Amendment of section heading, section and Note filed 5-30-2006; operative 6-29-2006 (Register 2006, No. 22).

16 CCR § 3340.41, 16 CA ADC § 3340.41
1CAC

16 CA ADC § 3340.41

END OF DOCUMENT

© 2009 Thomson Reuters/West. No Claim to Orig. U.S. Govt. Works.
Adobe Reader is required to view PDF images.



[Docs In Sequence](#) [Table of Contents](#)