

## **4. EVAPORATION LOSS SOURCES**

Evaporation losses include the organic solvents emitted from dry cleaning plants, surface coating operations, and degreasing operations. This chapter presents the volatile organic emissions from these sources. Where possible, the effect is shown of controls to reduce the emissions of organic compounds.