

EPA-450/2-77-012a

GRAY IRON
FOUNDRIES
AP-42 SECTION 7.10
REFERENCE No. 31

Note: This is a reference cited in AP 42, *Compilation of Air Pollutant Emission Factors, Volume I Stationary Point and Area Sources*. AP42 is located on the EPA web site at www.epa.gov/ttn/chief/ap42/

The file name refers to the reference number, the AP42 chapter and section. The file name "ref02_c01s02.pdf" would mean the reference is from AP42 chapter 1 section 2. The reference may be from a previous version of the section and no longer cited. The primary source should always be checked.

**CONTROL TECHNIQUES
FOR LEAD AIR EMISSIONS
VOLUME I:
CHAPTERS 1 - 3**

ENVIRONMENTAL PROTECTION
AGENCY

JUN 23 1980

LIBRARY SERVICES OFFICE



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Office of Air Quality Planning and Standards
Emission Standards and Engineering Division
Research Triangle Park, North Carolina 27711
Telephone: (919) 541-5271

December 1977

EPA-450/2-77-012

**CONTROL TECHNIQUES
FOR LEAD AIR EMISSIONS**

**VOLUME I:
CHAPTERS 1 - 3**

**U.S. ENVIRONMENTAL PROTECTION AGENCY
Office of Air and Waste Management
Office of Air Quality Planning and Standards
Research Triangle Park, North Carolina 27711**

December 1977

TABLE OF CONTENTS

	<u>Page</u>
SUMMARY	xix
1.0 INTRODUCTION	1-1
2.0 BACKGROUND INFORMATION	2-1
2.1 Definitions	2-1
2.2 Origin and Use of Lead	2-4
2.3 Types of Lead Emissions	2-5
2.4 Sampling and Analytical Methods	2-9
2.5 Sources of Lead Emissions	2-10
2.6 Control Devices	2-12
2.7 Fugitive Lead Emissions	2-34
2.8 Control Costs	2-36
2.9 Emission Estimates and Emission Factors	2-42
2.10 Emission Trends and Projections	2-44
2.11 Anticipated Impacts	2-52
2.12 Emergency Episode Procedures	2-58
2.13 References	2-59
3.0 COMBUSTION SOURCES	3-1
3.1 Leaded Gasoline	3-1
3.2 Coal, Oil, Waste Oil, and Solid Waste	3-76