

Gluten

# SPREAD OIL STAIN

THREE YEAR  
LIMITED WARRANTY

SPREAD OIL

Exterior stain will not crack, peel, or blister.


SPREAD OIL IS NOT OF THE  
TYPE THAT CRACKS, PEELS,  
OR BLENDS WITH THE SURFACE.

EPA Reg. No. 200-04 EPA Est. No. 200-PA-02,  
200-CA-01, 200-GA-01, 200-L-01, 200-TX-01

ACTIVE INGREDIENTS	
2, 4, 5, 6-Tetrachlorophthalonitrile	0.45%
Di (Tri-n-Butyltin) Oxide	0.30%
INERT INGREDIENTS	
	99.25%
<b>Total</b>	<b>100.00%</b>

**SOLID COLOR**  
**711 Tint Base**

**198 FL. OZ. (3 QT. 1 PT. 6 OZ.) 3.489L**



NON PHOTOCHEMICALLY REACTIVE

**PRECAUTIONARY STATEMENTS HAZARDS TO HUMANS AND DOMESTIC ANIMALS**  
**DANGER! KEEP OUT OF THE REACH OF CHILDREN. HARMFUL OR FATAL IF SWALLOWED OR ABSORBED THROUGH SKIN. CAUSES EYE AND SKIN IRRITATION. KEEP AWAY FROM HEAT AND OPEN FLAME.**  
 Avoid contact with skin, eyes, nose, mouth, throat, or clothing. If it gets in eyes or on skin or clothing, wear rubber gloves and wash with water immediately. If it gets in eyes, wash with water for 15 minutes. If swallowed, do not induce vomiting. Call a physician.  
**FIRST AID:** Wash with soap and water. Remove and wash contaminated clothing before reuse. If in eyes, immediately flush with water for 15 minutes. If swallowed, do not induce vomiting. Call a physician.  
**ENVIRONMENTAL HAZARDS:** This product is toxic to fish and wildlife. Do not apply directly to water. Do not contaminate water by cleaning equipment or disposing of waste.  
**PHYSICAL OR CHEMICAL HAZARDS:** Flammable, spontaneous combustibles. Soak oily cloths in water after use or place in a metal container far away from buildings and other combustible materials. **COMBUSTIBLE.** Do not use or store near heat or open flame.  
**STORAGE AND DISPOSAL:** Do not use or store inside the home. Do not reuse empty container. Wrap container and put in the trash can. Keep away from food and feed.

A durable wood preservative and water repellent stain for above ground use only that protects and beautifies all types of wood shingles, shakes, and rough siding, panels, and fencing. Protection and hiding of surface is usually obtainable in one coat without appreciably altering the textural beauty of wood. Lumber pre-treated with commercial preservatives should weather one season to minimize discoloration and lifting of the stain. **NOT FOR USE ON YARD FURNITURE, FLOORS OR DECKS. NOT RECOMMENDED FOR USE ON HARDBOARD (PRESSED WOOD, FIBERBOARD) OR SIMILAR MANUFACTURED BUILDING MATERIALS.**  
 NOTE: DRAMATONE® Colorant must be added to Tim Base® before application. See literature for color literature.

**DIRECTIONS FOR USE**

Do not violate Federal law to use this product in a manner inconsistent with its labeling.

**MATERIAL PREPARATION**

- Mix thoroughly, stirring with a slow rotating motion to assure color uniformity.
- Apply or thin for one coat application.
- If necessary, when applying two coats, first coat may be thinned with up to one part of paint thinner, mineral spirits, per gallon of stain. Do not thin with water or other stains or paints.
- Mix colorant with DRAMATONE Multi-Purpose Colorants only, as specified in Glidden color literature.

**SURFACE PREPARATION**

- **General and for New Wood:** All surfaces must be dry, well-ventilated, free of dirt, dust, oil, wax or any other contaminants that might affect adhesion or performance. Putty all cracks, use large pebbles with caul.
- Remove mildew. Scrub with solution of 1/2 cup bleach per quart water. Rinse thoroughly with water. Wear protective glasses and rubber gloves to avoid eye and skin irritation. Some surfaces under eaves, porches, and other recesses should be painted after other surfaces. Make sure all surfaces are in final condition.
- **Previously Finished Wood:** Remove loose, peeling, cracked paint by scrubbing. Feather sand edges. Lightly sand all hard, glossy, old finishes. On weathered surfaces under eaves, porches, etc., must be scrubbed with water to remove contaminants. Seal cracks with caul.
- **Metal (Gutters, Flashing):** Prime bare metal with No. 999 SPRED, Gloss Metal Primer. Prime bare galvanized metal with No. 998 SPRED, Gloss Galvanized Primer.

**APPLICATION**

- One gallon covers approximately 200 sq. ft. of smooth surface. Smooth, flat surfaces are 400 sq. ft. on horizontal and vertical surfaces. Coverage varies due to degree of surface texture and porosity.
- Apply on exterior surfaces only. Stir frequently during application.
- Always work from an overcast sky to assure desired results. Apply carefully, avoid dark shadows.
- Start is best done by brushing, working wet surface. Supplement with a pad applicator or brush and rollers. Spray at 1/2 to 10 ft. pressure, use spray masks or hoods. For aerosol spray, use #13 tip at 1500 psi.
- **Horizontal Work:** Do only 4 feet high at a time, extend height with a ladder. Use a brush to finish cracks, gutters, windows, and trim.
- **Vertical Work:** Do only 4 feet high at a time, complete panel at a time, finishing top to bottom.
- Do not spray when surface temperature is below 40 degrees F. Do not spray when surface temperature is above 90 degrees F.
- Do not spray when wind is blowing directly at you. Do not spray when rain is falling or is expected within 4 hours of application.
- Do not spray when equipment will be used for other purposes. Do not spray when equipment is being used for other purposes.