

Glidden

SPREED OIL STAIN

THREE YEAR LIMITED WARRANTY
Glidden SPREED O Exterior Stain will not crack, peel or blister for three years when applied according to the instructions on the label. This warranty specifically excludes labor or cost of labor.

DANGER: KEEP OUT OF REACH OF CHILDREN. FLAMMABLE.

ACTIVE INGREDIENTS
2, 4, 6-Tris-
chloro-1,3,5-triazine
(Tri-o-Buylon) Oxide 0.47%
0.30%
99.23%
100.00%
SOLID COLOR
700 White Birch
ONE GALLON 3.785

SPR Reg. No. 200-88 EPA Est. No. 200-PA-02,
200-CA-01, 200-CR-01, 200-IL-01, 200-TX-01



NON PHOTOCHEMICALLY
REACTIVE

PRECAUTIONARY STATEMENTS - HAZARDS TO HUMANS AND DOMESTIC ANIMALS

DANGER! KEEP OUT OF THE REACH OF CHILDREN. HARMFUL OR FATAL IF SWALLOWED OR ABSORBED THROUGH SKIN. CAUSES EYE AND SKIN IRRITATION. KEEP AWAY FROM HEAT AND OPEN FLAME.

Use only in well ventilated area. Do not breathe vapor or spray mist. Do not get in eyes or on skin or clothing. Wear rubber gloves and protective clothing when applying or handling freshly treated lumber.

FIRST AID: If on skin, wash with soap and water. Remove and wash contaminated clothing before reuse. If in eyes, immediately flush with water for 15 minutes. Call a physician. If swallowed, do not induce vomiting. Call a physician.

ENVIRONMENTAL HAZARDS: This product is toxic to fish and wildlife. Do not apply directly to water. Do not contaminate water by cleaning of equipment or disposal of waste.

PHYSICAL OR CHEMICAL HAZARDS: To avoid spontaneous combustion, soak any cloths in water after use or place in a closed metal container away from buildings and other combustible materials. **COMBUSTIBLE.** Do not use or store near heat or open flame.

STORAGE AND DISPOSAL: Do not use or store inside the home. Do not reuse empty container. Wrap container and put in trash receptacle. Keep away from food and feed.

A durable wood preservative and water repellent stain for above ground use only that protects and beautifies all types of wood shingles, shakes, and rough siding, panels and fencing. Protection and hiding of surface is usually obtainable in one coat without appreciably altering the textural beauty of wood. Lumber pre-treated with commercial preservatives should weather one season to minimize staining and rotting of the stain. **NOT FOR USE ON YARD FURNITURE, FLOORS OR DECKS. NOT RECOMMENDED FOR USE ON HARDBOARD (PRESSED WOOD, FIBERBOARD) OR SIMILAR MANUFACTURED BUILDING MATERIALS.**
NOTE: DRAMATONE® Colorant must be added to Tint Bases before application. See Glidden color literature.

DIRECTIONS FOR USE

Do not violate any federal law to use this product in a manner inconsistent with its labeling.

MATERIAL PREPARATION

- Mix thoroughly, stirring with a smooth lifting motion to assure color uniformity.
- Apply unthinned for one coat application.
- If necessary, when applying two coats, first coat may be thinned with up to one pint of paint thinner (mineral spirits) per gallon of stain. Do not thin with water, oils, other stains or paints.
- May be thinned with DRAMATONE Multi-Purpose Colorants, only, as specified in Glidden color literature.

SURFACE PREPARATION

- **General and for New Wood:** All surfaces must be dry, well-ventilated and cleared of dirt, dust, oil, wax or any other contaminants that might affect adhesion or performance. Fill all cracks, crevices, large openings with caulk.
- **Remove mildew:** scrub with solution of one tablespoon dry powdered laundry detergent and one quart hypochlorite type household bleach to three quarts warm water. Rinse thoroughly with water. Wear protective glasses and rubber gloves to avoid eye and skin irritation. Scrub surfaces under eaves, porch ceilings or recesses to remove accumulated contaminants. Make sure all surfaces are thoroughly dry.
- **Previously Finished Wood:** Remove blistered, peeling or cracked paint by scraping. Feather sand edges. Lightly sand all hard, glossy and finishes. Unweathered surfaces under eaves, porch ceilings, etc. must be scrubbed with water to remove contaminants. Seal all total cracks.
- **Metal (Gutters, Flashing):** Prime bare iron or steel with No. 99R SPRED Gloss Metal Primer. Prime bare galvanized metal, including aluminum, with No. 99R SPRED Gloss Galvanized Primer.

APPLICATION

- One gallon covers approximately 200-300 sq. ft. on smooth surfaces, 150-200 sq. ft. on rough surfaces and 300-400 sq. ft. on stained or painted surfaces. Coverage varies due to degree of surface texture and porosity.
- Use on exterior surfaces only. Stir frequently during application.
- Always pre-test in an inconspicuous area to assure desired results. Apply carefully to avoid dark lap marks.
- Stain is best applied by brushing, working well into surface. Supplement roller and pad application by brushing to fill crevices. Spray at 1/2 to 5/8 psi pressure. Use spray masks or hoods. For a press spray, use 5/13 tip at 1500 psi.
- **Horizontal Work:** Apply 4 to 6 boards at a time, extending each work area to structural breaks such as doors, windows, or corners.
- **Vertical Work:** Do only 4 to 6 boards or one complete pane at a time, brushing full, from top to bottom.
- Do not apply when surface or atmospheric temperatures are less than 50°F.
- Dries to touch in 6-8 hours under normal conditions (70°F, 50% R.H.). Recoat after 24 hours minimum.
- Clean up with No. 99R SPRED Brush & Roller Cleaner. Use paint thinner, mineral spirits, or kerosene to clean.

681

GGM GLIDDEN COATINGS & RESINS - Cleveland, Ohio 44115

© 1982 GCI