

SINCE 1915

# THE C-4 BRAND

## BLACK CREOSOTE COAL TAR SOLUTION

**PRESERVES AND LENGTHENS LIFE OF WOOD  
BRUSH OR SPRAY APPLICATION**

**ACTIVE INGREDIENTS**

Coal Tar Distillate	67%
Raw Coal Tar	16%
Coal Tar Acids	3%
<b>INERT INGREDIENTS</b>	<b>14%</b>

**DANGER: KEEP OUT OF REACH OF CHILDREN AND ANIMALS**

Do not get in eyes, on skin or clothing. Wash thoroughly. Keep away from food. May be fatal if swallowed or absorbed through skin. May produce severe burns. Avoid breathing spray mist. Combustible — Keep away from heat and open flame.


READ PRECAUTIONS ON SIDE PANEL

E. P. A. Registration Number 363-14

**STORE IN WARM PLACE**

EPA Est. 363-PA-1

5 GALLONS U. S. MEASURE



**DESCRIPTION**

Black Creosote is a time tested liquid wood preservative. Recommended for preservation of all types of exposed unpainted lumber such as fence posts, hinges, underground sills, sub frames, piers, bridges, boardwalks, etc. Protects against decay, rot and wood borers. For protection against termites, wood must be treated prior to use in construction.

**APPLICATION**

Lumber to be treated should be dry and seasoned before applying. When applying by brush, two flowing coats of Black Creosote applied at temperatures about 60°F is recommended. Where wood will be in direct contact with the ground, such as fence posts and heavy timbers, the wood should be peeled of bark and immersed in Black Creosote for a period of 12 to 48 hours.

When applying by brush, apply with stiff brush and cover knots, checked places and end of timber thoroughly.

**COVERAGE**

Approximately 100 square feet per gallon.

**BLACK CREOSOTE**  
**Durable Preservative for Wood**  
**Efficient Protection Against**  
**Rot or Decay**  
**and**  
**Wood Borers**  
**Successful Usage of Over 30 Years**

**ENVIRONMENTAL CAUTIONS**

This product is toxic to fish and wildlife. Keep out of any body of water. Do not apply where runoff is likely to occur. Do not contaminate water by cleaning of equipment, or disposal of wastes. Apply this product only as specified on this label.

**IMPORTANT**

Black Creosote remains in liquid about 40° F temperatures. Keep from freezing while in storage otherwise setting occurs. If exposed to temperatures below 40°F, place in warm area for 24 hours or more and shake well. Do not use on wood which is to be painted afterwards as creosote bleeds through most paints. Use Decays-Not Clear Wood Preservative for areas which are to be painted

**DANGER!**

Use with adequate ventilation. Avoid breathing of vapors and contact with the skin. Use protective cream or vaseline and wear goggles when spraying. To eliminate discomfort, wash with soap and water after use and apply vaseline.

If swallowed, **do not** induce vomiting, but call a physician at once. If product gets into eyes, flush with plenty of cold water and call a physician at once.

Do not reuse empty container. Wash equipment and containers thoroughly with water and detergent and dispose of wastes by burying in non-crop land away from water supplies. Containers should be disposed of by punching holes in them and burying with wastes.

This product will burn. Do not use, pour, spill, or store near heat or open flame. For outside use only. This product has a strong odor. Do not use where odor may penetrate to cause an odor problem. Do not use inside barns, silos, or other such structures where it may contact food and feed or livestock. Close container after each use.

**NOTICE:**

This product is offered in good faith, however, the seller is not responsible for damages of any kind caused by careless or improper handling or use.

**FOR EXTERIOR USE ONLY**

**USE THE C-4 BRAND  
AND  
C-4 YOURSELF**

MANUFACTURED BY  
**COOPERS CREEK CHEMICAL CORP.**  
 WEST CONSHOHOCKEN, PENNSYLVANIA, U.S.A. 19428

**USE THE C-4 BRAND  
AND  
C-4 YOURSELF**