

## PETTIT BOUNDAINE PAINT

CAUTION


CHER PRECAUTIONS ON BACK PANEL.

UNEPOXY
TROPIC
MEDIUM BLUE

Dec 22,1974

219

NET 1 GALLON



1.004

EPA Reg. No. 390-53



PETTIT PAINT CO., INC. BOROUGH OF ROCKAWAY, N.J. 07866 - SAN LEANDRO, CALIF. 94577

## **UNEPOXY COLORS**

Unepoxy is an effective hard racing anti-fouling boat bottom paint for various waters. It can be applied over PETTIT'S VINYLCIDE RED and most aged non-anti-fouling hard racing finishes. A small test area of Unepoxy on aged hard racing finishes is recommended to determine adhesion and compatibility to the old finish. Old, soft or semihard anti-fouling paints should be removed for best adhesion. Allow a minimum of 2 hours curing time between coats. After the final coat is applied, the boat may be launched after 8 hours minimum to within 2 months maximum.

FIBERGLASS: Wash fiberglass with PETTIT'S #12120 BRUSHING THINNER to remove parting agent, grease, and dirt. Sand thoroughly with medium grit sandpaper to dull the glossy fiberglass surface. Apply 2 coats of Unepoxy.

WOODEN HULLS: Old anti-fouling paint should be scraped to bare wood. PETTIT'S VINYLCIDE RED or aged non-anti-fouling hard racing finishes should be sanded thoroughly. If priming is necessary on bare wood, apply 1 coat of PETTIT'S RED LEAD PRIMER and let dry for 24 hours. Sand lightly and apply 2 coats of Unepoxy.

STEEL HULLS: To remove old rust and scale from the metal surface, scrape, sandblast, or wire brush. Wash the surface with PETIT'S #12120 BRUSHING THINNER to remove grease and embedded dirt. Apply 1 coat of PETTIT'S VINYL METAL PRIMER to bare metal and let dry 4 hours. Follow with 2 coats of PETTIT'S VINYL RED UNDERCOATER and let dry 2 hours between coats and 4 hours before applying 2 coats of Unepoxy.

CLEANING AND THINNING: Use PETTIT'S #12120 BRUSHING THINNER.

DO NOT USE THIS PRODUCT ON ALUMINUM HULLS. STIR PAINT THOROUGHLY BEFORE USING.

## CAUTION

## HARMFUL OR FATAL IF SWALLOWED. MAY CAUSE SKIN IRRITATION. COMBUSTIBLE.

CONTAINS COPPER COMPOUNDS AND AROMATIC HYDROCARBONS. Drink milk. Do not breathe spray mist. Do not get in eyes, on skin, or on clothing. May be absorbed through skin. In case of skin contact, remove contaminated clothing and immediately wash with soap and water. Wash clothes before reuse. Flush eyes with water. Get medical attention if irritation persists. Avoid storage near food or feed products. Do not apply to any surface that will be used by children. Do not reuse empty container. Destroy it by perforation or crushing. Bury or discard in a safe place. Do not use, pour, spill or store near heat or open flame. Do not contaminat water by cleaning of equipment, or disposal of wastes.

Use with adequate ventilation.

ONE GALLON U.S. STANDARD

KEEP OUT OF REACH OF CHILDREN.
IMPERIAL MEASURE 3 QTS. 13 FL. OZ.

EPA Est 390-NJ-1