



STEP-BY-STEP
INSTRUCTIONS
FOR REASONABLY
ACCURATE*
MEASUREMENT OF:

DMC Weed Control

FOLD OUT FOR
ILLUSTRATED
INSTRUCTIONS



NOTIFICATION
LABEL NOT REVERSIBLE
FROM PN NOTICE 88-4
DATE AUG 3 1990



Distributed by:
ProLuri Division
The O M Scott & Sons Company
Marysville, Ohio 43041

Printed in U.S.A.
All rights reserved.

MEASURING
INSTRUCTIONS
to be used with:



DMC Weed Control

1. Remove cap (A)
from container (B).





2. Place new cap (D)
and clear plastic
measuring tube (C)
on container.

3. Twist cap (D)
a quarter turn
counterclockwise
to expose opening
in lid.

4. Invert container so
material falls into
measuring tube.
Twist cap to control
and stop flow.

5. Tap measuring
tube to level
material. Check
for correct number
of ounces.

6. Carefully twist and
separate measuring
tube from cap (D)
and pour DMC Weed
Control into spray
tank.



CLF date

1-2 90

181
pms
538-240