
U.S. STANDARD



ONE GAL. NET.



ONE-COAT COPPER PAINT NAVY 16-X 473-74

CAUTION! HARMFUL IF SWALLOWED

KEEP OUT OF REACH OF CHILDREN
See other cautions on back panel

USDA REG. NO. 1719-15

Active Ingredients Cuprous Oxide...... 44.7% Total100.0%

XOOXT 473-74

MULTINE MALEUM MITS SO DNIZ WEGGALEGO

DIRECTIONS

This copper paint will protect the bottoms of bouts used in soft water from teredos, worms, barnacles, and other fouling. For best results the surface should be clean, dry, and free of any loose or scaling paint. This copper paint is suitable for wood or metal bouts.

NEW WORK: Metal halls should be cleaned by wire brushing, chipping, and scraping to remove all sust and scale. Prime by applying 2 coats of Anti-Corrosive paint according to directions on the can. When dry apply 2 coats of this copper paint allowing 4 hours drying between coats. Allow overnight if possible but at least 4 hours drying before returning the boat to the water.

Wooden boats should be clean and dry. The first coat should be thinned by adding 1/2 to 1 pint BLP MoPaxOI Low Odor Thinner 75-1 to a gallon. Allow 4 hours to dry and apply a second coat as it comes from the cm. (MoPaxOI Thinner or turpentine very be used sparingly to thin if necessary.) Allow overnight if possible but at least 4 hours drying before returning to the water.

REPAINT WORK: Immediately after removing from the water the hull should be thoroughly scrubbed with a stiff brush or broom working in running water from a hose. When all the same and slime is thus removed allow the hull to dry. Barnocles and grass should be removed by scraping and then the hull should be sanded to remove all loose and scaling paint.

METAL HULLS: Any rusted metal should be spot primed with Anti-Corrosive point after all rust has been removed. The entire hull should receive one or two coats of Anxi-Corrosive point depending on the condition of the previous coat of point and fixish as is new work above.

WOODEN HULL So After the hull has been washed, dried, and sanded apply one or two coats of copper paint as under new work above.

CAUTION: Use MoPaxOI Thinner or turpentine for thinning. Do not use Linseed Oil.

CAUTION! COMBUSTIBLE! Keep away from heat and open flome. CONTAINS COMPOUNDS HARMFUL IF EATEN. Do not apply on any interior surfaces of a dwelling, or a place used for the care of children, or on window sills, tays, cribs and other familiare which might be chewed by children. Avoid breathing vapor or spray mist and contact with skin. Wash thoroughly after handling and before eating or smoking. Keep container closed when not in use. Do not re-use empty container. Destroy it by perforating or crushing. Bury or discard in a safe place. KEEP OUT OF REACH OF CHILDREN. Use with adequate ventilation.

473-74X00XTLB



ક્રીફ