PRECAUTIONARY STATEMENTS HAZARDS TO HUMANS (and Domestic Animals)

DANGER

Corrosive. Causes severe eye damage and skin irritation. Do not get in eyes, on skin or on ciothing. Wear goggles or face shield and rubber gloves when handling. Do not take internally. Harmful or fatal if swallowed. Do not breathe vapor or spray mist. USE WITH ADEQUATE VENTILATION. Wash thoroughly with soap and water after handling and with soap and water after handling and before eating and smoking.

FIRST AID

in case of contact immediately flush in case of contact immediately flush eyes or skin with plenty of water for at least 15 minutes. For eyes call a physician. Remove and wash contaminated clothing before reuse.

If swallowed, do not induce vomiting. CALL PHYSICIAN IMMEDIATELY.

If Inhaled remove to fresh air. If not breathing give artificial respiration.

ENVIRONMENTAL HAZARDS

Do not contaminate water by cleaning of equipment or disposal of wastes.
PHYSICAL OR CHEMICAL HAZARDS

Flammable. Keep away from heat or open flame. Note — When product is used in confined areas or applied by spraying wear protective clothing and a pesticide respirator jointly approved by the Mining Enforcement and Safety Administration (formerly the U. S. Bureau of Mines) and by the National Institute for Occupational Safety and Health under the provisions of 30 CFR 11.



KEEP OUT OF THE REACH OF CHILDREN

DANGER

SEE SIDE PANEL FOR ADDITIONAL PRECAUTIONARY STATEMENTS

EPA Establishment No. 2568-MD-01 EPA Registration No. 2568-80

ACCEPTED WW 1 9 1982

JOTUN BCP MARINE COATINGS

Т

ANALYSIS

ANALYSIS
PIGMENT 53.14%
Phtalocyanine Slue, IX-D.,
Chrome Yellow
Titanium Dienide, Type II.
Zinc Oxide
Bentoalte Clay
Laert Pigments
Cuprous Oxide
Tribytyltin Fluoride
YEMIOLE 26 aces Rosin
Tricresyl Phosphate
Aromatic Hydrocarbons
Ethyl Alcohol
Additives

100.00% (C-347-D

DIRECTIONS

It is a violation of Federal Law to use this product in a manner inconsistent with its labeling.

Baltoguard is an anti-fouling paint based on Chlorina ed Rubbér. It may be used on wood, fibreglass, properly primed metal or most types of previous seasons anti-fouling paint that is in good condition.

Stir thoroughly both before and during application. Apply at least two coats-allowing 4 to 6 hours drying time between final coat and launch. Apply by brush, roller, or spray gun. Ordinarily thinning is not necessary, but where it is desired, add not more than 10% Regatta 3802 Xyiol Solvent.

SURFACE PREPARTION

FIBREGLASS: Sand the bottom thoroughly, using medium grit (about #100) paper. Wipe down carefully with REGATTA 3840 Fibreglass Solvent Wash. Use generous quantities of Solvent Wash and clean rags in order to remove the wax-like substance from the fibreglass

An alternate method of surface preparation is to use REGATTA 3840 Fibreglass Pre-Prime Wash and 3351 Fibreglass No-Sand Primer according to directions, thereby avoiding the necessity of sanding.

WOOD: Apply three coats Baltoguard directly to bare wood. Allow 4-6 hours between coats.

METAL: Apply one coat of REGATIA Vinyltex 50/51 Wash Primer followed by two coats of REGATIA 3630/3631 Epoxydur Black Mastic.

PREVIOUSLY COATED SURFACES: Sand thoroughly, then wipe down with 3802 Xylol Solvent.

STORAGE & DISPOSAL

Product that can not be used according to label instructions must be disposed of according to applicable Federal, state or local procedure.

CONTAINER DISPOSAL -- Triple rinse (or equivalent). Then offer for recycling or reconditioning, or puncture and dispose of in a sanitary landfill, or by other approved state and local procedures.

285020

1 U.S. GALLON 3.785 LITERS



JOTUN - BALTIMORE COPPER PAINT CO.

501 KEY HIGHWAY BALTIMORE, MD. 21230 (301) 539-0045

PRECAUTIONARY STATEMENTS

DANGER

HAZARD TO HUMANS AND DOMESTIC AMMALS Corrosive. Causes severe skin and

Corrocive. Causes severe skin and eye damage. Do not get on skin, cicthing or in eyes. Weer a face shield and rubber gloves when handling. Use in a well ventilated area. When used in confined areas or epplied by spraying, wear protective cicthing and a pesticide respirator jointly approved by the Mining Enforcement and Safety Administration (formerly the U.S. Bureau of Mines) and by the National Institute for Occupational Safety and Health under the provisions of 30 CFR 11. Harsful If swallowed or inhaled. Do not breathe vepore or spray mist.

PRACTICAL TREATMENT

in case of skin contact, remove conteminated clothing and immediately wash skin with soap and water. Get medical attention. Wash contaralnated clothing before rause. If inhaled, remove to fresh air. Use artificial respiration if breathing has stopped. Get medical attention. If swallowed, do not induce vomiting. This product contains petroleum distillates. Get medical attention. If in eyes, immediately flush with plenty of water. Get medical attention.

ENVIRONMENTAL HAZARDS
This product is toxic to fish. Do n

This product is textic to fish. Do not apply directly to water. Do not contaminate water by cleaning of equipment or disposal of wastes. Do not allow chips and dust generated during paint removal to enter water. Dispose of paint debris in an approved landfill.

CHEMICAL AND PHYSICAL HAZARDS

Do not use or store near heat or open flame.