



.

### WARNING! **COMBUSTIBLE!**

HARMFUL OR FATAL IF SWALLOWED

KEEP OUT OF REACH **OF CHILDREN** 

See additional warnings elsewhere on label



MANUFACTURED BY THE DOLPHIN PAINT & CHEMICAL COMPANY TOLEDO 3, OHIO, U.S.A.

# 9142 **Copper Bronze Bottom Paint**

### 9142 COPPER BRONZE BOTTOM PAINT

Active Ingredients:	33.6%
Inert Ingredients:	66.4%
	100.0%
Pigments: Copper Flakes—33.6%	33.6%
Vehicle: Phenolic Resin, Ester Gum, Hardened Rosin, Tung and Linseed Oils.	30.4%
Volatiles: Petroleum Thinner36.0%	36.0%
Copper as Metallic33.6%	100.0%

### NET CONT. 128 FL. OZS. (1 GAL.)

## QUALITY PRODUCTS SINCE 1885

### DOLFINITE COPPER BRONZE BOTTOM PAINT

A copper bronze bottom paint, containing a large portion of metallic copper bronze, producing a smooth, bright copper colored surface. Dolfinite Copper Bronze Bottom Paint has good adhesion to painted or unpainted surfaces.

DIRECTIONS FOR USE-Stir well before using and see that the surface is well sanded, clean, dry and free from dirt and grease. Allow 12 hours drying time between coats. Wait 24 hours after last coat before launching. Metal surfaces must be well primed prior to applying Copper Bronze **Bottom Paint.** 

**NEW WORK**—Three coats are recommended without thinning.

OLD WORK----The old surface should be well sanded, all loose paint removed and bare spots touched up. Apply two coats of Dolfinite Copper Bronze Bottom Paint without thinning. For a bright smooth finish, stir the paint well before using and occasionally while using.

WARNING — Contains Copper and Petroleum Distillate. Cannot be made non-poisonous. Harmful if swallowed or inhaled. May cause skin irritation or delayed chemical burns. Do Not breathe vapor, dust or spray mist. If sprayed or sanded, wear a mask to prevent inhalation. Do Not get in eyes, on skin or clothing. Clothing should be washed with soap and hot water immediately after using. Keep away from heat and open flame. Use with adequate ventilation. Close container after each use.

#### **KEEP OUT OF THE REACH OF CHILDREN**

NOTE: Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place.

U.S.D.A. Registration No. 3658-38



U.S.A.



Contraction of a

//