

BEST 4
SERVIS
BRAND

STANDARDIZED WOOD PRESERVING
CREOSOTE-100 Oil as a termite killer and repellent.

Creosote 100 contains a tenth amount of tar acid. It therefore effectively kills and repels Termites, Worms and Wood Boring insects.

BUILDINGS — Remove all loose wood from under and around buildings. Timbers to be placed in touch with foundation should be brushed or sprayed heavily with Creosote 100. Wood intended for use in contact with the soil should be brushed or sprayed with at least two coats or dipped not less than 12 to 48 hours.

FOUNDATIONS — Creosote 100 may also be used as a soil poison around foundations at the rate of 2 gallons to 5 cubic feet of soil or 1 gallon to 5 linear feet of trench. Dig a trench around the foundation of wooden structures to a depth of 30 inches, but not below the top of the footing if this is more shallow. Do not use near growing plants.

Standardized wood preserving Creosote 100 Oil is an outstanding wood preserver, termite killer and repellent. It will penetrate the wood both deeply and thoroughly. Especially refined and blended for low viscosity, Creosote 100 is easy to handle and ready to use by the Brush, Spray or Dip method. It is equally effective for above or below ground use.

Creosote-100 as a wood preserver brush or spray treatment — Apply two coats either hot or cold. Brush or spray all ends and joints of wood for at least 3 to 4 feet. Allow several hours for CREOSOTE 100 to penetrate the wood between applications.

CREOSOTE-100 A STANDARDIZED WOOD PRESERVING OIL

PROTECTS FROM ROT, DECAY AND TERMITES

ACTIVE INGREDIENT.

Creosote Oil — 100% Min. Content of Creosote Oil 100

Creosoted timber gives many times the service of un-treated wood.

WARNING:

KEEP OUT OF REACH OF CHILDREN

See Side Panels for Additional Warnings

DIPPING METHOD — Use either hot or cold. Fence posts and heavy timbers should be dipped for best results. Posts should be free of bark, dry and well seasoned. Dip for 12 to 48 hours.

WARNING: May be harmful or fatal if swallowed or absorbed through the skin. Do not splash on body or into eyes. Causes skin irritation. Avoid contact with skin and clothing. Use only where ventilation is adequate. Avoid breathing of vapors. Do not heat Creosote 100 to a temperature above 200 degrees.

Keep away from foodstuffs, pets and livestock.

Do not contaminate water by cleaning of equipment or disposal of wastes and containers.

Do not reuse empty container. Destroy it by perforating or crushing. Bury or discard in a safe place away from water supplies. Do not reuse empty drum. Return to drum merchant or destroy by perforating or crushing and burying in a safe place away from water supplies.

This product is toxic to fish and wildlife. Apply the product only as specified on this label.

NOTICE: Seller warrants that this product conforms to the ingredient statement on the label, usage conditions of use such as temperature, compatibility with other chemicals, and condition of application equipment, etc., etc. Seller makes no claims other than those stated on the label.

Crates 100-1000-15-50 Lit Content 12.5 Gal