## WRICO KMA

For control of bacterial slime in recirculating water systems.

APPLICATION: Add 50-300 ppm of Wrice KMA to the recirculating water system periodically as needed to control bacterial slime.

## ACTIVE INGREDIENTS

N n-alkyl\* -1,3-propylenediamine monoacetate Isopropyi alcohol

20.0% 10.0%

\*Alkyl groups as in the fatty acids of coconut oil.

INERT INGREDIENTS

70.0%

NET CONTENTS MARKED ELSEWHERE ON EACH CONTAINER

## WARNING:

Causes skin irritation. Do not get in eyes, on skin, or on clothing. Do not take internally. If in contact with eyes, flush with water for at least 15 minutes; see a doctor. If in contact with skin, flush with water; wash with soap and water. See a doctor if irritation persists. If in contact with clothing, remove and wash before use.

WRIGHT CHEMICAL CORPORATION 1319 Wabansia Avenue Chicago, Illinois USDA Reg. No. 5427-16

