

HET CONTENTS

5US Galacia 4 17 m. rad Gar 17 925 Litera

FARBOIL

DIRECTIONS

Preparation Do not apply any Farboil coating until surface is thoroughly cleaned of grease oil, loose paint dirt, mildew, rust scale or any other foreign material.

Apply coating to DRY SURFACE.

Farboil primer should be applied to bare or porous surface before painting.

Painting: Be sure to mix enough color at one time to do the entire job. If more than one container is used, box together thoroughly for complete color uniformity

Stir Paint Thoroughly From the Bottom.

Apply Farboil paints by brush, spray or roller

IMPORTANT: If it is necessary to paint under unusual conditions, call your Farboil Company Representative for technical advice

KEEP AWAY FROM FIRE OR OPEN FLAME

Do not re-use container, dispose of con-tainer properly when outty. Do not con-taminate vater by cleaning of equipment or disposal of vate.

FARBOIL COMPANY

A DIVISION OF BEATRICE BALTIMORE MARYLAND, U.S.A.

ACCEPTED

AUG 2 5 1975

Under the Rederal Insecticide, Fungicide, and Redemicide Act, as amended, for the posticide registered under 563373

1 (snewalink

CAUTION!

USE WITH ADEQUATE VENTI-

LATION. Avoid contact with skin

and breathing of vapor or spray

COMBUSTIBLE. Keep away from heat and open flame. Close con-

> KEEP OUT OF THE **REACH OF CHILDREN**

tainer after each use.