

nothing takes to water like . . .

Valspar[®]

**marine
finishes**

anti-fouling
BOTTOM PAINT
3594 ESCOLUX BRONZE

ONE GALLON
3.785 LITERS

WARNING! COMBUSTIBLE
HARMFUL OR FATAL IF SWALLOWED.
KEEP OUT OF REACH OF CHILDREN.
See Other Cautions on Back Panel.

*Active Ingredient
Copper as metal 36.2%
Copper Oxide .56%
Inert Ingredients 63.24%
100.00%



NO
ima
gua

water like . . .

ar®

ne

s

ng

PAINT

BRONZE

CHILDREN.

*Active Ingredient
 Copper as metal 36.2%
 Copper Oxide .56%
 Inert Ingredients 63.24%
 100.00%



ANALYSIS

Pigment—37.0%
 *Copper Bronze Powder. 100.0%
 Vehicle—63.0%
 Petroleum Hydrocarbon . 19.5%
 Tung Oil 12.7%
 Hydrogenated Rosin Ester 8.0%
 Aliphatic Hydrocarbons . 55.5%
 Aromatic Hydrocarbons . 4.3%
 100.0%

**COMBUSTIBLE
 CONTAINS
 PETROLEUM
 DISTILLATE
 AND COPPER**

If swallowed, do not induce vomiting. CALL PHYSICIAN IMMEDIATELY. Keep away from heat and open flame. Avoid prolonged contact with skin and breathing of vapor or spray mist. Close container after each use.

**Use Only With
 Adequate Ventilation.**

**KEEP OUT OF REACH
 OF CHILDREN.**

NOTE: Color shown on lid approximates color in can and is not a guarantee of an exact color match.

ESCOLUX BRONZE ANTI-FOULING BOTTOM PAINT

REPAINT WORK: If previous finish is a bronze bottom paint in good condition, clean, sand lightly and apply 2 or more coats of Anti-Fouling Escolux Bronze. If in doubt about surface condition, remove finish to bare surface and proceed as for New Work.

NEW WORK: Apply 3 or more coats of Anti-Fouling Escolux Bronze after the following special preparation:

Wood: Apply first coat thinned down with one pint of Paint Thinner per gallon of Escolux. Let dry and sand.

Fiberglass: Wash surface with foaming cleanser. Sand fiberglass thoroughly to remove all gloss. Wash with Thinner. Apply 1 or more coats of Valspar Fiberglass Primer No. 3487. Let Dry. Sand Lightly.

Aluminum: Wash with Valspar Vinyl Thinner No. 3080 then sand to remove any oxidation or other contaminants. Remove all dust and grit by washing again with Valspar Vinyl Thinner No. 3080. Apply one coat of Valspar Vinyl Wash Primer No. 3094 reduced equal part with Valspar Vinyl Wash Primer Reducer No. 3093 and allow to dry one hour. Then apply a minimum of two coats of Vinyl Zinc Chromate Primer No. 3084 allowing at least 3 hours between coats and before applying bottom paint.

NOTE: Stir paint thoroughly, before using and periodically while applying. Bronze has a tendency to settle and must be kept in a solution for best results. Covers 600 sq. ft. per gallon. Dries in 1 hour, recoat in 4 hours. LAUNCH BOAT: AFTER 48 HOURS AND PREFERABLY WITHIN 1 WEEK AFTER FINAL COAT.

DO NOT REUSE CONTAINER. DESTROY WHEN EMPTY. DO NOT USE, POUR, SPILL OR STORE NEAR HEAT OR OPEN FLAME.

E.P.A. REG. NO. 8177-11

**CONSUMER COATINGS DIVISION OF
 THE VALSPAR CORPORATION
 MINNEAPOLIS, MINNESOTA 55417**