PM-32 Reg # 8	622-49	
US ENVIRONMENTAL PROTECTION AGENCY OFFICE OF PESTICIDES PROGRAMS REGISTRATION DIVISION (75-767) WASHINGTON: DC 20460	EPA REGISTRATION NO. 8622-49	DATE OF ISSUANCE
	TERM OF ISSUANCE	528 a.g. lad
NOTICE OF PESTICIDE: REGISTRATION REREGISTRATION	Bromide Plus	
(Under the Federal Insecticide, Fungicide, and Rodenticide Act, as amended)		
NAME AND ADDRESS OF REGISTRANT (Include ZIP code)		
p	7	
Ameribrom, Inc.		
52 Vanderbilt Ave. New York, NY 10017		
New Tork, N. 1001.		
L		
NCTE: Changes in labeling formula differing in substance from that accepted in connection with this registration must be submitted to and accepted by the Registration Division prior to use of the label in commerce. In any correspondence on this product always refer to the above U.S. EPA registration number.		
On the basis of information furnished by the registrant, the shove named posticide is hereby Registered/Reregistered under the Federal Insecticide, Fungicide, and Rodenticide Act.		
A copy of the labeling accepted in connection with this Registration/Reregistration is returned herewith,		
Registration is in no way to be construed as an indorsement or approval of this product by this Agency. In order to protect health and the environment, the Administrator, on his motion, may at any time suspend or cancel the registration of a pesticide in accordance with the Act. The acceptance of any name in connection with the registration of a product under this Act is not to be construed as giving the registrant a right to exclusive use of the name or to its use if it has been covered by others.		
Based on your response to the Reregistration Eligibility Document, EPA has reregistered the above named product subject to the comments recorded in the succeeding paragraph. This action is taken under the authority of section 4(g)(2)(C) of the Federal Insecticide, Fungicide, and Rodenticide Act, as amended. Reregistration under this section does not eliminate the need for continual reassessment of pesticides. EPA may require submission of data at any time to maintain the registration of your product.		
Make the following labeling changes before you release the product for shipment:		
1. The terms "Active Ingredient" and Inert Ingredients" must be given the same prominence in the Ingredient statement on the product label.		
2. Add the following sentences to the Precautionary Statements on the second page of the submitted draft label:		
"Wash thoroughly with soap and water after handling. Remove contaminated clothing and wash before reuse.".		
ATTACHMENT IS APPLICABLE		

SIGNATURE OF APPROVING OFFICIAL

PATESEP 2 a 1345

~ 75

3. Revise the ingestion and "If On Skin" instruction in the Statement of Practical Treatment to read as follows:

If Swallowed: Call physician or Poison Control Center. Drink

one or two glasses of water and induce vomiting by

touching back of throat with finger. Do not give anything by mouth to an unconscious person.

If on Skin: Wash with plenty of soap and water. Get medical

attention.

A stamped copy of the product label is enclosed for your records.

Submit one copy of the final printed label before releasing the product in channels of trade with the revised labeling.

If these conditions are not complied with, the registration will be subject to cancellation in accordance with FIFRA sec. 6(e). Your release for shipment of the product constitutes acceptance of these conditions.

Œ)

Ruth G. Douglas Product Manager (32) Antimicrobial Program Branch Registration Division (7505C)

BROMIDE PLUS

A DISINFECTANT, SANITIZER, BACTERICIDE, SLIMICIDE, AND ALGICIDE FOR TREATING RECIRCULATING COOLING WATER SYSTEMS AND ONCE-THROUGH COOLING WATER SYSTEMS, PULP AND PAPER MILLS, AND WASTEWATER TREATMENT SYSTEMS.

SEP 20 1007 Chid the reduced insecucide, Act us

amended for the pesticide registered under EPA Resident

8600-49

KEEP OUT OF REACH OF CHILDREN

CAUTION

STATEMENT OF PRACTICAL TREATMENT

If in eyes:

Flush eyes immediately with plenty of water for at least 15 minutes.

Get medical attention if irritation persists.

If on skin:

Wash throroughly with soap and plenty of water. Remove and wash

contaminated clothing before reuse. Get medical attention if irritation

occurs.

If inhaled:

Remove person to fresh air. Get medical attention.

If swallowed:

Wash mouth thoroughly with plenty of water and give water or milk to

drink. Get medical attention immediately. Do not give liquids to an

unconscious person.

See side panels for additional precautionary statements.

EPA Reg. No. 8622-49

EPA Est. No. 707-PA-1

EPA Est. No. 8622-TX-1

EPA Est. No. 67834-OH-1

EPA Est. No. 67834-TX-1.

Manufactured by: AMERIBROM, INC.

52 VANDERBILT AVENUE NLW YORK, NEW YORK 10017

(212) 286-4000

PRECAUTIONARY STATEMENTS

HAZARD TO HUMANS AND DOMESTIC ANIMALS

CAUTION

HARMFUL IF SWALLOWED
HARMFUL IF ABSORBED THROUGH THE SKIN
AVOID BREATHING DUST
AVOID CONTACT WITH EYES, SKIN, CLOTHING

ENVIRONMENTAL HAZARDS

This product is toxic to fish and aquatic invertebrates. Do not discharge effluent containing this product into lakes, streams, ponds, estuaries, oceans, or other waters unless in accordance with the requirements of a National Pollutant Discharge Elimination System (NPDES) permit and the permitting authority has been notified in writing prior to discharge. Do not discharge effluent containing this product to sewer systems without previously notifying the sewage treatment plant authority. For guidance, contact your State Water Board or Regional Office of the EPA. Do not contaminate water by cleaning of equipment or disposal of waste. Use this product only as specified on this label.

CHEMICAL AND PHYSICAL HAZARDS

Avoid contact with strong oxidizers (except when in use), acids, alkaline and heavy metal salts.

STORAGE AND DISPOSAL

Do not contaminate water, food or feed by storage or disposal.

STORAGE: Store in a cool, will-ventilated area, in well-closed original containers.

PESTICIDE DISPOSAL: Pesticide wastes are acutely hazardous. Improper disposal of excess pesticide, spray mixture, or rinsate is a violation of Federal Law. If these wastes cannot be disposed of by use in accordance with label instructions, contact your Regional Office of the EPA for guidance.

METAL CONTAINERS: Triple rinse (or equivalent). Then offer for recycling or reconditioning or puncture and dispose of in a sanitary landfill, or by other procedures approved by state and local authorities.

PLASTIC CONTAINERS Triple rinse (or equivalent). Then offer for reconditioning, or puncture and dispose of in a sanitary landfill, or by incineration, or, if allowed by state and local authorities, by burning. If burned, stay out of smoke.

DO NOT SHIP WITH FOOD, FEEDS, DRUGS OR CLOTHING KEEP CONTAINER TIGHTLY CLOSED WHEN NOT IN USE

WARRANTS'

Seller warrants that this product conforms to its chemical description and is reasonably fit for the purposes stated on the label when used in accordance with label directions under normal conditions of use, but neither this warranty nor any other warranty of MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, express or implied, extends to the use of this product contrary to label instructions, or under abnormal conditions, or under conditions not reasonably foreseeable to Seller, and Buyer assumes the risk of any such use.

Net contents: LBS

with Comments

DIRECTIONS FOR USE

It is a violation of Federal Law to use this product in a manner inconsistent with its labeling.

BROMIDE PLUS is to be used in conjunction with an oxidant such as sodium hypochlorite (12.5%) or chlorine gas (99.9%) to produce the hypobromous acid.

BROMIDE PLUS may be added at the system inlet water or metered into the existing sodium hypochlorite piping to form a solution of sodium hypobromite. BROMIDE PLUS can be added whenever chlorination is applied, for all uses. Consult your feeder manufacturer for correct procedure and proper use of the feeder equipment.

INDUSTRIAL RECIRCULATING COOLING WATER SYSTEMS

Used effectively at dosages recommended to achieve exposures to 0.5-5.0 part per million (ppm) of 'active' residual bromine, or as needed to maintain control of algal, bacterial and fungal slimes in commercial and industrial cooling towers, heat exchange water towers, industrial water scrubbing systems, and influent systems such as flow through filters, lagoons, etc.

Dosage Rates

Initial Dose: When noticeably fouled, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to achieve the 'active' residual bromine level (0.5-5.0 ppm), measured about 5 minutes after treatment. A 0.5-2.0 mole ratio of sodium bromide to exidant is recommended. Typically, the recommended mole ratio may be achieved by using 1.5-6.0 lbs of chlorine gas (99.9%) or 1.3-5.2 gallons NaOCI (12.5%) for each gallon of BROMIDE PLUS

Subsequent Dose: When microbial control is evident, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to maintain the 'active' residual bromine level (0.5-5.0 ppm), measured about 5 minutes after treatment. Continue as in initial dose.

ONCE-THROUGH INDUSTRIAL COOLING WATER SYSTEMS

Used for the control of algal, bacterial and fungal slimes in once-through and closed-cycle fresh and sea water cooling systems. Apply BROMIDE PLUS and chlorine or sodium hypochlorite to the system inlet water or before any other contaminated area in the system.

Dosage Rates

Initial Dose: When noticeably fouled, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to achieve the 'active' residual bromine level (0.5-5.0 ppm) measured about 5 minutes after treatment. A 0.1-2.0 mole ratio of sodium bromide to oxidant is recommended. Typically, the recommended mole ratio may be achieved by using 1.5-6.0 lbs of chlorine gas (99.9%) or 1.3-5.2 gallons NaOCI (12.5%) for each gallon of BROMIDE PLUS.

Subsequent Dose: When microbial control is evident, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to maintain the 'active' residual bromine level (0.5-5.0 ppm) measured about 5 minutes after treatment. Continue as in initial dose.

PULP AND PAPER MILLS

Used for the control of algal, bacterial and fungal slimes, in pulp and paper mill fresh and sea water influent systems, cooling water systems, wasterwater treatment systems, nonpotable water systems and other process water. Apply BROMIDE PLUS with sodium hypochlorite or chlorine as directed.

Dosage Rates

Initial Dose: When noticeably fouled, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to achieve the 'active' residual bromine level (0.5-5.0 ppm), measured about 5 minutes after treatment. A 0.5-2.0 mole ratio of sodium bromide to oxidant is recommended. Typically, the recommended mole ratio may be achieved by using 1.5-6.0 lbs of chlorine gas (99.9%) or 1.3-5.2 gallons NaOCI (12.5%) for each gallon of BROMIDE PLUS.

Subsequent Dose: When microbial control is evident, add sufficient BROMIDE PLUS and chlorine or sodium hypochlorite to maintain the 'active' residual bromine level (0.5-5.0 ppm), measured about 5 minutes after treatment. Continue as in Initial dose.

WASTEWATER

BROMIDE PLUS when used as directed, will disinfect wastewater effectively. The amount of sodium, bromide required is determined by the degree of fouling. BROMIDE PLUS can be added to one or several locations of the wastewater system, if its construction permits. It is often added at the influent of the final clarifier or at the point in the system where a secondary treatment is given, prior to effluent discharge.

BROMIDE PLUS—and chlorine or sodium hypochlorite should be added in quantities sufficient to reach residual bromine levels of 0.3-1.0 ppm measured about 5 minutes after treatment. A 0.08 to 2.0 mole ratio of sedium bromide to oxidant is recommended. The treatment with BROMIDE PLUS can be evaluated by determining whether the total number of coliform bacteria and/or fecal coliform bacteria (using the MPN Procedure) has been reduced to a level permitted by governing regulations.

