

DEVOE

MARINE

PAINTS & COATINGS • WORLD-WIDE

ANTI-FOULING PAINT MD-3693

WARNING

KEEP OUT OF REACH OF CHILDREN
VAPOR HARMFUL—COMBUSTIBLE
HARMFUL IF SWALLOWED

Read carefully cautions on left panel
FOR USE BY PROFESSIONAL APPLICATORS ONLY

E.P.A. REG. NO. 9401-81

ACTIVE INGREDIENTS*	
Cuprous Oxide	12.64%
Copper Powder	1.56%
Bis (Tributyltin) Oxide	1.00%
INERT INGREDIENTS	84.80%
	100.00%

*Equivalent to 12.79% Metallic
Copper and 0.40% Metallic Tin

Directions For Use

Be sure that all surfaces are clean, free of moisture, scale, grease or oil. Remove all loose paint with wire brush or scraper. Mix thoroughly, both by stirring and then pouring from one clean container into another several times. Stir from time to time during application.

Apply one or two coats "as is" on ship bottom by brush or roller. For spraying, thin if necessary with MD-542 THINNER. Do not add oil or varnishes to this paint. Allow four hours between coats.

Anti-Fouling paints must be applied over suitable barrier coats and should not be applied directly to metal. Launching may be accomplished as soon as one hour after the final application.

MAF 3693 728A 10 5 73

DEVOE & RAYNOLDS
COMPANY, INC.

NEWARK, NEW JERSEY 07105

NEW ORLEANS, LA. 70117

SAN FRANCISCO CALIF. 94104

ALLONS

CAUTION

CONTAINS

**BIS (TRIBUTYL TIN) OXIDE
AND CUPROUS OXIDE**

DO NOT USE, POUR, SPILL OR
STORE NEAR HEAT OR OPEN
FLAME

Avoid breathing of vapor or spray
mist.

May be absorbed through skin.
Causes skin irritation.

Avoid contact with skin, eyes or
clothing.

Avoid storage near feed and food
products.

Close container after using. Do not
reuse empty container; destroy it
by perforating or crushing and
bury or discard in a safe place.

Do not contaminate water by clean-
ing of equipment or disposal of
waste.

FIRST AID: If swallowed, induce
vomiting. CALL A PHYSICIAN

In case of skin contact remove con-
taminated clothing and wash skin
with soap and water; for eyes,
flush with plenty of water and get
medical attention. Wash clothing
before reuse.

USE WITH ADEQUATE

VENTILATION

DEVON

MARINE

PAINTS & COATINGS • WORLD-WIDE

**ANTI-FOULING PAINT
MD-3696**

ACCEPT

WARNING

**KEEP OUT OF REACH OF CHILDREN
VAPOR HARMFUL — COMBUSTIBLE
HARMFUL IF SWALLOWED**

Read carefully cautions on left panel
FOR USE BY PROFESSIONAL APPLICATORS ONLY

E.P.A. REG. NO. 9461-82

5 U. S. GALLONS

ACTIVE INGREDIENTS
Cuprous Oxide
Copper Powder
Bis-Tributyltin
INERT INGREDIENTS

Equivalent to 22.3
Copper and 2.7

CAUTION

CONTAINS

**BIS (TRIBUTYL TIN) OXIDE
AND CUPROUS OXIDE**

DO NOT USE, POUR, SPILL OR STORE NEAR HEAT OR OPEN FLAME.

Avoid breathing of vapor or spray mist.

May be absorbed through skin. Causes skin irritation.

Avoid contact with skin, eyes or clothing.

Do not use for storage of feed and food products.

Close container after using. Do not reuse empty container; destroy it by perforating or crushing and bury or discard in a safe place.

Do not contaminate water by cleaning of equipment or disposal of wastes.

FIRST AID: If swallowed, induce vomiting. CALL A PHYSICIAN.

In case of skin contact remove contaminated clothing and wash skin with soap and water; for eyes, flush with plenty of water and get medical attention. Wash clothing before reuse.

USE WITH ADEQUATE

VENTILATION

DEVORE

MARINE

PAINTS & COATINGS • WORLD-WIDE

ANTI-FOULING PAINT MD-3693

WARNING

KEEP OUT OF REACH OF CHILDREN
**VAPOR HARMFUL—COMBUSTIBLE
HARMFUL IF SWALLOWED**

Read carefully cautions on left panel
FOR USE BY PROFESSIONAL APPLICATORS ONLY

E.P.A. REG. NO. 946181

ACTIVE INGREDIENTS*	
Cuprous Oxide	12.64
Copper Powder	1.56
Bis-Tributyltin Oxide	1.00
INERT INGREDIENTS	
	84.80
	100.00

*Equivalent to 12.7% Methyl
Copper and 0.4% Tin

Directions For Use

Be sure that all surfaces are clean, free of moisture, scale, grease or oil. Remove all loose paint with wire brush or scraper. Mix thoroughly, both by stirring and then pouring from one clean container into another several times. Stir from time to time during application.

Apply one or two coats (as is on ship bottom by brush or roller. For spraying, thin if necessary with MD-542 THINNER. Do not add oil or varnishes to this paint. Allow four hours between coats.

Anti-Fouling paints must be applied over suitable barrier coats and should not be applied directly to metal. Touching may be accomplished as soon as one hour after the final application.

NEWARK, N.J. 07102

**DEVORE & RAYNOLDS
COMPANY, INC.**

NEWARK, NEW JERSEY 07105
NEW ORLEANS, LA 70117
SAN FRANCISCO, CALIF 94104

5 U.S. GALLONS