

ENVIRONMENTAL HAZARDS: Do not apply directly to water. Do not contaminate water by cleaning of equipment or disposal of wastes.

PHYSICAL OR CHEMICAL HAZARDS: Flammable. Keep away from heat and open flames.

DIRECTIONS FOR USE: It is a violation of Federal law to use this product in a manner inconsistent with its labeling.

ANTI-FOULING PAINT FOR METAL BOTTOMS: Application of two coats is recommended for best performance.

Surface Preparation: Surfaces must be dry, clean, and free of dirt, dust, grease, oil, rust, loose paint, and other contaminants. Steel must be coated with suitable primer or anti-corrosive barrier coats before application of anti-fouling.

Mixing: Before use, power mix or box the paint until the product is uniform. Stir the paint at intervals during application to maintain uniformity.

Application: Apply by brush, spray or roller. Do not paint in cold or damp weather.

Thinning: Thin slightly with Thinner T-33 when required for application. Use Thinner T-33 for clean-up.

Coverage: A 2 mil dry film will be obtained at a theoretical spreading rate of 345-377 square feet per gallon, depending on the specific product used. Actual coverage will be less due to application techniques, job conditions and condition of surface.

Dry Time: At 70°F and 50% R.H., allow at least 4 hour dry time between coats, and a minimum of 8 hours before refloating.

When applied in confined areas, provide forced fresh air ventilation. Use fresh air masks and explosion-proof and non-sparking equipment.

STORAGE AND DISPOSAL

PESTICIDE DISPOSAL: Pesticide spray mixture or rinsate that cannot be used according to label instructions must be disposed of according to Federal, State and local procedures under the Resource Conservation and Recovery Act.

CONTAINER DISPOSAL: Triple rinse (or equivalent) and offer for recycling or reconditioning, or dispose of in a sanitary landfill, or by other approved State and local methods. ML-364 10-81

PRECAUTIONARY STATEMENTS HAZARDS TO HUMANS (& DOMESTIC ANIMALS) (ISH)

CONTAINS ORGANIC SOLVENT

WARNING!

FLAMMABLE
VAPOR HARMFUL
CAUSES IRRITATION
HARMFUL IF SWALLOWED



Avoid breathing vapors.
Avoid contact with eyes, skin and clothing.
Wash thoroughly after handling.
Use adequate ventilation.

Wear an air supplied mask to avoid breathing concentrated vapors in enclosed areas.
Keep container closed.

FIRST AID: If swallowed, immediately give 1 or 2 glasses of water and call a physician, hospital, emergency room or poison control center for ways to induce vomiting. Do not induce vomiting or give anything by mouth to an unconscious person. If inhaled, remove to fresh air. If not breathing, give artificial respiration, preferably mouth-to-mouth. Call a physician. In case of contact, immediately flush eyes with plenty of water for at least 15 minutes. Call a physician.