

Centurion

21



BACTERIOSTATIC WATER FILTER REPLACEMENT CARTRIDGE

"Inhibits the growth of bacteria within the filter"
CAUTION: Keep Out of Reach of Children

EPA Reg. No. 30095-2

EPA Est. No. 30030-00-1

Active Ingredient
Metallic Silver 1.05%

Inert Ingredient
Activated Carbon 98.95%


For
use on
Municipal
Tap Water
Supply

DIRECTIONS FOR USE ARE ENCLOSED WITH UNIT

Disposal — Wrap spent water filter cartridge in newspaper and discard with trash.

MANUFACTURED BY
International Water Systems, Inc.
6497 Proprietors Road
Worthington, Ohio 43085 USA

The total life of the unit is up to 3000 gallons of water, depending upon the quality and clarity of the tap water being processed. The unit is capable of treating 4 gallons of water for drinking and cooking daily for 2 years before the gallonage limitation has been reached and the filter cartridge must be replaced.



CENTURION 21-A

BACTERIOSTATIC
WATER FILTER
REPLACEMENT
CARTRIDGE



EPA Est. No. 38055-OH-1
EPA Reg. No. 38055-2

NET CONTENTS:
1 BACTERIOSTATIC
WATER FILTER
REPLACEMENT
CARTRIDGE



ACTIVE INGREDIENT
METALLIC SILVER 1.05%
INERT INGREDIENT
ACTIVATED CARBON 98.95%

READ ENCLOSED
DIRECTIONS
CAREFULLY

CAUTION: Keep Out of
Reach of Children

MANUFACTURED BY:
International Water
Systems, Inc.,
6497 Proprietors Rd.,
Worthington, Ohio
43085

Area Code:614
885-7768





Centurion[®] 21A

OWNER'S

MANUAL




WARRANTY,

SPECIFICATIONS,

AND

INSTALLATION

INSTRUCTIONS



Bacteriostatic Water Filter Unit

REPLACEMENT CARTRIDGE

CENTURION 21A BACTERIOSTATIC WATER FILTER UNIT
REPLACEMENT CARTRIDGE

INSTALLATION INSTRUCTIONS

GENERAL CLASSIFICATION

It is a violation of Federal law to use this product in a manner inconsistent with its labeling.

READ OVER BEFORE STARTING

1. Turn faucet lever to OFF position (faucet should be closed).
2. Turn saddle valve (perme unit) to OFF position clockwise.
3. Lift entire unit and place in large pan to catch any water.

NOTE!


There should be no water running from the faucet at this time.

Cut plastic strap off unit with scissors.

4. Disconnect the small 3/8" tube at base of unit from the small cartridge side only (allowing unit to drain).
5. Disconnect tubing at the top of the small cartridge (both containers will drain). Wait for drainage to stop.
6. Gently snap small cartridge out of track (F).
7. Replace with new Centurion 21A Bacteriostatic Water Filter (replacement cartridge).

READY FOR NEW TROUBLE!

8. Turn the saddle valve (perme unit) of the Centurion 21A to the ON position. Work the filter (replacement cartridge) into the saddle valve.
9. Turn the faucet lever to the ON position (allowing water to run through).
10. Turn the faucet lever to the OFF position under the saddle valve and turn the saddle valve to the ON position (counter clockwise).
11. Turn the faucet lever on with water, let faucet run for 10 minutes to flush the new cartridge filter (perme unit).
12. Turn the faucet lever off and remove. Verify that no water is running. If water is running within 10 minutes, purchase a new Centurion 21A Bacteriostatic Water Filter (replacement cartridge).



- | | |
|--------------------|------------------------------|
| A. FAUCET | G. TREATED WATER OUTLET |
| B. UNIT FAUCET | H. SELF TAPPING VALVE |
| C. HOT WATER LINE | I. T-FITTING |
| D. COLD WATER LINE | J. TREATED WATER TO ICEMAKER |
| E. WATER UNIT | K. FAUCET FITTING |
| F. TAP WATER INLET | |

INTERNATIONAL WATER SYSTEMS, INC.,

Warrants the following:

The Centurion 21A Bacteriostatic Water Filter Replacement Cartridge will be provided free from defects in both material and workmanship.

The Centurion 21A Bacteriostatic Water Filter Replacement Cartridge and all associated equipment furnished by the manufacturer will be unconditionally guaranteed for one year from date of purchase.

This warranty is limited to the replacement of the Centurion 21A Bacteriostatic Water Filter Cartridge Only. Due to the usage and wide variety of tap water, the life of the Centurion 21A Bacteriostatic Water Filter Unit Cartridge is not warranted.

Should a defect occur within the warranty period contact your local representative or the factory. IWS, Inc., will replace defective parts on the basis of F. O. B. manufacturers facility.

Failures due to accidents, fires, abuse or equipment misuse are not covered by this warranty. Service charge, transportation, and installation are not covered by this warranty.

This warranty is extended directly to the owner by the manufacturer and is the sole warranty applicable. Any other warranties or guarantees, oral or written, expressed or implied, are not recognized.

IMPORTANT! Please Note!

To Validate this warranty the enclosed registration card must be completed and mailed to IWS, Inc., within 10 days of Purchase.

To Change Filter Cartridge
or
Any Service Problems

Please contact your local representative
or
Call Area Code: 614/885-7768

or
Write to: International Water Systems, Inc.
6497 Proprietors Rd.
Worthington, Ohio 43085

OWNER'S WARRANTY REGISTRATION CARD
CENTURION 21 BACTERIOSTATIC WATER FILTER
REPLACEMENT CARTRIDGE
(Mail Within 10 days of installation)

Owner's Name _____ Phone _____
Address _____ City _____ St _____
Date Installed _____ No. in Household _____
Number of sinks in House _____ Location of Unit _____
Where Purchased _____ Price _____
Date _____ Installed By _____

Returning this card will assure you of notification of when to replace the Centurion 21 Bacteriostatic Water Filter Unit Cartridge.

The total life of the unit cartridge is up to 1000 gallons of water depending upon the quality and clarity of the tap water being processed. The unit cartridge is capable of treating 4000 gallons of water for drinking and cooking daily for 2 years. If in the 2000 gallon life cycle has been reached and the Centurion 21 Bacteriostatic Water Filter Unit Cartridge must be replaced.

Place
Stamp
Here

International Water Systems, Inc.
Plant and Executive Offices
6497 Proprietors Rd.
Worthington, Ohio
43085