

# **Geisinger Health System (Formerly: Aldan Industries, Inc.)**

**115 Woodbine Lane  
Danville, PA 17821  
Congressional District 11  
EPA ID #: PAD980551840  
Final Update**

## **Current Progress at the Site**

---

EPA has evaluated the data for this site and reports from the Pennsylvania Department of Environmental Protection showing that all past releases of hazardous waste or hazardous material have been remediated and no further action is necessary. On November 1, 2000, EPA began a Public Comment period for the proposal that no further Corrective Action is needed at Aldan. The comment period ended on December 18, 2000 and EPA did not receive any comments. On December 20, 2000, EPA issued a Final Determination that no further corrective actions are necessary at the Facility at this time.

## **Site Description**

---

The Aldan Industries, Inc. Facility in Mahoning Township, PA is an engineered coated fabrics manufacturing plant in business since August 1, 1997 and is currently subject to conditionally exempt small quantity generator regulations. Aldan Industries, Inc. has not generated any hazardous waste to date.

Prior to Aldan Industries, Inc. acquiring the site, TRW, Inc. and Textron, Inc. owned and operated manufacturing facilities at this location. These companies manufactured jet engine components and generated spent halogenated solvents, wastewater treatment sludge, and chromium and lead containing wastes. In January 1987, TRW, Inc. retained a consulting firm to conduct a hydrogeologic investigation to identify areas of environmental concern. An assessment revealed contaminated soils beneath the waste oil storage area and machine cleaning operations area. Monitoring wells revealed some groundwater impact. Under the cleanup, 265 cubic yards of soil were removed. The groundwater only required monitoring for 1 year. On February 11, 1988, TRW's consultant submitted a final report documenting completion of the site remediation. A recent review of the January 1988 report entitled "Soil Removal and Disposal Project" confirms the results of the analyses in the report and shows that all contaminants tested were below the current Statewide Health Standards established by Pennsylvania's Land Recycling and Environmental Remediation Standards Act (Act 2).

## Site Responsibility

---

---

RCRA Corrective Action activities at the Facility are being conducted under the direction of EPA Region 3 with assistance from the State.

## Institutional Controls

---

---

## Government Contacts

---

---

EPA Branch Chief  
Mr. Paul Gotthold - 3WC22  
U.S. Environmental Protection Agency - Region III  
1650 Arch Street  
Philadelphia, PA 19103-2029  
Phone: (215) 814-3410  
Email: [gotthold.paul@epa.gov](mailto:gotthold.paul@epa.gov)

Mr. John Hamilton  
Pennsylvania Department of Environmental Protection - Northcentral Region  
208 West Third Street  
Williamsport, PA 17701  
Phone: (570) 327-3651  
Email: [johamilton@state.pa.us](mailto:johamilton@state.pa.us)

For more information about EPA's corrective action webpage, including Environmental Indicators, please visit our site at: [www.epa.gov/reg3wcmd/correctiveaction.htm](http://www.epa.gov/reg3wcmd/correctiveaction.htm)